

A Safety Gate home (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

E Back to report listings (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2019&Ing=en

Q Search alerts (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search&lng=en)

Safe Products Online (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline)

The Rapid Alert System for Non-Food Products (RAPEX)

RAPEX - Weekly overview report of notifications

Week 39 - 2018



Alert number: A12/1383/18 Product: Earrings Name: Earrings "Spinne" Risk type: Chemical Category: Jewellery Brand: Orlob Accessoires Type / number of model: Article 5371 Risk level: Serious risk The earrings contain cadmium (measured value: 0.025% by weight). Cadmium is harmful to human health, because it accumulates in the body and can damage organs and may cause cancer. The product does not comply with the REACH regulation. Withdrawal of the product from the market Description: Silver-coloured earrings in the form of a spider's web with a spider, attached to a piece of black cardboard. Batch number / Barcode: 4260362027282 Country of origin: China Alert submitted by: Germany



Alert number: A12/1396/18 Product: Earrings Name: Unknown Risk type: Chemical Category: Jewellery Brand: Mosaic Type / number of model: A11092 Risk level: Serious risk The product releases an excessive amount of nickel (measured value: 0.67 µg/cm²/week). Nickel is a strong sensitiser and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin.

The product does not comply with the REACH Regulation.

Recall of the product from end users

Company recall page: https://mosaic.andmorefashion.com/toote-tagasikutsumine (https://mosaic.andmorefashion.com/toote-tagasikutsumine) **Description:** Earrings fixed to a grey cardboard label.

Batch number / Barcode: (EAN 4748305789652)

Country of origin: China

Alert submitted by: Estonia

Products were found and measures were taken also in: Latvia



Alert number: A12/1400/18 Product: Culinary siphon Name: Siphon tout inox Risk type: Injuries Category: Kitchen/cooking accessories Brand: MATHON Type / number of model: Reference No 57398 Risk level: Serious risk The product can explode during use, projecting fragments in the air. This can cause injuries to the user. The product does not comply with the requirements of the Pressure Equipment Directive. Withdrawal of the product from the market

Withdrawal of the product from the market **Description:** Stainless steel, whipped cream siphon 0.5 L. The product has been sold online. **Batch number / Barcode:** 3700541206356 **Country of origin:** China **Alert submitted by:** France



t Marcelli





Alert number: A12/1406/18 Product: Laser pointer with LED light Name: LASER & LED LIGHT Risk type: Damage to sight Category: Laser pointers Brand: Unknown Type / number of model: 2 in 1 LASER & LED LIGHT, 3 in 1 LASER & LED LIGHT & Carabiner Risk level: Serious risk The product does not have the necessary warnings related to its use. The direct entry of the laser beam into the eye can lead to damage to sight.

The product does not comply with the relevant European standard EN 60825-1 with regard to labelling.

Withdrawal of the product from the market **Description:** Laser pointer embedded with LED flash light and a key chain holder. The device has three operating buttons and is powered by cell batteries.

Batch number / Barcode: 6911614894036 Country of origin: China Alert submitted by: Cyprus





Alert number: A12/1431/18 Product: LED Lighting chain Name: Lampki choinkowe LED Risk type: Electric shock Category: Lighting chains Brand: YS Type / number of model: 1) 304B, 2) 306WW (306ML), 3) 07W Risk level: Serious risk The electrical insulation is inadequate and live parts may become accessible. Moreover, the controller is not sufficiently resistant to moisture. This can result in an electric shock for the user.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598. Withdrawal of the product from the market

Description: LED lighting chains with 100, 200 or 300 lights (depending on the model). Packaging: cardboard box **Batch number / Barcode:** 1) 8401501133044, 2) 8401501113077, 3) 8401501133068 **Country of origin:** China **Alert submitted by:** Poland



Alert number: A12/1393/18 Product: Portable lamp Name: Lampa Risk type: Electric shock Category: Lighting equipment Brand: MARKET Type / number of model: ITEM NO: 140802105 Risk level: Serious risk The insulation is inadequate. Moreover, the power cord can easily detach or become damaged, giving access to live parts. This could result in an electric shock for the user.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598-1. Withdrawal of the product from the market

Description: Clip-on lamp, height approx. 23 cm, sold without packaging. Label attached to the product. **Batch number / Barcode:** EAN: 4008021055005 **Country of origin:** Unknown

Alert submitted by: Poland



Alert number: A12/1394/18 Product: Nightlight Name: LED Night Lighting Risk type: Electric shock Category: Lighting equipment Brand: Qiaolian Type / number of model: Ref: 92032 Risk level: Serious risk The nightlight in the form of a flower may be attractive to children, who may consider it a toy. A child may pull the light out of the socket and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598. Withdrawal of the product from the market

Description: Nightlight made of transparent plastic material. When plugged into a socket, the lamp produces multi-coloured light. Packaged in a transparent blister pack with cardboard back.

Batch number / Barcode: 8787247920323 Country of origin: China

Alert submitted by: Poland









Alert number: A12/1426/18 Product: Children's night light Name: Fashion Plastic lamp Risk type: Electric shock Category: Lighting equipment Brand: Unknown Type / number of model: Unknown Risk level: Serious risk The light lacks a SELV (safety extra-li

The light lacks a SELV (safety extra-low voltage) device and an earth connection and the insulation is inadequate.

As a consequence, 240V from the mains are supplied to the product and live parts are accessible. The device could be connected to the mains supply without an earth connection, leading to an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598. Withdrawal of the product from the market

Description: A night light with cartoon characters on its shade. Batch number / Barcode: 8441780000279 THE PRODUCT IS COUNTERFEIT Country of origin: China Alert submitted by: Malta









Alert number: A12/1381/18 Product: Motorcycle Name: DL250 Risk type: Injuries Category: Motor vehicles Brand: Suzuki Type / number of model: Types: WDS0; EC type-approval: e4*168/2013*00069*01; Risk level: Serious risk The mounting inserts for the top case rack may not be strong enough. As a consequence, the top case rack could break and the top case fall onto the road, hindering following traffic. Recall of the product from end users Description: Motorcycle Batch number / Barcode: The part concerned is the Top Case rack for the Suzuki DL250 model produced before 16 February 2018. Country of origin: Japan Alert submitted by: Germany Products were found and measures were taken also in: Poland, Sweden

Airt number / M2193078 Product: Pease prove of the section of the sectin of the section of the section of the section of the sectin of t		
Name: Cales, E-Gase, Kerker Risk type: Fire Gategory, Motor whickes Band: Mercade-Searc Type / number of model: Type approval numbers: e1/2001/11/10/431/48, e1/2007/48/1680*06; types: 205, 238 Risk kerke: Searcs and the conservative sreating from oppration at full load coll of the oxver catching fire. Read of the product from end users Description: Pascing compary read code: 520150 Bath number / Barcode: Vehicles produced during March 2018 are affected. Country of angin: Cammary Product: Presengen com Name: GL, GEL, GLS, ML Risk type: Fire Category, Motor whiches Bath number / A12136518 Product: Presengen com Name: GL, GLE, GLS, ML Risk type: Fire Category, Motor whiches Band: Marcade-Barc Type / number of model: Type approval numbers: e1/2007/46/0582/01-19, e1/2007/46/0522-27; types: 166, 166 AMG Risk type: Envire Category, Motor whiches Bard: Marcade-Barc Type / number of model: Type approval numbers: e1/2007/46/0582/01-19, e1/2007/46/0522-27; types: 166, 166 AMG Risk type: Envires Category: Motor whiches Bard: Marod Marcade-Barc Type / number o	r t number: A12/1382/18	
Risk ope: Fine Genegory: Kelor vehices Genegory: Kelor vehices Genegory: Kelor vehices Read of the pockutor vehices Read of the pockutor form end users Read of the pockutor form end users Read of the pockutor form end users Bescription: Passenger car. Company recall code: 520/160 Betch number / Readow: Starkow of the destance is 200/161 Betch number / Readow: Readow of the pockue during March 2015 are affected. Country of origin: Genmany Product: Passenger car. Country of origin: Genmany Product: Passenger car. Country of origin: Genmany Product: Passenger car. Nume: C.L. CLE, CLS, ML Number / Al 21386/18 Product: Passenger car. Nume: C.L. CLE, CLS, ML Number of Index Tary Starkow of the components: As a consequence it may ignite and lead to free. Country of origin: Genmany Product: Passenger car. Nume: CL, CLE, CLS, ML Number of Index Tary Starkow of Type approval numbers: at 2207146/0588/101-19. at 12007146/0828/102-07, types: 186, 166 AMG Yrge / number of Index Tary Starkow of Type approval numbers: at 2207146/0588/101-19. at 12007146/0828/102-07, types: 186, 166 AMG Yrge / number of Index Tary Starkow of Type approval numbers: at 12007146/0588/101-19. at 12007146/0828/102-07, types: 186, 166 AMG Yrge / number of Index Adres Count of components: As a consequence it may ignite and lead to free. Country of origin: Genmany Products Passenger car under recall code AdsHS31. Betch number, 712038/18 Product: Yan Nume: Product: Type approval number: El'2007146/0587* and El'2200746/0587* jupe: Y Read Week Starbad risk Country of origin: Genmany Products were found and measures were taken also in: Croata, Estonia, Finland, Leeland, Luzenbourg, Poland, Slowakia, Slo	-	
Category: Motor vehicles Type I number of model: Type approval numbers: e1*2007/45/148, e1*2007/45/1660/05; types: 205, 238 Rik level: Seloci in Rik The lower engine compartment cover liab: the nocessary left-hand gap for the exhaust system. As a result, the exhaust system temperatures resulting from operation at full load could lea to the cover catching file. Recall of the product from and users Description: Passenger car. Company recall code: 8200150 Batch number / Barcode: Vehicles produced during March 2018 are affected. Country of origin: Gommany Aler stabulited by: Genmany Product: wer found and measures were taken also in: Poland, Sweden Aler stabulited by: Genmany Aler stabulited by: Genmany Aler stabulited by: Genmany Aler stabulited by: Genmany Product: Were found and measures were taken also in: Poland, Sweden Aler stabulited by: Genmany Aler stabulited by: Genmany Aler stabulited by: Genmany Aler stabulited by: Genmany Product: Were found and measures were taken also in: Poland, Sweden Aler stabulited by: Genmany Product: Were found and measures were taken also in: Poland, Sweden Aler stabulited by: Genmany Products were found and measures were taken also in: Costa, Estonia, Finland, Lostand, Lostand, Lostand, The aler also godd were manufactured between November 2010 and June 2016. Country of origin: Genmany Product: were found and measures were taken also in: Costa, Estonia, Finland, Iosland, Ireland, Lusembourg, Poland, Slovakia, S		
Brand: Merodes/Benz ''''''''''''''''''''''''''''''''''''		
Type I runber of model: Type-approval numbers: at 2001/16/10/31146, et 2007/46/16/6/06; types: 205, 238 The lower angine compartment cover lacks the necessary link-hand gap for the axhaut system. As a rost, the downal system temportners mayling from oporation at full load could lead to the cover catching fre. Rocal of the product from net users Description: Rescription:		
Risk Levi: Serious risk As a result, the orheads system tomporatures resulting from operation at full lead could lead to the cover catching free. Recail of the product from end users Description: Presenger car. Company recail code: (520150) Batch number: Alzerode: Vehicles produced during March 2018 are affected. County of orlin: Genamy Alert submitted by: Genamy Product: Presenger car. Name: GL, CEE, CES, ML Risk type: Fine Category: Mole control of the product. Product: Presenger car. Name: GL, CEE, CES, ML Risk type: Fine Category: Mole control of the Addition of the product. Product: Presenger car under seal control of the network on operation of the making out. Oil may leak out as pray onth to the contropenets. As a consequence it may ignite and lead to free. Recall of the product. Presenger car under recall code 4894531. Batch number / Barcode: Presenger car under recall code 4894531. Batch number / Barcode: Presenger car under recall code 4894531. Batch number / Barcode: Presenger car under recall code 4894531. Batch number / Barcode: Presenger		
The lower angine comparison cover leaks the necessary (infhand gap for the exhaust system. As a result, the output of the product from real users Description: Passengre car. Compary recall code: (2001 50) Batch number / Barcode: Whiteles produced during March 2018 are alfected. Country of origin: Sommany And submitted by: Germany And submitted by: German		
As a result, the exhaust system temperatures resulting from operation at full load could lead to the cover catching fire. Recail of the product from end users Description: Passenger car. Company recail code: 620150 Earth number Racodes: Vehindes produced during March 2018 are affected. Country of origin: Gemmany Products were found and measures were taken also in: Poland, Sweden And submitted for during March 2018 are affected. Country of origin: Gemmany Product: Reserves of the Adive Counter System's oil reservoir does not prevent oil from leaking out. Counter of the Adive Counter System's oil reservoir does not prevent oil from leaking out. Counter of the Adive Coure System's oil reservoir does not prevent oil from leaking out. Court as easting and the Adive Coure System's oil reservoir does not prevent oil from leaking out. Court as easting and the Adive Coure System's oil reservoir does not prevent oil from leaking out. Court of origin: Gemmany Alert submitted out from ord users Description: Passenger car under recail code 4094531. East number: Ratorode: The affected vehicles were manufactured between November 2010 and June 2016. Courting of origin: Gemmany Alert submitted by: Gemmany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Luxembourg, Poland, Slovakia, Slovavia, The Netherlando, Slova vehicles Brand:		
Recall of the product from and users Description: Reserve arc. Company recall code: 6200150 Barch number / Barcode: Vehicles produced during March 2018 are affected. Country of origin: Gommany Alert submitted by: Germany Products were found and measures were taken also in: Poland, Sweden And number / Barcode: Type approval numbers: aff2007/46*0598*01-19, aff2007/46*0528*02-07; types: 166, 166 AMG Risk type: Find Category: Motor vehicles Find: Mercode: Seene Seene Type / number of model: Type-approval numbers: aff2007/46*0598*01-19, aff2007/46*0528*02-07; types: 166, 166 AMG Risk two: Second and measures were taken also in: Poland, Sweden The seening cap of the Active Curve System's oil reservoir does not prevent oil from leaking out. Oil may leak out and spary on tho to components. As a consequence II may light and lead to fire. Recall of the product: from and users Description: Takenge: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products Were found and measures were taken also in: Croatis, Estonis, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakis, Slovenia, The Nethertands Alert number: A12138A/18 Product: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products Were found and measures were taken also in: Croatis, Estonis, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakis, Slovenia, The Nethertands Alert number: A12138A/18 Product: Wei Second and Measures Were taken also in: Croatis, Estonis, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakis, Slovenia, The Nethertands Alert number: A12138A/18 Product: Wei Second and Measures Were taken also in: Croatis, Estonis, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakis, Slovenia, The Nather: Second and Measures Were taken also in: Croatis, Estonis, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakis, Slovak		
Batch number / Barcoler: whiteles produced during March 2018 are affected. Country of origin: Germany Products were found and measures were taken also in: Poland, Sweden Alert aubhited by: Germany Products: Passenger car Name: GL, GLE, GLS, ML Nisk type: Fine Category: Motor whiteles Brand: Mercedee Benz Type / number of model: Type-approval numbers: e1*2007/46*0589*01-19, e1*2007/46*0528*02-07; types: 166, 168 AMG Risk teve: 58 could and measures are taken also during the and lead to fre. Read if the product source System's all reservoir does not prevent oil from leaking out. Oil may leak out and spray onto hot component. As a consequence it may ignite and lead to fre. Read if the product from and users Description: Passenger car underscal Description: Passenger car Name: Froace Risk type: injuries Category: Motor vehicles Brand: Troyte Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk type: injuries Category: Motor vehicles concerned were manufactured between June 2016 and December 2017. County of origin: France Passenger et and and measures were taken also in: Sweden Alert submitted by: Germany Product: Kan Company recall Code: 188MD-061 Risk type: injuries Category: Motor vehicles Risk type: injuries C		
Country of origin: Germany Andr submitted by: Germany Products were found and measures were taken also in: Poland, Sweden Alort number: A12138716 Product: Polarisenger cor Nume: GL, GLE, GLS, NL Risk type: Fire Category: Klofor vehicles Brand: Klercades: Benz Type / number of model: Type-approval numbers: of 12007/46*0598*01-19, of 12007/46*0626*02-07; types: 166, 166 AMG Risk texe: Serious risk The sealing cap of model: Type-approval numbers: of 12007/46*0598*01-19, of 12007/46*0626*02-07; types: 166, 166 AMG Risk texe: Serious risk The sealing cap of model: Type-approval numbers: of 12007/46*0598*01-19, of 12007/46*0626*02-07; types: 166, 166 AMG Risk texe: Serious risk The sealing cap of model: Type-approval numbers: of 12007/46*0598*01-19, of 12007/46*0626*02-07; types: 166, 166 AMG Risk texe: Serious risk The sealing cap of model: Type-approval numbers: a consequence it may ignite and lead to fire. Recall of the product from end user Description: Passenger car under recall code 46904531. Batch number / A1211386/18 Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovaki, Slovakia, Slovakia, Slovakia, Slov	scription: Passenger car. Company recall code: 6290150	
Alert aubinited by: Germany Product: Passenger car Name: Cli, OL; GLS, ML Rick type: Fire Category: Moor vehicles Brand: Mercades-Benz! Type / number of model: Type-approval numbers: e1*2007/46*0589*01-19, e1*2007/46*0282*02-07; types: 166, 166 AMG Rick type: Sing cli be Acbe Curve System's oil reservoir does not prevent oil from leaking out. Oil may leak out and spray on tho to components. As a consequence it may ginite and lead to fire. Recall of the product from ond users Description: Passenger car under recall code 4804531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Product: were found and measures Product: Were found and measures were taken also in: Croatia, Estonia, Finland, Ioeland, Ireland, Luxembourg, Polend, Slovakia, Ta Name: Fraeco Rick type: Injuries Category: Motor vehicles Brand: Toyle: Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Rick type: Injuries Category: Motor vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Brand: Toyle: Product: were found and measures were taken also in: Sweden Mert autor counting device can become difform the valicle and the tailer night become detached from the vehicle. Recal of the product from on difform of the valicle and the tailer night become detached from the vehicle. Recal of the product from on difform of the vehicle and the tailer night become detached from the vehicle. Recal of the product from on difform of the vehicle and the tailer night become detached from the vehicle. Recal of the product from on difform of the vehicle and the tailer night become detached from the vehicle. Recal of the product from on difform of the vehicle and the tailer night become detached from the vehicle. Recal of the product from o	ch number / Barcode: Vehicles produced during March 2018 are affected.	
Product sever found and measures were taken also in: Poland, Sweden Abert number: A12/1385/18 Product: Passenger car The Sealing Cap of Index Stever Steve Stevee Steve	untry of origin: Germany	
Addrt number: A12/1385/18 Product: Passenger car Name: GL, GLS, ML Risk type: Fire Category: Motor vehicles Brand: Micro3des Benz Type / number of model: Type-approval numbers: e1*2007/46*0598*01-19, e1*2007/46*0826*02-07; types: 166, 166 AMG Risk type: Store in the other of model: Type-approval numbers: e1*2007/46*0598*01-19, e1*2007/46*0826*02-07; types: 166, 166 AMG Risk two: Store in the other other of model: Type-approval numbers: e1*2007/46*0598*01-19, e1*2007/46*0826*02-07; types: 166, 166 AMG Risk two: Store in the other	rt submitted by: Germany	
Product: Passenger car: Name: GL, GLS, GLS, ML Name: GL, GLS, GLS, ML Risk type: Fire Gategory: Moor vehicles Brand: More decession: Type / number of model: Type-approval numbers: e1*2007/46*0589*01-19, e1*2007/46*0582*02-07; types: 166, 166 AMG Risk tevel: Social sink The sealing cap of the Addre Curve System's oil reservoir does not prevent oil from leaking out. Oil may lack act und spary onth hot components. As a consequence it may lighte and lead to fire. Recal of the product from end users Description: Passenger car: under recall code 4844331. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slova	uducts were found and measures were taken also in: Poland, Sweden	
Name: Cit, Cit, Cit, Sul. Risk type: Fire Category: Motor vehicles Brand: Microdes-Benz Type / number of model: Type-approval numbers: e1*2007/46*0598*01-19, e1*2007/46*082*02-07; types: 166, 166 AMG Risk level: Senious risk The sealing cap of the Active Curve System's oil reservoir does not prevent oil from leaking out. Oil may leak out and spray onto hot components. As a consequence it may ignite and lead to fire. Recall of the product from end users Description: Passenger car under recall code 4604631. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Methenands Alert number: A12/1386/18 Product: Were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Wen Product: Wen Product: Wen Risk type: Inpuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Senious risk The trailer coupling device can become deformed if a trailer is used. If this cours, it may become difficut to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from and users Description: Van. Company recall code: 188MD-081 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert number: A12/1387/18 Product: Went Found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Sout, Sout Sky, Sout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk teve: Senious risk There might be air In the brake liquid circuit of the ABS system. This can c	e rt number: A12/1385/18	
Risk type: Fire Gategory: Motor vehicles Brad: Mecceles-Benz Type / number of model: Type-approval numbers: e1'2007/46'0598'01-19, e1'2007/46'0826'02-07; types: 166, 166 AMG Risk text: 6atou sink The sealing cap of the Active Curve System's oil reservoir does not prevent oil from leaking out. Oil may leak out out a spray ontho to components. As a consequence it may ignite and lead to fire. Recall of the product from end users Description: Passenger car under recall code 4694531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Aret submitted by: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Lukembourg, Poland, Slovakia,	pduct: Passenger car	
Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Type-approval numbers: e1'2007/46'0588'01-19, e1'2007/46'022'02-07; types: 166, 166 AMG Rik kevi: Serious risk The sealing cap of the Active Curve System's oil reservoir does not prevent oil from leaking out. Oil may leak out and spray onto hot components. As a consequence it may ignite and lead to fire. Recall of the product from end users Description: Passenger car under recall code 4694531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert submitted by: Germany Product were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2'2007/46'0537' and E2'2007/46'0538'; type: V Risk teve: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from and users Description: Van. Company recall code: 18SMD-061 Batch number: A12/1387/18 Product: were found and measures were taken also in: Sweden Alert submitted by: Germany Product were found and measures were taken also in: Sweden Alert submitted by: Germany Product were found and measures were taken also in: Sweden Alert submitted by: Gorts with Risk twei: Serious risk The raile: Suesius Suest Submoted Risk twei: Serious risk The raile: Suest Submoted Risk twei: Ser	me: GL, GLE, GLS, ML	
Branz. Mercedes-Benz Type / number of model: Type-approval numbers: e1/2007/46/0588/01-19, e1/2007/46/0826/02-07; types: 166, 166 AMG Rik level: Serious risk The sealing cap of the Active Curve System's oil reservoir does not prevent oil from leaking out. Oil may leak out and spary on the to components. As a consequence it may ignite and lead to fire. Recall of the product from end users Description: Passenger car under recall code 4694.631. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. County of ofigin: Germany Aret submitted by: Germany Products were found and measures were taken also in: Croatis, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Aret number: 12/1386/18 Produet: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyla Type / number of model: Type-approval number: E2'2007/46'0537' and E2'2007/46'0538'; type: V Risk level: Serios risk The trailer coupling device can become deformed if a trailer is used. If this cours, it may become difficul to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: ISMND-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert number: A12/1387/18 Product: Watorcycle Name: Scout, Skout Skout Bobber Risk type: Injuries Category: Motor vehicles Branz: Indian Motorycle Company Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Skout Skout Bobber Risk type: Injuries Category: Motor vehicles Branz: Indian Motorycle Company Type Innuber of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Branz: Indian Motorycle Company Type Innuber of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Branz: Indian Motorycle Company Typ	k type: Fire	
Type / number of model: Type-approval numbers: e1*2007/46*0588*01-19, e1*2007/46*0582*02-07; types: 166, 166 AMG Risk level: Sarious risk The sealing cap of the Active Curve System's oil reservoir does not prevent oil from leaking out. Oil may leak out and spray onto hot components. As a consequence it may ignite and lead to fire. Recall of the product from end users Description: Passenger car under recall code 4694531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products were found and measures were taken also in: Creatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: Alert Number: Alert Number: Alert Number: View: View: Sinview: Sinview: Category: Not vehicles Sinview: Sinview: Brad: Toyla Type-approval number: E2*2007/46*0538*; type: V Risk Ivee: Next leve: Sarious rak Trace Risk Ivee: Sarious rak The taller couping device can become deformed if a trailer is used. If The trailer sought abs become delached from the vehicle. Rescal of the product from end users	tegory: Motor vehicles	
Risk beel: Serious risk The sealing cap of the Active Curve System's oil reservoir does not prevent oil from leaking out. Oli may leak out and spray onto hot components. As a consequence it may ignite and lead to fire. Recall of the product from end users Description: "Seasenger car under recall code 4694531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Adert submitted by: Germany Products were found and measures were taken also in: Creatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Nethertands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk type: injuries Category: Motor vehicles Brand: Toyota The traiter coupling device can become deformed if a trailer is used. If this accurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recail of the product from end users Description: Van. Company recail cade: 18SMD-061 Batch number: A12/1387/18		
The sealing cap of the Active Curve System's oil reservoir does not prevent oil from leaking out. Oil may leak out an spray onto hot components. As a consequence it may ignite and lead to fire. Recall of the product from end users Description: Passenger car under recall code 4694531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Alert submitted by: Germany Products were found and measures were taken also in: Creatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1366/18 Products were found and measures were taken also in: Creatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Category: Motor vehicles Brane: Proace Risk type: Injuries Category: Motor vehicles Brane: Toyota Type / number of model: Type-approval number: E2'2007/46'0537* and E2'2007/46'0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, Iru, may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 158MD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert submitted by: Germany Products: Korotycle Name: Scout, Scout Skyt, Scout Bobber Risk type: Injuries Category: Motorycle. Risk type: Injuries Category: Motorycle. Risk type: Injuries Category: Motorycle. Risk teve: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Winder States Category: Motorycle. Risk teve: Serious risk There might be air in the brake liquid cincuit of t		
Oil may leak out and spray onto hot components. As a consequence it may ignite and lead to fire. Recall of the product from end users Description: Passenger car under recall code 4694531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyla Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: Erance Alert submitted by: Germany Product: Moor vehicles Brand: Indian Motorycle Company Product: Woor vehicles Brand: Indian Motorycle Company Product: Woor model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Product: Motorycle. Brand: Indian Motorycle Company Product: Mot		
Recall of the product from end users Description: Passenger car under recall code 4694531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Alert submitted by: Germany Products were found and measures were taken also In: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: Injuries Category: Molor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Stxty, Scout Bobber Risk type: Serious risk Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number: A12/1387/18 Product: wotorcycle Name: Scout, Scout Stxty, Scout Bobber Risk type: Serious risk Risk type: Risk type: Risk type: Risk type: Risk Risk Risk Risk Risk Risk Risk Risk		
Description: Passenger car under recall code 4694531. Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: Injuries Category: Molor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk tevel: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: *un. Company recall code: ISSMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products: Wolorcycle Name: Scout, Scout Skity, Scout Bobber Risk type: Injuries Category: Molor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk tevel: Serious risk There might be air in the preformance of the brake, which could increase the risk of accident. Recall of the product from end users Description: *Motorycle Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk tevel: Serious risk There might be air in the preformance of the brake, which could increase the risk of accident. Recall of the product from end users Description: *Motorycle Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdorn		
Batch number / Barcode: The affected vehicles were manufactured between November 2010 and June 2016. Country of origin: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, if may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert number: A12/1387/18 Product: Motorcycle Name: Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Woder year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	·	
Country of origin: Germany Aert submitted by: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toroja Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk levei: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 185MD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Stout, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorcycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might beake liquid circuit of the ABS system. This can cause a descrease in the parformance of the brake, which could increase the risk of accident. Recall of the product form end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United States		
Alert submitted by: Germany Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk Ievei: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Product: Motorcycle Name: Socut, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Risk type: Injuries Risk type: Injuries Category: Motor vehicles Risk type: Injuries Risk type: Risk Risk Risk Risk Risk Risk Risk Risk		
Products were found and measures were taken also in: Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands Alert number: A12/1386/18 Product: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 185MD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout Skty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: India Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk Ther might be air in the brake liquid circuit of the ABS system. There might be air in the brake liquid circuit of the BAS system. There might be air in the brake liquid circuit of the brake, which could increase the risk of accident. Recall of the product from end users Description: Moder years Product States Alert number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States		
The Netherlands Alert number: A12/1386/18 Produce: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk levei: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, It may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 185MD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Produe:: Motorveycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk teve: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of mordul: Motorycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		ia.
Product: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category is Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	-	- ,
Product: Van Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category is Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Name: Proace Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Stout, Stout, Stout, Stout, Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk tevel: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Risk type: Injuries Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk tevel: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Category: Motor vehicles Brand: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk tevel: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Brad: Toyota Type / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Risk level: Serious risk The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk type: Injuries Category insk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom <td></td> <td></td>		
The trailer coupling device can become deformed if a trailer is used. If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	be / number of model: Type-approval number: E2*2007/46*0537* and E2*2007/46*0538*; type: V	
If this occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle. Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	k level: Serious risk	
Recall of the product from end users Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the yroduct from end users Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	e trailer coupling device can become deformed if a trailer is used.	
Description: Van. Company recall code: 18SMD-061 Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	is occurs, it may become difficult to control the vehicle and the trailer might become detached from the vehicle.	
Batch number / Barcode: The vehicles concerned were manufactured between June 2016 and December 2017. Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	call of the product from end users	
Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Alert submitted by: Germany Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Products were found and measures were taken also in: Sweden Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Alert number: A12/1387/18 Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Product: Motorcycle Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Name: Scout, Scout Sixty, Scout Bobber Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Risk type: Injuries Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	•	
Category: Motor vehicles Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Brand: Indian Motorycle Company Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Type / number of model: Model year 2017 & 2018 Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Risk level: Serious risk There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
There might be air in the brake liquid circuit of the ABS system. This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom	·	
This can cause a descrease in the performance of the brake, which could increase the risk of accident. Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Recall of the product from end users Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Description: Motorcycle. Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Batch number / Barcode: The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. Country of origin: United States Alert submitted by: United Kingdom		
Country of origin: United States Alert submitted by: United Kingdom		
Alert submitted by: United Kingdom		
	untry of origin: United States	

Alert number: A12/1389/18
Product: Passenger car
Name: Passat
Risk type: Injuries Category: Motor vehicles
Brand: Volkswagen
Type / number of model: Type-approval number: e1*2001/116*0307*; type: 3C
Risk level: Serious risk
The head restraint guide retaining spring is defective.
As a consequence, the headrest is not properly anchored to the seat's back and it may detach in case of an accident, leading to injuries.
Recall of the product from end users Description: Passenger car under recall code 72H7
Batch number / Barcode: The vehicles affected were manufactured between 4 May 2018 and 3 July 2018.
Country of origin: Germany
Alert submitted by: Germany
Products were found and measures were taken also in: Bulgaria, Croatia, Finland, Slovenia, Sweden, The Netherlands
Alert number: A12/1420/18
Product: Passenger car
Name: Cayenne
Risk type: Injuries
Category: Motor vehicles
Brand: Porsche
Type / number of model: Type-approval number: e13*2007/46*0900*01; type: 9YA; models: Porsche Cayenne, Porsche Cayenne S, Porsche Cayenne Diesel, Porsche Cayenne S Diesel, Porsche Cayenne E-Hybrid
Risk level: Serious risk
The belt buckles on the central rear seat are defective.
This increases the risk of injury for occupants.
Recall of the product from end users
Description: Passenger car. Company recall code: AJ08
Batch number / Barcode: The vehicles in question were manufactured between 6/12/2016 and 8/3/2018. Country of origin: Slovakia
Alert submitted by: Germany
Products were found and measures were taken also in: Bulgaria, Croatia, Finland, Iceland, Poland, Slovenia, Sweden, The Netherlands
Alert number: A12/1421/18 Product: Passenger car
Name: One Countryman, Cooper Countryman
Risk type: Fire, Injuries
Category: Motor vehicles
Brand: Mini
Type / number of model: Type-approval number: e1*2007/46*1682*00-04; type: FMX
Risk level: Serious risk A crash guard is lacking for the high-pressure fuel pump in the engine compartment.
In case of an accident, the high-pressure pump may be damaged, possibly leading to a fuel leakage and causing a fire.
Recall of the product from end users
Description: Passenger car. Company recall code: 0013900200
Batch number / Barcode: The vehicles in question were manufactured between 30 December 2016 and 13 August 2018.
Country of origin: Germany
Alert submitted by: Germany Products were found and measures were taken also in: Bulgaria, Croatia, Finland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, Sweden,
The Netherlands
Alert number: A12/1422/18 Product: Resconger car
Product: Passenger car Name: Panamera
Risk type: Injuries
Risk type: Injuries Category: Motor vehicles Brand: Porsche
Risk type: Injuries Category: Motor vehicles Brand: Porsche Type / number of model: Type-approval number: e13*2007/46*0971*05; type: 971
Risk type: Injuries Category: Motor vehicles Brand: Porsche Type / number of model: Type-approval number: e13*2007/46*0971*05; type: 971 Risk level: Serious risk
Risk type: Injuries Category: Motor vehicles Brand: Porsche Type / number of model: Type-approval number: e13*2007/46*0971*05; type: 971 Risk level: Serious risk Restricted durability of the coupling rods may affect the functioning of the rear anti-roll stabiliser (PDCC).
Risk type: Injuries Category: Motor vehicles Brand: Porsche Type / number of model: Type-approval number: e13*2007/46*0971*05; type: 971 Risk level: Serious risk Restricted durability of the coupling rods may affect the functioning of the rear anti-roll stabiliser (PDCC). As a consequence, driving behaviour can be impaired.
Risk type: Injuries Category: Motor vehicles Brand: Porsche Type / number of model: Type-approval number: e13*2007/46*0971*05; type: 971 Risk level: Serious risk Restricted durability of the coupling rods may affect the functioning of the rear anti-roll stabiliser (PDCC).
Risk type: Injuries Category: Motor vehicles Brand: Porsche Type / number of model: Type-approval number: e13*2007/46*0971*05; type: 971 Risk level: Serious risk Restricted durability of the coupling rods may affect the functioning of the rear anti-roll stabiliser (PDCC). As a consequence, driving behaviour can be impaired. Recall of the product from end users
Risk type: Injuries Category: Motor vehicles Brand: Porsche Type / number of model: Type-approval number: e13*2007/46*0971*05; type: 971 Risk level: Serious risk Restricted durability of the coupling rods may affect the functioning of the rear anti-roll stabiliser (PDCC). As a consequence, driving behaviour can be impaired. Recall of the product from end users Description: Passenger car. Company recall code: AJ06 Batch number / Barcode: The vehicles in question were manufactured between 9/9/2015 and 5/6/2018. Country of origin: Germany
Risk type: Injuries Category: Motor vehicles Brand: Porsche Type / number of model: Type-approval number: e13*2007/46*0971*05; type: 971 Risk level: Serious risk Restricted durability of the coupling rods may affect the functioning of the rear anti-roll stabiliser (PDCC). As a consequence, driving behaviour can be impaired. Recall of the product from end users Description: Passenger car. Company recall code: AJ06 Batch number / Barcode: The vehicles in question were manufactured between 9/9/2015 and 5/6/2018.

Alert number: A12/1423/18	
Product: Passenger car	
Name: RAM	
Risk type: Fire	
Category: Motor vehicles	
Brand: Dodge	
Type / number of model: Type-approval: individual approval	
Risk level: Serious risk	
A water pump is defective and may lead to a short-circuit	
This may result in a fire.	
Recall of the product from end users	
Description: Passenger car. Company recall code: T51	
Batch number / Barcode: The vehicles affected were produced between 24 October 2012 and 27 February 2017.	
Country of origin: United States	
Alert submitted by: Germany	
Products were found and measures were taken also in: Iceland	
Alert number: A12/1424/18	
Product: Passenger car	
Name: 918 Spyder	
Risk type: Injuries	
Category: Motor vehicles	
Brand: Porsche	
Type / number of model: Type-approval number: e13*KS07/46*0014*03; type: 918	
Risk level: Serious risk	
The bolts used to mount the longitudinal and transverse suspension arms may corrode over time.	
As a consequence, the bolts might break, impairing driving performance.	
Recall of the product from end users	
Description: Passenger car. Company recall code: AJ04	
Batch number / Barcode: The vehicles affected were produced between 9.7.2013 and 27.7.2015.	
Country of origin: Germany	
Alert submitted by: Germany	
Products were found and measures were taken also in: Poland, Slovenia, Sweden, The Netherlands	
Alert number: A12/1432/18	
Product: Passenger car	
Name: ASX	
Risk type: Injuries	
Category: Motor vehicles	
Brand: Mitsubishi	
Type / number of model: ASX (GA1W); Model year: 2011 -2018., Type-approval numbers: PL*4415*01, e1*2007/46*0368*02,	
e1*2007/46*0368*01, e1*2007/46*0368*03, e1*2007/46*0368*04, e1*2007/46*0368*05, e1*2007/46*0368*08, e1*2007/46*0368*07,	
e1*2007/46*0368*09,, e1*2007/46*0368*10, e1*2007/46*0368*11, e1*2007/46*0368*12, e1*2007/46*0368*13, e1*2007/46*0368*16,	
e1*2007/46*0368*15.	
Risk level: Serious risk	
The weld between the rear muffler and the tailpipe may crack.	
As a result, the tailpipe may detach and drop on the road, posing a risk to following traffic.	
Pecall of the product from and uppro	
Recall of the product from end users	
Description: Passenger car. Company recall code: ENL-18-022-SR	
Batch number / Barcode: Unknown	
Country of origin: Japan	
Alert submitted by: Poland	
Products were found and measures were taken also in: Bulgaria, Croatia, Finland, Ireland, Luxembourg, Portugal, Romania, Slovenia,	

Alert number: A12/1388/18 Product: Work gloves Name: 10 Weldex Risk type: Chemical Category: Protective equipment Brand: Keron Type / number of model: Article No 29737 EB-00219621 Risk level: Serious risk The amount of chromium (VI) in the leather is too high (measured value up to 9.2 mg/kg). Chromium (VI) is sensitising and may trigger allergic reactions. The product does not comply with REACH Regulation.

Recall of the product from end users **Description:** Work gloves, size 10 (XL) in light grey leather, long cuffs, with cardboard label. **Batch number / Barcode:** 4018653297377 **Country of origin:** India **Alert submitted by:** Germany **Products were found and measures were taken also in:** Luxembourg





Alert number: A12/1427/18 Product: Work gloves Name: Gaucho Risk type: Chemical Category: Protective equipment Brand: Active Keron Type / number of model: Model No 297234, size 10 Risk level: Serious risk The amount of chromium (VI) in the leather is too high (measured value: 15.3 mg/kg). Chromium (VI) is sensitising and may trigger allergic reactions.

The product does not comply with the requirements of the Personal Protective Equipment Directive and with the REACH Regulation. Recall of the product from end users, Withdrawal of the product from the market **Description:** Work glove made of beige leather and dark-green textile parts. **Batch number / Barcode:** 4018653002070 **Country of origin:** China **Alert submitted by:** Germany



Alert number: A12/1409/18 Product: Baby carrier Name: Sling by Fil'up Risk type: Entrapment, Injuries Category: Childcare articles and children's equipment Brand: Filt Type / number of model: 760 Risk level: Serious risk The fastening ring can break and the meshes of the net are too big. As a consequence, the sling can release and the child could fall or fingers can become trapped in the mesh.

Recall of the product from end users **Description:** Baby carrier made of a flexible net with fastening ring. **Batch number / Barcode:** PF: PF170814 **Country of origin:** France **Alert submitted by:** France **Products were found and measures were taken also in:** Denmark





Alert number: A12/1397/18 Product: Kick scooter Name: Hulajnoga aluminiowa Risk type: Injuries Category: Toys Brand: Unknown Type / number of model: AT1 Risk level: Serious risk There are accessible gaps between moving parts of the scooter. As a consequence, fingers can become trapped.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Withdrawal of the product from the market **Description:** Folding kick scooter, intended for children weighing less than 50 kg. Packaging: cardboard box.

Batch number / Barcode: 5900733470017 Country of origin: China

Alert submitted by: Poland







Alert number: A12/1398/18 Product: Puzzle mat Name: Puzzle Mat Risk type: Choking Category: Toys Brand: REGIO JÁTÉK; Sunta toys Type / number of model: 032015TSO1502016 Risk level: Serious risk Small parts of the mat can easily be detached. A child could put the small parts in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1. Recall of the product from end users, Withdrawal of the product from the market

Description: 36-piece colourful, puzzle foam mat included removable letters and numbers.Packaging: transparent plastic with paper label. **Batch number / Barcode:** 5996055591660

Country of origin: Malaysia

Alert submitted by: Hungary



Alert number: A12/1399/18 Product: Soft toy Name: Plüss kabala figurák Risk type: Choking Category: Toys Brand: Unknown Type / number of model: A-20092 Risk level: Serious risk The nose and the suction cup can easily detach from the soft toy, generating small parts. In addition, the fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the detached elements or the stuffing material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Recall of the product from end users, Withdrawal of the product from the market Description: Striped, plush clown with a red nose and a suction cup on its head.

Batch number / Barcode: 6956520200922

Country of origin: China

Alert submitted by: Hungary

Products were found and measures were taken also in: Slovakia





Alert number: A12/1402/18 Product: Luminous toy Name: Bébé chien lumineux Risk type: Choking Category: Toys Brand: Tous à la plage Type / number of model: reference 8763 Risk level: Serious risk Small parts can easily be detached from the toy. A young child could put a small part in the mouth, which could lead to choking.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Recall of the product from end users

Description: Pink plastic dog with a multi-coloured LED inside Batch number / Barcode: Batch 180563, EAN 3760192610452 Country of origin: China Alert submitted by: France



Alert number: A12/1404/18 Product: Musical box Name: Boîte à Musique 'Dancing hero' Risk type: Choking Category: Toys Brand: Trousselier Type / number of model: S95018 Risk level: Serious risk The figures can become detached from the base, generating small parts. A small child may put them in the mouth and choke

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Recall of the product from end users **Description:** Musical box made of wood and plastic, with removable plastic figures. **Batch number / Barcode:** 3760119600115, batch 1946-01-17 **Country of origin:** China **Alert submitted by:** France

Products were found and measures were taken also in: Germany, Luxembourg



Alert number: A12/1405/18 Product: Plastic doll with accessories Name: Educate the girl Risk type: Chemical Category: Toys Brand: GUI YUAN Type / number of model: NO.GY06 Risk level: Serious risk The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 16.7% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation. Withdrawal of the product from the market

Description: A plastic doll with accessories in a cardboard box with transparent window. **Batch number / Barcode:** 6911250195122 **Country of origin:** China

Alert submitted by: Cyprus





Alert number: A12/1407/18 Product: Plastic doll set Name: Fashion girl - Lovely style Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: No 8235B OTM0030488 Risk level: Serious risk The plastic material of the doll contains 2-ethylhexyl phthalate (DEHP), dibutyl phthalate (DBP), di-isononyl phthalate (DINP) (measured values: up to 21,4%, 0.2% and 2,3% by weight respectively). These phthalates may harm the health of children, causing possible damage to the reproductive system (DEHP and DBP) and liver (DINP).

The product does not comply with the REACH Regulation. Withdrawal of the product from the market **Description:** Set consisting of a plastic doll with additional pieces of clothing (several dresses and footwear), a hairbrush and a stand alone fan. **Batch number / Barcode:** 5290958013770

Country of origin: China Alert submitted by: Cyprus







Alert number: A12/1408/18 Product: Plastic doll with accessories Name: Beauty Fashionstar Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: N° YS1208 / AK 125019512-1 Risk level: Serious risk

The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 17.7% by weight), dibutyl phthalate (DBP) (measured value: 0.7% by weight) and di-'isononyl' phthalate (DINP) (measured value: 0.25% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system and the liver.

The product does not comply with the REACH Regulation. Withdrawal of the product from the market Description: A plastic doll with accessories in a cardboard box with transparent window. Batch number / Barcode: 2012090700058 Country of origin: China Alert submitted by: Cyprus



Alert number: A12/1410/18 Product: Plastic dolls with accessories Name: Lovely Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: No 20124 / 1-13359-20124-1FP Risk level: Serious risk The plastic material of the dolls' head contains 2-ethylhexyl phthalate (DEHP) (measured value: up to 28,09 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation. Withdrawal of the product from the market Description: Two plastic dolls with accessories in a cardboard box with transparent cover. Batch number / Barcode: 3342160108156 Country of origin: China Alert submitted by: Cyprus



Alert number: A12/1411/18 Product: Plastic doll Name: Happiness warm and Fragrant Risk type: Chemical Category: Toys Brand: Beautiful Girl Type / number of model: N° PS668-4 / E00400 Risk level: Serious risk The plastic material of the doll contains 2-ethylhexyl phthalate (DEHP), di-'isodecyl' phthalate (DIDP) and di-isononyl phthalate (DINP) (measured values: 24.9%, 16.3% and 18.2% by weight respectively). These phthalates may harm the health of children, causing possible damage to the reproductive system and the liver. The product does not comply with the REACH Regulation. Withdrawal of the product from the market Description: A plastic doll in a cardboard box with transparent window. Batch number / Barcode: 2200000100214 Country of origin: China

Alert submitted by: Cyprus



Alert number: A12/1412/18 Product: Plastic doll with accessories Name: BEAUTY Fashion Model / Fashion Girl Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: No. 1425 / 1-14309-1425 Risk level: Serious risk The arms and the legs of the doll contain bis (2-ethylhexyl) phthalate (DEHP) and di-isononyl phthalate (DINP) (measured values: 0,25 and 0,62% by weight respectively). These phthalates may harm the health of children, causing possible damage to the reproductive system (DEHP) and the liver (DINP). The product does not comply with the REACH Regulation. Withdrawal of the product from the market

Withdrawal of the product from the market **Description:** Plastic doll with accessories in a cardboard and plastic box. **Batch number / Barcode:** 3342862842099 **Country of origin:** China **Alert submitted by:** Cyprus



Alert number: A12/1413/18 Product: Plastic toy set Name: Peppa Pig Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: No. O126/ 8984 Risk level: Serious risk The plastic material of the toy contains 2-ethylhexyl phthalate (DEHP) (measured value: up to 18,51 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation. Withdrawal of the product from the market **Description:** Four plastic pigs in cardboard and plastic packaging. **Batch number / Barcode:** 5291410110266 **Country of origin:** China **Alert submitted by:** Cyprus



Alert number: A12/1418/18 Product: Toy stickers Name: Stickers Risk type: Chemical Category: Toys Brand: Playbox Type / number of model: 2470629 Risk level: Serious risk The product contains di (2-ethylhexyl phthalate (DEHP) (measured value: up to 0.18 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation. Withdrawal of the product from the marketWithdrawal of the product from the market Description: 3D toy stickers in PVC.

Batch number / Barcode: 7394311905608 Country of origin: China

Alert submitted by: Sweden



Alert number: A12/1428/18 Product: Toy drums Name: Tamburo Risk type: Strangulation Category: Toys Brand: GIAV PLAST Type / number of model: Batch 304 Risk level: Serious risk The drums are equipped with a strap intended to be worn fully or partially around the neck. The strap can get trapped during various activities of a child and create a loop around the child's neck, causing strangulation.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Withdrawal of the product from the market Description: Plastic toy drum. Batch number / Barcode: 8033641000469 Country of origin: Italy



Alert number: A12/1429/18 Product: Inflatable swim ring Name: SWIM RING Risk type: Chemical Category: Toys Brand: Numerous Star Type / number of model: 1400193 Risk level: Serious risk The valve of the swim ring contains di(2-etylhexyl) phthalate (DEHP) (measured value: 27% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation. Recall of the product from end users, Withdrawal of the product from the market Description: Pink inflatable swimm ring with fish motive. Packaging: plastic bag

Batch number / Barcode: 8005614001933 Country of origin: China

Alert submitted by: Hungary



Alert number: A12/1430/18

Product: Plastic doll set Name: Frozen Fever Risk type: Choking Category: Toys Brand: Unknown Type / number of model: No.WJ302 Risk level: Serious risk The hand mirror and hairbrush are too small. A child could put them in the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Withdrawal of the product from the market Description: Set consisting of two plastic dolls (depicting one adult mermaid and a girl mermaid), a hand mirror and a hairbrush. Batch number / Barcode: Unknown THE PRODUCT IS COUNTERFEIT Country of origin: China Alert submitted by: Malta





Alert number: A12/1433/18 Product: Toy tank Name: Super Tanks Risk type: Damage to hearing Category: Toys Brand: Unknown Type / number of model: No.70017 Risk level: Serious risk The sound level is too high and can consequently cause damage to hearing.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Recall of the product from end users, Withdrawal of the product from the market **Description:** Battery operated tank-shaped colourful plastic toy. The game emits flashing light and sound. Packaging: cardboard box with transparent window **Batch number / Barcode:** Unknown **Country of origin:** China **Alert submitted by:** Hungary



Alert number: A12/1392/18 Product: Men's shoes Name: Black White Duplicate Risk type: Chemical Category: Clothing, textiles and fashion items Brand: Unknown Type / number of model: Art.No: 13S111-75A Risk level: Serious risk

The shoes contain the polycyclic aromatic hydrocarbons (PAHs) benz(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene and benzo(a)pyrene, benzo(e)pyrene, dibenzo(a,h)anthracene and benzo(j)fluoranthene (measured values up to 28.3 mg/kg). PAHs are absorbed through skin contact and respiration. These PAHs are carcinogenic.

The product does not comply with the REACH Regulation.

Recall of the product from end users

Description: Men's leather shoes with plastic upper in black and white; white inner lining and insole, and a rubber sole in black-brown. Packaging: a cardboard box. The product has been sold online (e.g. via Amazon).

Batch number / Barcode: 4 060658 599260

Country of origin: Unknown

Alert submitted by: Germany



Alert number: A12/1401/18 Product: Toiletry Bag Name: Beauty care Risk type: Chemical Category: Clothing, textiles and fashion items Brand: Gaggs Type / number of model: Unknown Risk level: Serious risk The product contains cadmium (measured value: 0.0136 % by weight). Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer. The product does not comply with the REACH Regulation. Withdrawal of the product from the marketWithdrawal of the product from the market Description: Black toiletry bag Batch number / Barcode: 7332447272058 Country of origin: China Alert submitted by: Sweden



Alert number: A12/1403/18 Product: Bikini set Name: Unknown Risk type: Injuries Category: Clothing, textiles and fashion items Brand: YES ! DO KIDS Type / number of model: 56917 - KL104 Risk level: Serious risk The top part of the bikini set bears functional cords with free ends, to be tied at the back. The cords may become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682. Withdrawal of the product from the market Description: Girls' bikini swim set. Batch number / Barcode: 5299900973797 Country of origin: China Alert submitted by: Cyprus





Alert number: A12/1414/18 Product: Children's shirt Name: Unknown Risk type: Injuries Category: Clothing, textiles and fashion items Brand: Pink Baby Type / number of model: FH- 7325 / 18S5C13007 Risk level: Serious risk The product bears functional cords on the back. The cords could become trapped during various activities of a child and cause injuries.

The product does not comply with the relevant European standard EN 14682. Withdrawal of the product from the market **Description:** White shirt designed for 4 years old girls, with a black cat sketch, the phrase "Love you always" and several rhinestones and sequins on it.

Batch number / Barcode: 2210000270367 Country of origin: China Alert submitted by: Cyprus







Alert number: A12/1416/18 Product: Children's short trousers Name: Unknown Risk type: Injuries Category: Clothing, textiles and fashion items Brand: HOLLY WORK Type / number of model: MS-1036 / 18S5C62019 Risk level: Serious risk The product has decorative cords with toggles in the waist area. These can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682. Withdrawal of the product from the market Description: Grey blue short trousers intended for 8 years old children. Batch number / Barcode: 2210000289482 Country of origin: China Alert submitted by: Cyprus



Alert number: A12/1417/18 Product: Children's clothing set Name: Magic dreams Risk type: Injuries Category: Clothing, textiles and fashion items Brand: Next Star Type / number of model: TB10-191 / 2210000031487 Risk level: Serious risk There are decorative cords on the lower hems of the t-shirt. They can become trapped during various activities of the child, causing injuries.

The product does not comply with the relevant European standard EN 14682. Withdrawal of the product from the market **Description:** Children's clothing set consisting of a white t-shirt with decorative cords at the lower end of it and orange short trousers. **Batch number / Barcode:** 2210000031487 / 900773101914 **Country of origin:** China

Alert submitted by: Cyprus



Alert number: A12/1425/18 Product: Babies' clothing set Name: Unknown Risk type: Strangulation Category: Clothing, textiles and fashion items Brand: Kids moda Type / number of model: Art 2007 Risk level: Serious risk The product bears functional cords in the neck area. These cords can become trapped during various activities of a child, leading to strangulation.

The product does not comply with the relevant European standard 14682. Withdrawal of the product from the market Description: Baby clothing set consisting of a pink cardigan, a white t-shirt and a floral skirt designed for 12 months children . Batch number / Barcode: Unknown Country of origin: Italy Alert submitted by: Cyprus



Alert number: A12/1395/18 Product: Bag of cement Name: Type 1 42.5 Portland Cement Risk type: Chemical Category: Construction products Brand: Momtazan Cement Type / number of model: CEM 1 42.5 N Risk level: Serious risk The amount of chromium (VI) in the cement is too high. Chromium (VI) is sensitising and may trigger allergic reactions.

The product does not comply with the REACH Regulation. Recall of the product from end users, Withdrawal of the product from the marketBan on the marketing of the product and any accompanying measures

Description: 25kg bag of cement Batch number / Barcode: 0933310075210092 Country of origin: Iran

Alert submitted by: France

Alert number: A12/1384/18 Product: Bath product Name: Mini Cupcake SANTA'S HAT Risk type: Choking Category: Cosmetics Brand: TENTATION bulles de séduction Type / number of model: Fragrance: Freesia flower Risk level: Serious risk Due to its characteristic appearance, colour and size, this product may be mistaken for a foodstuff. The red Santa Claus hat and pieces of the whipped cream can easily detach. A child may put these pieces in the mouth and choke.

The product does not comply with the Cosmetics Regulation or with the requirements of the Food imitating Products Directive. Recall of the product from end users **Description:** Bath fizzer imitating a white cupcake with whipped cream, topped with a red Santa Claus hat and wrapped in red paper. **Batch number / Barcode:** lot: 176012 Code: 3700146609897 **Country of origin:** The Netherlands **Alert submitted by:** France



Alert number: A12/1390/18

Product: Skin lightening product Name: Lightening Program for Men Risk type: Chemical Category: Cosmetics Brand: Clairmen Type / number of model: Lotion Formula Risk level: Serious risk The product contains kojic acid (measured value: 1.0% by weight). Kojic acid can induce skin sensitisation and is not considered safe when used on large areas of skin. The product does not comply with the Cosmetics regulation. Ban on the marketing of the product and any accompanying measures Description: Beige, perfumed, skin lightening body lotion, packed in a plastic bottle with label, foil seal and screw cap. Batch number / Barcode: Lot: L#16045 Code: 6280675004235 Country of origin: Unknown Alert submitted by: Germany







Alert number: A12/1391/18 Product: Hairdryer Name: Professional Hair Dryer Risk type: Fire Category: Electrical appliances and equipment Brand: Sonar Type / number of model: SN-7730 Item no.:02485 Risk level: Serious risk The cross-sectional area of the power cord is inadequate. The wire could overheat, leading to a fire.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335-1. Withdrawal of the product from the market

Description: Electric hairdryer with plastic housing, 2600 W. Packaging: black cardboard box.

Batch number / Barcode: EAN: 8008280024855

Country of origin: China

Alert submitted by: Poland









Alert number: A12/1415/18 Product: Travel plug adaptor Name: Eastern Risk type: Fire Category: Electrical appliances and equipment Brand: Unknown Type / number of model: EA 1310 Risk level: Serious risk The product does not have a fuse. In case of an overload, this could lead to a fire. The product does not have a fuse. In case of an overload, this could lead to a fire. The product does not comply with the relevant national standard. Withdrawal of the product from the market Description: Travel adaptor which converts a BS plug to Schuko outlet with side earthing contacts. Batch number / Barcode: 7861179599848 Country of origin: China Alert submitted by: Cyprus









Alert number: A11/0077/18 **Product:** Kerosene heater Name: Petroolilämmitin 6.5 kW Risk type: Fire Category: Other Brand: Timco Tools Type / number of model: WKH-4400 Risk level: Other risk levels Fuel may leak from the product when it is tilted, which could flare up. The user may also place the heater too close to combustibles (e.g. due to the lack of proper instructions), which could then ignite due to the high temperatures measured. As a consequence the product could increase the risk of fire. Withdrawal of the product from the marketBan on the marketing of the product and any accompanying measures Description: Kerosene heater 6,5 kW. Packed in a cardboard box. Batch number / Barcode: 6438014129730 Country of origin: China Alert submitted by: Finland







Alert number: A11/0074/18 Product: Soft toy Name: vankús / párna Risk type: Choking Category: Toys Brand: Unknown Type / number of model: 77622 Risk level: Other risk levels The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child could take out the stuffing, put it in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Recall of the product from end users, Withdrawal of the product from the market **Description:** Yellow plush duck in pink trousers with a hat. The product is sold without packaging. **Batch number / Barcode:** 8686860077622 **Country of origin:** China **Alert submitted by:** Hungary



Alert number: A11/0075/18 Product: Soft toy Name: PLUSH MASCOT Risk type: Choking Category: Toys Brand: Hanya Type / number of model: GB5288 Risk level: Other risk levels The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams.

A small child could take out the stuffing, put it in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1. Recall of the product from end users, Recall of the product from end users, Withdrawal of the product from the market, Withdrawal of the product from the market

Description: Green plush frog decorated with a red embroidered heart and with a red ribbon on the neck. The product is sold without packaging. **Batch number / Barcode:** 6933952902983

Country of origin: China

Alert submitted by: Hungary



Alert number: A11/0076/18 Product: Soft toy Name: Unknown Risk type: Choking Category: Toys Brand: Abababy Type / number of model: Item 216 Risk level: Other risk levels The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child could take out the stuffing, put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1. Recall of the product from end users, Withdrawal of the product from the market Description: Cream-coloured plush teddy bear with brown eyes and pink nose. In the bear's hands there is a white cushion with an inscription: "Love You". The product is sold without packaging. Batch number / Barcode: 6978151300123 Country of origin: China Alert submitted by: Hungary





Alert number: A11/0073/18 Product: Electric blender Name: Nutritional Extractor Risk type: Electric shock Category: Electrical appliances and equipment Brand: ULTRAMAXX Type / number of model: VHGHSCIND0025 SK/F038/2014 Risk level: Other risk levels The electrical insulation is inadequate. There is a risk of electric shock for users.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335. Withdrawal of the product from the market Description: Electric blender in cardboard packaging. Batch number / Barcode: 0644812024221 Country of origin: Spain Alert submitted by: Croatia



