

### CONSUMERS

v

European Commission (http://ec.europa.eu/index\_en.htm) Consumers (http://ec.europa.eu/consumers/index\_en.htm) Consumers safety (http://ec.europa.eu/consumers/consumers\_safety/index\_en.htm) Safety products (http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/index\_en.htm)

A Rapid Alert System home (https://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/repository/content/pages/rapex/index\_en.htm

Eack to report listings (https://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/?event=main.listNotifications&year=2018)

Q Search alerts (https://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/?event=main.search)

Safe Products Online (https://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/?event=SafeProductsOnline)

# The Rapid Alert System for Non-Food Products (RAPEX)

## RAPEX - Weekly overview report of notifications

## week 44 - 2018

Notification A12/1511/18 from Report-2018-042 has been updated to modify the name, type and model.

Alert number: A12/1579/18 Product: Children's high chair Name: Unknown Risk type: Entrapment, Injuries Category: Childcare articles and children's equipment Brand: FLEXA Type / number of model: 82-10020-1 Risk level: Serious risk The high chair is unstable and the restraint system is inadequate. If a small child leans to the side of the high chair, it could overturn leading to injuries. A child may also put his head between the tray and the seat and get stuck.

The product does not comply with the relevant European standard EN 14988. **Measures taken by economic operators:** Withdrawal of the product from the market (By: Manufacturer) **Description:** Children's high chair made of wood and polymer. Pre-fitted with a waist/crotch restraint system. **Batch number / Barcode:** 5706459060217 **Country of origin:** Denmark **Alert submitted by:** Sweden



Alert number: A12/1605/18 Product: Soother holder Name: Schnullerhalter Risk type: Choking Category: Childcare articles and children's equipment Brand: Bieco Type / number of model: Reference: 23021029, Reference: 23021862 Risk level: Serious risk The extremities of the product protrude. A child could put a protruding part in the mouth, which could block the airways and cause choking.

Measures taken by economic operators: Recall of the product from end users (By: Distributor) Description: Soother holder with painted wooden beads. Batch number / Barcode: Ean : 4005544218627, Ean : 4005544210294 Country of origin: Germany Alert submitted by: France



Alert number: A12/1618/18
Product: Cuddle nest
Name: Cuddle Nest Ergo
Risk type: Suffocation
Category: Childcare articles and children's equipment
Brand: BabyDan
Type / number of model: Cuddle Nest
Risk level: Serious risk
The round shape of the sides and the bottom of the cuddle nest form a wedge.
If the child turns the head, it can get stuck between the side and bottom of the cuddle nest, leading to suffocation.
Measures taken by economic operators: Recall of the product from end users (By: Distributor)
Description: Cuddle nest that can also be used as a carrycot.
Batch number / Barcode: 1338-2920 = 5705548035709. 1338-7820 = 5705548035709. 1339-00 = 5705548035716
Country of origin: Turkey
Alert submitted by: Denmark

Alert number: A12/1599/18 Product: Children's outfit Name: Unknown Risk type: Strangulation Category: Clothing, textiles and fashion items Brand: Zhuzhu Rabbit Type / number of model: Unknown Risk level: Serious risk The product has drawstrings in the neck area. The drawstrings may become trapped during various activities of a child, leading to strangulation.

The product does not comply with the relevant European standard EN 14682. **Measures taken by economic operators:** Removal of the product listing from the Wish platform. **Measures ordered by public authorities:** Authority warning consumers of the risk **Description:** Children's sweatshirt and shorts. The product has been sold online (for example on the Wish marketplace). **Batch number / Barcode:** Unknown **Country of origin:** Unknown **Alert submitted by:** Finland



Alert number: A12/1600/18 Product: Face mask Name: Indian Healing Clay Risk type: Microbiological Category: Cosmetics Brand: Aztec Secret Health and Beauty Type / number of model: Unknown Risk level: Serious risk The total count of aerobic bacteria (measured quantity up to 3600 cfu/g) and the level of mould in the product is too high. If used on damaged skin or if it comes into contact with the eyes, the product may cause infection or irritation. The product does not comply with the Cosmetic Products Regulation.

Measures taken by economic operators: The product listing has been removed from the Amazon website Measures ordered by public authorities (to: Importer): Destruction of the product Description: Plastic jar containing clay mask. The product has been sold online (e.g. via Amazon and eBay). Batch number / Barcode: expiry dates 06/2020 and 03/2020 Country of origin: United States Alert submitted by: United Kingdom



Alert number: A12/1601/18 Product: Hair dye Name: Permanent Powder Hair Colour Risk type: Chemical Category: Cosmetics Brand: Bigen Hoyu Type / number of model: 58 Oriental Black Risk level: Serious risk The product contains too much p-phenylene

The product contains too much p-phenylenediamine (measured value: up to 10% by weight) and an insufficient coupling agent. Uncoupled p-phenylenediamine is an extremely potent skin sensitiser and may trigger allergic reactions.

The product does not comply with the Cosmetics Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Retailer)

**Description:** Grey powder to dye hair black in a printed plastic bottle with a screw cap. Sold in a printed cardboard box with a product leaflet. **Batch number / Barcode:** 0622 7, 4 987205 905599

Country of origin: Thailand

Alert submitted by: Germany



Alert number: A12/1602/18 Product: Hair dye Name: Permanent Powder Hair Colour Risk type: Chemical Category: Cosmetics Brand: Bigen Hoyu Type / number of model: 48 Dark Chestnut Risk level: Serious risk The product contains too much p-phenylenediamine and toluene-2,5-diamine sulphate (measured values: up to 4.9% and 4.2% by weight respectively) and an insufficient coupling agent. Uncoupled p-phenylenediamine and and toluene-2,5-diamine sulphate are extremely potent skin sensitisers and may trigger allergic reactions. The product does not comply with the Cosmetics Regulation. Measures taken by economic operators: Withdrawal of the product from the market (By: Retailer) Description: Grey powder to dye hair dark brown, in a printed plastic bottle with a screw cap. Sold in a printed cardboard box with a product leaflet. Batch number / Barcode: 098 1, 4 987205 905483 Country of origin: Thailand



Alert number: A12/1603/18 Product: Moisturizing cream/gel Name: Unknown Risk type: Chemical Category: Cosmetics Brand: Bust Size Type / number of model: Unknown Risk level: Serious risk The labelling indicates that the product contains methylisothiazolinone (MI) and methylchloroisothiazolinone (MCI). MI and MCI are sensitizing agents and can provoke allergic contact dermatitis to sensitized persons.

The product does not comply with the Cosmetic Products Regulation.

#### Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market

**Description:** Moisturizing cream/gel for the breast area in a white/blue/red 30 ml plastic tube, supplied in a white/blue/red cardboard box. **Batch number / Barcode:** 4607013230729; Batch Nr. 031848 **Country of origin:** Russian Federation

Alert submitted by: Latvia



Alert number: A12/1614/18 Product: Hair colouring product Name: Light Red Risk type: Microbiological Category: Cosmetics Brand: Henné Souad Type / number of model: Product Ref: 2213.300 Risk level: Serious risk The product is microbiologically contaminated with mesophilic aerobic bacteria, yeast and mould (measured values: 77,000 cfu/g for mesophillic aerobic bacteria and 9,000 cfu/g for yeast and mould). If used on damaged skin, or if it comes into contact with the eyes, the product may cause infection or irritation. The product does not comply with the Cosmetic Products Regulation. Measures taken by economic operators: Withdrawal of the product from the market (By: Retailer) Description: Henna hair dye sold in a blue box with yellow and red print. Batch number / Barcode: Batch number: K1367 Bar code: 3289070103003 Country of origin: France Alert submitted by: Ireland 04703/18/73 KLM INTERNET - IRANE

Alert number: A12/1611/18 Product: Electric razor Name: Technology Quality Life Risk type: Electric shock Category: Electrical appliances and equipment Brand: BOLI Razor Type / number of model: RSCW-6008 Risk level: Serious risk When connecting/disconnecting the plug to the mains, live parts are accessible. This could result in the user getting an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant standard EN 60335.

Measures ordered by public authorities (to: Retailer): Withdrawal of the product from the market Description: Men's brown and silver-coloured, electric razor. A 2-pin plug without a cable is attached to the product (the plug is connected directly to the razor). Packed in a cardboard box.

Batch number / Barcode: 29181777792

Country of origin: China

Alert submitted by: Czech Republic



Alert number: A12/1613/18 Product: Electric razor Name: Your Best Choice Risk type: Electric shock Category: Electrical appliances and equipment Brand: NO ONE Type / number of model: RSCW-V2/ZL201130129600.5 Risk level: Serious risk When connecting/disconnecting the plug at the mains, live parts are accessible. This could result in the user getting an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant standard EN 60335.

Measures ordered by public authorities (to: Retailer): Withdrawal of the product from the market

**Description:** Men's electric razor in a brown leather case. A 2-pin plug without cable is attached to the product (the plug is connected directly to the razor). The packaging is a brown cardboard box.

Batch number / Barcode: 29181777792

Country of origin: China

Alert submitted by: Czech Republic









Alert number: A12/1612/18 Product: Water shoes Name: Beachwalker XP Risk type: Chemical Category: Hobby/sports equipment Brand: Aqua Sphere Type / number of model: black/silver Risk level: Serious risk The shoes contain the polycyclic aromatic hydrocarbons (PAHs) benz(a)anthracene (measured value 2.4 mg/kg), chrysene (measured value 1.2 mg/kg) and benzo(e)pyrene (measured value 1.3 mg/kg). PAHs are absorbed through skin contact. These PAHs are carcinogenic. The product does not comply with the REACH Regulation. Measures taken by economic operators: Withdrawal of the product from the market (By: Distributor) Description: Black/silver neoprene water shoes; no packaging. Batch number / Barcode: Batch: PO# 16000441 EAN: 8032621391733, 8032621391740, 8032621391757, 8032621391764, 8032621391771, 8032621391788, 8032621391795, 8032621391801 Country of origin: China Alert submitted by: Germany



Alert number: A12/1606/18 Product: Laser pointer Name: 3in 1 LASER & LED LIGHT Risk type: Damage to sight Category: Laser pointers Brand: CP Type / number of model: N°: 15441 / 101240 Risk level: Serious risk The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market **Description:** Laser pointer with LED light and carabiner. Product size: 7.55 cm Packaging: sold in a display box. Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Hungary





1240





Alert number: A12/1615/18 Product: Laser pointer Name: 2 Function Laser & LED Light with Carabiner Clip Risk type: Damage to sight Category: Laser pointers Brand: ZK Type / number of model: ZK-9110 Risk level: Serious risk The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market Description: Laser pointer with LED light and carabiner. Product size: 6.72 cm. Packaging: sold individually from a display box. Batch number / Barcode: 786311428893

Country of origin: China

Alert submitted by: Hungary



Alert number: A12/1616/18 Product: Laser pointer Name: Unknown Risk type: Damage to sight Category: Laser pointers Brand: Unknown Type / number of model: FX686 Risk level: Serious risk The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market Description: Pen-shaped laser pointer. Packaging: sealable plastic bag. Product size: 13.3 cm

Batch number / Barcode: 20710415 Country of origin: Unknown Alert submitted by: Hungary







Alert number: A12/1608/18 Product: Passenger car Name: E-class Risk type: Injuries Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Type-approval numbers: e1\*2001/116\*0501\*29-33, e1\*2007/46\*1560\*02-07; types: 212, R1ES Risk level: Serious risk The operation of the active bonnet may be faulty because of a wrong positioning of the sensor hose in the front bumper. In the event of a collision with a pedestrian, the pedestrian would not be detected and the active bonnet would not be triggered. This could increase the potential risk of injury for the pedestrian. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: 8891135 Batch number / Barcode: The vehicles affected were produced between 11 October 2016 and 11 January 2018. Country of origin: Germany Alert submitted by: Germany Alert number: A12/1610/18 Product: Passenger car Name: Q30, QX30 Risk type: Injuries Category: Motor vehicles Brand: Infiniti Type / number of model: Type-approval number: e11\*2007/46\*2977; Type: H15 Risk level: Serious risk The description in the user manual of the child-proof lock for the rear door does not correctly indicate the locked and unlocked positions. This could result in the user inadvertently deactivating the safety feature. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: PG8B3 Batch number / Barcode: The vehicles in question were manufactured between 18.8.2015 and 15.1.2018. Country of origin: Japan Alert submitted by: Germany Alert number: A12/1621/18 Product: Passenger car Name: CLA, B-class Risk type: Injuries Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Type approval number: e1\*2001/116\*0470\*19-20 Type: 245 G Risk level: Serious risk The calibration of the occupant classification system for the passenger seat may not be adequate. As a consequence, the installation of a child seat may not deactivate the passenger airbag as required. In the event of an accident, the passenger airbag could therefore be deployed. This could increase the risk of injury to a child in a rear-facing child seat. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: 9192047 Batch number / Barcode: The vehicles affected were manufactured between 10 January 2018 and 14 February 2018. Country of origin: Germany Alert submitted by: Germany Alert number: A12/1622/18 Product: Passenger car Name: GS350, GS450h, IS350C, IS350 Risk type: Fire Category: Motor vehicles Brand: Lexus Type / number of model: Type-approval number: individual approval; type L10(a), S19(a), HL10(a), HS19(a), XE2(a Risk level: Serious risk A crack in the fuel pulsation damper may lead to a fuel leak. Fuel leakage close to a source of ignition may increase the risk of the vehicle catching fire. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car under Lexus recall code 18SMD-054 . Batch number / Barcode: The vehicles affected were produced between 27.5.2005 and 24.12.2014. Country of origin: Japan Alert submitted by: Germany

lisk type: injuries atagoor; Motor vehicles frame: Volvo type / number of model: Type-approval number: e9°2007/46°3146°03; type: X tisk taves: Satious risk as a result of incorrect assembly, the brake padal may move out of position. This could lead to trake failure. Teasures taken by economic operators: Recall of the product from end users (By: Manufacturer) teasures taken by economic operators: Recall of the product from end users (By: Manufacturer) teasures taken by economic operators: Recall of the product from end users (By: Manufacturer) teasures taken by economic operators: Recall of the product from end users (By: Manufacturer) teasures taken by economic operators: Recall of the product from end users (By: Manufacturer) teast ubmitted by: Germany torducts were found and measures were taken also in: Poland, The Netherlands tert number: A12/163/118 reduct: Passenger car tame: C-HR teasenger and the source car taken also in: Poland, The Netherlands test subset table to the found and measures were taken also in: Poland, The Netherlands test subset source and the source car taken also in: Poland, The Netherlands test source and the source car taken also in: Boland, Poland, TyzY10 tisk keys: Sarious risk he screws retaining the wheel bearings on the hub pol of the rear axle may not have been sufficiently tightened and can become loose. As a consequence, the source can cause the wheels to detach. tesarres taken by economic operators: Recall of the product from end users (By: Distributor) tescription: Passenger car. taken number / A12/1607/18 reducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands tert submitted by: Romania reducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands test source taken out number and subtor the sec of any tools and the button cell batteries inside are easily accessible. child muight put them in the mouther the work of any tools and the button cell batteries inside are easily accessible. child muight put them in the mouther mo		
roduct: Passenger car iame: X040 isk type: injuries stategory: Motor vehicles rand: Voko ype / number of model: Type-approval number: e9'2007/46'3146'03; type: X isk two: is circous risk s a result of incorrect assembly, the brake padal may move out of position. his could lead to brake failure. tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tessures taken by economic operators: Recall of the product from end users (By: Distributor) test submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands test gerois risk the accews retaining the wheal bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. as a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to datach. tessures taken by ecoonmic operators: Recall of the product from end users (By: Distributor) tescriftor: Passenger car. takeh number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 toontry of origi: Japan tert subhitted by: Romania test subhittes subhitses and whow who	Alert number: A12/1624/18	
iame: X240 iskt kype: injuries action: Volvo yer / number of model: Type-approval number; e9'2007/46'3146'03; type: X iskt kevti: Serious risk a result of incorrect assembly, the brake pedal may move out of position. his could lead to brake failure. Issuerse taken by economic operators: Recall of the product from and users (By: Manufacturer) isscription: Passenger car. Company recall code: R59899 atch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. ioutry of origin: Swoden iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands iter submitted by: Commany roducts were found and measures were taken also in: Bulgafa, Poland, The Netherlands iter submitted by: Romania roducts were found and measures were taken also in: Bulgafa, Poland, The Netherlands iter submitted by: Romania roducts were found and measures were taken also in: Bulgafa, Poland, The Netherlands iter submitted by: Romania roducts were found and measures were taken also in: Bulgafa, Poland, The Netherlands iter submitted by: Romania roducts were found and measures were taken also in: Bulgafa, Poland, The Netherlands iter submitted by: Romania roducts were fo		
itagiory: More vehicles: Irand: Volvo yer / number of model: Type-approval number: e9*2007/46*3146*03; type: X isk levei: Serious risk as result of incorrect assembly, the brake pedal may move out of position. his could lead to brake failure. Resurses taken by economic operators: Recall of the product from end users (By: Manufacturer) hesoription: Passenger car. Company recall code: R59899 atch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. ionutry of origin: Sweden left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands site serves realing the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. Is a consequence, the servers can detach during use of the vehicle. If this occurs during rotation of the wheels, It can damage elements of the raking system on the rear axle, or may cause the wheels to detach. results taken by economic operators: Recall of the product from end users (By: Distributor) rescription: Passenger car. left number: A farcode: Vehicles produced between 18 June 2018 and 28 August 2018 rotatch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 rest submitted by: Romania reducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands rest submitted by: Romania rest subm	Name: XC40	
itagiory: More vehicles: Irand: Volvo yer / number of model: Type-approval number: e9*2007/46*3146*03; type: X isk levei: Serious risk as result of incorrect assembly, the brake pedal may move out of position. his could lead to brake failure. Resurses taken by economic operators: Recall of the product from end users (By: Manufacturer) hesoription: Passenger car. Company recall code: R59899 atch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. ionutry of origin: Sweden left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany reducts were found and measures were taken also in: Poland, The Netherlands site serves realing the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. Is a consequence, the servers can detach during use of the vehicle. If this occurs during rotation of the wheels, It can damage elements of the raking system on the rear axle, or may cause the wheels to detach. results taken by economic operators: Recall of the product from end users (By: Distributor) rescription: Passenger car. left number: A farcode: Vehicles produced between 18 June 2018 and 28 August 2018 rotatch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 rest submitted by: Romania reducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands rest submitted by: Romania rest subm	Risk type: Injuries	
trand: Volvo ype / number of model: Type-approval number: e9*2007/46*3146*03; type: X Sike kive: Scrious risk as a result of incorrect assembly, the brake pedal may move out of position. his could lead to brake failure. Tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tescription: Passenger car. Company recall code: R59899 tatch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. toutry of origin: Sweden test submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands tert submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands test submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands test submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands test submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands test submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands test submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands test submitted by: Germany troducts were found and can become loose. a consequence, the screws can detach during us of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. tescription: Tassenger car. tescription: Tassenger		
ype / number of model: Type-approval number: e9*2007/46*3146*03; type: X isk lavel: Serious risk his could lead to brake failure. leasures taken by economic operators: Recall of the product from end users (By: Manufacturer) reseription: Passenger car. Company recall code: R598999 latch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. Jointry of origin: Sweden left submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands left submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands left number: A12/1631/18 roduct: Passenger car lame: C-HR lisk type: Injuries lategory: Motor vehicles rand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 lisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. Is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the rescription: Passenger car land: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 lisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. Is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the rescription: Passenger car. let thomater / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 rotatis submitted by: Romania roducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 roduct: Children's watch, list submitted by: Romania rotatis screws retaken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 rotatis: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily ac		
bisk level: Serious risk as a result of incorrect assembly, the brake pedal may move out of position. his could lead to brake failure. tessures taken by economic operators: Recall of the product from end users (By: Manufacturer) tesserption: Passenger car. Company recall code: RS6969 tatch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. tout stubmitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands tert submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands tert submitted vehicles tradient: CHR targety: Injuries tatagety: Moires takes on the rear axie, or may cause the wheels of the product from end users (By: Distributor) tesseritis: a submitted vehicles tradient: CHR tradient: CHR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk hes convex retaining the wheel bearings on the hub port of the rear axie may not have been sufficiently tightened and can become loose. as a consequence, the screws con detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axie, or may cause the wheels to detach. tesserition: Tassenger car. tarket number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 tournet of during: Japan tert submitted by: Romania troduct: Chifterins watch tert number: A12/1607/18 troduct: Chifterins watch test were: Serious risk he ausers taken also in: Bulgaria, Poland, The Netherlands tert number of model: Unknown tisk type: Chemical, Choking tageory: Moire is series taken also in: Bulgaria, Poland, The Netherlands tert number of model: Unknown tisk type: Chemical, Choking test series taken by economic operators: Recall of the		
s a result of incorrect assembly, the brake pedal may move out of position. his could lead to brake failure. Besurset skken by economic operators: Recall of the product from end users (By: Manufacturer) bescription: Passenger car. Company recall code: R56909 latch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. country of origin: Sweden Left submitted by: Germany: troducts were found and measures were taken also in: Poland, The Netherlands Left submitted by: Germany: troducts were found and measures were taken also in: Poland, The Netherlands Left submitted by: Germany: troducts were found and measures were taken also in: Poland, The Netherlands Left submitted by: Germany: troducts were found and measures were taken also in: Poland, The Netherlands Left submitted by: Germany: troducts were found and measures were taken also in: Poland, The Netherlands Left submitted by: Germany: troducts were found and measures were taken also in: Poland, The Netherlands Left submitted by: Germany: troducts were found and measures were taken also in: Poland, The Netherlands Left submitted by: Germany: taken were found by: CHR TIMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 Lift kiew!: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently lightened and can become loose. a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. Lessures taken by economic operators: Recall of the product from end users (By: Distributor) lescriptin: Passenger cat. Lets humber / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 Lot submitted by: Romania roducts were found and measures were taken also in: Bulgaria, Poland. The Netherlands Left submitted by: Romania roducts were found and measures were taken also in: Bulgaria, Poland. The Netherlands Left submitte		
his could lead to brake failure. Ideasures taken by economic operators: Recall of the product from end users (By: Manufacturer) secription: Passenger car. Company recall code: R59899 Troducts were found and measures were taken also in: Poland, The Netherlands Ider number / Al2/1631/18 roducts were found and measures were taken also in: Poland, The Netherlands Ider number: A12/1631/18 roduct: Passenger car. Iame: C-HR Ider secret and the secret		
taskers taken by economic operators: Recall of the product from end users (By: Manufacturer) hescription: Passenger car. Company produce delween 6.7.2018 and 9.8.2018. Sountry of origin: Sweden her submitted by: Gormany roducts were found and measures were taken also in: Poland, The Netherlands left number: A12/1631/18 roduct: Passenger car lame: C-HR lisk type: Injuries atagory: Motor vehicles rand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 lisk twee: Senious risk he screws retuining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. a o aonsequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. Lessures taken by economic operators: Recall of the product from end users (By: Distributor) tescription: Passenger car. latch number / Barcode: Vehicles produce between 18 June 2018 and 28 August 2018 country of origin: Japan left submitted by: Romania roducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 roduct: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat lisk type: Chemical, Choking tategory: Other trand: Unknown yp / number of model: Unknown lisk twee: Senious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). lessures taken by economic operators: Removal of the products from the Wish platform tessures taken by economic operators: Removal of the products from the Wish platform tessures taken by economic operators: Removal of the products from the Wish platform tessures or devel by public authorities : Authority awaring consumers of the risk tesperiors: Children's watch. Packed in clear		
Hescription: Passenger car. Company recall code: R59899 hatch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. Sourthy of origin: Sweden Hert submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands Hert number: A12/1631/18 roduct: Passenger car Lame: C-HR Lates type: Injuries Lategory: Motor vehicles trand: Toyota Ype / number of model: C-HR TIMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 Lisk kpe: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. a a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the rating system on the rear axle, or may cause the wheels to detach. Lessures taken by economic operators: Recall of the product from end users (By: Distributor) bescription: Passenger car. Latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 torducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands Lessures taken by economic operators: Recall of the graduaria, Poland, The Netherlands Lessures for atroon Uniese Quartz Sports Kids Wrist Wat Lisk type: Chemical, Choking Later submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands Lessures of atroon Uniese Quartz Sports Kids Wrist Wat Lisk type: Chemical, Choking List yeis: Scrious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. . child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. Lessures taken by sconmic operators: Removal of the products from the Wish platform Lessures taken by sconmic operators: Removal of the products from the Wish platform Lessures ordered by public authorities: Authority warning consumers of the risk Les		
latch number / Barcode: The vehicles affected were produced between 6.7.2018 and 9.8.2018. iountry of origin: Sweden liset submitted by: Germany troducts were found and measures were taken also in: Poland, The Netherlands liter number: A12/1631/18 troduct: Passenger car lame: C-HR tisk type: Injuries lategroup: Motor vehicles trand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. s a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the randing system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) rescription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 country of origin: Japan left submitted by: Romania roducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 roduct: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat lisk kype: Chemical, Choking lategroup: Other trand: Unknown ype / number of model: Unknown lisk kies: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. leasures taken by economic operators: Renoval of the products from the Wish platform leasures ordered by public authorities: Xiuhtority warning consumers of the risk teasures ordered by public authorities: Authority meaning consumers of the risk teasures ordered by public authorities: Authorities authorities: Authorities authorities: Authorities authorities authorities authorities authorities authorities authorities auth		
bountry of origin: Sweden later submitted by: Germany roducts were found and measures were taken also in: Poland, The Netherlands left number: A12/1631/18 roduct: Passenger car lame: C-HR lisk type: Injuries lategory: Motor vehicles rarad: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. Is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recail of the product from end users (By: Distributor) bescription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 country of origin: Japan left submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 roduct: Children's watch lame: Lovely Cartoon Unies Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking lategory: Other lated: Univer lisk Level: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. . child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. leasures taken by economic operators: Renoval of the product from the Wish platform leasures ordered by public authorities: Authority waming consumers of the risk platform leasures ordered by bulic authorities: Authority waming consumers of the risk leasures ordered by nublic authorities: Authority maing consumers of the risk leasures ordered by public authorities: Authority waming consumers of the risk leasures ordered by nublic authorities: Authority waming consumers of the risk leasures ordered: Unknown		
Ider t submitted by: Germany roduct: were found and measures were taken also in: Poland, The Netherlands  left number: A12/1631/18 roduct: Passenger car ame: C-HR take type: Injuries later or mode: C-HR TIMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. as a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) lescription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 ountry of origin: Japan left submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 roduct: Children's watch later lows risk he batter; Compariment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. child might put them in the mouth and swallow them, causing choking or damage to the gastrointestimal tract. leasures taken by economic operators: Recoval of the product soft of the risk level: Serious risk he batter; compariment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. child might put them in the mouth and swallow them, causing choking or damage to the gastrointestimal tract. leasures taken by economic operators: Recoval of the product was sold online (for example on Wish marketplace). later humber / Barcode: Unknown lisk level: Dercode: Unknown lisk level: Dercode: Unknown lisk level: Dercode: Unknown lisk level: Serious risk he batter; compariment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. child might put them in the mouth and swallow them,		
reducts were found and measures were taken also in: Poland, The Netherlands left number: A12/1631/18 roduct: Passenger car lame: C-HR isk type: Injuries rand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. s a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. teasures taken by economic operators: Recall of the product from end users (By: Distributor) bescription: Passenger car. tatch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 ountry of origin: Japan ter submitted by: Romania ter submitted by: Romania ter submitted by: Romania ter during the taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 roduct: Children's watch take type: Chemical, Choking tage or y Other test Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. c, thild might put them in the mouth and swallow them, causing choking or damage to the gastroinstatian tract. teasures taken by economic operators: Removal of the rydous from the Wish platform leasures taken by economic operators: Removal of the rydous from the Wish platform leasures taken by economic operators: Removal of the rydous from the solution cell batteries inside are easily accessible. c, thild might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. teasures taken by economic operators: Removal of the rydous from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk leasures taken by economic operators: Removal of the rydous from the Wish platform leasures ordered by public authorities: Authority warning consumers	Country of origin: Sweden	
lert number: A12/1631/18 roduct: Passenger car lame: C-HR lisk type: Injuries attegory: Motor vehicles trand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 lisk text: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the ranking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) lescription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 isountry of origin: Japan lert submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/160718 roduct: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat lisk type: Chemical, Choking ategory: Uther lisk level: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. . child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. leasures taken by economic operators: Removal of the products from the Wish platform leasures under by bublic authorities: Authority warning consumers of the risk leasures acken by bublic authorities: Authority warning consumers of the risk leasures taken by bublic authorities: Authority warning consumers of the risk leasures taken by bublic authorities: Authority warning consumers of the risk leasures taken by economic operators: Removal of the products from the Wish platform leasures taken by economic operators: Removal of the products from the Wish platform leasures taken by economic operators: Authority warning consumers of the risk leasures taken by economic operators: Authority w	Alert submitted by: Germany	
roduct: Passenger car Jame: C-HR tisk type: Injuries ataegory: Motor vehicles trand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) leascription: Passenger car. tatch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 ountry of origin: Japan Jert submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands 	Products were found and measures were taken also in: Poland, The Netherlands	
roduct: Passenger car Jame: C-HR tisk type: Injuries ataegory: Motor vehicles trand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) leascription: Passenger car. tatch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 ountry of origin: Japan Jert submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands 	Alert number: A12/1631/18	
lame: C-HR lisk type: injuries lategory: Motor vehicles irrand: Toyola ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 lisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. Is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) lescription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 isountry of origin: Japan lert submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 roduct: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat lisk type: Chemical, Choking lategory: Other lated number: Material (Lokking lategory: Other lategory: Other lategory: Other lategory: Dither lategory: Dither		
tisk type: Injuries tategory: Motor vehicles trand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk the screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. teasures taken by economic operators: Recall of the product from end users (By: Distributor) teacrifton: Parsenger car. tatch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 country of origin: Japa Jear submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands let submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands let number: A12/1607/18 troduct: Children's watch tame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking tategory: Other trand: Unknown ype / number of model: Unknown tisk level: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. achtid might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. teasures taken by economic operators: Removal of the products from the Wish platform teasures ordered by public authorities: Authority warning consumers of the risk teasription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). taketh number / Barcoce: Unknown	Name: C-HR	
iategory: Notor vehicles irrand: Toyola ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 itik level: Serious risk the screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) lescription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 obuntry of origin: Japan Jert submitted by: Romania roducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands let number: A12/1607/18 roduct: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat lisk type: Chemical, Choking lategory: Other larand: Unknown tisk level: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. • child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. leasures taken by economic operators: Removal of the products from the Wish platform leasures taken by public authorities: Authority warning consumers of the risk leasures taken by public authorities: Authority warning consumers of the risk leasures taken by public authorities: Authority warning consumers of the risk leasures taken by conomic operators: Removal of the products from the Wish platform leasures taken by conomic operators: Removal of the products from the Wish platform leasures taken by conomic operators: Removal of the products from the wish platform leasures taken by conomic operators: Removal of the products from the wish platform leasures taken by conomic operators: Removal of the products from the wish platform leasures taken by		
Irand: Toyota ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) bescription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 ioountry of origin: Japan Jet submitted by: Romania roducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands 		
ype / number of model: C-HR TMMT MY2018 // NGX10, NGX50, ZGX10, ZYX10 tisk level: Serious risk the screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. teasures taken by economic operators: Recall of the product from end users (By: Distributor) tescription: Passenger car. tact number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 ountry of origin: Japan Jert submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands Her number: A12/1607/18 troduct: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking ategory: Other trand: Unknown ype / number of model: Unknown tisk level: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. . child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. teasures taken by economic operators: Removal of the products from the Wish platform teasures taken by economic operators: Removal of the products from the Wish platform teasures taken by economic operators: Removal of the products from the Wish platform teasures taken by economic operators: Removal of the products from the Wish platform teasures taken by economic operators: Removal of the products from the Wish platform teasures taken by economic operators: Removal of the products from the Wish platform teasures taken by economic operators: Removal of the products from the Wish platform teasures taken by economic operators: Removal of the products from the Wish platform teasures taken by economic operators: Removal of the products from the Wish platform teas	•••	
Tisk level: Serious risk         he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose.         is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach.         leasures taken by economic operators: Recall of the product from end users (By: Distributor)         leasures taken by economic operators: Recall of the product from end users (By: Distributor)         leasures taken by economic operators: Recall of the product from end users (By: Distributor)         leasures taken by economic operators: Recall of the product from end users (By: Distributor)         leasures taken by economic operators: Recall of the product from end users (By: Distributor)         leasures taken by economic operators: Recall of the product from end users (By: Distributor)         leasures taken by economic operators: Recall of the product from end users (By: Distributor)         leasures taken by economic operators: Recall of the product from end users (By: Distributor)         leasures taken by economic operators: Recall of the products from the Wetherlands         least trip: Content is the stress of the measures were taken also in: Bulgaria, Poland, The Netherlands         least trip: Content is the content is the stress of the rest trip: Content is the rest trip: Content is thendetent is the stress of the rest trip: Conten	•	
he screws retaining the wheel bearings on the hub port of the rear axle may not have been sufficiently tightened and can become loose. Is a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. <b>leasures taken by economic operators:</b> Recall of the product from end users (By: Distributor) <b>lescription:</b> Passenger car. <b>tatch number / Barcode:</b> Vehicles produced between 18 June 2018 and 28 August 2018 <b>country of origin:</b> Japan <b>lear submitted by:</b> Romania <b>troducts were found and measures were taken also in:</b> Bulgaria, Poland, The Netherlands <b>lear turber:</b> A12/1607/18 <b>troduct:</b> Children's watch <b>lame:</b> Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat <b>tisk type:</b> Chemical, Choking <b>tategory:</b> Other <b>trand:</b> Unknown <b>ype / number of model:</b> Unknown <b>tisk level:</b> Serious risk <b>he</b> battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. <b>a</b> child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. <b>leasures taken by economic operators:</b> Removal of the products from the Wish platform <b>leasures taken by economic operators:</b> Removal of the products from the Wish platform <b>leasures taken by economic operators:</b> Removal of the products from the Wish platform <b>leasures taken by economic operators:</b> Removal of the products from the Wish platform <b>leasures taken by economic operators:</b> Removal of the products from the Wish platform <b>leasures taken by economic operators:</b> Removal of the products from the Wish platform <b>leasures ordered by public authorities:</b> Authority warning consumers of the risk <b>lescription:</b> Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). <b>latch number / Barcode:</b> Unknown <b>tountyr of origin:</b> Unknown		
s a consequence, the screws can detach during use of the vehicle. If this occurs during rotation of the wheels, it can damage elements of the raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) leascription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 country of origin: Japan left submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 troduct: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat litsk type: Chemical, Choking litel submitted by: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. leasures taken by economic operators: Removal of the products from the Wish platform leasures taken by economic aperators: Authority warning consumers of the risk leasures taken by economic operators: Removal of the products from the Wish platform leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by by Consumers of the risk leasures ordered by by Consumers of the risk leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk leasures taken by economic operators: Removal of the product was sold online (for example on Wish marketplace). Latch number / Barcode: Unknown licounty of origin:		
raking system on the rear axle, or may cause the wheels to detach. leasures taken by economic operators: Recall of the product from end users (By: Distributor) leascription: Passenger car. latch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 country of origin: Japan lert submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands left number: A12/1607/18 roduct: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking lategory: Other litrand: Unknown ype / number of model: Unknown tisk level: Serious risk the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. . child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk leasures ordered by public authorities: Authority warning consumers of the risk leasures forder is watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). latch number / Barcode: Unknown country of origin: Unknown		
Iteasures taken by economic operators: Recall of the product from end users (By: Distributor)         tescription: Passenger car.         tatch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018         country of origin: Japan         Ulert submitted by: Romania         troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands         Inter number: A12/1607/18         troduct: Children's watch         Iame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat         tisk type: Chemical, Choking         tategory: Other         trand: Unknown         type / number of model: Unknown         tisk level: Serious risk         he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible.         t. child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract.         teasures taken by economic operators: Removal of the products from the Wish platform         teasures oftered by public authorities: Authority warning consumers of the risk         teascription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace).         tatch number / Barcode: Unknown         totury of origin: Unknown		e elements of the
Alter submitted by: Romania inter submitter submitte		
Atch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018 country of origin: Japan Jert submitted by: Romania troducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands Jert number: A12/1607/18 Troduct: Children's watch Jame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking tategory: Other trand: Unknown ype / number of model: Unknown tisk level: Serious risk the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. A child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk Description: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). tatch number / Barcode: Unknown town of origin: Unknown	Measures taken by economic operators: Recall of the product from end users (By: Distributor)	
Resures ordered by public authorities: Authority warning consumers of the risk Resures ordered by public authorities: Authority warning consumers of the risk Resures ordered by public authorities: Authority warnings. The product was sold online (for example on Wish marketplace). Resure or origin: Unknown Resures or origin: Unknown	Description: Passenger car.	
Nert submitted by: Romania products were found and measures were taken also in: Bulgaria, Poland, The Netherlands Nert number: A12/1607/18 roduct: Children's watch Name: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking sategory: Other isrand: Unknown ype / number of model: Unknown tisk level: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. Neasures taken by economic operators: Removal of the products from the Wish platform Neasures ordered by public authorities: Authority warning consumers of the risk Nescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Hatch number / Barcode: Unknown Sountry of origin: Unknown	Batch number / Barcode: Vehicles produced between 18 June 2018 and 28 August 2018	
Aroducts were found and measures were taken also in: Bulgaria, Poland, The Netherlands  Jert number: A12/1607/18  Product: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking category: Other Grand: Unknown Ype / number of model: Unknown tisk level: Serious risk he battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. Child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. Reasures taken by economic operators: Removal of the products from the Wish platform Reasures ordered by public authorities: Authority warning consumers of the risk Rescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Children's watch. Children's watch. Packed in clear plastic, no markings. Children's watch. Children's watch. Children's wa	Country of origin: Japan	
Alert number: A12/1607/18 Product: Children's watch lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking category: Other trand: Unknown type / number of model: Unknown tisk level: Serious risk the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. A child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk lescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). tatch number / Barcode: Unknown country of origin: Unknown	Alert submitted by: Romania	
Product: Children's watch          Jame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat         Lisk type: Chemical, Choking         Stategory: Other         Brand: Unknown         ype / number of model: Unknown         tisk level: Serious risk         The battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible.         a child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract.         Beasures taken by economic operators: Removal of the products from the Wish platform         Beasures ordered by public authorities: Authority warning consumers of the risk         Description: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace).         Statch number / Barcode: Unknown         Scountry of origin: Unknown	Products were found and measures were taken also in: Bulgaria, Poland, The Netherlands	
Product: Children's watch          Jame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat         Lisk type: Chemical, Choking         Stategory: Other         Brand: Unknown         ype / number of model: Unknown         tisk level: Serious risk         The battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible.         a child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract.         Beasures taken by economic operators: Removal of the products from the Wish platform         Beasures ordered by public authorities: Authority warning consumers of the risk         Description: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace).         Statch number / Barcode: Unknown         Scountry of origin: Unknown	Alert number: A12/1607/18	
lame: Lovely Cartoon Unisex Quartz Sports Kids Wrist Wat tisk type: Chemical, Choking category: Other grand: Unknown type / number of model: Unknown tisk level: Serious risk the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. the battery compartment can easily be opened without the use of the grade to the gastrointestinal tract. leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk lescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Batch number / Barcode: Unknown country of origin: Unknown		
tisk type: Chemical, Choking category: Other Brand: Unknown ype / number of model: Unknown tisk level: Serious risk the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. A child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. Ieasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk eescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Batch number / Barcode: Unknown country of origin: Unknown		
<ul> <li>Category: Other</li> <li>Grand: Unknown</li> <li>Grand: Unknown</li> <li>Grand: Unknown</li> <li>Grand: Unknown</li> <li>Grand: Unknown</li> <li>Grand: Serious risk</li> <li>The battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible.</li> <li>Child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract.</li> <li>Reasures taken by economic operators: Removal of the products from the Wish platform</li> <li>Reasures ordered by public authorities: Authority warning consumers of the risk</li> <li>Rescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace).</li> <li>Reatch number / Barcode: Unknown</li> <li>Country of origin: Unknown</li> </ul>		
<ul> <li>Brand: Unknown</li> <li>Type / number of model: Unknown</li> <li>Risk level: Serious risk</li> <li>The battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible.</li> <li>Child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract.</li> <li>Reasures taken by economic operators: Removal of the products from the Wish platform</li> <li>Reasures ordered by public authorities: Authority warning consumers of the risk</li> <li>Reasures contered by public authorities: Authority warnings. The product was sold online (for example on Wish marketplace).</li> <li>Reatch number / Barcode: Unknown</li> <li>Country of origin: Unknown</li> </ul>		
<ul> <li>ype / number of model: Unknown</li> <li>tisk level: Serious risk</li> <li>the battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible.</li> <li>a child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract.</li> <li>leasures taken by economic operators: Removal of the products from the Wish platform</li> <li>leasures ordered by public authorities: Authority warning consumers of the risk</li> <li>Description: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace).</li> <li>Batch number / Barcode: Unknown</li> </ul>		
<ul> <li>A child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract.</li> <li>Iteasures taken by economic operators: Removal of the products from the Wish platform</li> <li>Iteasures ordered by public authorities: Authority warning consumers of the risk</li> <li>Description: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace).</li> <li>Batch number / Barcode: Unknown</li> <li>Country of origin: Unknown</li> </ul>		
The battery compartment can easily be opened without the use of any tools and the button cell batteries inside are easily accessible. In child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. In the asures taken by economic operators: Removal of the products from the Wish platform In the asures ordered by public authorities: Authority warning consumers of the risk Description: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Batch number / Barcode: Unknown Country of origin: Unknown		
A child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract. Measures taken by economic operators: Removal of the products from the Wish platform Measures ordered by public authorities: Authority warning consumers of the risk Mescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Batch number / Barcode: Unknown Country of origin: Unknown		
leasures taken by economic operators: Removal of the products from the Wish platform leasures ordered by public authorities: Authority warning consumers of the risk lescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Batch number / Barcode: Unknown country of origin: Unknown		essible.
leasures ordered by public authorities: Authority warning consumers of the risk bescription: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Batch number / Barcode: Unknown country of origin: Unknown	A child might put them in the mouth and swallow them, causing choking or damage to the gastrointestinal tract.	
Description: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish marketplace). Batch number / Barcode: Unknown Country of origin: Unknown	Measures taken by economic operators: Removal of the products from the Wish platform	
atch number / Barcode: Unknown country of origin: Unknown	Measures ordered by public authorities: Authority warning consumers of the risk	
country of origin: Unknown	Description: Children's watch. Packed in clear plastic, no markings. The product was sold online (for example on Wish markings)	etplace).
	Batch number / Barcode: Unknown	
	Country of origin: Unknown	
	Alert submitted by: Finland	
	•	



Alert number: A12/1604/18 Product: Wooden toy rattle Name: Cute Animal Design Wooden Toy Rattle Risk type: Choking Category: Toys Brand: Unknown Type / number of model: blue rattle: (E08.4.05) 5259028.67, orange rattle: (E08.4.05) 5259028.89, red rattle: (E08.4.05) 5259028.35 Risk level: Serious risk The ears and head on the top of the rattle can easily detach. A small child may put them in the mouth and choke. The size and shape of the rattle may also cause choking. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Measures taken by economic operators: Removal of the products from the Wish platform Measures ordered by public authorities: Authority warning consumers of the risk Description: Wooden painted rattle with a bell inside. Sold in a clear plastic bag with no markings. The product has been sold online, in particular on the Wish website. Batch number / Barcode: blue rattle: 19022013776157 , orange rattle: 19022013776157, red rattle: 19022013776157 Country of origin: China Alert submitted by: Finland



Alert number: A12/1609/18 Product: Toy slime Name: Barrel-o-slime Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: 205AO1791 LG IMPORTS, CY-0052753 CHYK Sarl Risk level: Serious risk The migration of boron from the toy slime is too high (measured value: up to 4263 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3. **Measures taken by economic operators:** Recall of the product from end users, Withdrawal of the product from the market (By: Distributor) **Description:** Toy slime in a cardboard box containing 12 units (2 blue, 2 red, 2 purple, 2 green, 2 black, 2 yellow) or 24 units (4 blue, 8 yellow, 6 red, 6 green)

Batch number / Barcode: 541324709164 Country of origin: China Alert submitted by: France



Alert number: A12/1617/18 Product: Plastic doll Name: Princess Catherine Doll Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: N° 3011, N° MH1014040 Risk level: Serious risk The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 26 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation. Measures ordered by public authorities (to: Retailer): Withdrawal of the product from the market Description: Plastic doll (approx. 30 cm tall) with long hair and a dress, available in different colours. Batch number / Barcode: 8418810140403 Country of origin: China Alert submitted by: Czech Republic



Alert number: A12/1619/18 Product: Plastic rattle Name: Grzechotka Risk type: Cuts Category: Toys Brand: Funny Baby Toys Type / number of model: U906T Risk level: Serious risk The toy has sharp edges. If a child plays with the product they may cause cuts.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. **Measures ordered by public authorities (to: Importer):** Withdrawal of the product from the market **Description:** Plastic rattle in the shape of a duck, packed in plastic bag with label attached. **Batch number / Barcode:** 5901811106446

Country of origin: China

Alert submitted by: Poland





Alert number: A12/1620/18 Product: Plastic doll Name: Mermaid Story Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: 02014G Risk level: Serious risk The plastic of the doll's head contains (2-ethylhexyl) phthalate (DEHP) (measured value: 26% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Importer) Description: Plastic mermaid doll accompanied by a little plastic hair brush. Packaged in a plastic blister with cardboard back. Batch number / Barcode: 7460801008484 Country of origin: China Alert submitted by: Poland



Alert number: A12/1623/18 Product: Toy police set Name: Police, City Heros Risk type: Choking Category: Toys Brand: KIG Type / number of model: Article No 301/4226 Risk level: Serious risk The suction cups can easily be detached from the projectiles. If a child puts the projectile in the mouth, the suction cup may detach and obstruct the airways.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. **Measures taken by economic operators:** Withdrawal of the product from the market (By: Retailer) **Description:** Toy police set consisting of a toy gun, projectiles with suction cups, handcuffs, a badge, etc. **Batch number / Barcode:** LOT: 19233; 4250052690001 **Country of origin:** Unknown



Alert number: A12/1625/18 Product: Squeezable toy Name: Squeezy buddies Risk type: Chemical Category: Toys Brand: Liniex ApS Type / number of model: turtle; 171209 Risk level: Serious risk The product contains the substances N,N-dimethylformamide, N,N-dimethyl-aminoethanol, cyclohexanone, triethylenediamine, bis (2-(dimethylamino) ethyl) ether and 1,1,4,7,7-pentamethyl-diethylenetriamine. There is a risk of eye and mucous membrane irritation and of liver damage. The product does not comply with the requirements of the Toy Safety Directive.

Measures taken by economic operators: Recall of the product from end users, Recall of the product from end users, Withdrawal of the product from the market, Withdrawal of the product from the market (By: Distributor, Importer)

Description: Squeezable toy (squishy) in the form of a yellow turtle, wrapped in a plastic bag.

Batch number / Barcode: 5713396500553

Country of origin: Unknown

Alert submitted by: Denmark



Alert number: A12/1626/18 Product: Squeezable toy Name: Squeezy Buddies Risk type: Chemical Category: Toys Brand: Liniex ApS Type / number of model: Pommes frites ; 50056 Risk level: Serious risk The product contains the substances N,N-dimethylformamide, N,N-dimethyl-aminoethanol, cyclohexanone, triethylenediamine, bis (2-(dimethylamino) ethyl) ether and 1,1,4,7,7-pentamethyl-diethylenetriamine. There is a risk of eye and mucous membrane irritation and of liver damage.

The product does not comply with the requirements of the Toy Safety Directive.

Measures taken by economic operators: Recall of the product from end users, Recall of the product from end users, Withdrawal of the product from the market (By: Distributor, Exporter, Importer)

Description: Squeezable toy (squishy) in the shape of french fries, wrapped in a plastic bag.

Batch number / Barcode: 5713396500560

Country of origin: Unknown

Alert submitted by: Denmark



Alert number: A12/1627/18 Product: Squeezable toy Name: Squishy Risk type: Chemical Category: Toys Brand: Hui Chen Type / number of model: 865-805 Risk level: Serious risk The product contains the substances N,N-dimethylformamide, cyclohexanone, triethylenediamine, 1,1,4,7,7-pentamethyl-diethylenetriamine and xylenes. There is a risk of eye and mucous membrane irritation, of liver damage and of effects on the nervous system. The product does not comply with the requirements of the Toy Safety Directive. Measures taken by economic operators: Recall of the product from end users, Recall of the product from end users, Withdrawal of the product from the market, Withdrawal of the product from the market (By: Distributor, Importer) Description: Squeezable toy (squishy) in the shape of a cat with fish, wrapped in a plastic bag. Batch number / Barcode: 6920182148052 Country of origin: Unknown Alert submitted by: Denmark



Alert number: A12/1628/18 Product: Squeezable toy Name: Squishy, icecream Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: 802708-34 Risk level: Serious risk The product contains the substances dimethylformamide, dimethyl-aminoethanol, cyclohexanone, triethylenediamine and bis (2- (dimethylamino)) ethyl) ether. There is a risk of eye and mucous membrane irritation and of liver damage. The product does not comply with the requirements of the Toy Safety Directive. Measures taken by economic operators: Recall of the product from end users, Withdrawal of the product from the market (By: Distributor) Description: Squeezable ice-cream toy (squishy) wrapped in a transparent plastic bag. Batch number / Barcode: Unknown

Country of origin: Unknown

Alert submitted by: Denmark



Alert number: A12/1629/18 Product: Squeezable toy Name: Squishy, orange cat burger Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: 802708-38 Risk level: Serious risk The product contains the substances I

The product contains the substances N,N-dimethylformamide, N,N-dimethyl-aminoethanol, cyclohexanone and triethylenediamine. There is a risk of eye and mucous membrane irritation and of liver damage.

The product does not comply with the requirements of the Toy Safety Directive.

**Measures taken by economic operators:** Recall of the product from end users, Withdrawal of the product from the market (By: Distributor) **Description:** Squeezable toy (squishy) in the shape of an orange burger with a cat face, wrapped in a plastic bag. **Batch number / Barcode:** 5707955029531

Country of origin: Unknown

Alert submitted by: Denmark



Alert number: A12/1630/18 Product: Squeezable toy Name: Soft'n Slo Squishies Risk type: Chemical Category: Toys Brand: ORB Type / number of model: Donut; 51501-00-R0 2321729 Risk level: Serious risk The product contains the substances N,N-dimethylformamide, N,N-dimethyl-aminoethanol, cyclohexanone, triethylenediamine, bis (2-(dimethylamino) ethyl) ether and 1,1,4,7,7-pentamethyl-diethylenetriamine. There is a risk of eye and mucous membrane irritation as well as liver damage.

The product does not comply with the requirements of the Toy Safety Directive.

Measures taken by economic operators: Recall of the product from end users, Withdrawal of the product from the market (By: Distributor) Description: Purple squeezable toy (squishy) shaped like a doughnut with insects on it, wrapped in a plastic bag. Batch number / Barcode: Unknown Country of origin: Canada

Alert submitted by: Denmark



Alert number: A12/1632/18 Product: Squeezable toy Name: Squishy, Fox Risk type: Chemical Category: Toys Brand: Hui Chen Type / number of model: 862-802 Risk level: Serious risk The product contains the substances dimethylformamide, dimethyl-aminoethanol, cyclohexanone, triethylenediamine and bis (2- (dimethylamino) ethyl) ether. There is a risk of eye and mucous membrane irritation and of liver damage. The product does not comply with the requirements of the Toy Safety Directive. Measures taken by economic operators: Recall of the product from end users, Recall of the product from end users, Withdrawal of the product from the market, Withdrawal of the product from the market (By: Distributor, Importer) Description: Squeezable toy in the form of a fox, wrapped in a transparent plastic bag. Batch number / Barcode: 6920182148021 Country of origin: China Alert submitted by: Denmark Alert number: A12/1633/18 Product: Toy slime Name: Furzschleim/ Farting putty Risk type: Chemical Category: Toys Brand: Coppenrath Verlag Type / number of model: Unknown Risk level: Serious risk The migration of boron from the toy slime is too high (measured value up to 6799 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3. Measures taken by economic operators: Withdrawal of the product from the market (By: Importer) Description: Putty-like slime (light green), gel mass in a plastic box, coated with colourless plastic film.

Batch number / Barcode: 4029753141095 Country of origin: Germany

Alert submitted by: Austria



Alert number: A12/1634/18 Product: Squeezable toy Name: Jumbo Sheep Risk type: Chemical Category: Toys Brand: Amigazone Type / number of model: SCY 80105105 Risk level: Serious risk The product contains the substances dimethylformamide, cyclohexanone, triethylenediamine and 1,1,4,7,7-pentamethyl-diethylenetriamine as well as xylenes. There is a risk of eye and mucous membrane irritation, liver damage and effects to the nervous system. The product does not comply with the requirements of the Toy Safety Directive. Measures taken by economic operators: Recall of the product from end users, The product listing has been removed from the online marketplace Description: Colourful squishy toy in the form of a lamb, wrapped in plastic. The product is sold online (in particular via WISH). Batch number / Barcode: Unknown Country of origin: Unknown Alert submitted by: Denmark

Alert number: A12/1635/18 Product: Squeezable toy Name: Unknown Risk type: Chemical Category: Toys Brand: Dingxu's store Type / number of model: 894968 H11-02-34-1 and 802708-61 Risk level: Serious risk The product contains the substances N,N-dimethylformamide, N,N-dimethyl-aminoethanol, cyclohexanone and triethylenediamine. There is a risk of eye and mucous membrane irritation and of liver damage.

The product does not comply with the requirements of the Toy Safety Directive.

**Measures taken by economic operators:** Recall of the product from end users, The product listing has been removed from the online marketplace

**Description:** Squeezable toy (squishy) in the shape of a burger with a cat face, wrapped in a plastic bag. The product has been sold online (in particular via Wish).

Batch number / Barcode: Unknown Country of origin: Unknown Alert submitted by: Denmark



Alert number: A12/1636/18 Product: Squeezable toy Name: Unknown Risk type: Chemical Category: Toys Brand: Good Buy Mall Type / number of model: LI70801007 Risk level: Serious risk The product contains the substances N,N-dimethylformamide, N,N-dimethyl-aminoethanol, cyclohexanone and triethylenediamine. There is a risk of eye and mucous membrane irritation and of liver damage. The product does not comply with the requirements of the Toy Safety Directive. Measures taken by economic operators: Recall of the product from end users, The product listing has been removed from the online marketplace Description: Squeezable toy (squishy) in the shape of an ice cream cone with a face, wrapped in a plastic bag. the product has been sold online (in particular via Wish). Batch number / Barcode: Unknown Country of origin: Unknown

Alert submitted by: Denmark

