

Alert number **[A12/00875/21](#)**

Product **Doll Stroller**



Risk type **Injuries**

The pushchair is not sufficiently resistant to load. As a consequence, it can easily collapse and a child playing with it may fall to the ground.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Doll stroller.**

Packaging description **Packed into a transparent back.**

Brand **HR**

Name **Baby - Lovely Happy Strollers**

Type / number of model **RD333C,B**

Barcode **2015050700204**

Weekly report number **Report-2021-24**

Alert submitted by **Cyprus**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

01/02/2021

Alert number **[A12/00871/21](#)**

Product **Toy keyboard**



Risk type	Choking
	Small parts (black keys) can easily detach from the toy. A small child may put them in the mouth and choke.
	The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.
Category	Toys
Type	Consumer
Description	Battery operated piano toy.
Packaging description	Packed into a carton window blisted.
Brand	Unknown
Name	Happy Concert
Type / number of model	899
Barcode	6902020072453
Weekly report number	Report-2021-24
Alert submitted by	Cyprus
Is the product counterfeit?	Unknown

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

01/02/2021

Alert number **[A12/00880/21](#)**

Product **Ceiling lamp**



Risk type **Electric shock**

The light bulb holder is not properly isolated. As a consequence, the user could touch live parts and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN IEC 60238.

Category **Lighting equipment**

Type **Consumer**

Description **Electric ceiling lamp made mainly of wood. Dimensions 40 x 40 cm [W x H], 1.1 kg. The bipolar mains cable consists of a textile-braided flexible PVC cable. An assembly kit for installing the lamp on the ceiling is included in the packaging.**

Brand **WOODSHIRE**

Type / number of model **Dalia**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **Unknown**

Country of origin **Russian Federation**

Measures ordered by public authorities

Import rejected at border
Other



Alert number **[A12/00860/21](#)**

Product **Grass trimmer head**



Risk type **Injuries**

The head may be mounted on a grass trimmer, against its intended use. Therefore the cutting attachments are unprotected and could break during use. Consequently, the user could be hit by the head or broken pieces and be injured.

The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters.

Category **Machinery**

Type **Consumer**

Description **Head with cutting attachments. It was advertised as suitable for use on commercially available grass trimmers and brush cutters. The product was sold online.**

Brand **Unknown**

Name **Trimmer Head with 6 Steel Razor For Lawn Mower 65**

Weekly report number **Report-2021-24**

Alert submitted by **Denmark**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public
authorities

Recall of the product from end users
Other

Date of entry into force

17/03/2021

Alert number **[A12/00861/21](#)**

Product **Grass trimmer head**



Risk type **Injuries**

The head may be mounted on a grass trimmer, against its intended use, be used as a hand-held chain saw. As a consequence, this could cause kickback or loss of control over the tool, resulting in injuries. Additionally, the chain saw elements and cutting attachments are unprotected and could break during use. Consequently, the user could be hit by the head or broken pieces and be injured.

The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters.

Category **Machinery**

Type **Consumer**

Description **Head with 2 blades with chain saw elements. It was advertised as suitable for use on commercially available grass trimmers and brush cutters and was sold online.**

Brand **Unknown**

Name **Lawn mower chain trimmer head brush cutter for gar**

Weekly report number **Report-2021-24**

Alert submitted by **Denmark**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public authorities **Stop of sales
Other**

Date of entry into force **11/03/2021**

Alert number **[A12/00862/21](#)**

Product **Grass trimmer head**



Risk type **Injuries**

The head may be mounted on a grass trimmer, against its intended use. Therefore the cutting attachments are unprotected and could break during use. Consequently, the user could be hit by the head or broken pieces and be injured.

The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters.

Category **Machinery**

Type **Consumer**

Description **Head with cutting attachments. It was advertised as suitable for use on commercially available grass trimmers and brush cutters. The product was sold online.**

Brand **Unknown**

Name **6 Blade Cutter Head Grass Trimmer 6 blade Cutter H**

Weekly report number **Report-2021-24**

Alert submitted by **Denmark**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public
authorities

Stop of sales
Other

Date of entry into force

11/03/2021

Alert number **[A12/00865/21](#)**

Product **Grass trimmer head**



Risk type **Injuries**

The head may be mounted on a grass trimmer, against its intended use. Therefore the cutting attachments are unprotected and could break during use. Consequently, the user could be hit by the head or broken pieces and be injured.

The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters.

Category **Machinery**

Type **Consumer**

Description **Head with cutting attachments. It was advertised as suitable for use on commercially available grass trimmers and brush cutters. The product was sold online.**

Brand **Unknown**

Name **lawn mower cutting equipment of the percussion typ**

Weekly report number **Report-2021-24**

Alert submitted by **Denmark**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public
authorities

Recall of the product from end users
Other

Date of entry into force

24/03/2021

Alert number

[**A12/00867/21**](#)

Product

Grass trimmer head parts

Risk type

Injuries

The product is for heads that may be mounted on a grass trimmers, against its intended use, and be used as a hand-held chain saw. As a consequence, this could cause kickback or loss of control over the tool, resulting in injuries. Additionally, the chain saw elements and cutting attachments are unprotected and could break during use. Consequently, the user could be hit by the head or broken pieces and be injured.

The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters.

Category

Machinery

Type

Consumer

Description

Replacement chains for grass trimmer heads with 2 blades with chain saw elements and cutting attachments. The heads were advertised as suitable for use on commercially available grass trimmers and brush cutters. The product was sold online.

Brand

Unknown

Name

2pcs Coil Chain Grass Garden Brush Cutter Chain 2p

Weekly report number

Report-2021-24

Alert submitted by

Denmark

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public authorities **Recall of the product from end users
Other**

Date of entry into force **06/04/2021**

Alert number **[A12/00868/21](#)**

Product **Grass trimmer head**



Risk type **Injuries**

The head may be mounted on a grass trimmer and may therefore, against its intended use, be used as a hand-held chain saw. As a consequence, this could cause kickback or loss of control over the tool, resulting in injuries. Additionally, the chain saw elements and cutting attachments are unprotected and could break during use. Consequently, the user could be hit by the head or broken pieces and be injured.

The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters.

Category **Machinery**

Type **Consumer**

Description **Head with 2 blades with chain saw elements and cutting attachments. It was advertised as suitable for use on commercially available grass trimmers and brush cutters. The product was sold online, in particular via eBay.**

Brand **Unknown**

Name **65Mn Coil Chain Trimmer Head Brushcutter Grass Tri**

Weekly report number **Report-2021-24**

Alert submitted by **Denmark**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public authorities **Recall of the product from end users
Other**

Date of entry into force **12/04/2021**

Alert number **[A12/00869/21](#)**

Product **Grass trimmer head**



Risk type **Injuries**

The head may be mounted on a grass trimmer, against its intended use. Therefore the cutting attachments are unprotected and could break during use. Consequently, the user could be hit by the head or broken pieces and be injured.

The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters.

Category **Machinery**

Type **Consumer**

Description **Head with cutting attachments. It was advertised as suitable for use on commercially available grass trimmers and brush cutters. The product was sold online, in particular via eBay.**

Brand **Unknown**

Name **Universal Weed Grass 6 Blade Steel Trimmer Head Br**

Weekly report number **Report-2021-24**

Alert submitted by **Denmark**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public authorities **Recall of the product from end users
Other**

Date of entry into force **12/04/2021**

Alert number **[A12/00872/21](#)**

Product **Passenger car**

Risk type **Fire
Injuries**

A short-circuit may occur in the battery. This could lead to overheating, increasing the risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Peugot**

Name **3008, 508**

EC-type approval/model **Types: M, F
e2*2007/46*0534*12, e2*2007/46*0628*05 - *7**

Production dates **The affected vehicles were manufactured between 14
October 2019 and 11 February 2020.**

Company recall code **KEB, KFC**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **France
Sweden**

Alert number

[**A12/00899/21**](#)

Product

Magazine with a bow and 3 arrows

Risk type

Choking

Some suction cups can be easily detached. If a child puts them in the mouth, the suction cups could detach and obstruct the airways.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category

Toys

Type

Consumer

Description

Set comprising: 1 issue of 'Benjamin Blümchen' magazine, 1 plastic bow (black and silver) with string (black) and 3 arrows (black) with suction cups (red)

Packaging description

The product is sold in a colourless printed plastic bag glued to a Benjamin Blümchen magazine

Brand

Benjamin Blümchen

Name

Benjamin Blümchen Nr. 6 - Ritterbogen mit 3 Pfeilen

Type / number of model

Modellnummer Spielzeug: 422106

Batch number

4198556503994

Weekly report number

Report-2021-24

Alert submitted by

Austria

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Withdrawal of the product from the market
Distributor**

Date of entry into force **02/06/2021**

Company recall code -
https://www.ages.at/produktwarnungen/produktwarnung/benjamin-bluemchen-magazin-62021/#pk_campaign=Produktwarnung&pk_kwd=PW-ID487

Alert number **[A12/00863/21](#)**

Product **Passenger car**

Risk type **Injuries**

Due to discrepancy in the dashboard manufacturing process, the front passenger airbag may fail to deploy optimally. This could impair its protective function, increasing the risk of injury in the event of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **AUDI**

Name **A4**

EC-type approval/model **e1*2001/116*0430*78**

Production dates **March 2021**

Company recall code **70I3**

Weekly report number **Report-2021-24**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Importer**

Date of entry into force **05/05/2021**

Alert number **[A12/00885/21](#)**

Product **Passenger car**

Risk type **Injuries**

The seatbelt reel mechanisms may be defective. As a result, the passengers might not be held in position in the event of sudden braking, increasing the risk of injury.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Ford**

Name **Fiesta, Ecosport**

EC-type approval/model **e9*2007/46*3142*18, *19, e9*2007/46*0092*32, Types: JHH, JK8**

Production dates **The affected vehicles were manufactured between 5 February and 9 March 2021.**

Company recall code **21S13**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code - **<http://www.etis.ford.com>**

Products were found and measures were taken also in **Greece
Ireland
Poland**

**Sweden
Slovenia**



Alert number **[A12/00879/21](#)**

Product **Massage gun**



Risk type **Electric shock**

The power supply unit supplied with the massage gun poses a risk of electric shock because the insulation is not sufficient and the creepage distance between the primary and secondary circuits are not sufficient.

The product does not comply with the requirements of the Low Voltage Directive and relevant European standard EN 60335-1 and -2

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Massage gun supplied with power supply. Electrical specifications of the power supply: Input:100-240VAC; 50/60Hz; 1A Output: 25,2VDC, 1A**

Packaging description **Sold in a brown cardboard package.**

Brand **CORE**

Name **Massage gun**

Type / number of model **Massage gun: #53000 677172
Power supply unit: YH-25210**

Barcode **6420613987668**

Weekly report number **Report-2021-24**

Alert submitted by	Finland
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	05/03/2021
Company recall code	- https://ip-agency.fi/

Alert number **[A12/00883/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

The electronic stability program (ESP) software is not adapted to the vehicle structure. This may lead to increased risk of an accident in certain driving situations.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Mercedes-Benz**

Name **Sprinter**

EC-type approval/model **Types: 906BA50, 906BB50, KL3A4, KL3A5
e1*2007/46*0294*10, e1*2007/46*0296*10,
e1*2007/46*1760*00, e1*2007/46*1762*00**

Production dates **The affected vehicles were manufactured between 12 March and 29 August 2018.**

Company recall code **VS3HOLAPLI (3290355)**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**


Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number

A11/00046/21

Product

Lighting chain



Risk type

Electric shock

When replacing the bulb, the user may have to use more pressure or a tool, making live parts accessible, which can cause an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Category

Lighting chains

Type

Consumer

Description

Lighting chain with 35 replaceable, warm white miniature lamps.

Packaging description

Colourful cardboard box.

Brand

LEXlight


Name

35er Lichterkette Klassik

Type / number of model	LK401, Model: LK401-55231B
Barcode	2 005077 145003
Weekly report number	Report-2021-24
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	Unknown
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	23/02/2021

Alert number **[A11/00045/21](#)**

Product **Lighting chain**



Risk type **Electric shock**

Due to the tight fit between the lamp holders and the lamps, the product poses a risk of electric shock when replacing the light source.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Category **Lighting chains**

Type **Consumer**

Description **Lighting chain with 20 / 50 replaceable, colourful miniature lamps.**

Packaging description **Cardboard box.**

Brand **Kik Textilien und Non-Food GmbH.**

Name **LICHTERKETTE**

Type / number of model	1. Model: TX20L, 2. Model: TX50L
Barcode	11046819141001000299 11046539141001000199
Weekly report number	Report-2021-24
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	10/02/2021

Alert number **[A12/00873/21](#)**

Product **Sleep bag for babies**



Risk type **Entrapment
Injuries
Suffocation**

The top stop of the slide fastener at the arm opening is placed on the top instead of bottom of the product. Furthermore, the neck opening is too large in relation to the child height/age. This can increase the risk of the baby to slip inside the sleep bag and suffocate. In addition, as there are loops (a bow and a loop label) on the sleep bag, the baby could entrap a finger in the bow.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 16781:2018.

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Sleep bag for babies of white and pink colour with a zipper at the front and a pink bow. The sleep bag has removable sleeves attached by a zipper.**

Packaging description **/**

Brand **DISNEY**

Name **PUSSYCATS**

Type / number of model **DPTU01\102 85cm/110cm**

Barcode **3534440371767**

Weekly report number	Report-2021-24
Alert submitted by	Luxembourg
Is the product counterfeit?	No
Country of origin	France
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Retailer
Date of entry into force	07/06/2021
Measures ordered by public authorities	Temporary ban on the supply, offer to supply and display of the product Retailer
Date of entry into force	20/05/2021
Measures ordered by public authorities	Warning consumers of the risks Retailer
Date of entry into force	08/06/2021

Alert number **[A12/00858/21](#)**

Product **Balloons**



Risk type **Chemical**

The rubber of the balloons releases an excessive amount of nitrosamines (measured total value: 0.16 mg/kg) and nitrosatable substances (measured total value: 1.84 mg/kg), which generate nitrosamines among which n-nitrosodiethylamine (NDEA) and n-nitrosodimethylamine (NDMA). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-12.

Category **Toys**

Type **Consumer**

Description **Set of balloons in different colours.**

Packaging description **The set is sold in a transparent plastic bag.**

Brand **SHUAIAN BALLOONS**

Barcode **6 920170 828171**

Weekly report number **Report-2021-24**

Alert submitted by **Cyprus**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

20/01/2021

Alert number

[A12/00881/21](#)

Product

USB power supply unit



Risk type

**Burns
Electric shock
Fire**

The device is not resistant to high temperatures, its casing may deform leaving live parts accessible. The user may suffer burns or get electrocuted. The device may cause fire.

The product does not comply with the Low Voltage Directive and the relevant European standard EN 60950-1.

Category

Electrical appliances and equipment

Type

Consumer

Description

USB power supply unit with two ports.

Packaging description

Cardboard box.

Brand

Hoco

Name

Dual Port Charger Fast Charging

Type / number of model

C62A

Barcode

EAN 6957531094944

Weekly report number

Report-2021-24

Alert submitted by

Poland

Is the product counterfeit?

Unknown

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force

04/05/2021

Products were found and measures were taken also in

**Bulgaria
Lithuania**

Alert number

A12/00859/21

Product

Finger paint



Risk type

Chemical

The red and green finger paints release an excessive amount nitrosamines (measured values up to: 0.19 mg/ kg), among which n-nitrosodiethanolamine (NDELA). Nitrosamamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-12.

Category

Toys

Type

Consumer

Description

Set of 4 finger paints in plastic containers.

Packaging description

The set is sold in a cardboard with a transparent window.

Brand

MONT MARTE KIDS

Name	4 Brilliant Colours
Type / number of model	MMKC0003_V05
Batch number	80612
Barcode	9 328577 008443
Weekly report number	Report-2021-24
Alert submitted by	Cyprus
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	20/01/2021

Alert number **[A12/00896/21](#)**

Product **Infant Swing**



Risk type **Suffocation**

Infants who are placed unrestrained in the product and later found on their stomach are at risk of suffocation.

The product does not comply with the requirements of the General Product Safety Directive.

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Infant swing with two use modes: a powered glider seat and an infant rocker.**

Brand **Fisher Price**

Name **2-in-1 Soothe 'n Play Glider**

Weekly report number **Report-2021-24**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market
Importer**

Company recall code **- <https://www.fisher-price.com/en-us/product/2-in-1-soothe-n-play-glider-plus-ggw85>**

Products were found and
measures were taken also in

Greece
Croatia



Alert number

[A11/00044/21](#)

Product

Popcorn maker



Risk type

Burns

The product is attractive to children. A child may touch the accessible hot heating surface of the product and suffer burns.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335.

Category

Electrical appliances and equipment

Type

Consumer

Description

Red plastic covered popcorn machine in the shape of a retro popcorn maker trolley with a see-through window. The product was also sold online.

Packaging description

Colourful cardboard box.

Brand

mikamax

Name	POPCORN MACHINE
Type / number of model	PM-2800
Barcode	8 718182 071764
Weekly report number	Report-2021-24
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	17/12/2020

Alert number **[A12/00878/21](#)**

Product **Particle filter mask**



Risk type **Health risk / other**

The total filtration capacity of the mask is insufficient (measured mean values: as low as 72%). Consequently, the product does not fulfil the health and safety requirements; thus, even if combined with other recommended measures, it may not properly protect.

The product does not comply with the Personal Protective Equipment (PPE) Regulation and with the relevant European standard EN 149.

Category **Protective equipment**

Type **Consumer**

Description **Protective respiratory filtration half-face mask, was of uniform white material and without valve. The mask had light blue straps that fit around the head.**

Packaging description **The product is sold in white/blue cardboard boxes, containing a total of 20 masks. It mentions the batch, the European standard EN 149, and it is marked with "FFP2" and with CE 2797.**

Brand **CLEANAIR**

Name **Filtering half mask**

Type / number of model **10300**

Batch number **manufacturing date 2020-05
Batch 20130**

Barcode	(241)00001016(37)20
Weekly report number	Report-2021-24
Alert submitted by	Slovenia
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Withdrawal of the product from the market Distributor
Date of entry into force	10/05/2021

Alert number **[A12/00884/21](#)**

Product **Passenger car**

Risk type **Injuries**

The propellant used in the airbag inflator of the passenger airbags, manufactured by Takata, may experience a material alteration over time due to degradation occurring after prolonged exposure to high absolute humidity and high-temperature cycling. In the event of an airbag being deployed, the excessive internal pressure may cause the inflator body to rupture and metal fragments may pass through the cushion material causing injury to the occupants.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Audi**

Name **A4, A4 Cabrio, RS4, A6, RS6**

EC-type approval/model **Types: 8E, 8H, QB, 4F, 4F1
e1*2001/116*0151*, e1*2001/116*0177*,
e1*2001/116*0243*, e1*2001/116*0254*,
e1*2001/116*0276*, e13*2007/46*1080***

Production dates **The affected vehicles were manufactured between 12 May 2003 and 29 September 2011.**

Company recall code **69R7**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic **Recall of the product from end users**

operators

Manufacturer

Products were found and
measures were taken also in

Greece

Alert number

[A12/00898/21](#)

Product

Children's car seat



Risk type

Injuries

In the event of a car-crash, the car seat may not properly restrain the child to minimize the displacement of the body. As a consequence, the child could be injured. Furthermore, compulsory information about the installation of the child in the seat is uncomplete leading to a possible wrong installation and increasing the risk of injuries.

The product does not comply with Regulation UN/ECE No 44-04.

Category

Childcare articles and children's equipment

Type

Consumer

Description

Child restraint system.

Packaging description

Cardboard box.

Brand

Ding Baby

Name

MamaLoes Ding Twist 360° Autostoel 0-36kg

Type / number of model

**Twist 360°
YB104A**

Barcode

8719425388441

Weekly report number

Report-2021-24

Alert submitted by

Luxembourg

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

21/05/2021

Measures ordered by public authorities

**Recall of the product from end users
Retailer**

Date of entry into force

21/05/2021

Alert number **[A12/00894/21](#)**

Product **Passenger car**

Risk type **Injuries**

The 15A fuse to the low-pressure fuel pump may blow. As a result, the engine could stall and not be able start, increasing the risk of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of Motor Vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Type (Chassis): 224 (0000146 - 0056564), 225 (0002219 - 0372524), 227 (0000461 - 0041330), 234 (0063113 - 0083763), 235 (0097111 - 0134603), 236 (0078477 - 0110020), 238 (0102246 - 0167533), 246 (0279852 - 0541849), 256 (0463538 - 0585584).**

Packaging description **S60, V60, V60CC, S90, V90, V90CC, S90L, XC60 and XC90 vehicles equipped with engine 08 (B4204T20), 10 (B4204T23), 25 (B4204T26), A2 (B4204T27), A3 (B4204T29), AK (B4204T31), AL (B4204T44), AM (B4204T50), BA (B1APHEV), BF (B1CPHEV), BG (B1DPHEV), BM (B1EPHEV) and BR (B1FPHEV).**

Brand **Volvo**

Name **S60, V60, V60CC, S90, V90, V90CC, S90L, XC60 and XC90.**

EC-type approval/model **Type: 224, 225, 227, 234, 235, 236, 238, 246, 256.**

Production dates **The affected vehicles were manufactured in 2019 and 2020.**

Company recall code **R10100**

Weekly report number **Report-2021-24**

Alert submitted by **Portugal**

Is the product counterfeit?

No

Country of origin

Sweden

Measures taken by economic operators

**Recall of the product from end users
Distributor**

Products were found and measures were taken also in

**France
Greece
Croatia
Sweden
Slovakia**

Alert number **[A12/00887/21](#)**

Product **Passenger car**

Risk type **Injuries**

The lower axle tie rod may break. As a result, the vehicle handling may be impaired and there may be a potential loss of control, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Porsche**

Name **Panamera, Taycan**

EC-type approval/model **Types: Y1A, 971
e13*2007/46*0919*04, e13*2007/46*0971*15**

Production dates **The affected vehicles were manufactured between
29 January 2018 and 11 May 2021.**

Company recall code **AMB2**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Greece
Poland
Sweden**

Alert number **[A12/00886/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

The front-axle brake hose could be damaged by friction over its lifetime. This could lead to reduced braking function, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Mercedes-Benz**

Name **Sprinter**

EC-type approval/model **Types: KL3A4, FL3A4, KL3A5, FL3A5
e1*2007/46*1760*00, e1*2007/46*1761*00,
e1*2007/46*1762*00, e1*2007/46*1763*00**

Production dates **The affected vehicles were manufactured between
3 January 2018 and 21 February 2019.**

Company recall code **VS3BRELAU (4296094)**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Greece
Croatia
Ireland**

Alert number **[A12/00888/21](#)**

Product **Passenger car**

Risk type **Injuries**

The rear head rests might not have been attached correctly. As a result, they could become displaced or detached from the seat in the event of an accident, increasing the risk of injury.

Category **Motor vehicles**

Type **Consumer**

Description **C-class Cabriolet (BR 205) and E-Class Cabriolet (BR 238).**

Brand **Mercedes- Benz**

Name **C-Class, E-Class**

EC-type approval/model **Types: 204, 204AMG,R1EC
e1*2001/116*0431*62, e1*2001/116*0464*20, *22,
e1*2007/46*1666*20, *21**

Production dates **The affected vehicles were manufactured between
29 January and 22 March 2021.**

Company recall code **9190209**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**


Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code **- <http://www.mercedes-benz>**

Products were found and **France**

measures were taken also in

**Greece
Ireland
Poland**



Alert number **[A12/00897/21](#)**

Product **Massage gun**



Risk type **Electric shock**

The power charger supplied with the massage gun poses a risk of electric shock because the insulation is not sufficient and the creepage distance between the primary and secondary circuit is not sufficient.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335-1 and EN 60335-2.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Massage gun with a power charger. Power charger
Electrical specifications: input: 100-240VAC, 50/60Hz
output: 12VDC, 1A**

Packaging description **Sold in a brown cardboard box.**

Brand **HMS**

Name **Massage Gun**

Type / number of model **PDM3125, Power charger : HC-122002**

Barcode **5907695574234**

Weekly report number **Report-2021-24**

Alert submitted by **Finland**

Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	31/03/2021
Products were found and measures were taken also in	Poland

Alert number **[A12/00895/21](#)**

Product **Passenger car**

Risk type **Injuries**

An incorrect wiring harness configuration to the restraints control module (RCM) links the wrong seat belt buckle. As a result, the driver's seat belt pre-tensioner may not operate in the event of an accident, increasing the risk of injury.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Jaguar E-Pace, model year 2021.**

Brand **Jaguar**

Name **E-Pace**

EC-type approval/model **e5*2007/46*1050*02**

Production dates **Model year: 2021**

Company recall code **H344**

Weekly report number **Report-2021-24**

Alert submitted by **Poland**


Is the product counterfeit? **Unknown**

Country of origin **United Kingdom**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and **France**

measures were taken also in



Alert number **[A12/00893/21](#)**

Product **Passenger car**

Risk type **Injuries**

The NADI (non-azide driver inflator) type airbag may have improper sealing that could allow moisture to enter into the propellant. If the propellant afterwards dries out, it could lead to decreased density resulting in a too high burn rate. Consequently the airbag may not deploy as designed and provide less protection, increasing the risk of injury.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Mitsubishi models: Lancer Station Wagon (CB0W, CD0W), Lancer (CJ0A), Colt (CK0A), Pajero Pinin (H66W), Space Runner (N60W, N73W), L400 / Space Gear (PA0V, PA0W, PB0V, PC0W, PD0V, PD0W), Pajero (V20C, V20W, V40W, V55W)**

Brand **Mitsubishi**

Name **Lancer Station Wagon, Lancer, Colt, Pajero Pinin, Space Runner, L400 / Space Gear, Pajero**

Production dates **Lancer: Model Year 1996-2000
Colt: Model Year 1996-2000
Pajero Pinin: Model Year 1998
Space Runner: Model Year 1999-2000
L400 / Space Gear: Model Year 1998-1999
Pajero: Model Year 1998-2000
Lancer Station Wagon: Model Year 1997-2000**

Company recall code **ENL-21-013-SR**

Weekly report number **Report-2021-24**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Japan**


Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **02/06/2021**

Products were found and measures were taken also in **Greece
Sweden**

Alert number **[A12/00891/21](#)**

Product **Children's trousers**



Risk type **Injuries**

The product bears long cords with free ends in the waist area. The cords may become trapped during various activities of a child, leading to injuries.

The product does not comply with the requirements of the General Product Safety Directive and with the relevant European standard EN 14682.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Children's trousers in black, with pockets on the sides, on the front of the left leg - a sticker on the girl's image and the inscription "Love yourself". Trouser's waist is made of elastic weave knitted fabric with rubber and metallic thread twine with free ends.**

Brand **Narmini Kids**

Name **Children's trousers, size 1/86**

Type / number of model **Size 1/86**

Barcode **0000000034227**

Weekly report number **Report-2021-24**

Alert submitted by **Lithuania**

Is the product counterfeit?

No

Country of origin

Turkey

Measures ordered by public authorities

**Withdrawal of the product from the market
Distributor**

Alert number **[A12/00889/21](#)**

Product **Children's trousers**



Risk type **Injuries**

The product bears long cords in the waist area. The cords may become trapped during various activities of a child, leading to injuries.

The product does not comply with the requirements of the General Product Safety Directive and with the relevant European standard EN 14682.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Children's black pants, has pockets with zippers, the inscription "Pursuit" on the front next to the left pocket, a drawstring inside the waist of the trousers.**

Brand **Unknown**

Name **Children's sports trousers, size 128**

Type / number of model **GF-6039**

Weekly report number **Report-2021-24**

Alert submitted by **Lithuania**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public
authorities

Withdrawal of the product from the market
Distributor



Alert number **[A12/00892/21](#)**

Product **Glue**



Risk type **Chemical**

The glue contains an excessive amount of toluene (measured values: 73% by weight). Toluene is neurotoxic, if inhaled or in contact with the skin, and might also affect the unborn child.

The product does not comply with the REACH Regulation.

Category **Chemical products**

Type **Consumer**

Description **Glue tube colored (red, green, black, white) 40 ml, marked with manufacturer's information in Russian.**

Packaging description **The packaging is marked with information in the state language.**

Brand **Anles**

Name **Universal glue 88 M 40 ml**

Barcode **4601567000593**

Weekly report number **Report-2021-24**

Alert submitted by **Lithuania**

Is the product counterfeit? **No**

Country of origin **Russian Federation**

Measures ordered by public authorities **Withdrawal of the product from the market
Importer**

Date of entry into force **10/06/2021**

Alert number **[A12/00890/21](#)**

Product **Passenger car**

Risk type **Injuries**

The bolts on the rear stabiliser bracket could come loose over time. The loose bracket could then interact with other components, causing damage and increasing the risk of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Subaru Impreza and XV, model year 2017 - 2019.**

Brand **Subaru**

Name **Impreza, XV**

EC-type approval/model **E13*2007/46*1648*03; E1*2007/46*0597*08; E13*2007/46*1648*04; E13*2007/46*1648*05; E13*2007/46*1648*06**

Production dates **Model Year 2017 - 2019**

Company recall code **SRT307**

Weekly report number **Report-2021-24**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and
measures were taken also in

Slovakia



Alert number **[A12/00876/21](#)**

Product **Foldable sunbed**



Risk type **Entrapment
Injuries**

Due to the sunbed folding mechanism, the user's fingers can get trapped between the seat and the folding mechanism. This can also lead to injuries and even amputation of one or more fingers.

The product does not comply with the requirements of the General Product Safety Directive and relevant European standard EN 581-1

Category **Furniture**

Type **Consumer**

Description **Red or black sunbed. The product was also sold online.**

Brand **Kayoba**

Name **Solsång**

Type / number of model **000858
000859**

Weekly report number **Report-2021-24**

Alert submitted by **Sweden**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public
authorities

**Recall of the product from end users
Manufacturer**

Date of entry into force

15/03/2021

Company recall code

- <https://www.jula.se/kundservice/aterkallade-produkter/>

Alert number **[A12/00874/21](#)**

Product **Doll stroller**



Risk type **Injuries**

The pushchair is not sufficiently resistant to load. As a consequence, it can easily collapse and a child playing with it may fall to the ground.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Doll stroller.**

Packaging description **Cardboard box.**

Brand **One Six Eight**

Name **Baby stroller**

Type / number of model **CS8817-5**

Barcode **6988173333337**

Weekly report number **Report-2021-24**

Alert submitted by **Cyprus**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

01/02/2021

Alert number **[A12/00877/21](#)**

Product **Pushchair**



Risk type **Injuries**

The pushchair is not stable and can tip unexpectedly. This can cause the child sitting in it to fall out and to suffer injuries.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 1888-1

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Grey and black pushchair, including carrycot. Three wheels. The product was also sold online.**

Packaging description **Cardboard box**

Brand **North 13.5**

Name **13.5 Maxi Jogger and carrycot, North Maxi Jogger 2 and carrycot**

Type / number of model
**869814
 649561
 649562
 649568
 649569
 708776
 708777
 869812
 869813
 869815
 869820
 869821**

Batch number	All batches
Weekly report number	Report-2021-24
Alert submitted by	Sweden
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Recall of the product from end users Manufacturer
Date of entry into force	23/09/2020
Company recall code	- https://www.jollyroom.dk/kundeservice/tilbagekaldelser/north-13-5-maxi-jogger - https://www.jollyroom.se/kundeservice/aterkallelser/north-13-5-maxi-jogger-north-13-5-maxi-jogger-2
Products were found and measures were taken also in	Austria

Alert number **[INFO/00126/21](#)**

Product **Passenger car**

Risk type **Injuries**

The eCall function may not be available due to deactivated communication module. As a result, in the event of an accident it would not be possible to establish a voice connection with the emergency call centre, either automatically or by activating the SOS button, nor would it be possible to transmit vehicle data. In this case, it would not be possible to direct emergency services to the vehicle, which could increase the impact of the accident.

Category **Motor vehicles**

Type **Consumer**

Description **CLA (BR 117), CLA (BR 118), GLA (BR 156), M-Class/GLE/GL/GLS (BR 166), GLE/GLS (BR 167), SLK/SLC (BR 172), A-Class (BR 176), A-Class (BR 177), AMG GT (BR 190), C-Class (BR 205), E-Class coupé/cabrio (BR 207), E-Class (BR 213), S-Class (BR 222), E-Class coupé/cabrio (BR 238)**

Packaging description **B-Class (BR 246), B-Class/GLA/GLB (BR 247), GLC (BR 253), CLS (BR 257), AMG GT 4-door coupé (BR 290), GLE coupé (BR 292), EQC (BR 293) and G-Class (BR 463)**

Brand **Mercedes-Benz**

Name **Various models**

EC-type approval/model **Types: 204 K, 204 AMG, 207, 212, R1ES, 221, R1EC, 245 G, F2B, 204 X, R1ECLS, R1EAMG, 166, 204 X, 463, 463A e1*2001/116*0431*37-61, e1*2001/116*0457*30-51, e1*2001/116*0464*17-22, e1*2001/116*0502*21, e1*2001/116*0501*24-48, e1*2007/46*1560*00-21, e1*2001/116*0335*30-46, e1*2007/46*1666*00-16, e1*2001/116*0470*15-23, e1*2007/46*1912*00-09, e1*2001/116*0470*15-25, e1*2007/46*0598*18-26, e1*2007/46*1885*00-12, e1*2007/46*0548*09-20, e1*2007/46*1829*00-13, e1*2007/46*0233*11-19, e1*2007/46*1909*00-09, e1*2001/116*0480*20-40, e1*2007/46*1818*00-11, e1*2007/46*1878*00-10, e1*2001/116*0480*31-40, e1*96/79*0064*36-38, e1*2007/46*1830*00-07**

Production dates	The affected vehicles were manufactured between 5 November 2015 and 30 October 2020.
Company recall code	5499617
Weekly report number	Report-2021-24
Alert submitted by	Germany
Is the product counterfeit?	No
Country of origin	Germany
Measures taken by economic operators	Recall of the product from end users Manufacturer
Company recall code	- https://www.mercedes-benz.de
Products were found and measures were taken also in	Ireland Poland

Alert number **[A12/00854/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

The high-voltage battery module may be attached incorrectly. As a result, it could become detached from the vehicle and fall onto the road, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Mercedes-Benz**

Name **eSprinter**

EC-type approval/model **e1*2007/46*1760*02 - *04, Type: KL3A4**

Production dates **The affected vehicles were manufactured between 20 November 2019 and 8 September 2020.**

Company recall code **V3ESCRABAT (4794051)**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/00856/21](#)**

Product **Passenger car**

Risk type **Injuries**

The screw connections in the undercarriage may be inadequate. This could lead to unstable driving conditions, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Porsche**

Name **911 Carrera, GT, GT3**

EC-type approval/model **e13*2007/46*0992*11, e13*KS07/46*1613*03, e13*KS07/46*0991*02, Types: 992, 991R, 991H**

Production dates **The affected vehicles were manufactured between 20 August 2019 and 27 January 2020.**

Company recall code **AMA6**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **France
Sweden**

Alert number **[INFO/00125/21](#)**

Product **Passenger car**

Risk type **Injuries**

Due to a defect in the emergency call system, a temporary fall in the on-board voltage levels resulting from an accident could cause the location of the vehicle communicated when an emergency call is made to not correspond to the actual location of the vehicle. This could delay the arrival of emergency vehicles, potentially increasing the effects of the accident.

Category **Motor vehicles**

Type **Consumer**

Description **Models: CLA-Class, GLA-Class, M-/GLE-/GL-/GLS-Class, GLE-/GLS-Class, SLK-/SLC-Class, A-Class, AMG GT, C-Class, E-Class Coupe/Convertible, E-Class, S-Class Coupe/Convertible, CLS-Class, S-Class, SL-Class, B-/GLA-/GLB-Class, GLC-Class, AMG GT 4-doors Coupe, GLE-Class Coupe, EQC-Class, G-Class**

Brand **Mercedes-Benz**

Name **Various models**

EC-type approval/model **e1*2001/116*0248*11-14, e1*2007/46*1666*00-20, e1*2001/116*0470*15-18, e1*2007/46*1909*00-23, e1*2001/116*0480*18-41, e1*2007/46*1884*00, e1*2007/46*1818*00-13, e1*2001/116*0470*15-25, e1*2007/46*1207*04-09, e1*2007/46*1912*00-09, e1*2007/46*0598*18-26, e1*2007/46*0826*08-13, e1*2007/46*1885*00-12, e1*2007/46*0548*10-20, e1*2001/116*0470*15, e1*2001/116*0502*21, e1*2001/116*0501*24-50, e1*2007/46*1560*00-23, e1*2001/116*0335*31 -46, e1*2001/116*0396*18 -20, e1*2007/46*0485*15-16, e1*2007/46*0643*06 -07, e1*98/14*0169*24-34, e1*2007/46*1207*04-08, e1*2007/46*1829*00-13, e1*2007/46*0233*08-20, e1*2001/116*0431*38-42, e1*2001/116*0464*18-22, e1*2001/116*0457*31-52, e1*2001/116*0463*17-20 , e1*2001/116*0431*38-62, e1*2007/46*1878*00-11, e1*96/79*0064*36 -38, e1*2007/46*1830*00 -09
221 AMG, 218, 218 AMG, 230, 230 AMG, R1EC, F2B, 204 X, 204 X AMG, R1ECLS, R1EAMG, 463, 463A**

Types: 245 G, 245 G AMG, F2CLA, 166, 166 AMG, H1GLE, 172, F2A, 197, 204, 204 AMG, 204 K, 204 K AMG, 212, R1ES, 221,

Production dates	The affected vehicles were manufactured between 4 January 2016 and 31 January 2021.
Company recall code	5497401, 5497403, 5497411, 5497418, 5497405, 5497407, 5497409, 5497413, 5497414, 5497416, 5497420, 5497422
Weekly report number	Report-2021-24
Alert submitted by	Germany
Is the product counterfeit?	No
Country of origin	Germany
Measures taken by economic operators	Recall of the product from end users Manufacturer
Company recall code	- https://www.mercedes-benz.de
Products were found and measures were taken also in	France Greece Poland

Alert number **[A12/00853/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

Due to an error in the assembly process, there might be a single, loose screw in the steering support. The loose screw could cause a sudden, temporary blocking of the steering while the vehicle is in motion, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car/lorry/light commercial vehicle**

Brand **Ford**

Name **Transit, Transit Custom**

EC-type approval/model **TR*2007/46*8161*18, TR*2007/46*7472*29, e1*2007/46*1096*16, e1*2007/46*1096*17, e1*2007/46*1096*19, e1*2007/46*1098*14, e1*2007/46*1098*15, e1*2007/46*1098*17, e1*2007/46*1100*15, Types: FED6, FCD6, FED, FDD, FCD, FAD, FCC, FAC e1*2007/46*1100*14, e1*2007/46*1100*16, e1*2007/46*1100*19, e5*2007/46*1032*03, e5*2007/46*1032*06, e1*2007/46*1005*20, e1*2007/46*1005*15, e1*2007/46*1005*16, e1*2007/46*1005*18, e5*2007/46*1034*06, e5*2007/46*1034*02, e5*2007/46*1034*08**

Production dates **The affected vehicles were manufactured between 30 June 2019 and 26 April 2021.**

Company recall code **21S27**


Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit?	No
Country of origin	Turkey
Measures taken by economic operators	Recall of the product from end users Manufacturer
Company recall code	- https://www.etis.ford.com
Products were found and measures were taken also in	Ireland Sweden

Alert number **[A12/00900/21](#)**

Product **Jacket with hood**



Risk type **Strangulation**

There are long functional cords with free ends in the hood of the sweatshirt. They can become trapped during various activities of a child, leading to strangulation.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 14682.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Waterproof jacket with animals printed, a hood and a zipper and pockets on the front. The hood has functional elastic cords with size adjusters. Fiber composition (100% polyester). The product was also sold online.**

Brand **Bembi**

Name **Jacket Super Hero**

Type / number of model **BE_KT212-R01**

Batch number **art. 33212013335**

Barcode **4823109601635**

Weekly report number **Report-2021-24**

Alert submitted by **Lithuania**

Is the product counterfeit?

No

Country of origin

Ukraine

Measures ordered by public
authorities

**Withdrawal of the product from the market
Distributor**

Date of entry into force

31/05/2021

Alert number **[A12/00855/21](#)**

Product **Passenger car**

Risk type **Injuries**

The rear-right head airbag was manufactured from defective material. As a result, it may provide no protection in a side-on collision, increasing the risk of injury to vehicle occupants.

Category **Motor vehicles**

Type **Consumer**

Description **Model: T6.1 vehicles equipped with side and curtain airbags for the driver and front passenger as well as curtain airbags in the passenger compartment.**

Brand **VW**

Name **T6**

EC-type approval/model **e1*2001/116*0289; Type: 7HMA**

Production dates **The affected vehicles were manufactured on 19 January 2021.**

Company recall code **69CB**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**


Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/00901/21](#)**

Product **Raincoat with hood**



Risk type **Strangulation**

There are long functional cords with free ends in the hood of the raincoat. They can become trapped during various activities of a child, leading to strangulation.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 14682.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Colourful raincoat with pockets on the front, a zipper and a hood. The hood has functional elastic cords with size adjusters. The product was also sold online.**

Brand **Bembi**

Name **Raincoat**

Type / number of model **BE_KT180-Z01L**

Batch number **art. 33180023339**

Barcode **4823101640472**

Weekly report number **Report-2021-24**

Alert submitted by **Lithuania**

Is the product counterfeit?

No

Country of origin

Ukraine

Measures ordered by public
authorities

**Withdrawal of the product from the market
Distributor**

Date of entry into force

31/05/2021

Alert number **[INFO/00128/21](#)**

Product **Passenger car**

Risk type **Injuries**

The automatic and manual emergency call service may not function as intended outside the network coverage of certain network providers due to a software error. As a result, the eCall may not be used as intended to place an emergency call to direct emergency services to the vehicle. Depending on network availability, voice communication would still be possible by calling 112 as a fallback option.

Category **Motor vehicles**

Type **Consumer**

Description **LA, GLA, M-Klasse/GLE/GL/GLS, SLK/SLC, A-Klasse, AMG GT, C-Klasse, E-Klasse Coupé/Cabrio, E-Klasse, S-Klasse Coupé/Cabrio, CLS, S-Klasse, SL, B-Klasse/GLA/GLB, GLC, AMG GT 4-Türer Coupé, GLE Coupé, G-Klasse**

Brand **Mercedes-Benz**

Name **Various models**

EC-type approval/model **Types: 245 G, F2CLA, 245 G, 166, H1GLE, 172, F2A, 197, F2B, 204 X, R1ECLS, R1EAMG, 463, 463A, R1EC, 197BS, 204, 204 K, 204 K AMG, 212, R1ES, 221, 230 e1*2001/116*0431*39-60, e1*2001/116*0457*32-50, e1*2001/116*0463*18-20, e1*2001/116*0501*28-47, e1*2007/46*1560*01-18, e1*2001/116*0335*32-46, e1*98/14*0169*25-34 e1*2001/116*0470*16-23, e1*2007/46*1912*00-08, e1*2001/116*0470*16-25, e1*2007/46*0598*18-26, e1*2007/46*1885*00-10, e1*2007/46*0548*11-20, e1*2007/46*1829*00-12, e1*2007/46*0233*09-19, e1*2007/46*1909*00-09, e1*2001/116*0480*21-38, e1*2007/46*1818*00-10, e1*2007/46*1878*00-10, e1*96/79*0064*36-26, e1*2007/46*1830*00-07, e1*2007/46*1666*00-16, e1*KS07/46*0076*01,**

Production dates **30.8.2016 to 24.7.2020**

Company recall code **5499616**

Weekly report number	Report-2021-24
Alert submitted by	Germany
Is the product counterfeit?	No
Country of origin	Germany
Measures taken by economic operators	Recall of the product from end users Manufacturer
Company recall code	- http://www.mercedes-benz
Products were found and measures were taken also in	France Poland

Alert number **[A12/00870/21](#)**

Product **Pickup truck**

Risk type **Injuries**

A defective brake clip may cause the service brake to fail. This could increase the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Pickup truck**

Brand **Dodge**

Name **RAM**

EC-type approval/model **Individual approval, Type: DS**

Production dates **The affected vehicles were manufactured between 26 October 2020 and 7 April 2021.**

Company recall code **Y14**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[INFO/00127/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

Under certain conditions there may be a gear recognition malfunction, causing the reversing light to stop working.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Mercedes-Benz**

Name **Vito**

EC-type approval/model **Types: 639/2, 639/4
e1*2007/46*0457*22 - *25, e1*2007/46*0458*17 - *21**

Production dates **The affected vehicles were manufactured between 10 October 2019 and 26 March 2021.**

Company recall code **VS2SENGOR (2698060)**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Spain**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/00857/21](#)**

Product **Passenger car**

Risk type **Injuries**

A bore hole in the universal joint on the steering shaft may have incorrect size. As a result, there could be play between the bearing fitted into the bore hole and the universal joint, which could cause the joint to become detached over time. This would impair the vehicle's steerability, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Model series: CLA (BR 117), GLA (BR 156), A-Class (BR 176) and B-Class (BR 242, 246).**

Brand **Mercedes-Benz**

Name **A-Class, B-Class, CLA, GLA**

EC-type approval/model **Types: 245 G, 245 G AMG
e1*2001/116*0470*16-18, e1*2007/46*1207*05-06**

Production dates **The affected vehicles were manufactured between 30 November 2016 and 14 July 2017.**

Company recall code **4692030**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code - **<https://www.mercedes-benz.de>**

Products were found and
measures were taken also in

Greece
Ireland
Poland
Sweden
Slovenia
Slovakia



Alert number **[INFO/00129/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

Increased wear on a sealing ring in the electric parking brake delivery spindle may lead to leakage of the braking system on the brake saddle of the rear axle.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Mercedes-Benz**

Name **Sprinter**

EC-type approval/model **e1*2001/116*0354*21 - *27, e1*2001/116*0424*15 - *17, e1*2007/46*0294*10 - *15, e1*2007/46*0296*10 - *15, e1*2007/46*0300*15 - *20, e1*2007/46*0301*17 - *22, e1*2007/46*0304*06 - *09, e1*2007/46*0305*11 - *14, e1*2007/46*0308*06 - *09, e1*2007/46*0312*12 - *15, e1*2007/46*1760*00 - *04, e1*2007/46*1761*00 - *04, e1*2007/46*1762*00 - *01, e1*2007/46*1763*00 - *04**

Production dates **The affected vehicles were manufactured between 12 May 2017 and 8 March 2021.**

Company recall code **VS3BREPB (4296093)**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic **Recall of the product from end users**

operators

Manufacturer

Products were found and
measures were taken also in

**Greece
Ireland**

Alert number **[A12/00864/21](#)**

Product **Babies' rattle**



Risk type **Choking**

Small parts (the balls) can easily detach from the rattle. A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Babies' rattle.**

Packaging description **Packed into a carton, window blisted.**

Brand **Jumbo Baby**

Name **Rattle**

Type / number of model **FS35710-8**

Batch number **GR0012006004**

Barcode **0457352000033**

Weekly report number **Report-2021-24**

Alert submitted by **Cyprus**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Retailer**

Date of entry into force **01/02/2021**

Alert number **[A12/00866/21](#)**

Product **Passenger car**

Risk type **Injuries**

The plate of the brake pedal may become detached when under load. This could restrict the application of the brake, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Opel**

Name **Insignia**

EC-type approval/model **Types: Z-B
e8*2007/46*0264*16, e8*2007/46*0264*18**

Production dates **The affected vehicles were manufactured between 5 February and 7 April 2021.**

Company recall code **E212103161 (21-C-077)**

Weekly report number **Report-2021-24**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Croatia
Poland
Sweden
Slovakia**

Alert number **[A12/00882/21](#)**

Product **Baby's soother**



Risk type **Chemical**

The product contains Bisphenol A (BPA) (measured value: 2.3 mg/kg). BPA may damage fertility and has been identified as a substance affecting the hormonal systems of humans and animals.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 1400.

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Black and white baby's soother with a picture of a rainbow over a cloud and the word 'Daddy' written on it. The product is sold online, in particular via Wish.**

Brand **Ten@Night**

Name **Ddig Baby Girl Abdl personnalisé grande taille en silicone adulte Pacifier taille plus adulte Pacifi**

Weekly report number **Report-2021-24**

Alert submitted by **France**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators

Removal of this product listing by the online marketplace
Other