

Cartelli della raccolta 'EN ISO 7010'



F001  
Fire extinguisher



F002  
Fire hose reel



F003  
Fire ladder



F004  
Collection of  
firefighting equipment



F005  
Fire alarm call point



F006  
Fire emergency  
telephone



M002  
Refer to instruction  
manual-booklet



M003  
Wear ear protection



M004  
Wear eye protection



M005  
Connect an earth  
terminal to the ground



M006  
Disconnect mains plug  
from electrical outlet



M007  
Opaque eye  
protection must be



M008  
Wear safety footwear



M009  
Wear protective  
gloves



M010  
Wear protective  
clothing



M011  
Wash your hands



M012  
use handrail



M013  
Wear a face shield



M014  
Wear head protection



M015  
Wera high-visibility  
clothing



M016  
Wear a mask



M017  
Wear spiratory  
protection



M018  
Wear a safety harness



M019  
Wear a welding mask



M020  
Wear safety belts



M021  
Disconnect before  
carryng out



M022  
Use barrier cream



M023  
Use footbridge



M024  
Use this walkway



M025  
Protect infant's eyes  
with opaque eye

Cartelli della raccolta 'EN ISO 7010'



M026  
Use protective apron



P001  
General prohibition sign



P002  
No smoking



P003  
No open flame; Fire,  
open ignition source



P004  
No thoroughfare



P005  
Not drinking water



P006  
No access for forklift  
trucks and other



P007  
No access for people  
with active implanted



P008  
No metallic articles or  
watches



P010  
Do not touch



P011  
Do not extinguish with  
water



P012  
No heavy load



P013  
No activated mobile  
phones



P014  
No access for people  
with metallic implants



P015  
No reaching in



P017  
No pushing



P018 - No sitting



P019 - No stepping on  
surface



P020  
Do not use lift in the  
event of fire



P021 - No dogs



P022  
P022 - No eating or  
drinking



P023  
Do not obstruct



P024  
Do not walk or stand  
here



P025  
Do not use this  
incomplete scaffold



P026  
Do not use this device  
in a bathtub, shower



P027  
Do not use this lift for  
people



P028  
Do not wear gloves



P029  
No photography



P030  
Do not tie knots in  
rope



P031  
Do not alter the state  
of the switch

Cartelli della raccolta 'EN ISO 7010'



P032  
Do not use for face grinding



P033  
Do not use for wet grinding



P034  
Do not use with hand-held grinding



W001  
General warning sign



W002  
Warning; explosive material



W003  
Warning; Radioactive material or ionizing



W004  
Warning; laser beam



W005  
Warning; Non-ionizing radiation



W006  
Warning; Magnetic field



W007  
Warning; Floor-level obstacle



W008  
Warning; Drop (fall)



W009  
Warning; Biological hazard



W010  
Warning; Low temperature-freezing



W011  
Warning; Slipper surface



W012  
Warning; Electricity



W013  
Warning; Guard dog



W014  
Warning; Forklift trucks and other



W015  
Warning; Toxic material



W016  
Warning; Toxic material



W017  
Warning; Hot surface



W018  
Warning; Automatic Start-up



W019  
Warning; Crushing



W020  
Warning; Overhead obstacle



W021  
Warning; Flammable material



W022  
Warning; Sharp element



W023  
Warning; Corrosive substance



W024  
Warning; Crushing of hands



W025  
Warning; Counterrotating rollers



W026  
Warning; Battery charging



W027  
Warning; Optical radiation



W028  
Warning; Oxidizing  
substance



W029  
Warning; Pressurized  
cylinder