

# The Rapid Alert System for Non-Food Products (RAPEX)

## *RAPEX - Weekly overview report of notifications*

week 27 - 2016

Notification A12/0333/16 from Report-2016-011 has been updated to clarify the production codes affected by the recall.

**Alert number:** A12/0816/16

**Product:** Ethanol for flueless stoves/fireplaces

**Name:** ETHANOL

**Risk:** Chemical, Fire

**Category:** Chemical products

**Brand:** DOMESTIX

**Type/number of model:** Unknown

**Risk level:** Serious risk

The liquid can leak when the bottle tips over due to a problem with the bottle-cap fastening, leading to a risk of eye damage as the product is classified as eye irritant and a risk of fire as it is a flammable substance. The product does not comply with the Regulation on the classification, labelling and packaging of substances and mixtures (CLP).

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Distributor)

**Description:** Organic ethanol in a transparent, plastic, 2-litre bottle with a red plastic cap. On the rear side of the label appears the batch number, instructions for use, safety advice, hazard pictograms and the company name.

**Batch number/Barcode:** Batches 160108, 155115 and P043

**Country of origin:** Belgium

**Alert submitted by:** France



**Alert number:** A12/0832/16

**Product:** Body wash

**Name:** BodyWash

**Risk:** Microbiological

**Category:** Cosmetics

**Brand:** DiaClin

**Type/number of model:** Expiry Date 08-2017 30 ml

**Risk level:** Serious risk

The product is contaminated with a high charge of mesophilic aerobic bacteria, especially enterobacteriaceae (total measured value: 13500 cfu/g), posing a risk of infection, particularly to damaged skin. The product does not comply with the Cosmetic Products Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Manufacturer)

**Description:** Body wash ("Diabetic Skin care") supplied in a white container with pump (30 ml).

**Batch number/Barcode:** 8714207351538, Batch Code 14H271

**Country of origin:** The Netherlands

**Alert submitted by:** The Netherlands



**Alert number:** A12/0822/16

**Product:** Videophone

**Name:** Lena

**Risk:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Extel

**Type/number of model:** Model : MN LENA 11 3. Reference : 812211 and 822211. Type JS-S436EO

**Risk level:** Serious risk

The clearance and creepage distances between the primary and secondary circuits of the transformer are insufficient. This could lead to accessible parts being at mains voltage. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950.

**Measures taken by economic operators:** Withdrawal of the product from the market (By:

Importer)

**Description:** Videophone

**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0823/16

**Product:** Extension lead

**Name:** Unknown

**Risk:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Qiaosheng

**Type/number of model:** Unknown

**Risk level:** Serious risk

The holes in the sockets are not protected by shutters. The user can consequently access live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant national standard.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** A 20m extension lead with orange socket in the form of an apple having one 3-pin socket and three 2-pin sockets on the sides.

**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Malta



**Alert number:** A12/0824/16

**Product:** Extension lead

**Name:** NB BANUO

**Risk:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Qiaosheng

**Type/number of model:** model 088

**Risk level:** Serious risk

The holes in the sockets are not protected by shutters. The user can consequently access live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant national standard.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Extension lead with multiple socket outlets.

**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Malta



**Alert number:** A12/0825/16

**Product:** Extension lead

**Name:** Explosion Proof Socket

**Risk:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Qiaosheng

**Type/number of model:** model: 161

**Risk level:** Serious risk

The holes in the sockets are not protected by shutters. The user can consequently access live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant national standard.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Extension lead with multiple socket outlets.

**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Malta



**Alert number:** A12/0826/16

**Product:** Extension lead

**Name:** Unknown

**Risk:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Qiaosheng

**Type/number of model:** QS-5336

**Risk level:** Serious risk

The holes in the sockets are not protected by shutters. The user can consequently access live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant national standard.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Extension lead with multiple socket outlets.

**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Malta



**Alert number:** A12/0827/16

**Product:** Extension lead

**Name:** Unknown

**Risk:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Qiaosheng

**Type/number of model:** QS-5338

**Risk level:** Serious risk

The holes in the sockets are not protected by shutters. The user can consequently access live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant national standard.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Extension lead with multiple socket outlets.

**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Malta



**Alert number:** A12/0829/16

**Product:** Travel plug adapter

**Name:** TV Computer Telephony Phone Connector

**Risk:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Run and Teng

**Type/number of model:** Unknown

**Risk level:** Serious risk

The holes in the sockets are not protected by shutters. The user can consequently access live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant national standard.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Two-pin Europlug adapter with socket for US style plugs

**Batch number/Barcode:** 9 200000 000395

**Country of origin:** China

**Alert submitted by:** Malta



**Alert number:** A12/0837/16

**Product:** Aquarium light

**Name:** LED Aquarium Light

**Risk:** Electric shock, Fire

**Category:** Electrical appliances and equipment

**Brand:** LEDGLE

**Type/number of model:** SKU X0000IRPXXR

**Risk level:** Serious risk

The product is inadequately earthed and has no protection against the ingress of water. The cross sectional area of the supply cord and the dimensions of the plug are not correct. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598 and the relevant national standard.

**Measures taken by economic operators:** Destruction of the product (By: Distributor)

**Description:** LED dimmable aquarium luminaire. Packaged in plain cardboard box.

**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** United Kingdom



**Alert number:** A12/0819/16

**Product:** Garden chairs

**Name:** SILLA PLEGABLE ('Folding chair')

**Risk:** Cuts, Injuries

**Category:** Furniture

**Brand:** Marco's Toys

**Type/number of model:** Item references: 1.)1710, 2.)1711, 3.) 1712

**Risk level:** Serious risk

The chairs can easily tip forwards and sideways when a load is placed on the armrest, leading to injuries if a person falls from the chair. The armrest can also break at the tube joint, leaving sharp edges exposed. The products do not comply with the relevant European standard EN 581.

**Measures ordered by public authorities:** Import rejected at border

**Description:** Folding outdoor chairs in different designs with metallic frames. A cardboard label is attached to the products.

**Batch number/Barcode:** 1.) 8435399017100, 2.) 8435399017117 3.) 8435399017124

**Country of origin:** China

**Alert submitted by:** Spain





**Alert number:** A12/0831/16

**Product:** Bicycle forks

**Name:** Full Carbon Racelight T (RT) / Racelight T Full Carbon / 12K Racelight T / 12K

**Risk:** Injuries

**Category:** Hobby/sports equipment

**Brand:** Kinesis UK

**Type/number of model:** F-10E and F-58

**Risk level:** Serious risk

The aluminium crown of the forks can separate from the steerer tube or from the fork legs. This may cause the rider to fall. 3 accidents reported.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Carbon fibre bicycle forks. Recall notice will be displayed on the following website: <http://shop.upgradebikes.co.uk/Catalogue/Technical/Kinesis/RACELIGHT-T-CARBON-FORK-2003-2009-RECALL-NOTICE>

**Batch number/Barcode:** Model years affected: Full Carbon Racelight T (RT): 2003/2005  
Racelight T Full Carbon: 2006 12K Racelight T: 2007/2009 12K: 2009

**Country of origin:** Taiwan

**Alert submitted by:** United Kingdom



**Alert number:** A12/0830/16

**Product:** Novelty lighter

**Name:** Unknown

**Risk:** Fire

**Category:** Lighters

**Brand:** Zhongliang Lighters

**Type/number of model:** 201430422251.X 201430422252.4

**Risk level:** Serious risk

The lighter is appealing to children who may play with it and cause a fire. The product does not comply with the Commission Decision 2006/502 EC prohibiting the placing on the market of novelty lighters and with the relevant European standard EN 13869.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Novelty lighter in the form of a shoe.

**Batch number/Barcode:** Unknown

**Country of origin:** Unknown

**Alert submitted by:** Malta



**Alert number:** A12/0828/16

**Product:** Light

**Name:** Yoso

**Risk:** Electric shock

**Category:** Lighting equipment

**Brand:** Luigi Ferro

**Type/number of model:** Black: BRI-A104/HK11155A06, Grey: BRI-A106/HK11155A11, White: BRI-A105/HK11155A05

**Risk level:** Serious risk

The insulation of the flexible cable is likely to be damaged when the lamp is moved. The user could consequently receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

**Measures taken by economic operators:** Recall of the product from end users, Withdrawal of the product from the market (By: Importer)

**Description:** Floor standing halogen lamp supplied in a cardboard box.

**Batch number/Barcode:** 31/15 - year 2015

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0817/16

**Product:** Passenger car

**Name:** 207

**Risk:** Fire

**Category:** Motor vehicles

**Brand:** Peugeot

**Type/number of model:** Type-approval numbers: e2\*2001/116\*0340\*; Type: W\*\*\*\*\*

**Risk level:** Serious risk

A problem with the electric cable harness for the seat heater could lead to excessive heating of the seat and the risk of a fire starting even when the vehicle is parked.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Passenger car

**Batch number/Barcode:** The vehicles concerned were produced between 29 June 2009 and 29 May 2015.

**Country of origin:** France

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** Bulgaria, The Netherlands

**Alert number:** A12/0818/16

**Product:** Passenger car

**Name:** Twingo

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Renault

**Type/number of model:** Twingo III (X07 R4S version E1): e2\*2007/46\*0457\*00, e2\*200746\*0457\*01, e2\*2007/46\*0457\*02 e2\*200746\*0457\*03, e2\*2007/46\*0457\*04, e2\*2007/46\*0457\*05, e2\*2007/46\*0457\*06

**Risk level:** Serious risk

The fixing device for the rear bench seat may break in the event of a frontal collision, with a potential risk of any luggage in the boot entering the front of the vehicle.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Passenger car

**Batch number/Barcode:** Concerns vehicles with a non-split folding bench seat manufactured from April 2014 up to and including 24 November 2015.

**Country of origin:** France

**Alert submitted by:** France

**Products were found and measures were taken also in:** Estonia, Germany

**Alert number:** A12/0838/16

**Product:** Passenger car

**Name:** Mazda 2, CX-3, CX-9

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Mazda

**Type/number of model:** Type-approval numbers: e13\*2001/116\*0254\*09-13 e1\*2007/46\*1335\*03-04; type: De DJ1, TB1

**Risk level:** Serious risk

The screw connection between the stub axle and the shock absorber may come loose. As a result, the vehicle may no longer be steerable.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Passenger car

**Batch number/Barcode:** The vehicles concerned were produced between 19 December 2012 and 2 December 2015.

**Country of origin:** Japan

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** Ireland, The Netherlands

**Alert number:** A12/0839/16

**Product:** Caravan

**Name:** Averso, Averso top, Averso Plus, Premio, Premio Plus

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Bürstner

**Type/number of model:** Type-approval numbers: e1\*2007/46\*0147, e1\*2007/46\*0189; types: EG/B?, EG/B3

**Risk level:** Serious risk

The side service door may fall open while the vehicle is in motion and protrude horizontally into the road. The contents of the caravan could fall into the road posing a hazard for following vehicles. The open door may pose a risk of collision with other road users.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Caravan

**Batch number/Barcode:** The vehicles affected were produced from 2014 to 2016.

**Country of origin:** France

**Alert submitted by:** Germany

**Alert number:** A12/0840/16

**Product:** Passenger car

**Name:** Phaeton

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** VW

**Type/number of model:** Type approval number: e1\*2001/116\*0189\* Type: 3D

**Risk level:** Serious risk

The adhesion of the glass cover on the sliding roof may be insufficient due to contamination during the production process. The glass cover could detach whilst the vehicle is moving and endanger traffic following behind.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Passenger car with sunroof.

**Batch number/Barcode:** The vehicles in question were manufactured between 25 April 2007 and 17 June 2008.

**Country of origin:** Germany

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** The Netherlands

**Alert number:** A12/0841/16

**Product:** Passenger car

**Name:** Aygo

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Toyota

**Type/number of model:** Unknown

**Risk level:** Serious risk

The shaft of the steering column could break leading to a loss of steering control and the risk of an accident.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Small 2 door passenger car.

**Batch number/Barcode:** Vehicles produced from 9 September 2014 to 15 October 2014.

**Country of origin:** Japan

**Alert submitted by:** Malta

**Products were found and measures were taken also in:** Bulgaria, Estonia, Germany, The Netherlands

**Alert number:** A12/0842/16

**Product:** Passenger car

**Name:** A8

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Audi

**Type/number of model:** Type approval number: e1\*2001/116\*0198\* Type: 4E

**Risk level:** Serious risk

The adhesion of the glass cover on the sunroof may be insufficient due to impurities in the area of the adhesive surfaces. The glass cover may consequently fall onto the road while driving, endangering traffic following behind.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Passenger car

**Batch number/Barcode:** The vehicles in question were manufactured between May 2007 and September 2008.

**Country of origin:** Germany

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** The Netherlands

**Alert number:** A12/0843/16

**Product:** Passenger car

**Name:** C1

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Citroën

**Type/number of model:** C1 (B4)

**Risk level:** Serious risk

Part of the steering column assembly could fail, which could lead to loss of control of the vehicle.

**Measures taken by economic operators:** Recall of the product from end users (By: Importer)

**Description:** Passenger car

**Batch number/Barcode:** Production period: 09-09-2014 to 15-09-2014

**Country of origin:** Czech Republic

**Alert submitted by:** Portugal

**Products were found and measures were taken also in:** Germany, The Netherlands

**Alert number:** A12/0844/16

**Product:** Passenger car

**Name:** 108

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Peugeot

**Type/number of model:** Unknown

**Risk level:** Serious risk

Part of the steering column assembly could fail, which could lead to loss of control of the vehicle.

**Measures taken by economic operators:** Recall of the product from end users (By: Importer)

**Description:** Passenger car

**Batch number/Barcode:** Production period: 10-09-2014 to 12-09-2014

**Country of origin:** Czech Republic

**Alert submitted by:** Portugal

**Products were found and measures were taken also in:** Germany, The Netherlands

**Alert number:** A12/0820/16

**Product:** Toy scooter

**Name:** 3 Wheel Scooter Paw Patrol

**Risk:** Injuries

**Category:** Toys

**Brand:** SAMBRO

**Type/number of model:** Item n°: PWP-7010; Reference Toys R Us : 191579

**Risk level:** Serious risk

The grips protecting the handlebar ends can detach. If a child falls on the unprotected handlebar end, this can cause severe injuries such as puncture of the abdomen. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures taken by economic operators:** Recall of the product from end users, Withdrawal of the product from the market (By: Distributor)

**Description:** Blue and red 3-wheeled scooter made of plastic and metal, intended for children of age 2+. Cardboard packaging.

**Batch number/Barcode:** 5055114307311, Batch: 04/15

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0821/16

**Product:** Toy ponies

**Name:** TOYS BABY

**Risk:** Chemical

**Category:** Toys

**Brand:** AMY

**Type/number of model:** Item No: JR 1408208

**Risk level:** Serious risk

The plastic material of the pony contains di-(2-ethylhexyl) phthalate (DEHP) (measured value: 32.1% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. According to the REACH Regulation, DEHP, DBP and BBP phthalates are prohibited in all toys and childcare articles.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** A set of two pink plastic ponies with a pink and purple mane and tail.

**Batch number/Barcode:** 1408208006300

**Country of origin:** China

**Alert submitted by:** Czech Republic



**Alert number:** A12/0833/16

**Product:** Toy pony

**Name:** Fairy Tale World

**Risk:** Chemical

**Category:** Toys

**Brand:** Ameiya / Hammy Toys

**Type/number of model:** 333C

**Risk level:** Serious risk

The plastic of the ponies contains di(2-ethylhexyl)phthalate (DEHP) (measured value up to 33% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. According to the REACH Regulation the phthalates DEHP, DBP and BBP are prohibited in all toys and childcare articles.

**Measures ordered by public authorities:** Recall of the product from end users, Withdrawal of the product from the market

**Description:** Plastic ponies in different colours, supplied in transparent plastic packaging and sold in display boxes.



**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/0834/16

**Product:** Children's swing chair

**Name:** Kinder Hollywoodschaukel Rot, Beetle - Kid's Swing Chair, Beetle Design

**Risk:** Injuries

**Category:** Toys

**Brand:** DEUBA

**Type/number of model:** Art. 100081; E/05 Colour: Red

**Risk level:** Serious risk

While children are swinging, the swing chair can overturn. Children can fall and be hit by the metal roof of the swing chair, causing injuries to the head and the neck. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-8.


**Measures ordered by public authorities:** Ban on the marketing of the product and any accompanying measures

**Description:** Swing chair for children, supplied in a cardboard box, size: 1130x450x120 mm.

**Batch number/Barcode:** 4250525300420

**Country of origin:** Germany

**Alert submitted by:** Czech Republic



**Alert number:** A11/0064/16

**Product:** Firework

**Name:** Tiger Power

**Risk:** Burns, Damage to hearing

**Category:** Pyrotechnic articles

**Brand:** Tropic Fire

**Type/number of model:** TP1000

**Risk level:** Other risk level

The burning time of the initial fuse may be too long, or a rupture might occur during functioning of some individual flash bangers. If there is a delay in the explosion, users may return to check the product and could get burned by an unexpected explosion or be exposed to a high level of noise due to the short distance. The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

**Measures taken by economic operators:** Warning consumers of the risks (By: Importer)

**Description:** Flash Banger firework, model: TP1000, CAT. F 3.

**Batch number/Barcode:** 1170-F3-02599, 36F236/029/15

**Country of origin:** China

**Alert submitted by:** Bulgaria

