

# The Rapid Alert System for Non-Food Products (RAPEX)

## RAPEX - Weekly overview report of notifications

week 2 - 2017

Notifications A12/1716/16 and A12/1717/16 in Report-2016-051 of 23 December 2016 have been updated with new traceability information.

**Alert number:** A12/0009/17

**Product:** Lederhose (Leather trousers)

**Name:** Unknown

**Risk:** Chemical

**Category:** Clothing, textiles and fashion items

**Brand:** Bessmann/Country-Line

**Type/number of model:** X-9477, colour 63

**Risk level:** Serious risk

The amount of Chromium (VI) found in the leather is too high (measured value 10.6 mg/kg). Chromium (VI) is sensitising and may trigger allergic reactions. The product does not comply with the REACH regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Importer)

**Description:** Knee-length leather trousers with bib made of dark brown leather; lining: 100% cotton. Sample size 50.

**Batch number/Barcode:** 76202722

**Country of origin:** Pakistan

**Alert submitted by:** Germany



**Alert number:** A12/0015/17

**Product:** Tooth powder

**Name:** Pure herbal tooth powder

**Risk:** Microbiological

**Category:** Cosmetics

**Brand:** VICCO

**Type/number of model:** Unknown

**Risk level:** Serious risk

The product is microbiologically contaminated: it contains a high level of aerobic mesophilic bacteria (measured value up to  $4.2 \times 10^5$  cfu/0.5g). If used on damaged skin or if it comes in contact with the eyes, the product may cause infection or irritation. The product does not comply with the Cosmetic Products Regulation.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Herbal tooth powder packed in a yellow plastic container (100 g)

**Batch number/Barcode:** Bar code: 8901288021003, Batch number.: N41203721

**THE PRODUCT MAY BE COUNTERFEIT**

**Country of origin:** India

**Alert submitted by:** Latvia



**Alert number:** A12/0005/17

**Product:** Angle grinder

**Name:** Angle Grinder

**Risk:** Electric shock

**Category:** Machinery

**Brand:** Villager

**Type/number of model:** VLN432

**Risk level:** Serious risk

The housing does not have enough strength and could break during normal use leaving live parts accessible. The product does not comply with the requirements of the Machinery Directive and the relevant European standard EN 60745.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Angle grinder packed in cardboard box.

**Batch number/Barcode:** 8606104032187

**Country of origin:** China

**Alert submitted by:** Slovenia



**Alert number:** A12/0001/17

**Product:** Passenger car

**Name:** Discovery Sport and Range Rover Evoque

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Land Rover, Range Rover

**Type/number of model:** Model years 2016 and 2017

**Risk level:** Serious risk

The tightening torque of the lower control arm fixing may not be correct, causing the vehicle steering to be affected. This could increase the risk of a vehicle crash.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Passenger car

**Batch number/Barcode:** Land Rover Discovery Sport: built between 31/03/16 and 25/08/16, Range Rover Evoque: built between 31/3/16 and 25/8/16

**Country of origin:** United Kingdom

**Alert submitted by:** United Kingdom

**Products were found and measures were taken also in:** Germany, Ireland, Poland, The Netherlands

**Alert number:** A12/0012/17

**Product:** Passenger car

**Name:** Discovery and Evoque

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Land Rover, Range Rover

**Type/number of model:** 2017 model year

**Risk level:** Serious risk

An engine harness may not have been routed correctly during assembly. This may lead to chafing and cause engine malfunction. In extreme cases the engine may cut out.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Passenger car

**Batch number/Barcode:** Land rover Discovery: built between 4/7/16 and 10/10/16, Range Rover Evoque: built between 4/7/16 and 10/10/16

**Country of origin:** United Kingdom

**Alert submitted by:** United Kingdom

**Products were found and measures were taken also in:** Ireland, Poland, The Netherlands

**Alert number:** A12/0013/17

**Product:** Passenger car

**Name:** Duster, Logan and Sandero

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Dacia

**Type/number of model:** e2\*2001/116\*0314 ext. 58 to 61 // e2\*2007/46\*0030 ext. 17 to 24

**Risk level:** Serious risk

In the event of an impact the driver's airbag may not deploy.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Passenger car

**Batch number/Barcode:** Vehicles manufactured between 24/09/2012 and 04/11/2012, between 10/12/2012 and 20/01/2013, between 12/04/2013 and 26/05/2013 and between 06/11/2013 and 15/12/2013.

**Country of origin:** Romania

**Alert submitted by:** Portugal

**Products were found and measures were taken also in:** Ireland, Poland, Sweden, The Netherlands

**Alert number:** A12/0014/17

**Product:** Passenger car

**Name:** NX200, NX200t and NX300h

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Lexus

**Type/number of model:** NX200 (ZGZ10, ZGZ15), NX200t (AGZ10, AGZ15) and NX300h (AYZ10, AYZ15)

**Risk level:** Serious risk

Due to improper programming of the brake control module, there is a possibility that under certain conditions the parking brake may not be set automatically when the brake hold system is deactivated (as designed). If this occurs, and the transmission is left in a gear other than "Park" or "Reverse", the vehicle could creep forward or backward.

**Measures taken by economic operators:** Recall of the product from end users (By: Importer)

**Description:** Passenger car

**Batch number/Barcode:** Production years: 2014 - 2016

**Country of origin:** Japan

**Alert submitted by:** Portugal

**Products were found and measures were taken also in:** Estonia, Poland, Slovakia, The Netherlands

**Alert number:** A12/0017/17

**Product:** Passenger car

**Name:** Quattroporte, Ghibli

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Maserati

**Type/number of model:** EC type-approval: e3\*2007/46\*0224\*05-06; type: M156

**Risk level:** Serious risk

A wrong rear differential has been fitted into the cars and might break which can result in loss of control over the vehicle.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Description:** Passenger car.

**Batch number/Barcode:** The vehicles affected were produced between 1 July 2013 and 12 October 2016.

**Country of origin:** Italy

**Alert submitted by:** Germany

**Alert number:** A12/0018/17

**Product:** Motorcycle

**Name:** DL650A / XA L2-L6

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Suzuki

**Type/number of model:** Unknown

**Risk level:** Serious risk

The insulation material of the windings for the stator of the alternator may be damaged by engine heat causing a short-circuit between the windings and reducing the current generated. If this happens, insufficient charging of the battery could lead to the engine stalling during running.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Motorcycle

**Batch number/Barcode:** Manufactured between 21.04.2011 and 14.10.2016.

**Country of origin:** Japan

**Alert submitted by:** Poland

**Products were found and measures were taken also in:** Denmark, Germany, Ireland, Sweden, The Netherlands

**Alert number:** A12/0019/17

**Product:** Passenger car

**Name:** Wrangler

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Jeep

**Type/number of model:** Model years 2016 and 2017

**Risk level:** Serious risk

In the event of a crash, the front impact sensor wiring may be pulled until it detaches before a signal can be received by the Occupant Restraint Controller (ORC). If the ORC module does not receive a signal from the front impact sensor, both frontal air bags and the seat belt pre-tensioners will not deploy, increasing the risk of injury.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Passenger car

**Batch number/Barcode:** Unknown

**Country of origin:** United States

**Alert submitted by:** Poland

**Alert number:** A12/0020/17

**Product:** Passenger car

**Name:** V40, V40CC, S60, S60CC, V60, V60CC, XC60, S90, V90, XC90

**Risk:** Injuries

**Category:** Motor vehicles

**Brand:** Volvo

**Type/number of model:** Model year 2017.

**Risk level:** Serious risk

Due to a problem with the airbag inflators, the airbags may fail to deploy in the event of a crash, increasing the risk of injury to the occupants.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Passenger car

**Batch number/Barcode:** Unknown

**Country of origin:** Sweden

**Alert submitted by:** Poland

**Products were found and measures were taken also in:** Germany, Ireland, Slovakia, Sweden, The Netherlands

**Alert number:** A12/0002/17

**Product:** Plastic doll

**Name:** FROZEN 2

**Risk:** Chemical

**Category:** Toys

**Brand:** Diversity Fashion

**Type/number of model:** No.8082

**Risk level:** Serious risk

The plastic material of the doll's head contains di-(2-ethylhexyl) phthalate (DEHP) (measured value 28.6% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. According to the REACH Regulation the phthalates DEHP, DBP and BBP are prohibited in all toys and childcare articles.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Plastic doll, about 30 cm tall, with a blue dress, emitting sounds when pressing a button.

**Batch number/Barcode:** QL2369 2M240 / 8823696606002

**THE PRODUCT MAY BE COUNTERFEIT**

**Country of origin:** China

**Alert submitted by:** Czech Republic



**Alert number:** A12/0003/17

**Product:** Plastic doll

**Name:** FRAGRANTLY MEMORIES/ My iDEA

**Risk:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type/number of model:** No.8188

**Risk level:** Serious risk

The plastic material of the doll's head contains di-(2-ethylhexyl) phthalate (DEHP) (measured value 28.4% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. According to the REACH Regulation the phthalates DEHP, DBP and BBP are prohibited in all toys and childcare articles.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Plastic dolls, about 27 cm tall in different dresses. The doll is supplied in a cardboard box with transparent window.

**Batch number/Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Czech Republic



**Alert number:** A12/0004/17

**Product:** Plastic doll

**Name:** Unknown

**Risk:** Chemical

**Category:** Toys

**Brand:** Diversity Fashion

**Type/number of model:** No.391

**Risk level:** Serious risk

The plastic material of the doll's head contains di-(2-ethylhexyl) phthalate (DEHP) (measured value 28.1% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. According to the REACH Regulation the phthalates DEHP, DBP and BBP are prohibited in all toys and childcare articles.

**Measures ordered by public authorities:** Withdrawal of the product from the market

**Description:** Plastic doll, about 27 cm tall, with blue dress, supplied in a cardboard box with transparent window.

**Batch number/Barcode:** QL2366 2M360/ 8823666603505


**THE PRODUCT MAY BE COUNTERFEIT**

**Country of origin:** China

**Alert submitted by:** Czech Republic



**Alert number:** A12/0006/17  
**Product:** Musical toy  
**Name:** Music Carriage  
**Risk:** Choking  
**Category:** Toys  
**Brand:** MT (MEITAI TOYS)  
**Type/number of model:** NO. 2012C  
**Risk level:** Serious risk  
 Small parts can easily be detached (the wheels, the rotating part and the decorative flower) and be put in the mouth by small children, causing them to choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.  
**Measures ordered by public authorities:** Ban on the marketing of the product and any accompanying measures  
**Description:** Plastic musical toy in various colours (pink, violet and white) on four wheels with rotating parts and two horses, operated by an AA type battery.  
**Batch number/Barcode:** \*021361\*  
**Country of origin:** China  
**Alert submitted by:** Lithuania



**Alert number:** A12/0007/17  
**Product:** Toy picnic set  
**Name:** Fancy & Funny  
**Risk:** Choking  
**Category:** Toys  
**Brand:** M - Mountains China  
**Type/number of model:** 3352/9063-4JTP  
**Risk level:** Serious risk  
 The plastic box can break generating small parts. Stickers on the cups come off. A child may put these small parts in the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.  
**Measures ordered by public authorities:** Import rejected at border  
**Description:** Toy plastic picnic set in a plastic box. Cardboard packaging with transparent window.  
**Batch number/Barcode:** 1012000906342  
**Country of origin:** China  
**Alert submitted by:** Spain



**Alert number:** A12/0008/17

**Product:** Toy gun

**Name:** Soft Bullet Blaster

**Risk:** Choking

**Category:** Toys

**Brand:** Fighter

**Type/number of model:** Code 513614 - N° Ref. SB295

**Risk level:** Serious risk

The suction cups detach easily from the projectiles. If a child puts the projectile in the mouth, for instance to wet the suction cup so that it better sticks to surfaces, the suction cup may come loose and obstruct the airways. The product does comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures ordered by public authorities:** Import rejected at border

**Description:** Plastic toy gun with soft projectiles with suction-cups. Packaging: cardboard box with a window.

**Batch number/Barcode:** 8421609229500

**Country of origin:** China

**Alert submitted by:** Spain

