

•

European Commission (http://ec.europa.eu/index\_en.htm) Consumers (http://ec.europa.eu/consumers/index\_en.htm) Consumers safety (http://ec.europa.eu/consumers/consumers\_safety/index\_en.htm) Safety products (http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/index\_en.htm)

## The Rapid Alert System for Non-Food Products (RAPEX)

## RAPEX - Weekly overview report of notifications

week 8 - 2017





Alert number: A12/0206/17 Product: Skin product Name: "Cream multi-purpose with melissa and raspberry" Risk type: Chemical Category: Cosmetics Brand: MIRRA Type / number of model: Unknown

Risk level: Serious risk

The cream contains methylisothiazolinone (MI) and methylchloroisothiazolinone (MCI). Dermal contact with MCI/MI-containing products can provoke allergic contact dermatitis to sensitised persons. According to the Cosmetic Products Regulation, MCI/MI is prohibited in leave-on cosmetic products. The product does not comply with the Cosmetic Products Regulation.

Measures taken by economic operators: Withdrawal of the product from the market, Withdrawal of the product from the market (By: Importer, Retailer)

Description: Skin cream in a white plastic tube (50 ml) with a green cap.

Batch number / Barcode: 0317R07, Bar code 4602819004611

Country of origin: Russian Federation

Alert submitted by: Estonia



Alert number: A12/0193/17 Product: Charger Name: USB MINI TRAVEL CHARGER Risk type: Electric shock Category: Electrical appliances and equipment Brand: PETER JÄCKEL Type / number of model: 12630, 12629 12631 and 12632 Risk level: Serious risk There is no double insulation. The mechanical strength is insufficient which could lead to live parts becoming accessible. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950. Measures taken by economic operators: Warning consumers of the risks, Withdrawal of the product from the market (By: Manufacturer) Description: USB charger in blister pack. Batch number / Barcode: 4031574126298, 4031574126304, 4031574126311, 4031574126328 Country of origin: China Alert submitted by: Germany PETER JÄCKEI 1A

Alert number: A12/0200/17 Product: Heating blender Name: Licuadora Calefactora Risk type: Burns Category: Electrical appliances and equipment Brand: HOMDAY Type / number of model: 363546

Risk level: Serious risk

The handle used to open the lid becomes too hot during use and could burn the fingers of the user. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335.

Measures taken by economic operators: Destruction of the product, Recall of the product from end users, Withdrawal of the product from the market (By: Importer)

Description: A heating blender supplied in a cardboard box.

Batch number / Barcode: 07/2016; 3491953635468 Country of origin: China

Alert submitted by: France



Alert number: A12/0214/17 Product: Plug adapter Name: Przejsciowka polsko - brytyjska Risk type: Electric shock Category: Electrical appliances and equipment Brand: Düwi International Type / number of model: 24018 Risk level: Serious risk It is possible for one of the pins of the adapter to be plugged into the socket while the other pin is accessible to the user and becomes a live part. Measures taken by economic operators: Withdrawal of the product from the market (By: Distributor) Description: A Polish-British plug adapter. Batch number / Barcode: EAN: 4008297240181 Country of origin: China Alert submitted by: Poland



Alert number: A12/0189/17
Product: Air gun
Name: Cross Fire
Risk type: Damage to sight
Category: Hobby/sports equipment
Brand: Skyma
Type / number of model: SM.1001A
Risk level: Serious risk
The laser is not correctly labelled and lacks warnings, which could lead to unsafe use. The product does not comply with the relevant European standard EN 60825-1 with respect to labelling and warnings.
Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market
Description: Air gun with laser sight.

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Cyprus



Alert number: A12/0205/17 Product: Bracelet Name: Unknown Risk type: Chemical Category: Jewellery Brand: Glitter Type / number of model: 151 Crystal S Risk level: Serious risk The migration of nickel from the metal parts on the inside of the bracelet is too high (measured values: 2 µg/cm2/week). Nickel is a strong sensitizer and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin. The product does not comply with

Measures taken by economic operators: Withdrawal of the product from the market (By: Distributor)

Description: A strass bracelet approx. 3 cm wide, consisting of a number of glass rhinestones connected together by a rubber band. No packaging, but the product is attached to a black plastic tag marked "Glitter" and "151 Crystal S".

Batch number / Barcode: 306518102000

Country of origin: China

the REACH Regulation.



European Commission - Rapid Alert System Alert number: A12/0219/17 Product: Bracelet Name: Talisman St. Christopher Risk type: Chemical Category: Jewellery Brand: Chrysalis Type / number of model: Unknown Risk level: Serious risk The product contains lead (measured value: up to 0,14 % by weight). Exposure to lead is harmful for human health. The product does not comply with the REACH regulation. Measures ordered by public authorities: Withdrawal of the product from the market Description: Silver-coloured bracelet with a talisman. Batch number / Barcode: 250000021268 Country of origin: Hong Kong Alert submitted by: The Netherlands Alert number: A12/0222/17 Product: Earrings Name: Accessoires Risk type: Chemical Category: Jewellery Brand: Unknown Type / number of model: Art.:58-595, AXART:01.06.350.2595, Colour: Gun metal, MV ID 714937.3, season 9, theme 153 Risk level: Serious risk The product contains lead (measured value: 0.15 %). Exposure to lead is harmful for human health. The product does not comply with the REACH regulation. Measures ordered by public authorities: Withdrawal of the product from the market Description: A set of 9 different earrings on black cardboard. Batch number / Barcode: 5859571493701031 Country of origin: China Alert submitted by: The Netherlands ACCESSOIR SIZE: ONE SIZE 58-595 RT:01.06.3

Alert number: A12/0223/17 Product: Earrings Name: Unknown Risk type: Chemical Category: Jewellery Brand: C & S Paris Type / number of model: Unknown

Risk level: Serious risk

The metal part of the earnings contains cadmium (measured value 34,5 % by weight). Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer. The product does not comply with the REACH Regulation. Measures ordered by public authorities: Withdrawal of the product from the market

Description: Silver coloured earrings with purple and glass stones.

Batch number / Barcode: Ean 1815130 200508 / batch code 13 NROEA2 - 01057 - 50

Country of origin: China

Alert submitted by: The Netherlands



Alert number: A12/0224/17 Product: Necklace Name: Kette Risk type: Chemical Category: Jewellery Brand: Unknown Type / number of model: 215 Risk level: Serious risk The product contains cadmium (measured value 0,03 % by weight). Cadmium is harmful to human health because it accumulates in the body, can damage organs and may cause cancer. The product does not comply with the REACH regulation. Measures ordered by public authorities: Withdrawal of the product from the market Description: A silver coloured necklace with 3 hearts on a white cardboard. Batch number / Barcode: 39924001751000000150 Country of origin: China Alert submitted by: The Netherlands Kette



Alert number: A12/0191/17 Product: Electric planer Name: Professional Power Tool Solutions Risk type: Cuts Category: Machinery Brand: Metabo Type / number of model: Ho 0882 **Bisk level:** Serious risk The protective guard does not fully cover the blades on the side of the planer or the unused part of the cutting head. The product does not comply with the requirements of the Machinery Directive and the relevant European standard EN 60745. Measures taken by economic operators: Recall of the product from end users, Withdrawal of the product from the market (By: Distributor) Description: Power tool (planer). Batch number / Barcode: Lot 60088200. Manufactured in 2016. Country of origin: Germany Alert submitted by: France Products were found and measures were taken also in: Finland, Slovenia netabo Alert number: A12/0194/17 Product: Motorcycle Name: Scrambler, Scrambler Sixty2 Risk type: Injuries Category: Motor vehicles Brand: Ducati Type / number of model: Scrambler Sixty2: Type: KA, EC type approval: e49\*168/2013\*00001\*, Scrambler: Type: K1, EC type approval: e9\*2002/24\*6054\* Risk level: Serious risk The fixing nuts of the side stand could loosen. This could lead to the side stand sensor no longer correctly capturing the position of the side stand. As a result, it may be possible to ride the motorcycle when the side stand is still down or the engine might stop unexpectedly whilst riding. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Motorcycle Batch number / Barcode: Vehicles manufactured between 2015 and 2017. Country of origin: Italy Alert submitted by: Germany Products were found and measures were taken also in: Croatia, Denmark, Ireland, Luxembourg, Poland, Slovakia, Slovenia, Sweden, The Netherlands, United Kingdom Alert number: A12/0195/17 Product: Motorcycle Name: Goldwing GL1800A Risk type: Injuries Category: Motor vehicles Brand: Honda Type / number of model: Unknown Risk level: Serious risk The propellant used in the air bag inflators may degrade over time due to heat cycles and exposure to moisture. In the event that the airbag is activated, the excessive internal pressure may cause the inflator body to rupture and metal fragments may pass through the cushion material. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Motorcycle Batch number / Barcode: Vehicles built between 12/06/2008 and 03/12/2008. Country of origin: Japan Alert submitted by: United Kingdom Products were found and measures were taken also in: Estonia, Finland, Germany, Luxembourg, Poland, Slovakia, Slovenia, Sweden, The Netherlands

European Commission - Rapid Alert System
Alert number: A12/0199/17
Product: Passenger car / van
Name: Traveller and Expert
Risk type: Injuries
Category: Motor vehicles
<b>Brand:</b> Peugeot <b>Type / number of model:</b> e2*2007/46*0532*01, e2*2007/46*0532*02, e2*2007/46*0533*01, e2*2007/46*0533*02
Risk level: Serious risk
The pinion valve on the steering rack may have been assembled incorrectly. This could lead to a loss of mechanical coupling between the pinion
alve and the steering rack and hence a loss of steering control.
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Description: Passenger car / van
Batch number / Barcode: Expert: manufactured between 13/06/2016 and 07/09/2016, Traveller: manufactured between 07/07/2016 and
26/08/2016 Country of origin: France
Alert submitted by: France
Products were found and measures were taken also in: Denmark, The Netherlands, United Kingdom
Alert number: A12/0201/17
Product: Passenger car / van Name: Traveller and Expert
Risk type: Injuries
Category: Motor vehicles
Brand: Peugeot
Type / number of model: e2*2007/46*0532*01, e22007/46*0533*00, e22007/46*0533*01
Risk level: Serious risk
The fastenings of the front shock absorbers could become loose. A loss of retention of a shock absorber could make it difficult for the driver to control the trajectory of the vehicle.
Veasures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Description: Passenger car / van
Batch number / Barcode: Expert: manufactured between 22/01/2016 and 23/06/2016, Traveller: manufactured between 25/02/2016 and
23/06/2016
Country of origin: France
Alert submitted by: France Products were found and measures were taken also in: Denmark, Poland, Sweden, The Netherlands, United Kingdom
Alert number: A12/0202/17
Product: Passenger car
Name: 1, 3, 5, 6, 7, X1, Z4 Series
Risk type: Injuries
Category: Motor vehicles Brand: BMW
Type / number of model: Type: 1K2, 1C, 1K4, 3L, 3K, 3C, 5L, 5K, K-N1, GT, KL, 6C, 7L, X1, ZR; EC type approval: e1*2007/46*0273,
p1*2007/46*0277, e1*2007/46*0283, e1*2007/46*0314, e1*2007/46*0315, e1*2007/46*0316, e1*2007/46*0363, e1*2007/46*0455,
e1*2007/46*0508, e1*2007/46*0215, e1*KS07/46*0013, e1*2007/46*0562, e1*2007*46*0276, e1*2007/46*0275, e1*2007/46*0373
Risk level: Serious risk
The universal joint of the drive shaft might break, causing a sudden loss of propulsion.
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Description: Passenger car Batch number / Barcode: Vehicles manufactured between 2010 and 2011.
Country of origin: Germany
Alert submitted by: Germany
Products were found and measures were taken also in: Croatia, Denmark, Ireland, Poland, Slovakia, Slovenia, Sweden, The Netherlands
Next sumber: 110/0000/17
Alert number: A12/0203/17 Product: Passenger car
Name: X1 Series
Risk type: Injuries
Category: Motor vehicles
Brand: BMW
Type / number of model: Type: UKL-L, F1X; EC type approval: e1*2007/46*0371, e1*2007/46*1676
Risk level: Serious risk The necessary opening lines in the area of the passenger airbag cover may not have been machined correctly. In the event of an accident, the
The necessary opening lines in the area of the passenger airbag cover may not have been machined correctly. In the event of an accident, the passenger airbag may consequently not be able to unfold correctly, increasing the risk of injury for the passenger.
Veasures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Description: Passenger car
Batch number / Barcode: Vehicles manufactured between June 2016 and January 2017.
Country of origin: Germany
Alert submitted by: Germany
Products were found and measures were taken also in: United Kingdom

Alert number: A12/0207/17	
Product: Passenger car / van	
Name: Traveller and Expert	
Risk type: Fire	
Category: Motor vehicles	
Brand: Peugeot	
	eller: e2*2007/46*0532*00, e2*2007/46*0532*01, e2*2007/46*0532*02; Expert 4: e2*2007/46*0533*00,
e2*2007/46*0533*01.	
Risk level: Serious risk	
, ,	of a fuel pipe seal in the filler cap area could lead to loss of fuel when the tank is filled completely or in the event that
the vehicle overturns.	a provide very Depart of the second water and wanter (Dr. Manufacture)
Description: Passenger car / v	c operators: Recall of the product from end users (By: Manufacturer)
	nufactured between 1.2.2013 and 9.7.2016, Manufactured between 3.2.2016 and 9.7.2016
Country of origin: France	
Alert submitted by: France	
	asures were taken also in: Croatia, Denmark, Finland, Poland, Slovakia, Slovenia, Sweden, The Netherlands, United
Kingdom	
Alert number: A12/0208/17	
Product: Passenger car	
Name: 3008	
Risk type: Injuries	
Category: Motor vehicles	
Brand: Peugeot	
Type / number of model: e2*2	2007/46*0534*00, e2*2007/46*0534*01, e2*2007/46*0534*02
Risk level: Serious risk	
A possible fault with the seals	at the end of the fuel hose intended for the fuel system of the additional compartment heater (available as an
accessory) could lead to a fuel	
•	c operators: Recall of the product from end users (By: Manufacturer)
Description: Passenger car	
	Inufactured between 12/04/2016 and 03/11/2016
Country of origin: France Alert submitted by: France	
•	asures were taken also in: Finland, Sweden
Name: Traveller and Expert Risk type: Injuries Category: Motor vehicles	
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016	operators: Recall of the product from end users (By: Manufacturer)
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c <b>operators:</b> Recall of the product from end users (By: Manufacturer) an
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) ran bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c <b>operators:</b> Recall of the product from end users (By: Manufacturer) an
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) ran pert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) ran bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) ran bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) ran bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) ran bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) an bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and asures were taken also in: Denmark, Finland, Poland, Slovakia, Sweden, United Kingdom
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën Type / number of model: e2*2	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) ran bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën Type / number of model: e2*2 Risk level: Serious risk	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. operators: Recall of the product from end users (By: Manufacturer) an bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and asures were taken also in: Denmark, Finland, Poland, Slovakia, Sweden, United Kingdom
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën Type / number of model: e2*2 Risk level: Serious risk The tightening torque of the br	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. c operators: Recall of the product from end users (By: Manufacturer) an bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and asures were taken also in: Denmark, Finland, Poland, Slovakia, Sweden, United Kingdom
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën Type / number of model: e2*2 Risk level: Serious risk The tightening torque of the br system less effective. Measures taken by economic	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. operators: Recall of the product from end users (By: Manufacturer) an bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and asures were taken also in: Denmark, Finland, Poland, Slovakia, Sweden, United Kingdom
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën Type / number of model: e2*2 Risk level: Serious risk The tightening torque of the br system less effective. Measures taken by economic Description: Van	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. <b>2 operators:</b> Recall of the product from end users (By: Manufacturer) an bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and <b>asures were taken also in</b> : Denmark, Finland, Poland, Slovakia, Sweden, United Kingdom 2007/46*0530*01, e2*2007/46*0531*01 rake servo to the pedal may be incorrect. This could lead to air getting into the brake servo, making the brake assist <b>2 operators:</b> Recall of the product from end users (By: Manufacturer)
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën Type / number of model: e2*2 Risk level: Serious risk The tightening torque of the br system less effective. Measures taken by economic Description: Van Batch number / Barcode: Jur	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. • operators: Recall of the product from end users (By: Manufacturer) ran bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and asures were taken also in: Denmark, Finland, Poland, Slovakia, Sweden, United Kingdom 2007/46*0530*01, e2*2007/46*0531*01 rake servo to the pedal may be incorrect. This could lead to air getting into the brake servo, making the brake assist
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën Type / number of model: e2*2 Risk level: Serious risk The tightening torque of the br system less effective. Measures taken by economic Description: Van Batch number / Barcode: Jur 11/06/2016.	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. <b>2 operators:</b> Recall of the product from end users (By: Manufacturer) an bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and <b>asures were taken also in</b> : Denmark, Finland, Poland, Slovakia, Sweden, United Kingdom 2007/46*0530*01, e2*2007/46*0531*01 rake servo to the pedal may be incorrect. This could lead to air getting into the brake servo, making the brake assist <b>2 operators:</b> Recall of the product from end users (By: Manufacturer)
Brand: Peugeot Type / number of model: e2*2 Risk level: Serious risk Incorrect tightening of the fixin airbags or to the engine stoppi Measures taken by economic Description: Passenger car / v Batch number / Barcode: Exp 20/07/2016 Country of origin: France Alert submitted by: France Products were found and me Alert number: A12/0210/17 Product: Van Name: Spacetourer, Jumpy Risk type: Injuries Category: Motor vehicles Brand: Citroën Type / number of model: e2*2 Risk level: Serious risk The tightening torque of the br system less effective. Measures taken by economic Description: Van Batch number / Barcode: Jur	gs of the airbag housing and of the electrical chassis of the compartment harness could lead to malfunction of the ing. <b>2 operators:</b> Recall of the product from end users (By: Manufacturer) an bert: Manufactured between 09/05/2016 and 19/08/2016, Traveller: Manufactured between 11/05/2016 and <b>asures were taken also in</b> : Denmark, Finland, Poland, Slovakia, Sweden, United Kingdom 2007/46*0530*01, e2*2007/46*0531*01 rake servo to the pedal may be incorrect. This could lead to air getting into the brake servo, making the brake assist <b>2 operators:</b> Recall of the product from end users (By: Manufacturer)

Alert number: A12/0211/17	
Product: Van	
Name: Traveller and Expert	
Risk type: Injuries Category: Motor vehicles	
Brand: Peugeot	
Type / number of model: e2*2007/46*0532*00, e2*2007/46*0532*01, e2*2007/46*0532*02, e2*2007/46*0533*00, e2*2007/46*0532*02, e2*2007/46*0532*02, e2*2007/46*0533*00, e2*2007/46*0532*02, e2*2007/46*0533*00, e2*2007/46*0533*00, e2*2007/4	6*0533*01,
e2*2007/46*0533*02, e2*2007/46*0533*03	
Risk level: Serious risk Some seals for the bodywork are missing. As a result, water could enter the passenger compartment and cause the airbag contro	l modulo to
malfunction, which could lead to the airbag being deployed unexpectedly.	
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)	
Description: Van	
Batch number / Barcode: Expert: manufactured between 22/10/2015 and 27/10/2016., Traveller: manufactured between 22/01	/2016 and
27/10/2016. Country of origin: France	
Alert submitted by: France	
Products were found and measures were taken also in: Bulgaria, Croatia, Denmark, Finland, Ireland, Malta, Poland, Slovakia, S	Slovenia, Sweden,
The Netherlands, United Kingdom	
Alert number: A12/0213/17	
Product: Van	
Name: Spacetourer, Jumpy Risk type: Injuries	
Risk type: Injunes Category: Motor vehicles	
Brand: Citroën	
Type / number of model: e2*2007/46*0530*00, e2*2007/46*0530*01, e2*2007/46*0530*02, e2*2007/46*0531*00, e2*2007/46*0530*01, e2*2007/46*0530*02, e2*2007/46*0531*00, e2*2007/46*0530*01, e2*2007/46*0530*02, e2*2007/4	6*0531*01,
e2*2007/46*0531*02, e2*2007/46*0531*03	
Risk level: Serious risk Some seals for the bodywork are missing. As a result, water could enter the passenger compartment and cause the airbag contro	l module to
malfunction, which could lead to the airbag being deployed unexpectedly.	
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)	
Description: Van	
Batch number / Barcode: Jumpy: manufactured between 15/10/2015 and 27/10/2016., Spacetourer: manufactured between 2 27/10/2016.	0/10/2015 and
Country of origin: France	
Alert submitted by: France	
Products were found and measures were taken also in: Bulgaria, Croatia, Denmark, Finland, Ireland, Malta, Poland, Slovakia, S	Slovenia, Sweden,
The Netherlands	
Alert number: A12/0217/17	
Product: Van	
Name: Citan Risk type: Injuries	
Category: Motor vehicles	
Brand: Mercedes-Benz	
Type / number of model: Type-approval number: e2*2007/46*0129* and e2*2007/46*0130*; Type: 415	
Risk level: Serious risk There may be cracks in the steering column tube. This means that the steering column might not withstand the force of an accid	opt which could
increase the risk of the driver sustaining injuries.	ent, which could
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)	
Description: Van	
Batch number / Barcode: The vehicles concerned were produced between 16 November and 8 December 2016.	
Country of origin: Germany Alert submitted by: Germany	
Products were found and measures were taken also in: Denmark, Poland, Sweden, The Netherlands, United Kingdom	
Alert number: A12/0218/17	
Product: Passenger car	
Name: SX4 S-Cross and Vitara	
Risk type: Environment	
Brand: Suzuki	
Brand: Suzuki Type / number of model: SUZUKI SX4 S-Cross (AKK) and SUZUKI VITARA (APK)	
Category: Motor vehicles Brand: Suzuki Type / number of model: SUZUKI SX4 S-Cross (AKK) and SUZUKI VITARA (APK) Risk level: Serious risk The ambient temperature sensor may malfunction. If this occurs, the engine controller will not detect sensor failure and conseque	ently the MIL
Brand: Suzuki Type / number of model: SUZUKI SX4 S-Cross (AKK) and SUZUKI VITARA (APK) Risk level: Serious risk The ambient temperature sensor may malfunction. If this occurs, the engine controller will not detect sensor failure and conseque (Malfunction Indicator Light) will not illuminate. These systems monitor the vehicle's exhaust and pollution control devices to ensu	-
Brand: Suzuki Type / number of model: SUZUKI SX4 S-Cross (AKK) and SUZUKI VITARA (APK) Risk level: Serious risk The ambient temperature sensor may malfunction. If this occurs, the engine controller will not detect sensor failure and conseque (Malfunction Indicator Light) will not illuminate. These systems monitor the vehicle's exhaust and pollution control devices to ensu operating properly. The product does not comply with the OBD (On-board diagnostics) regulation.	-
Brand: Suzuki Type / number of model: SUZUKI SX4 S-Cross (AKK) and SUZUKI VITARA (APK) Risk level: Serious risk The ambient temperature sensor may malfunction. If this occurs, the engine controller will not detect sensor failure and conseque (Malfunction Indicator Light) will not illuminate. These systems monitor the vehicle's exhaust and pollution control devices to ensu operating properly. The product does not comply with the OBD (On-board diagnostics) regulation. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)	-
Brand: Suzuki Type / number of model: SUZUKI SX4 S-Cross (AKK) and SUZUKI VITARA (APK) Risk level: Serious risk The ambient temperature sensor may malfunction. If this occurs, the engine controller will not detect sensor failure and conseque (Malfunction Indicator Light) will not illuminate. These systems monitor the vehicle's exhaust and pollution control devices to ensu operating properly. The product does not comply with the OBD (On-board diagnostics) regulation.	-
Brand: Suzuki Type / number of model: SUZUKI SX4 S-Cross (AKK) and SUZUKI VITARA (APK) Risk level: Serious risk The ambient temperature sensor may malfunction. If this occurs, the engine controller will not detect sensor failure and conseque (Malfunction Indicator Light) will not illuminate. These systems monitor the vehicle's exhaust and pollution control devices to ensu operating properly. The product does not comply with the OBD (On-board diagnostics) regulation. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car	-
Brand: Suzuki Type / number of model: SUZUKI SX4 S-Cross (AKK) and SUZUKI VITARA (APK) Risk level: Serious risk The ambient temperature sensor may malfunction. If this occurs, the engine controller will not detect sensor failure and conseque (Malfunction Indicator Light) will not illuminate. These systems monitor the vehicle's exhaust and pollution control devices to ensu operating properly. The product does not comply with the OBD (On-board diagnostics) regulation. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car Batch number / Barcode: The vehicles concerned were manufactured between 19/01/2015 and 26/09/2016.	-

Alert number: A12/0190/17 Product: Educational toy Name: Apple Wars - Whack-a-Mole Game Risk type: Choking Category: Toys Brand: Guang Kang Toys Type / number of model: 1507K693 / NO. B3-2 Risk level: Serious risk The small figures detach easily and can be swallowed by small children. The size/shape of the hammer is not sufficient and could cause children to choke. The product does not comply with the Toy Safety Directive and the relevant EN 71-1. Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market Description: Plastic multifunctional, battery-operated toy. Batch number / Barcode: 8675415076937 Country of origin: China Alert submitted by: Cyprus APPLE WARS 0 199 Mole NO.83-2 🚼 💶 🔯 APPLE WAR Alert number: A12/0198/17 Product: Soft musical toy Name: Play Baby's first guitar Risk type: Choking Category: Toys Brand: Unknown Type / number of model: ref. 11543

Risk level: Serious risk

The fabric around the guitar is closed at the back by velcro. Small children could easily open it and gain access to the foam stuffing inside. Small fragments of foam can be detached and put in the mouth by small children, who may choke on them. The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.

Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market

Description: A pink fabric, sound-emitting guitar operated by batteries. The product is sold in cardboard packaging with a transparent plastic panel. Batch number / Barcode: 8413930115430

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0204/17 Product: Toy xylophone Name: Music Zone Risk type: Choking Category: Toys Brand: Fantástiko, YI ZHI TOYS / Type / number of model: ref. 32480, 9388-65

Risk level: Serious risk

The white screws on the keys can easily be detached. Small children could put these small parts in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.

Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market

Description: Plastic xylophone with colourful keys, sold in a cardboard and plastic packaging.

Batch number / Barcode: batch 12/2014 8424345324805

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0225/17 Product: Play set Name: Special Agent Risk type: Choking Category: Toys

Brand: Unknown

Type / number of model: NGHB989836 Risk level: Serious risk

The suction cups detach easily from the projectiles. If a child puts the projectile in the mouth, the suction cup may detach and obstruct the airways. The product does comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Measures ordered by public authorities (to: Distributor): Ban on the marketing of the product and any accompanying measures

Description: A toy play set consisting of a black radio transmitter; a green duck; black binoculars and an orange toy gun with three projectiles. Batch number / Barcode: 6991209898366

Country of origin: China

Alert submitted by: Lithuania

