

CONSUMERS

¥

European Commission (http://ec.europa.eu/index_en.htm) Consumers (http://ec.europa.eu/consumers/index_en.htm) Consumers safety (http://ec.europa.eu/consumers/consumers_safety/index_en.htm) Safety products (http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/index_en.htm)

A Rapid Alert System home (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm

Eack to report listings (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2018)

Q Search alerts (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search)

Safe Products Online (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline)

The Rapid Alert System for Non-Food Products (RAPEX)

RAPEX - Weekly overview report of notifications

week 37 - 2018

Notification A12/1059/18 published on report 31-2018 of 03/08/2018 and withdrawn temporarily at the request of the notifying country has been re-published in the same weekly report following analysis of new tests that the authority has considered confirm the risks linked to the product.

Alert number: A12/1308/18 Product: Liquid for electronic cigarettes Name: (Various) Risk type: Chemical Category: Chemical products Brand: ORIGINAL Type / number of model: Nicotine strengths: 12 mg/ml and 18 mg/ml Risk level: Serious risk This product contains nicotine (12 or 18 mg/ml), which is classified as acutely toxic, but it does not have a leaflet providing the consumer with information about safe and correct use of the product. The user therefore has no information to avoid the dangers incurred when the product comes into contact with the skin or if it is ingested. The product does not comply with the requirements of the Tobacco Products Directive (2014/40/EU). Measures taken by economic operators: Action was taken to bring the products into compliance i.e. an information leaflet was supplied to all retailers in the Republic of Ireland to be placed with each unit packet. , Recall of the product from end users (By: Manufacturer) Description: Liquid for e-cigarettes. 18 different flavours (Menthol, Platinum, Sapphire Tobacco, Blackfire, Tutti frutti, Pink Lemonade, Blue Bonbon, Cherry, Strawberry Kiwi & Apple, Strawberry, Cola, Pear Drops, Blueberry, Rollin Blend, Double Menthol, Blacklce, Cherry Menthol); in different coloured packaging Batch number / Barcode: Black ice 12mg/ml Batch Code: 61143 51814 55741 58759 , Blackfire 12mg/ml Batch Code: 57200 61512 , Blackfire 18 mg/ml Batch Code: 57201 61144 55729 , Blackice 18 mg/ml Batch Code: 61144 55908 58759 57191 58759 , Blue Bon Bon 12 mg/ml Batch Code: 51595 58602 , Blue Bon Bon 18mg/ml Batch Code: 55785 43267 55879 , Blueberry 12mg/ml Batch Code: 58652 58952 60447 , Blueberry 18mg/ml Batch Code: 58686 57173, Cherry 12mg/ml Batch Code: 55865 58688 58842, Cherry 18mg/ml Batch Code: 58689 37690 60275, Cherry Menthol 12mg/ml Batch Code: 61089, Cherry Menthol 18mg/ml Batch Code: 58796, Cola 12mg/ml Batch Code: 58442, Cola 18mg/ml Batch Code: 58861 58843 , Menthol 12mg/ml Batch Code: 60956 , Menthol 18mg/ml Batch Code: 60957 , Pear Drops 12mg/ml Batch Code: 60645 58888 , Pear Drops 18mg/ml Batch Code: 58903 53425 58908 , Pink Lemonade 18mg/ml Batch Code: 58997 51504 55766 17596 58551 Pink Lemonade 12mg/ml Batch Code: 51504 58550 , Platinum 12mg/ml Batch Code: 15375 15388 15385 15354 15350 , Platinum 18mg/ml Batch Code: 15378 15351 15376 15389 15355 15351, Rolling Blend 12mg/ml Batch Code: 58888 61552 58668 , Rolling Blend 18mg/ml Batch Code: 58669 61554, Sapphire 12mg/ml Batch Code: 15385 57275 55722 15304, Sapphire 18mg/ml Batch Code: 15311 15302 15386 55729, Strawberry 12mg/ml Batch Code: 58845, Strawberry 18mg/ml Batch Code: 58946, Strawberry Kiwi & Apple 12mg/ml Batch Code: 61054 59013, Strawberry Kiwi & Apple 18mg/ml Batch Code: 59026, Tutti Frutti 12mg/ml Batch Code: 51767 58996 61505, Tutti Frutti 18mg/ml Batch Code:51768 58997

Country of origin: United Kingdom Alert submitted by: Ireland



Alert number: A12/1312/18 Product: Bath thermometer Name: Bath Thermometer Risk type: Choking Category: Childcare articles and children's equipment Brand: ROTHO Type / number of model: Model oops; item number 20057-0001-BJ. Risk level: Serious risk The top part of the thermometer protrudes. A child could put the protruding part in the mouth, which could block the airways and cause choking.

The product does not comply with the relevant national standard. **Measures taken by economic operators:** Recall of the product from end users (By: Distributor) **Description:** Sword-shaped bath thermometer.

Batch number / Barcode: Unknown

Country of origin: Germany

Alert submitted by: France

rotho



Alert number: A12/1321/18 Product: Pushchair Name: Speed plus S night Risk type: Injuries Category: Childcare articles and children's equipment Brand: Hauck Type / number of model: 1356886 Risk level: Serious risk The inclination angle between the backrest and the seat is too small, the pushchair is unstable when the backrest is reclined and an attachment device can break at the back of the pushchair. As a consequence, the pushchair can tip over on an inclined surface or collapse and the child can fall to the ground.

The product does not comply with the relevant European standard EN 1888. Measures ordered by public authorities (to: Importer): Import rejected at border Description: Pushchair with a luggage carrier, a front bar and a canopy. Batch number / Barcode: Unknown Country of origin: China Alert submitted by: France



Alert number: A12/1324/18 Product: Children's high chair Name: Feeding high chair BOBO Risk type: Injuries Category: Childcare articles and children's equipment Brand: Lorelli Type / number of model: Beige Owl, Art. No. 10100271719 Risk level: Serious risk The high chair is not sufficiently stable and can easily tip over backwards. A sitting child may fall and suffer injuries.

The product does not comply with the relevant European standard EN 14988.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market **Description:** White and beige foldable high chair. The seat is decorated with the picture of an owl. Packaging: cardboard box. Maximum load capacity: 15 kg

Batch number / Barcode: 3 800151 938262 Country of origin: China Alert submitted by: Hungary



Alert number: A12/1301/18 Product: Leather bracelet Name: DEV karkötő Risk type: Chemical Category: Clothing, textiles and fashion items Brand: DEVERGO Type / number of model: 1D518088BR2100 Risk level: Serious risk The metal fastener of the bracelet contains lead (measured value: 3.35% by weight). Exposure to lead is harmful for human health.

The product does not comply with the REACH Regulation. Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market Description: Black leather bracelet with metal skull decoration and metal fastener. Packaging: plastic bag Batch number / Barcode: 5996542182647 Country of origin: Unknown Alert submitted by: Hungary



Alert number: A12/1304/18 Product: Babies' clothing set Name: Unknown Risk type: Choking Category: Clothing, textiles and fashion items Brand: Rasiya Type / number of model: Unknown Risk level: Serious risk Small decorative elements (rhinestones) may be easily detached. A small child may put them in the mouth and choke.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market **Description:** White romper suit, with a sewn-on silver crown and 'Princess' inscription, and a cap. The clothing is decorated with pink bows and glued rhinestones. Size: 3-6 M **Batch number / Barcode:** Unknown

Country of origin: Turkey Alert submitted by: Hungary





Alert number: A12/1306/18 Product: Leather bracelet Name: karkötő bőr díszes Risk type: Chemical Category: Clothing, textiles and fashion items Brand: Lora Beauty Type / number of model: 86083 Risk level: Serious risk The amount of chromium (VI) in the leather is too high (measured value: 8 mg/kg). Chromium (VI) is sensitising and may trigger allergic reactions.

The product does not comply with REACH Regulation.

Measures ordered by public authorities (to: Importer): Recall of the product from end users, Withdrawal of the product from the market **Description:** Three-piece leather bracelet with magnetic metal buckle. The product is decorated with coloured stripes and gold coloured rings. **Batch number / Barcode:** 5999095552998 **Country of origin:** China

Alert submitted by: Hungary



Alert number: A12/1307/18 Product: Girls' trousers Name: Unknown Risk type: Choking Category: Clothing, textiles and fashion items Brand: Grace Type / number of model: Art No.G40659 Risk level: Serious risk The small decorative elements of the trousers may be easily detached. A small child could put them in the mouth and choke.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market Description: Beige trousers with pink belt for children. The product is decorated with glued rhinestones. Size: 98 Batch number / Barcode: Unknown Country of origin: China Alert submitted by: Hungary 14/9/2018









The product does not comply with the Cosmetics Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Retailer) Description: Henna products in a green and gold box with an image of henna decorated hands. The box contains a number of similarly branded individual cones which contain the product and are used for application. Batch number / Barcode: Batch Number: 48533, Bar Code: 3574641063016 Country of origin: Pakistan Alert submitted by: Ireland



Alert number: A12/1294/18 Product: USB charger Name: USB-C Home Charger 2A Risk type: Electric shock Category: Electrical appliances and equipment Brand: 4-OK Type / number of model: CLUS2C / RT-29A Risk level: Serious risk The capacitor connected across the reinforced insulation is inadequate. As a consequence, parts of the product can become live.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European Standard EN 60950. **Measures ordered by public authorities (to: Distributor):** Recall of the product from end users **Description:** USB charger in a cardboard box with plastic window **Batch number / Barcode:** 8428728097973 **Country of origin:** China **Alert submitted by:** Finland

Travel Adapter

0.35A 50-60Hz





Alert number: A12/1296/18 Product: USB hub with power supply Name: 7+2 Port USB - HUB 3.0 Risk type: Electric shock Category: Electrical appliances and equipment Brand: goobay Type / number of model: OGD-D507 Risk level: Serious risk The clearance and creepage distance between the primary and accessible secondary circuits are not sufficient. As a consequence, accessible parts of the product may become live.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European Standard EN 60950.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users Description: USB hub with 7+2 ports and power supply, packed in a cardboard box Batch number / Barcode: 4040849678363 Country of origin: China Alert submitted by: Finland



Alert number: A12/1298/18 Product: Power converter Name: Unknown Risk type: Electric shock, Fire Category: Electrical appliances and equipment Brand: US-TRONIC Type / number of model: Model TTR-100-REV 180210 Risk level: Serious risk The product's design enables partial insertion of the pins, thus leaving live parts accessible. Furthermore, conductors in the switch are held in place simply by welding and therefore are not fixed sufficiently.

This could lead to a risk of electric shock or fire.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 61558. **Measures taken by economic operators:** Recall of the product from end users (By: Importer) **Description:** Travel adaptor/power converter used to change 110 V into 220 V **Batch number / Barcode:** Unknown **Country of origin:** China

Alert submitted by: France



Alert number: A12/1300/18 Product: Mobile phone charger Name: Home charger 2.4A Risk type: Electric shock Category: Electrical appliances and equipment Brand: 4-OK Type / number of model: IPCL25 (charger: RT-35) Risk level: Serious risk The electrical insulation is insufficient. The clearance and creat

The electrical insulation is insufficient. The clearance and creepage distances between the primary and secondary circuits are too small. Accessible parts could consequently become live which could result in the user receiving an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950. **Measures ordered by public authorities (to: Distributor):** Recall of the product from end users **Description:** Mobile phone charger in a white printed cardboard box with plastic window. **Batch number / Barcode:** 8428728099847

Country of origin: China

Alert submitted by: Finland



BiPod DiPhone DiPad

Alert number: A12/1302/18 Product: USB charger Name: Home Charger Risk type: Electric shock Category: Electrical appliances and equipment Brand: 4-OK Type / number of model: RT-29 / in packaging: CLMU1N Risk level: Serious risk The insulation and the clearance /creepage distances between the primary and accessible secondary circuits are not sufficient. As a consequence, accessible parts of the product may become live. The product does not comply with the requirements of the Low Voltage Directive and the relevant European Standard EN 60950. Measures ordered by public authorities (to: Distributor): Recall of the product from end users Description: USB charger in a printed cardboard box with plastic window. Batch number / Barcode: 8428728063039 Country of origin: China Alert submitted by: Finland Smartphone [] odel: RT-29 out: AC110-240 - 0,35A 50-60Hz For Indoor use of Made in China

Alert number: A12/1303/18 Product: USB charger Name: Home charger + car charger Risk type: Electric shock Category: Electrical appliances and equipment Brand: 4-OK Type / number of model: DT-09T Risk level: Serious risk The insulation and the clearance /creepage distances between the primary and the accessible secondary circuits are not sufficient. As a consequence, accessible parts of the product may become live. The product does not comply with the requirements of the Low Voltage Directive and the relevant European Standard EN 60950. Measures ordered by public authorities (to: Distributor): Recall of the product from end users Description: Two-in-one USB and car charger, sold in a printed cardboard box with plastic window. Batch number / Barcode: 8428728016721 Country of origin: China Alert submitted by: Finland





Travel Adapter Model: DT-09T Input: ACIO-240 - 0.35A 50-60Hz Output: DC 5.0V == 1A C C D D D For Indoor use only Made in China Alert number: A12/1314/18 Product: Battery charger Name: Nuprol Lipo 3 Risk type: Electric shock Category: Electrical appliances and equipment Brand: Nuprol Ltd Type / number of model: Lipo 3 Risk level: Serious risk The electrical insulation is inadequate. As a result, accessible parts can become live and the user could receive an electric shock from them.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335. **Measures taken by economic operators:** Withdrawal of the product from the market (By: Importer) **Description:** Black battery charger with adaptor, packed in a cardboard box. **Batch number / Barcode:** Unknown

Country of origin: China

Alert submitted by: United Kingdom



Alert number: A12/1315/18 Product: Battery charger/discharger Name: Quattro Risk type: Electric shock Category: Electrical appliances and equipment Brand: Nuprol Ltd Type / number of model: B6AC Risk level: Serious risk The electrical insulation of the charger is inadequate. As a result, accessible parts of the product could become live. The user could receive an electric shock from them.

The continuity resistance of the earth circuit is not ensured.

The product does not comply with the Low Voltage Directive and the relevant European standard EN 60335. **Measures taken by economic operators:** Destruction of the product (By: Importer) **Description:** Red multi charger in its aluminium case. **Batch number / Barcode:** Unknown **Country of origin:** China **Alert submitted by:** United Kingdom



Alert number: A12/1316/18 Product: Battery charger Name: Lipo battery charger Risk type: Electric shock Category: Electrical appliances and equipment Brand: Nuprol Ltd Type / number of model: Nimh 3 Risk level: Serious risk The electrical insulation is inadequate. As a result, accessible parts of the product could become live. The user could receive an electric shock from them.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335. **Measures taken by economic operators:** Destruction of the product (By: Importer) **Description:** Black charger with adaptor, packed in a cardboard box.

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: United Kingdom





Alert number: A12/1317/18 Product: Battery charger Name: Lipo Battery charger Risk type: Electric shock Category: Electrical appliances and equipment Brand: Nuprol Ltd Type / number of model: SM4 Risk level: Serious risk The electrical insulation is inadequate. As a result, accessible parts of the product could become live. The user could receive an electric shock from them.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335. Measures taken by economic operators: Destruction of the product (By: Importer) Description: Black charger with adaptor, packed in a cardboard box. Batch number / Barcode: Unknown Country of origin: China Alert submitted by: United Kingdom



Alert number: A12/1325/18 Product: Hairdryer Name: Professional HairDryer Risk type: Burns, Electric shock, Fire Category: Electrical appliances and equipment Brand: NOVA Type / number of model: N-670 (on the packaging); 16772 / 1200237 (on a label) Risk level: Serious risk The hairdryer does not have a thermal cut-out device. The plastic material of the casing is combustible. The mains cable is not properly anchored. The hair dryer can overheat and catch fire. Melted plastic can cause burns. The mains cable could detach leaving the live conductors accessible. The product does not comply with the Low Voltage Directive and the relevant European standard EN 60335.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market **Description:** Black and red electric hairdryer with removable, transparent reducer part. Packaged in a colourful cardboard box. Batch number / Barcode: 8 039012 002377 ; 6 925979 750012

Country of origin: Unknown

Alert submitted by: Hungary







Alert number: A12/1299/18 Product: LED night light Name: LED Energy Saving Night Light Risk type: Electric shock Category: Lighting equipment Brand: Unknown Type / number of model: HG8739YW, HG8739WT Risk level: Serious risk The night-light cover detaches as soon as the night light is pulled from the socket. As a consequence, live parts become accessible.

The product does not comply with the requirements of the Low Voltage Directive.

Measures taken by economic operators: Removal of the product listings from the Amazon website, Warning consumers of the risks (By: Retailer)

Description: LED night light in the shape of a star, available in white and yellow. The product has been sold online (e.g. via Amazon). **Batch number / Barcode:** Serial Nos: 411L-1374, 438L-0772, 0773; year of manufacture: 2018

Country of origin: China

Alert submitted by: Germany







Alert number: A12/1326/18 Product: LED floodlight Name: LED FLOOD LIGHT Outdoor 10W Risk type: Electric shock Category: Lighting equipment Brand: Unknown Type / number of model: PRO-02637 – BOP-157; DVY-01361 (on the label of packaging) Risk level: Serious risk The product has no earth connection. The external wires are PVC-insulated. The cables are not properly anchored and are in contact with sharp parts. The protection against water ingress is insufficient. The user could consequently touch live parts and receive an electric shock from accessible live parts.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598. **Measures ordered by public authorities (to: Distributor):** Recall of the product from end users, Withdrawal of the product from the market **Description:** Remote controlled RGB LED floodlight (fixed luminaire). Packaging: colourful cadboard box.

Batch number / Barcode: Unknown

Country of origin: Unknown

Alert submitted by: Hungary



Alert number: A12/1297/18 Product: Passenger car Name: Insignia B Risk type: Fire Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e8*2007/46*0264*01, e8*2007/46*0264*02, e8*2007/46*0264*03, e8* e8*2007/46*0264*05; type: Z-B Risk level: Serious risk Defective sealing may lead to moisture penetrating the central locking control unit. This could result in a short-circuit and the melting of the door-locking plug, possibly leading to a fire. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car Batch number / Barcode: The vehicles affected were produced between February 2017 and March 2018. Country of origin: Germany Alert submitted by: Germany Alert number: A12/1310/18	2007/46*0264*04,
Product: Passenger car	
Name: 2, CX-3, MX-5	
Risk type: Fire	
Category: Motor vehicles	
Brand: Mazda	
Type / number of model: Type-approval number: Mazda MX-5: e11*2007/46*2661*00 - e11*2007/46*2661*01 Mazda CX - e1*2007/46*1335*11 Mazda2: e1*2007/46*1335*01 - e1*2007/46*1335*12 TYP: ND, DJ1 Risk level: Serious risk	<-3: e1*2007/46*1335*03
The engine control unit of the direct-current converter may be defective.	
This could result in a short circuit and damage of the converter, which can lead to a fire.	
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)	
Description: Passenger car	
Batch number / Barcode: The vehicles in question were manufactured between 5 August 2014 and 24 April 2017.	
Country of origin: Japan	
Alert submitted by: Germany	
Alert number: A12/1313/18 Product: Van Name: Sprinter Risk type: Injuries Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Type-approval numbers:e1*2001/116*0354, e1*2007/46*0296*0301 Type: 906 AC 35, 906 BB = Risk level: Serious risk The exit assistance system deactivates prematurely after switching off the ignition. As a consequence, there is no warning when exiting the vehicle in dangerous situations. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Van Batch number / Barcode: The vehicles in question were manufactured between 4 December 2017 and 20 June 2018. Country of origin: Germany Alert submitted by: Germany Products were found and measures were taken also in: The Netherlands Alert number: A12/1319/18	50, 906 BB 35
Product: Passenger car Name: Polo, Up	
Risk type: Injuries	
Category: Motor vehicles	
Category: Motor vehicles	
Category: Motor vehicles Brand: VW	
Category: Motor vehicles Brand: VW Type / number of model: Approval No: e1*2001/116*0510*##, e13*2007/46*1167*13; Type: 6R, AA Risk level: Serious risk A poorly welded towing eye may have been included in the vehicle's tool kit.	
Category: Motor vehicles Brand: VW Type / number of model: Approval No: e1*2001/116*0510*##, e13*2007/46*1167*13; Type: 6R, AA Risk level: Serious risk A poorly welded towing eye may have been included in the vehicle's tool kit. As a consequence, it could break off during towing and the vehicle being towed would lose forward propulsion and, on been	coming detached, the
Category: Motor vehicles Brand: VW Type / number of model: Approval No: e1*2001/116*0510*##, e13*2007/46*1167*13; Type: 6R, AA Risk level: Serious risk A poorly welded towing eye may have been included in the vehicle's tool kit. As a consequence, it could break off during towing and the vehicle being towed would lose forward propulsion and, on bee towing rope may hit people or objects.	coming detached, the
Category: Motor vehicles Brand: VW Type / number of model: Approval No: e1*2001/116*0510*##, e13*2007/46*1167*13; Type: 6R, AA Risk level: Serious risk A poorly welded towing eye may have been included in the vehicle's tool kit. As a consequence, it could break off during towing and the vehicle being towed would lose forward propulsion and, on beet towing rope may hit people or objects. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)	coming detached, the
Category: Motor vehicles Brand: VW Type / number of model: Approval No: e1*2001/116*0510*##, e13*2007/46*1167*13; Type: 6R, AA Risk level: Serious risk A poorly welded towing eye may have been included in the vehicle's tool kit. As a consequence, it could break off during towing and the vehicle being towed would lose forward propulsion and, on ber towing rope may hit people or objects. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car.	coming detached, the
Category: Motor vehicles Brand: VW Type / number of model: Approval No: e1*2001/116*0510*##, e13*2007/46*1167*13; Type: 6R, AA Risk level: Serious risk A poorly welded towing eye may have been included in the vehicle's tool kit. As a consequence, it could break off during towing and the vehicle being towed would lose forward propulsion and, on bee towing rope may hit people or objects. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Batch number / Barcode: The vehicles affected were produced between 1/10/2015 and 29/10/2017.	coming detached, the
Category: Motor vehicles Brand: VW Type / number of model: Approval No: e1*2001/116*0510*##, e13*2007/46*1167*13; Type: 6R, AA Risk level: Serious risk A poorly welded towing eye may have been included in the vehicle's tool kit. As a consequence, it could break off during towing and the vehicle being towed would lose forward propulsion and, on bee towing rope may hit people or objects. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Batch number / Barcode: The vehicles affected were produced between 1/10/2015 and 29/10/2017. Country of origin: Germany, South Africa	coming detached, the
Category: Motor vehicles Brand: VW Type / number of model: Approval No: e1*2001/116*0510*##, e13*2007/46*1167*13; Type: 6R, AA Risk level: Serious risk A poorly welded towing eye may have been included in the vehicle's tool kit. As a consequence, it could break off during towing and the vehicle being towed would lose forward propulsion and, on ber towing rope may hit people or objects. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Batch number / Barcode: The vehicles affected were produced between 1/10/2015 and 29/10/2017.	coming detached, the

Alert number: A12/1320/18	
Product: Van	
Name: Expert 4	
Risk type: Injuries	
Category: Motor vehicles	
Brand: Peugeot	
Type / number of model: Type aproval numbers: e2*2007/46*0533*00, e2*2007/46*0533*01, e2*2007/46*0533*02, e2*2007/46*0533*03	
Risk level: Serious risk	
The tow hitch bracket can deform when it is placed under maximum pressure.	
This may affect the driving behaviour of the vehicle and/or the retention of the trailer, which could lead to accidents.	
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)	
Description: Van	
Batch number / Barcode: The vehicles affected were produced between 21/01/2016 and 05/10/2017 - VIN numbers: VF3VBBHVBFZ057363	3 to
VF3VFAHXHHZ080425	
Country of origin: France	
Alert submitted by: France	
Alert number: A12/1323/18	
Product: Passenger car	
Name: Range Rover PHEV and Range Rover Sport PHEV	
Risk type: Injuries	
Category: Motor vehicles	
Brand: Land Rover	
Type / number of model: Type approval number: E11*2007/46*0649 and E11*2007/46*0909 (sport) Model: 2018 and 2019 PHEV (plug-in hy	vbrid
electric vehicle)	
Risk level: Serious risk	
The fuel level gauge does not work properly and will not indicate actual fuel levels below 30%.	
The car could run out of fuel inadvertiently, causing an engine stall which could lead to an accident	
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)	
Description: Hybrid passenger car	
Batch number / Barcode: The vehicles affected were produced between 28/03/2017 and 25/05/2018	
Country of origin: United Kingdom	
Alert submitted by: United Kingdom	
Alert number: A12/1327/18	
Product: Passenger car	
Name: C-HR Hybrid, Prius and Prius Plug-in	
Risk type: Fire	
Category: Motor vehicles	
Brand: Toyota	
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approva	al
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approva number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641.	al
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approva number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk	
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approva number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641.	
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approva number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk	
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approval number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a port of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time	rtion
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approva number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a por of the wire harness could contact the cover.	rtion
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approval number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a port of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time	rtion
 Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approval number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a por of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, causing an electrical short circuit to occur between the damaged wires and generate heat. If sufficient heat is 	rtion
Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approval number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a port of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, causing an electrical short circuit to occur between the damaged wires and generate heat. If sufficient heat is generated, there is an increased risk of fire. Measures taken by economic operators: Recall of the product from end users (By: Importer)	rtion
 Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approver number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a port of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, causing an electrical short circuit to occur between the damaged wires and generate heat. If sufficient heat is generated, there is an increased risk of fire. Measures taken by economic operators: Recall of the product from end users (By: Importer) Description: Passenger car. 	rtion
 Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approver number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a port of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, causing an electrical short circuit to occur between the damaged wires and generate heat. If sufficient heat is generated, there is an increased risk of fire. Measures taken by economic operators: Recall of the product from end users (By: Importer) Description: Passenger car. Batch number / Barcode: Production Period: C-HR Hybrid (26/05/2016 - 08/05/2018), Prius (01/07/2015 - 15/05/2018) and Prius Plug-in 	rtion
 Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approver number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a port of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, causing an electrical short circuit to occur between the damaged wires and generate heat. If sufficient heat is generated, there is an increased risk of fire. Measures taken by economic operators: Recall of the product from end users (By: Importer) Description: Passenger car. Batch number / Barcode: Production Period: C-HR Hybrid (26/05/2016 - 08/05/2018), Prius (01/07/2015 - 15/05/2018) and Prius Plug-in (23/03/2016 - 14/05/2018). 	rtion
 Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approver number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a port of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, causing an electrical short circuit to occur between the damaged wires and generate heat. If sufficient heat is generated, there is an increased risk of fire. Measures taken by economic operators: Recall of the product from end users (By: Importer) Description: Passenger car. Batch number / Barcode: Production Period: C-HR Hybrid (26/05/2016 - 08/05/2018), Prius (01/07/2015 - 15/05/2018) and Prius Plug-in (23/03/2016 - 14/05/2018). Country of origin: Japan 	rtion
 Brand: Toyota Type / number of model: - Model Name (Model Code): C-HR Hybrid (ZYX10), Prius (ZVW50) and Prius Plug-in (ZVW52); - EC-type approver number: e11*2007/46*2971, e11*2007/46*3704, e11*2007/46*3641. Risk level: Serious risk The engine wire harness has a cover attached where it is connected to the hybrid vehicle Power Control Unit. Due to assembly variation, a port of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, causing an electrical short circuit to occur between the damaged wires and generate heat. If sufficient heat is generated, there is an increased risk of fire. Measures taken by economic operators: Recall of the product from end users (By: Importer) Description: Passenger car. Batch number / Barcode: Production Period: C-HR Hybrid (26/05/2016 - 08/05/2018), Prius (01/07/2015 - 15/05/2018) and Prius Plug-in (23/03/2016 - 14/05/2018). 	rtion

Alert number: A12/1328/18 Product: Motorcycle Name: Street Triple Risk type: Injuries Category: Motor vehicles Brand: Triumph Type / number of model: Type aproval number: e11*168/2013*00248*01 Modell: Street Triple R and Street Triple RS Risk level: Serious risk The electrical circuits in the left hand switch cube are sealed incorrectly. This can cause moisture to penertrate the cube, which can cuase malfunctioning of the turn signal indicator and headlamp control switches, and lead to an accident. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Motorcycle of the Roadster range. Batch number / Barcode: The affected vehicles were manufactured between 31 March 2017 and to 04 January 2018. Serial Numbers: from 831983 to 873231 Country of origin: United Kingdom Alert submitted by: United Kingdom Products were found and measures were taken also in: Poland, The Netherlands Alert number: A12/1318/18 Product: Pressure cooker

Name: Autocuiseur 7L Risk type: Burns Category: Pressure equipment/vessels Brand: NEW KOOL'OR / Bäcken Type / number of model: Design DSW 22-7L Risk level: Serious risk It is possible to open the pressure cooker while it is still under steam pressure. This can cause burns to users.

The product does not comply with the requirements of the pressure equipment directive and the relevant European standard EN 12778. **Measures ordered by public authorities (to: Manufacturer):** Recall of the product from end users **Description:** Pressure cooker with jaws.

Batch number / Barcode: 3 612403821167 Country of origin: China Alert submitted by: France







Alert number: A12/1309/18 Product: Water bullet gun Name: Crystal Fighter Risk type: Choking, Injuries Category: Toys Brand: Unknown Type / number of model: NO-1000697 Risk level: Serious risk The bullets expand in size by more than 50% when placed in water. If the small bullets are put into the mouth by children and swallowed by children, they could expand causing fatal occlusion of the respiratory tract or intestinal blockage. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Measures taken by economic operators: Withdrawal of the product from the market (By: Importer) Description: Plastic, battery-powered, toy gun which shoots water bullets. The bullets need to be soaked in water before shooting. Packed in a cardboard box with a plastic window. Batch number / Barcode: EAN: 5902444006974

Country of origin: China

Alert submitted by: Poland



Alert number: A12/1311/18 Product: Balloons Name: Party ballonnen Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: Art 1542745 Risk level: Serious risk The amount of nitrosamines (0.68 mg/kg) released by the balloons is too high. Nitrosamines are carcinogenic via inhalation, ingestion or dermal exposure. A child can get exposed to them by putting the balloon in the mouth.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-12. **Measures ordered by public authorities:** Withdrawal of the product from the market **Description:** Balloons, 8 pieces, in a plastic bag with label.

Batch number / Barcode: 8718827055821

Country of origin: Unknown

Alert submitted by: The Netherlands



Alert number: A12/1322/18 Product: Plastic doll Name: Baba figura kulcstartó Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: No.0830/1400487 Risk level: Serious risk The plastic material of the doll's head contains 2-ethylhexyl phthalate (DEHP) (measured value: 31 % by weight).

This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market **Description:** 25 cm tall plastic dolls attached with a key-ring.

Batch number / Barcode: 8013614004878 Country of origin: China

Alert submitted by: Hungary





Alert number: A11/0067/18 Product: Visibility vest Name: Ortona Risk type: Injuries Category: Protective equipment Brand: Unknown Type / number of model: WX-B1001 Risk level: Other risk level The reflectance of the vest is inadequate. As a result, the user is not sufficiently visible in situations where high visibility is essential.

The product does not comply with the requirements of the Personal Protective Equipment Directive and the relevant European standard EN ISO 20471.

Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market Description: Orange visibility vest with two reflective stripes. Packaged in a transparent plastic bag. Batch number / Barcode: Size: XL, cat. II, color: orange. Country of origin: China

Alert submitted by: Poland

