An official EU website



CONSUMERS

- * Safety Gate home (https://ec.europa.eu/consumers/consumers safety/safety products/rapex/alerts/repository/content/pages/rapex/index en.htm)
- I Back to report listings (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2021&Ing=er
- Q Search alerts (https://ec.europa.eu/consumers/consumers safety/safety products/rapex/alerts/?event=main.search&Ing=en)
- IPSW (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=ipsw:home)

The Rapid Alert System for Non-Food Products (RAPEX)

RAPEX - Weekly overview report of notifications

Week 6 - 2021

At the request of the notifying authority, notification A11/00005/21 has been upgraded to serious risk with the new reference number A12/00192/21 on 12 February 2021.

Alert number: A12/00175/21

Product: Chair Name: Office chair Risk type: Injuries Category: Furniture

Brand:

Type / number of model: 6130

Type of alert: Products with serious risks

The chair is not sufficiently stable and the rolling resistance is too low. The chair can consequently easily overturn, leading to the user falling and suffering injuries. / The product does not comply with the relevant European standard EN 1335-2.

Withdrawal of the product from the market

Description: Height-adjustable work chair with armrests, soft seat and backrest, with plastic base and a regular five-beam star shape and a gas seat height-adjustable lift, rotating around a vertical axis. The work chair has a seat tilting device. The product was also sold online.

Batch number / Barcode: 4772013064985

NO

Country of origin: People's Republic of China

Alert submitted by: Lithuania







Alert number: A12/00154/21 Product: Training Bar Name: Multi Training Bar Risk type: Environment

Category: Hobby/sports equipment

Brand: Kettler

Type / number of model: 07361-600
Type of alert: Products with serious risks

The product contains short-chain chlorinated paraffins (SCCPs) (measured value 13000 mg/kg). SCCPs remain in the environment and are toxic to aquatic life in low concentrations. They bioaccumulate in humans and animals and thus pose a risk to human health and to the environment. / The product does not comply with the Regulation on persistent organic pollutants (POPs),

Ban on the marketing of the product and any accompanying measures

Description: Workout tool

Batch number / Barcode: 4001397470656

NO

Country of origin: People's Republic of China

Alert submitted by: Luxembourg















Alert number: A12/00182/21 Product: Training Bracelet Name: Smart Bracelet

Risk type: Chemical, Environment Category: Hobby/sports equipment

Brand: Smart Bracelet

Type / number of model: Training Bracelet/TW64

Type of alert: Products with serious risks

The plastic of the charger cord contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP)(measured values up to 1,8% and 0,6% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product also contains short chain chlorinated paraffins (SCCPs) (measured value 17000 mg/kg). The placing on the market and use of articles containing SCCPs is banned. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bioaccumulate in wildlife and humans, posing a risk to human health and the environment. / The product does not comply with REACH Regulation and with Regulation on Persistent Organic Pollutants (POPs).

Withdrawal of the product from the marketRemoval of this product listing by the online marketplace

Description: Green training bracelet.

Batch number / Barcode:

UNKNOWN

Country of origin: Unknown Alert submitted by: Norway







Alert number: A12/00155/21

Product: Earrings

Name: Vintage Bohemian New Design Hook Women Retro Ethnic Drop Dangle Gypsy Earrings

Risk type: Chemical Category: Jewellery Brand: Fashion Jewelry Type / number of model:

Type of alert: Products with serious risks

The product contains an excessive amount of cadmium (measured values up to: 95.5% by weight). Cadmium is harmful to human health because it accumulates in the body, can damage the kidney and bones, and it may cause cancer. / The product does not comply with the REACH Regulation.

Recall of the product from end users, Withdrawal of the product from the market

Description: Silver coloured dangle earrings with blue stone. The product was also sold online, in particular via eBay.

Batch number / Barcode:

NO

Country of origin: People's Republic of China

Alert submitted by: Sweden



Alert number: A12/00156/21

Product: Earrings

Name: Antique Fashion Tribal Ethnic Ethnic Indian Jewelry Women Drop Tassle Earrings

Risk type: Chemical Category: Jewellery Brand: Fashion Jewelry Type / number of model:

Type of alert: Products with serious risks

The product contains an excessive amount of cadmium (measured values up to: 92.9% by weight). Cadmium is harmful to human health because it accumulates in the body, can damage the kidney and bones, and it may cause cancer. / The product does not comply with the REACH Regulation.

Recall of the product from end users, Withdrawal of the product from the market

Description: Brass coloured metal earrings. The product was also sold online, in particular via eBay.

Batch number / Barcode:

NO

Country of origin: People's Republic of China

Alert submitted by: Sweden



Alert number: A12/00157/21

Product: Ring

Name: Quality Antique Bronze Copper Rose Retro Funky Kit

Risk type: Chemical Category: Jewellery

Brand:

Type / number of model:

Type of alert: Products with serious risks

The product contains an excessive amount of cadmium (measured values up to: 87% by weight). Cadmium is harmful to human health because it accumulates in the body, can damage the kidney and bones, and it may cause cancer. / The product does not comply with the REACH Regulation.

Recall of the product from end users, Withdrawal of the product from the market

Description: Gold coloured metal ring shaped like a flower. The product was also sold online, in particular via eBay.

Batch number / Barcode:

NO

Country of origin: People's Republic of China

Alert submitted by: Sweden



Alert number: A12/00158/21 Product: Necklace with pendant

Name:

Risk type: Chemical Category: Jewellery Brand: Fashion Jewellery Type / number of model:

Type of alert: Products with serious risks

The pendant contains an excessive amount of cadmium (measured values up to: 68% by weight). Cadmium is harmful to human health because it accumulates in the body, can damage the kidney and bones, and it may cause cancer. / The product does not comply with the REACH Regulation.

Withdrawal of the product from the marketOther

Description: Golden necklace with a 4 cm-long pendant in the shape of a horse. Decorated with stones (glass?) in purple. The product was also sold online.

Batch number / Barcode:

UNKNOWN

Country of origin: Unknown Alert submitted by: Denmark



Alert number: A12/00168/21 Product: Portable LED lamp

Name: Super Bright Hand Crank Solar LED Lantern / Kemping fény

Risk type: Burns, Electric shock, Fire Category: Lighting equipment

Brand:

Type / number of model: LS-360
Type of alert: Products with serious risks

The cables inside the mains power cord are too thin. They could overheat during use. The insulation and size of the pins of the mains plug and output connector are inappropriate, leaving live parts accessible. The plastic part of the integrated plug of the luminaire is made of combustible material. Live parts may become accessible without the use of any tools. User may consequently suffer burns, receive an electric shock or the product may cause a fire. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Import rejected at border

Description: Black and gray rechargeable and portable camping lamp with 36 LEDs, which can be operated directly from the mains, car charger, batteries, crank dynamo or by the solar module. It is supplied with a mains and a car charger.

Batch number / Barcode: 8 595501 654569

NC

Country of origin: People's Republic of China

Alert submitted by: Hungary









Alert number: A12/00170/21 Product: LED music bulb Name: LED MUSIC BULB/APP Risk type: Electric shock Category: Lighting equipment

Brand:

Type / number of model: DLS-6

Type of alert: Products with serious risks

The lamp shade can be removed easily while the lamp is connected to the lamp holder. The Insulation of touchable metal parts is inadequate. A user could touch live parts and receive an electric shock. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 62560.

Import rejected at border

Description: Remote-controlled LED lamp with built in loudspeaker that can play music via bluetooth.

Batch number / Barcode: 8 595578 910162

NO

Country of origin: People's Republic of China

Alert submitted by: Hungary











Alert number: A12/00176/21

Product: Pneumatic powered gates for use in milking parlour

Name:

Risk type: Entrapment Category: Machinery

Brand: Dairymaster, Dairymaster Air Back Gate

Type / number of model:

Type of alert: Products with serious risks

There are gaps in the structure pneumatic powered gate where the user may get parts of the body entrapped. / The product does not comply with

the requirements of the Machinery Directive

Making the marketing of the product subject to prior conditions

Description: Gate for animals' control in Milking parlour powered by compressed air.

Batch number / Barcode:

NO

Country of origin: Ireland
Alert submitted by: Ireland



Alert number: A12/00148/21 Product: Passenger car Name: C3, C4, DS3, DS4, DS5

Risk type: Injuries Category: Motor vehicles Brand: Citroen, DS

Type / number of model: Types: S, N, K, e2*2007/46*0003*00 - *45; e2*2007/46*0040*02 - *29 e2*2007/46*0060*08 - *09; *15; e2*2007/46*0079*04 - *05 e2*2007/46*0092*01 - *16 e2*2007/46*0156*01 e2*KS07/46*0004*00 - *03 - *09, e2*KS07/46*0005*00 - *01

e24*2007/46*0019*02 - *03 e24*2007/46*0027*00 e24*2007/46*0028*00 e11*2007/46*0113*06 TR*2007/46*8360*00

Type of alert: Products with serious risks

The gas generator of the driver and/or front-seat passenger airbag could be defective. This may result in uncontrolled inflation and the release of metal fragments when the airbag is activated, causing injury to the occupants of the vehicle. /

Recall of the product from end users

Description: Passenger car Batch number / Barcode: GYY

NO

Country of origin: France Alert submitted by: Germany

Products were found and measures were taken also in: Croatia, Poland, Slovenia, Sweden

Alert number: A12/00149/21 Product: Passenger car Name: C-Class, EQC, GLC Risk type: Fire, Injuries Category: Motor vehicles Brand: MERCEDES-BENZ

Type / number of model: Type-approval numbers: e1*2001/116*0431*55-58, e1*2001/116*0457*46-49, e1*2001/116*0480*35-36, Types: 204,

204 K, 204 X

Type of alert: Products with serious risks

The wiring harness for the steering control device may have been damaged during the production process and can allow moisture to ingress into the control unit. This may lead to the loss of electric steering support, increasing the risk of accident. Moreover, a short circuit of the damaged

wiring harness can occur, leading to increased risk of fire. /

Recall of the product from end users

Company recall page: https://www.mercedes-benz.de (https://www.mercedes-benz.de) Description: Model series: C class (BR 205), GLC (BR 253) and EQC (BR 293).

Batch number / Barcode: 5491022

NO

Country of origin: Germany Alert submitted by: Germany

Products were found and measures were taken also in: Croatia, Greece, Poland

Alert number: A12/00150/21

Product: Caravan Name: Averso Risk type: Injuries Category: Motor vehicles

Brand: Bürstner

Type / number of model: Typ lt.Typgen.: E-2007/46, T-2007/46, Typgenehmigungsnummer: e13*2007/46*1873*06, e13*2007/46*1877*03

Type of alert: Products with serious risks

Parts of the rear panelling may not be adequately affixed. As a result, they could become detached and fall onto the road, posing a risk to the

following traffic. /

Recall of the product from end users

Description: Caravan

Batch number / Barcode: 512-771/10228/20

NO

Country of origin: Germany Alert submitted by: Germany

Alert number: A12/00151/21 Product: Motorhome

Name: Euroline, Business Edition

Risk type: Injuries
Category: Motor vehicles

Brand: Westfalia

Type / number of model: e13*KS07/46*1471*01, Type: 81BE

Type of alert: Products with serious risks

The gas pressure springs of the seats could be defective. This may lead to inadequate seat-locking, increasing the risk of injury. /

Recall of the product from end users

Description: Motorhome

Batch number / Barcode: W20S02

NO

Country of origin: Germany
Alert submitted by: Germany

Alert number: A12/00152/21 Product: Passenger car

Name: S-Class Risk type: Injuries Category: Motor vehicles Brand: MERCEDES-BENZ

Type / number of model: e1*2007/46*2115*01, Type: R2S

Type of alert: Products with serious risks

The internal tie rods used for the front axle steering may not have been intended for the type of vehicle, and thus, could be too short. In such a case, the rods could be bent or pulled out in the event of an additional, sudden force. This would impair the steerability of the vehicle, increasing

the risk of an accident. /

Recall of the product from end users

Company recall page: https://www.mercedes-benz.de/ (https://www.mercedes-benz.de/)

Description: Model series BR 223. Batch number / Barcode: 4691005

NO

Country of origin: Germany
Alert submitted by: Germany

Products were found and measures were taken also in: Poland

Alert number: A12/00153/21 Product: Buses and lorries

Name: TGS, TGX, TGM, TGL, Lions Coach

Risk type: Injuries Category: Motor vehicles

Brand: MAN

 $Type \ / \ number \ of model: \ Models: B.2007.46.006, L.2007.46.001, L.2007.46.003, TGL02, L.2007.46.011, L.2007.46.009, L.2007.46.013, \\ L.2007.46.009, B.2007.46.006, Type-approval numbers: e4*2007/46*0099*12, e4*2007/46*0229*38, e4*2007/46*0231*08, *17, *07, L673*00, *09, *05, 7, e4*2007/46*0239*11, *29, *23, *38, *09, *26, *35, *37, *28, *24, L674*06, *01, , e4*2007/46*0237*35, e4*2007/46*0418*36, \\ Type \ / \ number \ of model: Models: B.2007.46.006, L.2007.46.001, L.2007.46.003, TGL02, L.2007.46.001, L.2007.46.009, L.2007.46.003, L.2007.46.003, L.2007.46.003, TGL02, L.2007.46.001, L.2007.46.009, L.2007.46.003, L.2007.46.003, TGL02, L.2007.46.001, L.2007.46.009, L.2007.46.003, L.2007.46.003, TGL02, L.2007.46.003, L.2007.46.003, TGL02, L.2007.46.003, TGL02, L.2007.46.003, L.2007.46.003, L.2007.46.003, TGL02, L.2007.46.003, TGL02, L.2007.46.003, L.2007.46.003, L.2007.46.003, L.2007.46.003, TGL02, L.2007.4$

e4*2007/46*0237*37, e4*2007/46*0099*36 Type of alert: Products with serious risks

The fatigue strength of the trailer coupling device marked 'FFV' may be inadequate due to an anomaly in the manufacturer's tempering process.

As a result, the device could crack and break, increasing the risk of an accident.

Recall of the product from end users
Description: Buses and lorries
Batch number / Barcode: TI 7193TA

NO

Country of origin: Germany Alert submitted by: Germany

Alert number: A12/00162/21 Product: Passenger car

Name: X

Risk type: Injuries Category: Motor vehicles

Brand: Tesla

Type / number of model: e4*2007/46*0667*09, *10, *11; Type: 002

Type of alert: Products with serious risks

Due to defective adhesive bonding, a decorative trim strip may become detached from the vehicle. Consequently, in may fall onto the road, posing a risk to the following traffic /

Recall of the product from end users

Company recall page: https://www.tesla.com/support/annual-and-recall-service?redirect=no (https://www.tesla.com/support/annual-and-recall-service?redirect=no)

Description:

Batch number / Barcode: SB-20-12-005

NO

Country of origin: United States Alert submitted by: Germany Alert number: A12/00163/21 Product: Passenger car

Name: Jeep: Gladiator, Wrangler; Dodge: RAM 1500 Pickup Truck, RAM 2500 Pickup Truck

Risk type: Injuries Category: Motor vehicles Brand: Jeep, Dodge

Type / number of model: Type-approval number: Individual approval

Type of alert: Products with serious risks

The seat-belt retractors could be defective. As a result, their restraining effect in the event of an accident cannot be guaranteed, increasing the

risk of injury. /

Recall of the product from end users

Description:

Batch number / Barcode: W67

NO

Country of origin: United States Alert submitted by: Germany

Alert number: A12/00165/21 Product: Passenger car

Name: Sorento (MQ4), Sorento Hybrid (MQ4 HEV)

Risk type: Injuries Category: Motor vehicles

Brand: KIA

Type / number of model: e4*2007/46*1530*00 Type of alert: Products with serious risks

The eCall system (transmitting the vehicle identification number to the emergency call center) could malfunction and not transmit the VIN number of the affected vehicle when an airbag has been deployed. This can cause a delay in the rescue intervention, leading to increased risk of injury.

Recall of the product from end users

Description: Passenger car Batch number / Barcode:

NO

Country of origin: Republic of Korea Alert submitted by: Belgium

Products were found and measures were taken also in: Germany, Poland, Slovakia, Sweden

Alert number: A12/00166/21 Product: Passenger car

Name: XC40 Risk type: Injuries Category: Motor vehicles

Brand: VOLVO

Type / number of model: e9*2007/46*3146*07, e9*2007/46*3146*08

Type of alert: Products with serious risks

Two brake booster nuts are not tightened with the correct torque. This could over time reduce brake performance, increasing the risk of an

accident. /

Recall of the product from end users Description: Passenger car Batch number / Barcode: R10070

NO

Country of origin: Sweden Alert submitted by: Belgium

Products were found and measures were taken also in: Greece, Slovakia, Sweden

Alert number: A12/00177/21

Product: Lorry
Name: Actros, Arocs
Risk type: Injuries
Category: Motor vehicles
Brand: MERCEDES-BENZ

Type / number of model: Models: 963-0-A, 963-4-A, 963-0-C, 963-4-C, 963-0-D, 963-7-E, 963-4-E, Type-approval numbers: e1*2007/46*0726,

e1*2007/46*0727, e1*2007/46*0732, e1*2007/46*0734, e1*2007/46*0735, e1*2007/46*0736, e1*2007/46*0737

Type of alert: Products with serious risks

Due to a damaged socket spanner, the four nuts of the battery-device carrier might not have been fastened at the required torque. As a result, the bolt connections could become detached from the vehicle frame increasing the risk of accidents.

Recall of the product from end users

Description: Lorry

Batch number / Barcode: BGT-SCHR

NO

Country of origin: Germany
Alert submitted by: Germany

Products were found and measures were taken also in: Poland

Alert number: A12/00178/21

Product: Bus

Name: Lion's City: A21, A23, 12C

Risk type: Injuries Category: Motor vehicles

Brand: MAN

Type / number of model: Type-approval numbers: e1*2007/46*1955*03, e4*2007/46*0202*34,*35,*39, e4*2007/46*0250*35, Models:

B.2007.46.017, B.2007.46.010, B.2007.46.012 Type of alert: Products with serious risks

A grease used to lubricate mechanical components within the pressure relief device may harden in the event of prolonged exposure to high heat.

Hardened grease prevents the controlled emergency venting of tanks, leading in the worst case to the gas tank exploding. In such a case, damage to property and/or personal injury cannot be excluded.

Recall of the product from end users

Description: Bus

Batch number / Barcode: TI 7312TR

NO

Country of origin: Poland Alert submitted by: Germany

Alert number: A12/00179/21

Product: Passenger van / Light commercial vehicle

Name: Sprinter Risk type: Injuries Category: Motor vehicles Brand: Mercedes-Benz

Type / number of model: Type-approval numbers: e1*2001/116*0354*25 -26, e1*2001/116*0424*17, e1*2007/46*0296*13-14,

e1*2007/46*0301*20-21, e1*2007/46*0304*08, e1*2007/46*0305*13, e1*2007/46*1760*01-04, Types: 906 AC 35, 906 AC 35/4x4, 906BB50,

906BB35, 906BB50/4x4, 906BB35/4x4, KL3A4 Type of alert: Products with serious risks

Due to a production error and the possible ageing of the materials, brake fluid may leak from the brake hose. As a result, the braking performance

may be impaired, increasing the risk of an accident. /

Recall of the product from end users

Description: Passenger van / Light commercial vehicle Batch number / Barcode: VS3MONTLAU (4296091)

NO

Country of origin: Germany Alert submitted by: Germany

Products were found and measures were taken also in: Croatia, Greece, Sweden

Alert number: A12/00180/21 Product: Passenger car Name: Chiron, Divo Risk type: Injuries Category: Motor vehicles

Brand: Bugatti

Type / number of model: Type-approval numbers: e1*KS07/46*0008*05 - e1*KS07/46*0008*13, Type: 5B

Type of alert: Products with serious risks

The rear left-hand drive shaft may be affected by a functional defect. As a result, it may fail, increasing the risk of an accident. /

Recall of the product from end users

Description: Passenger car.

Batch number / Barcode: BUGCR032

NO

Country of origin: France Alert submitted by: Germany

Alert number: A12/00181/21
Product: Passenger car

Name: Tiguan Risk type: Injuries Category: Motor vehicles

Brand: VW

Type / number of model: Type-approval number: e1*2001/116*0450*, Type: 5N

Type of alert: Products with serious risks

Due to to errors in the adhesive bonding process, the upper rear (roof) spoiler may be insufficiently affixed. As a result, it can become detached

from the vehicle and fall onto the road, posing a risk to the following traffic. /

Recall of the product from end users Description: Tiguan R-Line vehicles. Batch number / Barcode: 66M3

NO

Country of origin: Germany Alert submitted by: Germany

Products were found and measures were taken also in: Iceland, Sweden

Alert number: A12/00192/21 Product: Shock-absorber Name: Eurorepar

Risk type: Injuries
Category: Motor vehicles
Brand: Eurorepar

Type / number of model:

Type of alert: Products with serious risks

Risk: the anti-roll bracket may be wrenched off. This will cause the vehicle's steering system may vibrate, increasing the risk of an accident. /

Recall of the product from end users

Description: Shock-absorber; batch numbers of the defective items: 1832, 1836,1840, 1904, 1909, 1911, 1913, 1916 and 1917.

Batch number / Barcode:

NO

Country of origin: Tunisia Alert submitted by: France

Alert number: A12/00160/21

Product: Soother holder clip with cord

Name: Speenketting Risk type: Choking

Category: Childcare articles and children's equipment

Brand: Bezisa

Type / number of model: Leather in different colours

Type of alert: Products with serious risks

The clip of the soother holder is easily detached. A child could put it in the mouth and choke on it. / The product does not comply with the relevant

European standard EN 12586. Recall of the product from end users

Description: Soother holder cord made of leather, in various colors, with a metal clip. The product was also sold online.

Batch number / Barcode:

NO

Country of origin: The Netherlands
Alert submitted by: The Netherlands



Alert number: A12/00171/21

Product: Firework Name: Powershot 9

Risk type: Burns, Damage to sight, Injuries

Category: Pyrotechnic articles Brand: Fyrværkerieksperten

Type / number of model: CE registration number: 0200-F2-0084, Dess. 07346.6340

Type of alert: Products with serious risks

The product may explode at too low altitude and can burst too close to the ground. Bystanders can be hit by parts of the firework, causing burns and/or damage to sight. / The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

Withdrawal of the product from the market Description: 9-shot battery of shot tubes.

Batch number / Barcode:

NO

Country of origin: Democratic Republic Of Congo

Alert submitted by: Denmark











Alert number: A12/00159/21 Product: Wooden trainset

Name: Houten treinbaan Little Dutch 21 dlg.

Risk type: Choking Category: Toys Brand: Little Dutch

Type / number of model: LD4423 2019.500.5019 Type of alert: Products with serious risks

The product has a small part (chimney of the locomotive). A child may put it in the mouth and choke on it. / The product does not comply with the requirements of the Toy Safety Directive 2009/48/EC and the relevant standard EN 71-1.

Ban on the marketing of the product and any accompanying measures

Description: Wooden train

Batch number / Barcode: 8713291444232

NO

Country of origin: People's Republic of China Alert submitted by: The Netherlands





Alert number: A12/00161/21 Product: Toy ironing board Name: Baby Cart Series Risk type: Injuries Category: Toys Brand: Le Xin Bao

Type / number of model: BZ6071
Type of alert: Products with serious risks

The ironing board is not sufficiently stable and can tip over when using the product. This could lead to injuries. Furthermore, the child's fingers could be entrapped between moving parts, causing injuries. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.

Recall of the product from end users, Withdrawal of the product from the market

Description: Children's ironing board covered in pink and white dotted fabric. The metallic frame is grey and there is a plastic locking device just

under the board.

Batch number / Barcode: 4792850000885

UNKNOWN


Country of origin: People's Republic of China

Alert submitted by: Hungary











Alert number: A12/00172/21 Product: Plastic headband

Name: Hračka

Risk type: Chemical, Choking

Category: Toys

Brand:

Type / number of model: LT6-188-15
Type of alert: Products with serious risks

The battery compartment is easily opened/broken, leaving the button batteries accessible. A child could put them in the mouth, which could cause damage to the child's gastrointestinal tract if swallowed. / The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 62115.

Withdrawal of the product from the market

Description: Plastic headband with reindeer horns and LED diodes, which are powered by two button batteries - cells. The battery power supply is located in a plastic heart, which is in the middle of the headband.

Batch number / Barcode: 6 961 888 601 885

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Czechia









Alert number: A12/00173/21 Product: Musical toy

Name: Airplane musical instruments

Risk type: Choking, Cuts

Category: Toys Brand: aiyingle

Type / number of model: 668-16
Type of alert: Products with serious risks

The toy contains small parts that can easily detach. A small child may put them in the mouth and choke on them. Furthermore, the toy has sharp edges that may cause cuts. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Withdrawal of the product from the market

Description: Airplane-shaped plastic musical instrument with metal plates and two plastic sticks.

Batch number / Barcode: EAN 5902429917677

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Poland





Alert number: A12/00164/21

Product: Handwash

Name: Handreiniger Citrus Duft (bzw. Citrus Power)

Risk type: Chemical Category: Cosmetics Brand: LINDA

Type / number of model:

Type of alert: Products with serious risks

The product contains lead (measured value: 150 mg/kg). Lead is harmful for human health as it accumulates in the body and may damage the unborn child. / The product does not comply with the Cosmetic Products Regulation.

Destruction of the product, Warning consumers of the risks, Withdrawal of the product from the marketRecall of the product from end users

Description: Handwash - milky handwash to remove dirt from hands

Batch number / Barcode: EAN 4400086010034

NO

Country of origin: Germany Alert submitted by: Germany









Alert number: A12/00167/21 Product: Extension lead Name: Rainbow 5 Pro Risk type: Electric shock, Fire

Category: Electrical appliances and equipment

Brand: Esperanza

Type / number of model: ELK 101, ELK 101KR Type of alert: Products with serious risks

The product is missing the overcurrent protector. Thus, in overvoltage conditions, the circuits may overheat and cause fire. The

creepage/clearance distances are inadequate. Device's casing may get damaged leaving live parts accessible. The user may get electrocuted. /

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950-1.

Destruction of the product. Withdrawal of the product from the market

Description: Extension lead with five socket outlets with individual switches and surge protection.

Batch number / Barcode: EAN 5901299913802, EAN 5901299935033

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Poland













Alert number: A12/00169/21 Product: Extension lead Name: 4-Way Socket

Risk type: Electric shock, Fire

Category: Electrical appliances and equipment

Brand: TITANUM

Type / number of model: TL 129
Type of alert: Products with serious risks

The cable is inadequately soldered and may detach leaving live parts accessible. The user may get electrocuted. The product is missing the overcurrent protector. Thus, in overvoltage conditions, the circuits may overheat and cause fire. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950-1.

Destruction of the product, Withdrawal of the product from the market

Description: Extension lead with four socket outlets, switch and surge protection.

Batch number / Barcode: EAN 5905784769417

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Poland









Alert number: A12/00174/21 Product: USB adaptor Name: SMART CHARGER KIT Risk type: Electric shock

Category: Electrical appliances and equipment

Brand: TREQA

Type / number of model: CS-203 Type of alert: Products with serious risks

The clearance/creepage distances between the primary and accessible secondary circuits are not sufficient. The user could receive an electric shock from accessible live parts. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950-1.

Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market

Description: White USB adaptor.

Batch number / Barcode: 6986591372037

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Croatia





Alert number: INFO/00020/21

Product: Earrings

Name: Fantasy Ohrringe mit Glas

Risk type: Chemical Category: Jewellery

Brand:

Type / number of model: E50147, E50147B, E50147G, E50147L, E50147R, E50147S

Type of alert: Products with other risk levels

The product contains an excessive amount of lead (measured value: 9 % by weight). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children. / The product does not comply with the REACH Regulation.

Stop of sales, Withdrawal of the product from the market

Description: Fantasy earrings with coloured glass (blue, green, lilac, red or black), sized 1,7 cm per 3,7 cm. The upper part of the earring is in metal. The product is also sold online.

Batch number / Barcode:

UNKNOWN

Country of origin: Czechia
Alert submitted by: Germany



Alert number: INFO/00017/21 Product: Passenger car

Name: GLC Risk type: Injuries Category: Motor vehicles Brand: Mercedes-Benz

Type / number of model: e1*2001/116*0480*30 to 32, e1*2007/46*1884*00, Types: 204X, 204X AMG

Type of alert: Products with other risk levels

The LED multi-beam headlamps may not be adjusted in accordance with the specifications. As a result, the vehicles' illumination range could be significantly reduced, leading to increased risk of an accident. /

Recall of the product from end users

Company recall page: https://www.mercedes-benz.de/ (https://www.mercedes-benz.de/)

Description: Model series BR 253. Batch number / Barcode: 8291902

NO

Country of origin: Germany Alert submitted by: Germany Alert number: INFO/00022/21
Product: Particle filter mask
Name: Disposable Children's Mask
Risk type: Health risk / other
Category: Protective equipment

Brand: FLIPPY

Type / number of model: Size: 175 x 95 mm Type of alert: Products with other risk levels

The product advertises a protective potential against viral particles but its filtering capacity has not been certified as such by the relevant European body. As a result, the product may not meet the health and safety requirements and therefore may not be adequately protected if not combined with additional measures. / The product does not comply with the Personal Protective Equipment Regulation and with the relevant European standard EN 149.

Withdrawal of the product from the market

Description: Non-medical 3 layers disposable children's protective mask. The product exists in colours blue, black, pink, and white.

Batch number / Barcode: 6426485336825


UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Romania







Alert number: INFO/00021/21

Product: Plastic doll

Name:

Risk type: Choking Category: Toys

Brand:

Type / number of model:

Type of alert: Products with other risk levels

Smart parts can easily detached. As a consequence, a smaill child may put them in the mouth and choke on them. / The product does not comply with the requirements of Toy Safety Directive and relevant European standard EN 71-1.

Withdrawal of the product from the market

Description: A plastic doll with plaits in a dress of various colors, decorated with beads and textile flowers, which has a chain with a key ring attached to the top of the head.

Batch number / Barcode:

UNKNOWN

Country of origin: Unknown Alert submitted by: Czechia



