
Alert number **[A12/01431/21](#)**

Product **Passenger car**

Risk type **Fire**

The clutch pressure plate cannot permanently withstand the mechanical loads. This could lead to the loss of power transmission and to increased risk of fire. Furthermore, a hydraulic hose on the gearbox may leak.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Jeep**

Name **Gladiator, Wrangler**

EC-type approval/model **Individual approval**

Production dates **23.08.2017 - 19.02.2020**

Company recall code **Y03**

Weekly report number **Report-2021-41**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number	<u>A12/01412/21</u>
Product	Wooden puzzle - airplane



Risk type **Choking**

Small parts may easily detach from the toy. A small child may put it in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Made of 7 different coloured wooden parts in the shape of an airplane, with one part showing a cloud and another part with the inscription Plane. These parts are placed on a wooden plywood in the shape of a square.**

Packaging description **Transparent plastic foil.**

Brand **Unknown**

Type / number of model **C01722**

Batch number **21284**

Barcode **5991800017228**

Weekly report number **Report-2021-41**

Alert submitted by **Slovakia**

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public authorities

**Withdrawal of the product from the market
Distributor**

Date of entry into force

31/08/2021

Measures ordered by public authorities

**Recall of the product from end users
Distributor**

Date of entry into force

31/08/2021

Measures ordered by public authorities

**Warning consumers of the risks
Distributor**

Date of entry into force

31/08/2021

Alert number **[A11/00087/21](#)**

Product **Soft toy**



Risk type **Choking**

The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the stuffing material in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Reversible octopus-shaped plush toy.**

Packaging description **Cardboard label.**

Brand **Unknown**

Name **Soft toy**

Type / number of model **C9597**

Barcode **5881800095978**

Weekly report number **Report-2021-41**

Alert submitted by **Croatia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures
Distributor**

Date of entry into force **27/07/2021**

Alert number **[A11/00088/21](#)**

Product **Soft toy**



Risk type **Choking**

Due to the weakness of certain seams, the fibrous stuffing material of the toy is easily accessible. A child may put it in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Purple Teddy Bear, height: 100 cm**

Brand **Unknown**

Name **Purple Bear**

Type / number of model **MRT-478**

Weekly report number **Report-2021-41**

Alert submitted by **Croatia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Import rejected at border
Importer**

Date of entry into force **02/08/2021**



Alert number **[A12/01417/21](#)**

Product **Doll stroller**



Risk type **Injuries**

The pushchair has only one safety lock and is not sufficiently resistant to load. As a consequence, it could easily collapse while a child is playing with or sitting on the pushchair, causing the child to fall to the ground or trap the fingers or limbs.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Pushchair for dolls in pink colour on 4 double plastic wheels with a bent handle. The product is made of thin plastic tubes and covered with a pink textile fabric.**

Packaging description **Transparent plastic foil.**

Brand **Sonia**

Name **Baby Little Stroller**

Type / number of model **P25479
SO-8817AF**

Barcode **8586022425479**

Weekly report number **Report-2021-41**

Alert submitted by	Slovakia
Is the product counterfeit?	No
Country of origin	Hong Kong
Measures ordered by public authorities	Warning consumers of the risks Importer
Measures ordered by public authorities	Recall of the product from end users Importer
Measures ordered by public authorities	Withdrawal of the product from the market Importer

Alert number **[A12/01411/21](#)**

Product **Laser pointer**



Risk type **Damage to sight**

The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 60825-1.

Category **Laser pointers**

Type **Consumer**

Description **Laser pointer category III (as classified by manufacturer) with a wavelength of 532nm ± 10nm and a maximum output power of 2000 mW.**

Packaging description **Cardboard box.**

Brand **Unknown**

Name **Green Laser Pointer**

Type / number of model **303**

Weekly report number **Report-2021-41**

Alert submitted by **Slovakia**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Stop of sales
Retailer**

Measures ordered by public
authorities

**Warning consumers of the risks
Retailer**

Alert number **[A12/01418/21](#)**

Product **Laser epilator**



Risk type **Damage to sight**

The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 60825-1.

Category **Other**

Type **Consumer**

Description **Laser epilator for hair removal by emitting laser radiation.**

Packaging description **Cardboard box.**

Brand **Benus**

Name **Personal Laser Hair Remover System**

Type / number of model **CW-808**

Weekly report number **Report-2021-41**

Alert submitted by **Slovakia**

Is the product counterfeit? **No**

Country of origin **Republic of Korea**

Measures ordered by public
authorities

**Recall of the product from end users
Distributor**

Date of entry into force

23/08/2021

Measures ordered by public
authorities

**Withdrawal of the product from the market
Distributor**

Date of entry into force

23/08/2021

Measures ordered by public
authorities

**Warning consumers of the risks
Distributor**

Date of entry into force

23/08/2021



Alert number

[INFO/00158/21](#)

Product

Particle filter mask



Risk type **Health risk / other**

The particle/filter retention of the material is insufficient (measured values: as low as 75%). Consequently, the product does not fulfil the health and safety requirements; thus, even if combined with other recommended measures, it may not properly protect.

The product does not comply with the Personal Protective Equipment (PPE) Regulation and with the relevant European standard EN 149.

Category **Protective equipment**

Type **Consumer**

Description **FFP2 non-medical protective mask as depicted; white and blue packaging with 5 masks: Masvan CE2163**

Packaging description **Milky white plastic packaging with 5 masks and partially blue inscription, English text**

Brand **Masvan**

Name **FFP2 non-medical protective mask**

Type / number of model **KND-003**

Batch number **20201001**

Barcode **6973167894222**

Weekly report number	Report-2021-41
Alert submitted by	Germany
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Recall of the product from end users Other
Measures taken by economic operators	Ban on the marketing of the product and any accompanying measures Retailer

Alert number **[A12/01415/21](#)**

Product **Thermostat**



Risk type **Electric shock
Fire**

The power supply cord can be easily pulled out, leaving the wires' live ends accessible. Furthermore, the output socket has no protective contact. A user may touch accessible live parts and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and with the European standards EN 60730-1 and EN 60730-2-9.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **The product is used as a temperature controller for aquariums, terrariums, incubators.**

Packaging description **The product is sold in a blue and green cardboard box. Product sold online.**

Brand **ZUH TOMAR**

Name **Regulator temperatury RT-2**

Type / number of model **RT-2**


Barcode **5903867513803**

Weekly report number **Report-2021-41**

Alert submitted by	Czechia
Is the product counterfeit?	No
Country of origin	Poland
Measures ordered by public authorities	Withdrawal of the product from the market Retailer
Date of entry into force	09/08/2021

Alert number **[A12/01416/21](#)**

Product **Thermostat**



Risk type **Electric shock**

The power supply cord can be easily pulled out, leaving the wires' live ends accessible. Furthermore, the output socket has no protective contact, and it is possible to connect it with a single pin pole, leaving the second pin of the plug accessible and live. A user may touch accessible live parts and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and with the European standards EN 60730-1 and EN 60730-2-9.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **The product is used as a temperature controller for aquariums, terrariums, incubators.**

Packaging description **The product is sold in a black and green cardboard box. Product sold online.**

Brand **ZUH TOMAR**

Name **Regulator RT-2C**

Type / number of model **RT-2C**

Weekly report number **Report-2021-41**

Alert submitted by **Czechia**

Is the product counterfeit?

No

Country of origin

Poland

Measures ordered by public
authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

09/08/2021

Alert number **[A12/01414/21](#)**

Product **Felt pens**



Risk type **Chemical**

The grey felt pen contains an excessive amount of the preservatives 2-Methyl-4-isothiazolin-3-one (MI) and 5-chloro-2-methyl-4-isothiazolin-3-one (CMI) (measured values: 4.2 mg/kg and 5.9 mg/kg, respectively). MI and CMI are strong sensitizers and can provoke allergic contact dermatitis to sensitised persons.

The product does not fulfil the requirements of the Toy Safety Directive.

Category **Toys**

Type **Consumer**

Description **25 felt pens in various colours. Product sold online, in particular via Bol.com**

Packaging description **The items are sold in a transparent packaging with white label.**

Brand **Grafix**

Name **Felt pens 25 pieces**

Type / number of model **ref. 150003**

Batch number **201050**

Barcode **8715427063430**

Weekly report number	Report-2021-41
Alert submitted by	Belgium
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	17/08/2021

Alert number **[A12/01422/21](#)**

Product **Passenger car**

Risk type **Injuries**

The control parameters of the electronic stability control (ESC) may be incorrect. This could result in a loss of control over the vehicle, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Bentley**

Name **Bentayga**

EC-type approval/model **e5*2007/46*1125*, Type 4V**

Production dates **9.6.2021 - 29.9.2021**

Company recall code **RE21/29**

Weekly report number **Report-2021-41**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United Kingdom**


Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number

[A12/01421/21](#)

Product

Particle filter mask



Risk type

Health risk / other

The particle/filter retention of the material is insufficient (measured values: as low as 83%). Consequently, the product does not fulfil the health and safety requirements, and an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection; thus, even if combined with other recommended measures, it may not properly protect.

The product does not comply with the Personal Protective Equipment (PPE) Regulation and the relevant European standard EN 149.

Category

Protective equipment

Type

Consumer

Description

White protective respiratory filtration half-face mask with the brand name, the EN standard, FFP2 and the NR marking printed on.

Packaging description

Box with logo, description of the product, quantity (50 units) and indication of the EN149:2001 + A1:2009 and the filter efficiency (>94%). Instructions for use in English.

Brand

Biosis Healing

Name

Biosis Healing Protective Mask

Type / number of model

BH-YEG-15.5x10.5

Batch number

620071013

Weekly report number	Report-2021-41
Alert submitted by	Ireland
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Destruction of the product Other
Date of entry into force	05/08/2021

Alert number **[A12/01423/21](#)**

Product **Passenger car**

Risk type **Injuries**

The right-hand rear brake calliper may be incorrectly assembled, which could cause certain components to fail when the parking brake is activated. As a result, the vehicle may inadvertently roll away from the parking space, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **NISSAN**

Name **NV400**

EC-type approval/model **Type: M1
e2*2007/46*0137*30**

Production dates **10.2.2021 - 26.2.2021**

Company recall code **PN1C2**

Weekly report number **Report-2021-41**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Greece**

Alert number **[A12/01419/21](#)**

Product **Motorcycle**

Risk type **Injuries**

Due to an error in the assembly process, the wire harness may be pinched between the pillion step and the frame body or between the luggage box and the frame body. As a result, disconnection and short circuit of the wire harness may occur, causing the engine to stall while riding and increasing the risk of an accident.

The product does not meet the requirements laid down in the Regulation on the type-approval and market surveillance of two- or three-wheel vehicles and quadricycles.

Category **Motor vehicles**

Type **Consumer**

Description **Model codes: X-ADV750M (RH10) and NSS750M (RH11);
Model year: 2021.**

Brand **HONDA**

Name **X-ADV750M, NSS750M**

EC-type approval/model **e6*168/2013*00057*00, e6*168/2013*00058*00,
e6*168/2013*00064*00, e6*168/2013*00065*00**

Production dates **X-ADV750M - 23.10.2020 - 26.3 2021, NSS750M - 29.9.2020
- 5.8.2021**

Company recall code **3M7**

Weekly report number **Report-2021-41**

Alert submitted by **Belgium**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Importer**

Date of entry into force

30/09/2021

Products were found and
measures were taken also in

**Greece
Croatia
Ireland
Poland
Slovakia**

Alert number

A12/01432/21

Product

Magnetic toy set



Risk type

Choking Injuries

The toy is made of small parts (balls) with a high magnetic flux. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways. If various are swallowed, they could attract one another causing intestinal blockage or perforation.

The product does not comply with the requirements of the Toy Safety Directive and of the relevant European standard EN 71-1.

Category

Toys

Type

Consumer

Description

Set of 512 performant rare earth magnets sold together with a metal basis and a splitter.

Packaging description

The product is sold in a transparent plastic box.

Brand

Speks

Name	512 krachtige zeldzame aarde magneten
Type / number of model	deep end
Barcode	850021697204
Weekly report number	Report-2021-41
Alert submitted by	Luxembourg
Is the product counterfeit?	No
Country of origin	United States
Measures ordered by public authorities	Withdrawal of the product from the market Retailer
Date of entry into force	29/09/2021
Measures ordered by public authorities	Withdrawal of the product from the market Retailer
Date of entry into force	29/09/2021
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	29/09/2021

Alert number

[A12/01427/21](#)

Product

Magnetic toy set



Risk type

Choking Injuries

The toy is made of small parts (balls) with a high magnetic flux. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways. If various are swallowed, they could attract one another causing intestinal blockage or perforation.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category

Toys

Type

Consumer

Description

Multicolour magnetic balls.

Packaging description

The product is sold in a cylindric metal box with a lid.

Brand

Unknown

Name

Kulki magnetyczne

Type / number of model

ZA3157 (808C)

Barcode

1401404632148

Weekly report number

Report-2021-41

Alert submitted by

Poland

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Destruction of the product
Importer**

Date of entry into force **12/08/2021**

Measures taken by economic operators **Withdrawal of the product from the market
Importer**

Date of entry into force **12/08/2021**

Alert number

A12/01433/21

Product

Magnetic toy set



Risk type

Choking Injuries

The toy is made of small parts (balls) with a high magnetic flux. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways. If various are swallowed, they could attract one another causing intestinal blockage or perforation.

The product does not comply with the requirements of the Toy Safety Directive and of the relevant European standard EN 71-1.

Category

Toys

Type

Consumer

Description

Set of 512 rare earth magnet balls sold with a splitter card and a translucent box.

Packaging description

The product is sold in a transparent plastic box.

Brand

Speks

Name	512 krachtige zeldzame aarde magneten
Type / number of model	denim
Barcode	850021697150
Weekly report number	Report-2021-41
Alert submitted by	Luxembourg
Is the product counterfeit?	No
Country of origin	United States
Measures ordered by public authorities	Withdrawal of the product from the market Retailer
Date of entry into force	29/09/2021
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	29/09/2021

Alert number **[A12/01424/21](#)**

Product **Passenger car**

Risk type **Fire**

The anti-lock brake system (ABS) may have an electrical defect. This could result in a short circuit, increasing the risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Hyundai**

Name **Genesis**

EC-type approval/model **e4*2007/46*1030*00, Type: DH**

Production dates **01.01.2013 - 31.12.2016**

Company recall code **11D054**

Weekly report number **Report-2021-41**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Republic of Korea**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Ireland**

Alert number

A12/01413/21

Product

Lighting chain



Risk type

Electric shock

The accessible wires have inadequate insulation. The user could touch accessible live parts, which may cause an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Category

Lighting chains

Type

Consumer

Description

Lighting chain with 50 non-replaceable cool white LED lamps.

Packaging description

Packaging: transparent plastic box with a printed card inside


Brand

EMOS

Name	50 LED LIGHTS / Christmas LED Lights
Type / number of model	LED-50 250CM CW IP20 ZYK0101
Barcode	5592920032183
Weekly report number	Report-2021-41
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Distributor
Date of entry into force	27/04/2021

Alert number **[A12/01420/21](#)**

Product **Fireworks**



Risk type

**Burns
Damage to sight
Injuries**

The firework battery is unstable and can fall over during burning, meaning that the individual fireworks shoot out in unintended directions. The persons nearby could be hit by the shock wave, burning material and/or flames with the risk of burns, injuries and damage to the eyes.

The product does not comply with the requirements of the Pyrotechnics Directive 2013/29/EU and the relevant European standard EN 15947.

Category

Pyrotechnic articles

Type

Consumer

Description

Battery of 16 single shot tubes. Class F2.

Packaging description

Coloured cuboid box.

Brand

Dragon

Name	Las Vegas
Type / number of model	XN36-81601
Batch number	DG 2020-1
Barcode	EAN 5903314040388
Weekly report number	Report-2021-41
Alert submitted by	Poland
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Destruction of the product Importer
Date of entry into force	09/09/2021
Measures taken by economic operators	Withdrawal of the product from the market Importer
Date of entry into force	09/09/2021

Alert number

[A12/01434/21](#)

Product

Magnetic toy set



Risk type

**Choking
Injuries**

The toy is made of small parts (balls) with a high magnetic flux. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways. If various are swallowed, they could attract one another causing intestinal blockage or perforation.

The product does not comply with the requirements of the Toy Safety Directive and of the relevant European standard EN 71-1.

Category

Toys

Type

Consumer

Description

Set of 512 performant rare earth magnets sold together with a metal basis and a splitter.

Packaging description

The product is sold in a transparent plastic box.

Brand

Speks

Name	512 krachtige zeldzame aarde magneten
Type / number of model	original
Barcode	850021697143
Weekly report number	Report-2021-41
Alert submitted by	Luxembourg
Is the product counterfeit?	No
Country of origin	United States
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	29/09/2021
Measures ordered by public authorities	Withdrawal of the product from the market Retailer
Date of entry into force	29/09/2021

Alert number **[A12/01435/21](#)**

Product **Beach sandals**



Risk type **Chemical**

The plastic material of the product contains an excessive amount of dibutyl phthalate (DBP) (measured value: 12.3 % by weight). This phthalate may harm the health by causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Ladies' beach sandals, size 39, colour: blue-and-white striped with yellow lemons (also sold in other sizes).**

Packaging description **Pair of two bathing shoes, without further packaging, joined together with a printed, hanging label.**

Brand **Barfuss**

Name **Damen Barfuss Badeschuhe Größe 39**

Batch number **2 200269 187476**

Barcode **2 200269 187476**

Weekly report number **Report-2021-41**

Alert submitted by **Germany**

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures taken by economic operators

**Destruction of the product
Distributor**

Date of entry into force

01/10/2021

Measures taken by economic operators

**Recall of the product from end users
Importer**

Date of entry into force

01/10/2021

Measures taken by economic operators

**Stop of sales
Distributor**

Date of entry into force

01/10/2021

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force

01/10/2021

Alert number

[A12/01426/21](#)

Product

Laser fog light for car



Risk type

Damage to sight

The laser beam is too powerful (up to 41.3 mW). Direct viewing of the laser beam could cause damage to sight.

The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 60825-1.

Category

Laser pointers

Type

Consumer

Description

Red laser additional fog light for car. Technical parameters stated on the box and on the labels on the product.

Packaging description

Blue cardboard box.

Brand

Unknown

Name

Anti-collision laser warning light of automobile

Type / number of model

sj-F061

Weekly report number

Report-2021-41

Alert submitted by

Slovakia

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public authorities

**Recall of the product from end users
Distributor**

Date of entry into force

22/09/2021

Measures ordered by public authorities

**Withdrawal of the product from the market
Distributor**

Date of entry into force

22/09/2021

Measures ordered by public authorities

**Warning consumers of the risks
Distributor**

Date of entry into force

22/09/2021



Alert number **[A12/01429/21](#)**

Product **Passenger car**

Risk type **Injuries**

The driver airbag may be defective. As a result, fragments of the inflator inside the airbag may project out when the driver airbag is activated, causing injuries to the car occupants.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of Motor Vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Volvo cars models S60 and S80.**

Packaging description **Chassis: from 0147869 to 0446916; from 0000193 to 0741211.**

Brand **Volvo**

Name **S60, S80**

EC-type approval/model **Type: 184, 384.**

Production dates **S60 (2001 -2009); S80 (2001 - 2006).**

Company recall code **R10125**

Weekly report number **Report-2021-41**

Alert submitted by **Portugal**

Is the product counterfeit? **No**

Country of origin **Sweden**

Measures taken by economic **Recall of the product from end users**

operators

Distributor

Products were found and
measures were taken also in

Greece

Alert number **[A12/01428/21](#)**

Product **Passenger car**

Risk type **Injuries**

Due to an error in the assembly process, the occupant detection system (ODS) of the front passenger seat had not been installed on the seat cushion. As a result, no audible signal sounds and no warning symbol will appear on the instrument panel to warn the driver when the front passenger seat is occupied but the seat belt is not fastened. This may increase the risk of not having the seat belt fastened in the event of an accident, increasing the risk of injury.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **LAND ROVER**

Name **Defender (LE), Discovery (LR)**

EC-type approval/model **e5*2007/46*0092, e5*2007/46*1055**

Production dates **10.07.2020 - 11.08.2021**

Company recall code **N626**

Weekly report number **Report-2021-41**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Slovakia**

Measures taken by economic operators

**Recall of the product from end users
Manufacturer**

Date of entry into force

05/10/2021

Products were found and measures were taken also in

Ireland

Alert number **[A12/01430/21](#)**

Product **Passenger car**

Risk type **Injuries**

Due to a design change introducing an internal chamfer in the rear seat back lock button, the latch actuation rod can catch on this chamfer, preventing its upwards movement. As a result the rear seat back may not be securely latched when returned to its upright position after folding, and the occupant of the rear seat and any items stored in the luggage compartment may not be correctly restrained in the event of an accident, increasing the risk of injury.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of Motor Vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Range affected VIN's: SJNFAAF16U1 (000063 - 064161).**

Brand **Nissan**

Name **Juke (F16)**

EC-type approval/model **e9*2007/46*6697**

Production dates **18/09/2019 - 28/08/2020**

Company recall code **PG1CE**

Weekly report number **Report-2021-41**

Alert submitted by **Portugal**

Is the product counterfeit? **No**

Country of origin **United Kingdom**

Measures taken by economic **Recall of the product from end users**

operators

Distributor

Products were found and
measures were taken also in

**Poland
Slovakia**

Alert number **[A12/01425/21](#)**

Product **Laser pointer**



Corrigendum **A12/01425/21: in agreement with the National Authorities, the risk level was changed to "Serious".**

Risk type **Damage to sight**

The laser beam is too powerful (up to 21.6 mW). Direct viewing of the laser beam could cause damage to sight.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 60825-1.

Category **Laser pointers**

Type **Consumer**

Description **Laser pointer in a fabric sleeve. Product sold online, in particular on Bol.com**

Packaging description **Cardboard box**

Brand **HT Supplies**

Name **Laserpoiner**

Type / number of model **407653**

Barcode **8785252431766**

Weekly report number **Report-2021-41**

Alert submitted by	The Netherlands
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Other
Date of entry into force	30/08/2021
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	30/08/2021