

CONSUMERS

European Commission (http://ec.europa.eu/index_en.htm) Consumers (http://ec.europa.eu/consumers/consumers_safety/index_en.htm) Safety products (http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/index_en.htm)

A Rapid Alert System home (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm

E Back to report listings (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2018)

Q Search alerts (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search)

🖬 Safe Products Online (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline)

The Rapid Alert System for Non-Food Products (RAPEX)

RAPEX - Weekly overview report of notifications

week 40 - 2018

Notification A11/0049/14 published in report 20-2014 of 23 May 2014 has been withdrawn at the request of the notifying authority following the Judgement of the General Court in Case T-474/15



Alert number: A12/1450/18 Product: Girls' bikini Name: Unknown Risk type: Injuries Category: Clothing, textiles and fashion items Brand: Hello Bikini Type / number of model: 04110003 Art No: HELLO-036 Risk level: Serious risk There are cords to be tied at the back of the garment. These cords can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682.

Measures ordered by public authorities (to: Retailer): Withdrawal of the product from the market Description: Bikini in light blue, yellow and pink colour. The bikini is intended for 6-year old girls and has functional cords to be tied at the back. Batch number / Barcode: 2500000049651 Country of origin: China Alert submitted by: Cyprus





Alert number: A12/1451/18 Product: Girls' bikini Name: Unknown Risk type: Injuries Category: Clothing, textiles and fashion items Brand: VIOLETTA junior Type / number of model: ARTON: BB898 Risk level: Serious risk There are cords to be tied at the back of the garment. These cords can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682. **Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market **Description:** White and pink bikini for 11/12 year-old girls, with functional cords to be tied at the back. **Batch number / Barcode:** 250000052682 **Country of origin:** China **Alert submitted by:** Cyprus



Alert number: A12/1452/18 Product: Girls' clothing set Name: Unknown Risk type: Injuries Category: Clothing, textiles and fashion items Brand: YES!DO KIDS Collection Classic Type / number of model: PP3326 / 18S5B10007 Risk level: Serious risk There is a decorative ribbon to be tied at the back of the dress. The ribbons can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682. **Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market **Description:** Girls' white dress and black bolero. The skirt of the dress has a floral pattern and there are ribbons to be tied at the back. The dress is intended for girls of 18 months. **Batch number / Barcode:** 2210000280120 **Country of origin:** China **Alert submitted by:** Cyprus



Alert number: A12/1469/18 Product: Children's dress Name: Unknown Risk type: Choking Category: Clothing, textiles and fashion items Brand: RNS RONIS Type / number of model: Unknown Risk level: Serious risk The small decorative rhinestones can be easily detached, generating small parts. A small child may put the small parts in the mouth and choke. Measures ordered by public authorities (to: Retailer): Withdrawal of the product from the market Description: Children's sleeveless dress with small decorative rhinestones glued at the front. Batch number / Barcode: Unknown Country of origin: Bulgaria

Alert submitted by: Bulgaria



Alert number: A12/1470/18 Product: Children's dress Name: Unknown Risk type: Choking Category: Clothing, textiles and fashion items Brand: Baby Dji Type / number of model: Unknown Risk level: Serious risk The pearls on the dress can easily be detached, generating small parts. A small child can put them in the mouth and choke. Measures ordered by public authorities (to: Distributor): Withdrawal of the product from the market Description: Children's white dress with a decorative belt made up of rose-shaped flowers and white pearls. Batch number / Barcode: Unknown Country of origin: Bulgaria Alert submitted by: Bulgaria



Alert number: A12/1453/18 Product: Skin product Name: ANTI STRESS CREAM Risk type: Chemical Category: Cosmetics Brand: Danielle Laroche Type / number of model: Unknown Risk level: Serious risk Methylchloroisothiazolinone (MCI) and Methylisothiazolinone (MI) are listed in the ingredients of this leave-on product. MI and MCI are sensitising agents and can provoke allergic contact dermatitis to sensitised persons. The product does not comply with the Cosmetic Products Regulation. Measures ordered by public authorities (to: Distributor): Ban on the marketing of the product and any accompanying measures Description: Cosmetic face moisturiser supplied in a white and silver cardboard box. Batch number / Barcode: Batch No. 17A0059, barcode 7290101264255 Country of origin: Israel Alert submitted by: Lithuania Danielle Laroche S CREAM

Alert number: A12/1467/18 Product: Travel plug adapter Name: Universal Travel Adapter Risk type: Electric shock Category: Electrical appliances and equipment Brand: UNITED Type / number of model: UTA1647 Risk level: Serious risk A Schuko-type electrical plug without a connected protective conductor could be inserted into the device. The user can come into contact with live parts.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335-1. **Measures taken by economic operators:** Withdrawal of the product from the market (By: Importer)

Measures ordered by public authorities (to: Importer): Destruction of the product, Recall of the product from end users **Description:** The cube-shaped travel adaptor (6.2 cm x 4.8 cm x 7.5 cm) has an extensible UK (or USA/AUS) plug secured by a sliding switch and a second extensible Euro plug. The device also incorporates a USB charging socket (5V, 1000 mA) and two replaceable fuses. **Batch number / Barcode:** 5709884030459

Country of origin: China

Alert submitted by: Germany









Alert number: A12/1458/18 Product: Earrings Name: Skull Stud Earrings Jewelry Halloween Risk type: Chemical Category: Jewellery Brand: Unknown Type / number of model: 04655397 Risk level: Serious risk The earrings contain cadmium (measured value: 71 % by weight). Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH regulation.

Measures ordered by public authorities (to: Importer): Ban on the marketing of the product and any accompanying measures Description: Halloween jewellery. Skull-shaped, brass coloured, with little black stud earrings. The product has been sold online. Batch number / Barcode: Unknown Country of origin: China

Alert submitted by: Sweden



Alert number: A12/1475/18 Product: Earrings Name: ER Lena Mixy 993 Risk type: Chemical Category: Jewellery Brand: Colloseum Accessories Type / number of model: 0316175C 161 Risk level: Serious risk The product contains cadmium (measured value: 15% in weight). Cadmium is harmful to human health because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Retailer)

Description: Earrings consisting of a silver-coloured metal circle with rhinestones hanging from a straight hook. Presented on a white cardboard sheet with black imprint. **Batch number / Barcode:** 4057328159091

Country of origin: China Alert submitted by: Germany





Alert number: A12/1457/18 Product: Pressure cooker Name: Clic Clac Set Autocuiseur poignées rabattable Risk type: Burns, Injuries Category: Kitchen/cooking accessories Brand: ARTHUR MARTIN Type / number of model: AM2240 4 litres AM2240 7 litres Risk level: Serious risk It is possible to open the lid of the pressure cooker while it is under pressure and the pressure cooker can become deformed. User could suffer burns from the steam, or, liquid can leak from it and extinguish the flame of the hot plate. As a consequence natural gas could be released.

The product does not comply with the requirements of the Pressure Equipment Directive and the relevant European standard EN12778. **Measures taken by economic operators:** Recall of the product from end users (By: Distributor) **Measures ordered by public authorities (to: Manufacturer):** Destruction of the product, Recall of the product from end users **Description:** 4- and 7-litre pressure cookers for domestic use sold as a set. The same lid is used for both bodies. **Batch number / Barcode:** 3508510022552 **Country of origin:** China **Alert submitted by:** France



Alert number: A12/1471/18 Product: Laser pointer Name: 2 in 1 LASER & LED LIGHT Risk type: Damage to sight Category: Laser pointers Brand: JD Type / number of model: SIN. 2016908 Risk level: Serious risk The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market Description: Laser pointer with LED light and key chain. Packaging: display box. Product size: approx 6.1 cm Batch number / Barcode: Unknown Country of origin: China Alert submitted by: Hungary



Alert number: A12/1472/18 Product: Laser pointer Name: LASER & LED LIGHT Risk type: Damage to sight Category: Laser pointers Brand: Unknown Type / number of model: ZL 2008 3028 7657.6; ZL 2006 2004 1106.7 Risk level: Serious risk The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market Description: Laser pointer with LED light and carabiner. Packaging: several units in a display box. Product size: 7.7 cm Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Hungary



Alert number: A12/1473/18 Product: Laser pointer Name: Unknown Risk type: Damage to sight Category: Laser pointers Brand: QD Type / number of model: Unknown Risk level: Serious risk The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market Description: Laser pointer with LED light and carabiner. The product is sold without packaging. Product size: 7.3 cm Batch number / Barcode: Unknown Country of origin: China Alert submitted by: Hungary European Commission - Rapid Alert System



Alert number: A12/1436/18 Product: Table lamp Name: Unknown Risk type: Electric shock Category: Lighting equipment Brand: Gilbert Type / number of model: 47384 Risk level: Serious risk The lampholder insulation is inadequate and the cord anchorage is insufficient. The user can therefore access live parts receiving an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598. **Measures ordered by public authorities (to: Importer):** Withdrawal of the product from the market

Description: Table lamp shaped like a cat. Batch number / Barcode: 7392248473849 Country of origin: Unknown Alert submitted by: Sweden



Alert number: A12/1440/18 Product: Log splitter Name: Pikahalkomakone 7 Ton / 51cm Risk type: Injuries Category: Machinery Brand: Timco Tools Type / number of model: WP-7N Risk level: Serious risk The two-handed safety switch does not function correctly. The user could trigger the splitter with only one hand while having the second hand /arm in the trajectory of the pressure plate or close to the wedge, increasing the risk of injuries.

The product does not comply with the requirements of the Machinery Directive and the relevant European Standard EN 609-1. **Measures ordered by public authorities (to: Importer):** Recall of the product from end users **Description:** Electrical kinetic wedge splitter with a force of 7 tons.

Batch number / Barcode: Unknown Country of origin: China

Alert submitted by: Finland



Alert number: A12/1434/18
Product: Lorry
Name: TGA, TGS, TGX
Risk type: Injuries
Category: Motor vehicles
Brand: MAN
Fype / number of model: Type-approval numbers: e4*2007/46*0229*, e4*2007/46*0231*, K681*, K685*; type: L.2007.46.00, L.2007.46.003,
rga02, tga03
Risk level: Serious risk
Due to a limited structural durability, cracks may occur on the front-axle wheel flanges. Such cracks could result in the mounting face of the rim on
he front axle rupturing completely.
This could lead to the loss of a front-axle wheel turning the vehicle uncontrollable.
Veasures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Description: Lorry
Batch number / Barcode: The vehicles affected were produced between May 2001 and July 2017.
Country of origin: Germany
Alert submitted by: Germany
Alert number: A12/1435/18
Product: Lorry
Name: Actros 963, Antos 963, Arocs 964
Risk type: Injuries
Category: Motor vehicles
Brand: Mercedes-Benz
Type / number of model: Type-approval No. e1*2007/46*0726-043 Type:963-0-A; 963-0-B; 963-0-C; 963-0-D; 963-0-F; 963-2-A; 963-2-B; 963-2-
E; 963-2-F; 963-4-A; 963-4-B; 963-4-C; 963-4-D; 963-4-E; 963-4-F; 963-7-E; 963-8-G; 96
Risk level: Serious risk
The outer section of the front cab air deflector may become detached from the inner section or from the vehicle.
n the worst case, the outer section may fall off increasing the risk of accident.
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Description: Lorry
Batch number / Barcode: The vehicles concerned were manufactured between 2017 and 2018.
Country of origin: Germany
Alert submitted by: Germany
Alert submitted by: Germany
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket.
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result.
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018.
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018.
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Fype / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert submitted by: Germany
Alert submitted by: Germany Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert submitted by: Germany Alert number: A12/1444/18
Alert submitted by: Germany Alert number: A12/1444/18 Product: Passenger car Alert number: A12/1444/18 Product: Passenger car Alert number: A12/1444/18 Product: Passenger car Alert submitted by: Germany Alert su
Alert submitted by: Germany Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert number: A12/1444/18 Product: Passenger car Name: CT6
Alert submitted by: Germany Alert number: A12/1444/18 Product: Passenger car Alert number: A12/1444/18 Product: Passenger car Alert number: A12/1444/18 Product: Passenger car Alert submitted by: Germany Alert su
Alert submitted by: Germany Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert number: A12/1444/18 Product: Passenger car Name: CT6
Alert submitted by: Germany Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Weasures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert submitted by: Germany Alert number: A12/1444/18 Product: Passenger car Name: CT6 Risk type: Injuries
Alert submitted by: Germany Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Fype / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert submitted by: Germany Alert number: A12/1444/18 Product: Passenger car Name: CT6 Risk type: Injuries Category: Motor vehicles Cate
Alert submitted by: Germany Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert submitted by: Germany Alert number: A12/1444/18 Product: Passenger car Name: CT6 Risk type: Injuries Category: Motor vehicles Brand: Cadillac
Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert number: A12/1444/18 Product: Passenger car Name: CT6 Risk type: Injuries Category: Motor vehicles Brand: Cadillac Type / number of model: Type-approval number: E13*2007/46*1650*00-05; Type: O1SL
Alert submitted by: Germany Alert submitted
Alert submitted by: Germany Alert submitted
Alert submitted by: Germany recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Alert submitted by: Germany Alert number: A12/1444/18 Product: Passenger car Alert submitted by: Germany Alert submitted by:
Alert submitted by: Germany Alert sub submitted by: Germany sub submitted submitted su
Alert submitted by: Germany Alert submitted by: Germany Alert number: A12/1443/18 Product: Passenger car Name: Ampera-e Risk type: Injuries Category: Motor vehicles Brane: Opel Type / number of model: Type-approval numbers: e13*2007/46*1777*00 - *05; Type: 1G0F Risk level: Serious risk A foreign object could fall into the upper steering column jacket. The steering column may block as a result. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: E18-180146 Batch number / Barcode: The vehicles affected were produced between 27 June 2016 and 31 August 2018. Country of origin: United States Nert submitted by: Germany Alert number: A12/1444/18 Product: Passenger car Name: CT6 Risk type: Injuries Category: Motor vehicles Brand: Cadillac Type / number of model: Type-approval number: E13*2007/46*1650*00-05; Type: O1SL Risk teve: Serious risk Athesive residue on the Isofix mounting brackets may prevent the child seat from being installed correctly. As a consequence, the protection of the child may not be guaranteed. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: 1822EEU Batch number / Barcode: Vehicles produced between 2016 and 2018 are affected.
Alert submitted by: Germany Alert sub submitted by: Germany sub submitted submitted su

51	2016 European Commission - Rapid Alert System
	Alert number: A12/1447/18
	Product: Passenger car
	Name: E-class, CLS, AMG GT
	Risk type: Injuries
	Category: Motor vehicles
	Brand: Mercedes-Benz
	Type / number of model: Type-approval numbers: e1*2001/116*0501*31-*35, e1*2007/46*1560*05-*08, e1*2007/46*1818*00-*01; Types: 212,
	R1ES, R1ECLS
	Risk level: Serious risk
	The calibration of the occupant classification system for the passenger seat does not work correctly.
	If a child seat is installed on the passenger seat, the airbag might not be deactivated and be deployed in the event of an accident.
	Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
	Description: Passenger car. Company recall code: 9192046 Batch number / Barcode: The vehicles concerned were produced between April 2017 and June 2018.
	Country of origin: Germany
	Alert submitted by: Germany
	Alert number: A12/1448/18
	Product: Passenger car
	Name: GLE, GLS
	Risk type: Injuries
	Category: Motor vehicles
	Brand: Mercedes-Benz
	Type / number of model: Type-approval number: e1*2007/46*0598*23-24, e1*2007/46*0826*11-12 Types: 166, 166 AMG
	Risk level: Serious risk
	The pistons on the rear axle brake callipers are inadequate.
	This may lead to reduced braking performance or failure of the rear brake circuit. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
	Description: Passenger car. Company recall code: 4292034
	Batch number / Barcode: The vehicles concerned were produced between April 2018 and June 2018.
	Country of origin: Germany
	Alert submitted by: Germany
	Alert number: A12/1460/18
	Product: Passenger car
	Name: Range Rover, Range Rover Sport, Discovery
	Risk type: Injuries
	Category: Motor vehicles Brand: Land Rover
	Type / number of model: Type Approval Numbers : Range Rover: E11*2007/46*0649; Range Rover Sport: E11*2007/46*0909; Discovery:
	E11*19/2011*249/2012*1247*01
	Risk level: Serious risk
	The Autonomous Emergency Braking (AEB) feature may not activate, without a warning message informing the driver.
	There is an increased risk of accident.
	Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
	Description: Passenger car. Company recall code: N227 Issue 1
	Batch number / Barcode: Specific vehicles built between 13/11/2017 and 17/03/2018
	Country of origin: United Kingdom
	Alert submitted by: United Kingdom
	Products were found and measures were taken also in: Germany
	Alert number: A12/1461/18
	Product: Passenger car
	Name: Outlander, Outlander PHEV
	Risk type: Injuries
	Category: Motor vehicles
	Brand: Mitsubishi
	Type / number of model: Outlander (GF0W) Outlander PHEV (GG2W), Type approval numbers: e1*2001/116*0406*26, e1*2001/116*0406*25,
	e1*2001/116*0406*24, e1*2001/116*0406*23
	Risk level: Serious risk
	The door lock mechanism in the door latch might not operate properly in high temperatures.
	As the result the door may not be locked properly and could open while the vehicle is moving.
	Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
	Description: Passenger car. Company recall code: ENL-18-020-SR
	Batch number / Barcode: Model Year: - Outlander (GF0W): 2014,5 - 2016,5 - Outlander PHEV (GG2W): 2015-2016
	Country of origin: Japan
	Alert submitted by: Poland Products were found and measures were taken also in: The Netherlands

Alert number: A12/1462/18 Product: Passenger car Name: Outlander, Outlander PHEV, Lancer, Lancer Sportback Risk type: Injuries Category: Motor vehicles Brand: Mitsubishi Type / number of model: Outlander (GF0W) Outlander PHEV (GG2W) Lancer (CY0A) Lancer Sportback (CX0A), Type approval numbers: e1*2001/116*0441*19, e1*2001/116*0441*20, e1*2001/116*0406*22, e1*2001/116*0406*25, e1*2001/116*0406*24, e1*2001/116*0406*26, e1*2001/116*0406*21, e1*2001/116*0406*20,, e1*2001/116*0406*23 Risk level: Serious risk The engine control relay unit (ECU) or valve lift control relay can heat up abnormally. As the result the engine can stall whilst driving. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: ENL-18-021-SR Batch number / Barcode: Model Year: - Outlander (GF0W): 2014,5 - 2017 - Outlander PHEV (GG2W): 2014,5-2016 - Lancer (CY0A): 2015-2016 - Lancer Sportback (CX0A): 2015-2016 Country of origin: Japan Alert submitted by: Poland Products were found and measures were taken also in: The Netherlands Alert number: A12/1464/18 Product: Passenger car Name: Tiguan Allspace Risk type: Injuries Category: Motor vehicles Brand: VW Type / number of model: Type-approval number: e1*2001/116*0450*33; Type: 5N Risk level: Serious risk The lower securing eye of the rear gas-filled shock absorbers may be incorrectly welded. As a consequence, the shock absorber attachment on the rear axle may come loose and affect vehicle handling. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: 4218 Batch number / Barcode: The vehicles affected were produced between 15.1.2018 and 14.3.2018. Country of origin: Germany Alert submitted by: Germany Products were found and measures were taken also in: The Netherlands Alert number: A12/1465/18 Product: Passenger car Name: Compass Risk type: Injuries Category: Motor vehicles Brand: Jeep Type / number of model: Type-approval number: e11*2007/46*4037*02; Type: MX Risk level: Serious risk Due to inadequate welding, the front transverse control arm may break. This could consequently lead to a loss of driving stability. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Copmany recall code: U42 Batch number / Barcode: The vehicles affected were produced between 12 January 2018 and 21 January 2018. Country of origin: United States Alert submitted by: Germany Alert number: A12/1466/18 Product: Passenger car Name: Compass Risk type: Injuries Category: Motor vehicles Brand: Jeep Type / number of model: Type-approval number: e11*2007/46*4037*01; Type: MX Risk level: Serious risk The electrical connections for the daytime running lamps are inadequate and the lights may be disabled by the driver. As a consequence, the visibility of the vehicle and its identification by other drivers may be reduced. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Company recall code: T77 Batch number / Barcode: The vehicles in question were manufactured between 15 December 2016 and 26 October 2017. Country of origin: United States Alert submitted by: Germany

Alert number: A12/1468/18 Product: Passenger car Name: EcoSport Risk type: Injuries Category: Motor vehicles Brand: Ford Type / number of model: Type approval number e9^2007/46*0092*17 Risk level: Serious risk The lower control arm weld may not be correctly welded. As a consequence, the front wheel assembly may hit the wheel arch, causing the front wheel to lock up, resulting in loss of steering control and motive power. Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) Description: Passenger car. Batch number / Barcode: Specific vehicles built between 02/05/2017 and 10/06/2017 Country of origin: India Alert submitted by: United Kingdom Products were found and measures were taken also in: The Netherlands Alert number: A12/1441/18 Product: Luggage tag Name: Luggage tag, Smiley Risk type: Chemical Category: Other Brand: Unknown Type / number of model: Unknown Risk level: Serious risk The product contains lead (measured value: 0.5%). Exposure to lead is harmful for human health. It also contains di-(2-ethylhexyl) phthalate (DEHP) (measured value 7.4 % by weight) This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Distributor) Measures ordered by public authorities (to: Distributor): Withdrawal of the product from the market Description: Luggage tag in the shape of a yellow smiley in PVC material Batch number / Barcode: 5037200041699 Country of origin: China Alert submitted by: Sweden



Alert number: A12/1437/18 Product: Plastic doll Name: Charm Girl - Friend Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: N° 6623 Risk level: Serious risk The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 20.1% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.

Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market **Description:** Plastic doll with accessories in a cardboard box with transparent cover.

Batch number / Barcode: 5290509051978 Country of origin: China

Alert submitted by: Cyprus



Alert number: A12/1438/18 Product: Plastic doll Name: Sweet Love Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: N° 669 Risk level: Serious risk The plastic material of the doll's head contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 9.9% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation. Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market Description: A baby doll in a pink plastic bath tub. Batch number / Barcode: 5291410115278 Country of origin: China Alert submitted by: Cyprus

weeto





Alert number: A12/1439/18 Product: Plastic doll Name: Happy Girl Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: N° 5558 Risk level: Serious risk The plastic material of the doll conta

The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 19.8 % by weight), di-butyl phthalate (DBP) (measured value: 0.9% by weight) and di-'isononyl' phthalate (DINP) (measured value: 13.3% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system or the liver.

The product does not comply with the REACH Regulation.

Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market Description: Plastic doll in a cone-shaped cardboard package. Batch number / Barcode: Unknown Country of origin: China Alert submitted by: Cyprus





Alert number: A12/1442/18 Product: Children's fancy-dress costume Name: DRAGON Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: Article code: 88067 Risk level: Serious risk The orange textile of the costume contains the flame retardant tris(1,3-dichloro-2-propyl)phosphate (TDCP) (measured value up to 21 mg/kg) The flame retardant can be harmful to children due to its carcinogenic properties and acute toxicity. The product does not comply with the requirements of the Toy Safety Directive. Measures taken by economic operators: Recall of the product from end users (By: Importer) Description: Fancy-dress costume in the form of a blue dragon with orange wings, sold in transparent plastic packaging. Batch number / Barcode: 3613600062353 Country of origin: China Alert submitted by: France







Alert number: A12/1445/18 Product: Plastic doll with accessories Name: Beauty New Series Risk type: Chemical Category: Toys Brand: Unknown Type / number of model: Unknown Risk level: Serious risk The plastic material of the doll's head contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 28.3% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.

Measures ordered by public authorities (to: Importer): Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market

Description: Doll with removable soft plastic head and accessories (bicycle, helmet, two additional dresses) in colourful cardboard packaging. **Batch number / Barcode:** Unknown

Country of origin: China

Alert submitted by: Germany



Alert number: A12/1446/18 Product: Soft toy Name: plüss figura Risk type: Choking Category: Toys Brand: Unknown Type / number of model: No:0827/1400146 Risk level: Serious risk The eyes and the nose can easily detach from the soft toy, generating small parts.

A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. **Measures ordered by public authorities (to: Distributor):** Recall of the product from end users, Withdrawal of the product from the market **Description:** Red plush monkey wearing glasses and a plaid tie. The product is sold without packaging. **Batch number / Barcode:** 8009214001461 **Country of origin:** China

Alert submitted by: Hungary





Alert number: A12/1454/18 Product: Toy scooter Name: roller Risk type: Injuries Category: Toys Brand: Big Type / number of model: Art.Nr.800056868 Risk level: Serious risk The steering tube can become detached while the child is riding the scooter. The child could consequently fall and get injured.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1. **Measures ordered by public authorities (to: Distributor):** Recall of the product from end users, Withdrawal of the product from the market **Description:** Green and blue, plastic, four-wheeled scooter. The scooter is packed in a cardboard box. Max load capacity: 20 kg **Batch number / Barcode:** 4004943568685

Country of origin: Germany Alert submitted by: Hungary









Alert number: A12/1455/18 Product: Toy scooter Name: lábbal hajtható kismotor Risk type: Injuries Category: Toys Brand: REGIO JATEK Type / number of model: Art.3743 Risk level: Serious risk The steering column can break while the child is riding the scooter. As a result, the child could fall off and get injured.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. **Measures ordered by public authorities (to: Importer):** Recall of the product from end users, Withdrawal of the product from the market **Description:** A four-wheeled, plastic scooter imitating a snake, in green and orange colours with a foldable steering column. **Batch number / Barcode:** 4823037603473 **Country of origin:** Ukraine

Alert submitted by: Hungary





Alert number: A12/1456/18
Product: Toy scooter
Name: SCOOTER
Risk type: Injuries
Category: Toys
Brand: Unknown
Type / number of model: A5716-BH-J-006-010 (on a label)
Risk level: Serious risk
The steering column is not sufficiently resistant to load and can deform. In addition, the front wheel is too small and could get stuck in holes in the
ground.
This could cause the child to lose balance and fall off, leading to injuries.
The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.
Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market
Description: Foldable, two-wheeled, metal framed scooter with height adjustable handlebar, decorated with fairytale figures.
Batch number / Barcode: 5160855320083

Country of origin: China

TIM

Alert submitted by: Hungary



Alert number: A12/1459/18 Product: Squeezable toy Name: Squishes - Slow Rising Scented Squishy Risk type: Choking, Suffocation Category: Toys Brand: Unknown Type / number of model: Item number 67887 Risk level: Serious risk Due to its shape, colour, appearance and size th

Due to its shape, colour, appearance and size, the product may be mistaken for foodstuff and the outer plastic packaging is too thin and too large. Small parts can easily be detached from the product and this may lead children to put them in the mouth and choke. If a child plays with the packaging the plastic could cover the mouth and nose, blocking the airways.

The product does not comply with the requirements of the Food-imitating products directive and the Toy Safety Directive. **Measures ordered by public authorities (to: Retailer):** Recall of the product from end users

Description: Squeezable (squishy) toy in the shape of a slice of cake, coloured pink and white with a strawberry on top.

Batch number / Barcode: 5053944678878

Country of origin: China

Alert submitted by: United Kingdom





Alert number: A12/1463/18 Product: Plush toy Name: Plüss kabala figurák Risk type: Choking Category: Toys Brand: Unknown Type / number of model: A-20089 Risk level: Serious risk The eyes, nose and the suction cup can easily detach from the toy, generating small parts. A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. **Measures taken by economic operators:** Recall of the product from end users (By: Retailer) **Description:** Plush teddy bear (approximately 20 cm tall) with a suction cup attached by a cord. **Batch number / Barcode:** 6956520200892 **Country of origin:** China

Alert submitted by: Slovenia



Alert number: A12/1474/18 Product: Pull-along toy Name: Ella Risk type: Choking Category: Toys Brand: Scratch Europe Type / number of model: 6181009 Risk level: Serious risk The knob on the back of the dog can easily detach. A child could put it in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. **Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market **Description:** Wooden pull-along toy, in the shape of a dog, with white body and pink wheels and tail. The dog can play music and has a bell at

Description: Wooden pull-along toy, in the shape of a dog, with white body and pink wheels and tail. The dog can play music and has a bell at the neck.

Batch number / Barcode: Batch: 22154121601045 Code: 5414561810094 Country of origin: China Alert submitted by: The Netherlands

