



European Commission ([http://ec.europa.eu/index\\_en.htm](http://ec.europa.eu/index_en.htm)) Consumers ([http://ec.europa.eu/consumers/index\\_en.htm](http://ec.europa.eu/consumers/index_en.htm))

Consumers safety ([http://ec.europa.eu/consumers/consumers\\_safety/index\\_en.htm](http://ec.europa.eu/consumers/consumers_safety/index_en.htm))

Safety products ([http://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/index\\_en.htm](http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/index_en.htm))

🏠 [Rapid Alert System home \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/repository/content/pages/rapex/index\\_en.htm\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

☰ [Back to report listings \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.listNotifications&year=2018\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2018)

🔍 [Search alerts \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.search\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search)

👉 [Safe Products Online \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=SafeProductsOnline\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline)

## The Rapid Alert System for Non-Food Products (RAPEX)

### *RAPEX - Weekly overview report of notifications*

week 41 - 2018

**Alert number:** A12/1478/18

**Product:** Girls' bikini

**Name:** Unknown

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** Modern Ocean

**Type / number of model:** 04110097 ART:CR1908

**Risk level:** Serious risk

The top part of the bikini has functional cords to be tied at the back.

The cords can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682.

**Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market

**Description:** Black and red bikini for 6 year-old girls.

**Batch number / Barcode:** 2500000050596

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/1479/18

**Product:** Girls' bikini

**Name:** Unknown

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** Hello Bikini

**Type / number of model:** 04110005 Art No: HELLO-013

**Risk level:** Serious risk

The top part of the bikini has functional cords to be tied at the back.

The cords can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682.

**Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market

**Description:** Pink bikini for 2 year-old girls.

**Batch number / Barcode:** 2500000049675

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/1480/18

**Product:** Leather shoes

**Name:** Unknown

**Risk type:** Chemical

**Category:** Clothing, textiles and fashion items

**Brand:** Natura

**Type / number of model:** A11039-11

**Risk level:** Serious risk

The amount of chromium (VI) found in the outer leather is too high (measured value up to 7,9 mg/kg). Chromium (VI) is sensitising and may trigger allergic reactions.

The product does not comply with the REACH Regulation.

**Measures ordered by public authorities (to: Importer):** Import rejected at border

**Description:** Red leather ankle boots with zip, red shoe laces and medium-high heels.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Finland



**Alert number:** A12/1481/18

**Product:** Girls' dress

**Name:** Unknown

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** Mono Star fashion&girl

**Type / number of model:** F3020

**Risk level:** Serious risk

The dress has functional cords to be tied at the back.

The cords can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682.

**Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market

**Description:** Denim dress with cords in the waist area, intended for 6 year-old girls.

**Batch number / Barcode:** 2210000279445

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/1482/18

**Product:** Girls' bikini

**Name:** Unknown

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** Power Flower

**Type / number of model:** AA158 / 18S1C16002

**Risk level:** Serious risk

The top part of the bikini has functional cords to be tied at the back.

The cords can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682.

**Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market

**Description:** Blue and white bikini with floral pattern intended for children up to 10 year-old.

**Batch number / Barcode:** 2210000283442, 5553724141580

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/1483/18

**Product:** Girls' bikini

**Name:** Unknown

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** YES ! DO KID'S

**Type / number of model:** YES-99045

**Risk level:** Serious risk

The top part of the bikini has functional cords to be tied at the back.

The cords can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European standard EN 14682.

**Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market

**Description:** Pink bikini with floral pattern intended for 9-10 year-old girls.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/1489/18

**Product:** Children's bikini

**Name:** Unknown

**Risk type:** Choking

**Category:** Clothing, textiles and fashion items

**Brand:** Ronis Kids Fashion

**Type / number of model:** Unknown

**Risk level:** Serious risk

Small decorative elements (rhinestones) may be easily detached.

A small child may put them in the mouth and choke.

**Measures ordered by public authorities (to: Distributor):** Withdrawal of the product from the market

**Description:** Children's bikini, decorated with glued small rhinestones, intended for girls up to 3 years of age.

**Batch number / Barcode:** Unknown

**Country of origin:** Bulgaria

**Alert submitted by:** Bulgaria



**Alert number:** A12/1493/18

**Product:** Leather handbag

**Name:** Unknown

**Risk type:** Chemical

**Category:** Clothing, textiles and fashion items

**Brand:** Unknown

**Type / number of model:** Article No 84049

**Risk level:** Serious risk

The amount of nickel released from the clasp of the bag is too high (measured value up to 51 µg/cm<sup>2</sup>/week).

Nickel is a strong sensitiser and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Recall of the product from end users (By: Retailer)

**Description:** Handbag with detachable strap, available in various designs, with a silvery metal ball clasp. No packaging.

**Batch number / Barcode:** 4008280340874

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1486/18

**Product:** Tea light candle

**Name:** Unknown

**Risk type:** Fire

**Category:** Decorative articles

**Brand:** Maisen

**Type / number of model:** Unknown

**Risk level:** Serious risk

The candle's container is destroyed as the candle burns which could lead to a risk of fire.

The product does not comply with the relevant European standard EN 15493.

**Measures ordered by public authorities (to: Distributor):** Withdrawal of the product from the market

**Description:** Tea light candle available with five different fragrances – coffee, apple, lavender, ocean and rose.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Bulgaria



**Alert number:** A12/1495/18

**Product:** Earrings

**Name:** ER Lena Mixy

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Colloseum Accessories

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains cadmium (measured value: 50 % by weight).

Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Ban on the marketing of the product and any accompanying measures (By: Retailer)

**Description:** Metal earrings with rhinestones, sold on a white plastic cardboard.

**Batch number / Barcode:** 4057328159114

**Country of origin:** China

**Alert submitted by:** Germany





**Alert number:** A12/1496/18

**Product:** Earrings

**Name:** ER Lena Mixy

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Colloseum Accessories

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains cadmium (measured value: 45 % by weight).

Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Retailer)

**Description:** Two metal earrings in the shape of leaves with black rhinestones on a white cardboard.

**Batch number / Barcode:** 4057328158933

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1497/18

**Product:** Necklace

**Name:** NL Katie Mixy

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Colloseum Accessories

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains lead (measured value: 20% in weight).

Lead is harmful to human health as it accumulates in the body and may damage the unborn child.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Retailer)

**Description:** Gold-colored necklace on white cardboard sheet with black imprint

**Batch number / Barcode:** 4057328220081

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1498/18

**Product:** Necklace

**Name:** NL Katie Mixy

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Colloseum Accessories

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains lead (measured value: 16% in weight).

Lead is harmful to human health as it accumulates in the body and may damage the unborn child.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Retailer)

**Description:** Rose-golden coloured necklace with pendant on white cardboard.

**Batch number / Barcode:** 4057328220050

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1499/18

**Product:** Necklace

**Name:** NL Aimee Mixy

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Colloseum Accessories

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains cadmium (measured value: 90 % by weight).

Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Retailer)

**Description:** Leather necklace with gold-coloured metal pendants in the shape of wings, on white cardboard.

**Batch number / Barcode:** 4057328204449

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1502/18

**Product:** Necklace

**Name:** NL Aimee Mixy

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Colloseum Accessories

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains cadmium (measured value: 90% by weight).

Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Retailer)

**Description:** Silver-coloured necklace in the shape of a dream catcher with black beads, attached to a white cardboard label.

**Batch number / Barcode:** 4057328204463

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1503/18

**Product:** Earrings

**Name:** ER Lena Mixy

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Colloseum Accessories

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains cadmium (measured value: 45% by weight).

Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Retailer)

**Description:** Metal earring in the shape of a leaf, on white cardboard.

**Batch number / Barcode:** 4057328158995

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1504/18

**Product:** Necklace

**Name:** NL Aimee Mixy

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Colloseum Accessories

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains cadmium (measured value: 90% by weight).

Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Retailer)

**Description:** Gold-coloured necklace with feather-styled pendant on white cardboard.

**Batch number / Barcode:** 4057328204487

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1487/18

**Product:** Novelty lighter

**Name:** LIGHTER BULLET 2009

**Risk type:** Fire

**Category:** Lighters

**Brand:** Unknown

**Type / number of model:** Unknown

**Risk level:** Serious risk

The lighter is appealing to children.

Children may play with it and cause a fire.

The product does not comply with the relevant European standard EN 13869.

**Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market

**Description:** A lighter in the form of a bullet.

**Batch number / Barcode:** Unknown

**Country of origin:** Unknown


**Alert submitted by:** Bulgaria



**Alert number:** A12/1488/18  
**Product:** Novelty lighter  
**Name:** Unknown  
**Risk type:** Fire  
**Category:** Lighters  
**Brand:** ZHONGLIANGLIGHTER  
**Type / number of model:** 201430422251.x and 201430422252.x4  
**Risk level:** Serious risk  
 The lighter is appealing to children.  
 Children may play with it and cause a fire.

The product does not comply with the relevant European standard EN 13869.

**Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market  
**Description:** A lighter in the form of a purple and white sports shoe with a key-ring attached.  
**Batch number / Barcode:** Unknown  
**Country of origin:** Unknown  
**Alert submitted by:** Bulgaria



**Alert number:** A12/1476/18  
**Product:** Lorry  
**Name:** Atego  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Mercedes-Benz  
**Type / number of model:** Type-approval numbers: e1\*2007/46\*1170, e1\*2007/46\*1171, e1\*2007/46\*1650, e1\*2007/46\*1651, e13\*2007/46\*1741, e13\*2007/46\*1742; types: 967PKX2, 967PKX3, 967PKX3-T, 967PKX2-T, 967PKX2-M, 967PKX3-M  
**Risk level:** Serious risk  
 The hose coupling on the connecting pipe to the multiple tank system may slip out of place.  
 This could result in leakage of a considerable amount of fuel, thus increasing the risk of accident for the following traffic.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Lorry  
**Batch number / Barcode:** The vehicles in question were manufactured between 1 November 2016 and 28 February 2018.  
**Country of origin:** Germany  
**Alert submitted by:** Germany

**Alert number:** A12/1484/18  
**Product:** Passenger car  
**Name:** Grandland X  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Opel  
**Type / number of model:** Type-approval number: e2\*2007/46\*0597\*04; type: Z  
**Risk level:** Serious risk  
 The crankcase seal plug has not been correctly tightened.  
 This may lead to oil leaking through the engine compartment onto the road, creating a hazard for following traffic.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car. Company recall code: E181801720 (18-C-058)  
**Batch number / Barcode:** The vehicles affected were produced between April 2018 and May 2018.  
**Country of origin:** France  
**Alert submitted by:** Germany

**Alert number:** A12/1485/18  
**Product:** Passenger car  
**Name:** C4 Aircross  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Citroën  
**Type / number of model:** e2\*2007/46\*0117\*02, e2\*2007/46\*0117\*03, e2\*2007/46\*0117\*04, e2\*2007/46\*0117\*05, e2\*2007/46\*0117\*06  
**Risk level:** Serious risk  
 The axle of the parking brake caliper has not been correctly sealed and might corrode.  
 As a consequence, the parking brake may become less effective or fail completely.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car. Company recall code: GJC  
**Batch number / Barcode:** Vehicles manufactured between 1.10.2012 and 1.2.2016 — VIN: VF7BU9HD8DZ900101 to VF7BU9HD5GZ909876  
**Country of origin:** France  
**Alert submitted by:** France

**Alert number:** A12/1490/18  
**Product:** Lorry  
**Name:** Atego  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Mercedes-Benz  
**Type / number of model:** Type-approval numbers: e1\*2007/46\*1170, e1\*2007/46\*1171; types: 967PKX2, 967PKX3  
**Risk level:** Serious risk  
 The barrel nuts on the adapter plate of the traction assistance (skid chain) may become detached.  
 This could result in the loss of the skid-chain unit, increasing the risk of accident for the following traffic.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Lorry  
**Batch number / Barcode:** The vehicles affected were produced between 15 August 2017 and 7 September 2017.  
**Country of origin:** Germany  
**Alert submitted by:** Germany

**Alert number:** A12/1491/18  
**Product:** Passenger car  
**Name:** Mondeo  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Ford  
**Type / number of model:** Type Approval number e13\*2001/116\*0249\*35  
**Risk level:** Serious risk  
 The glass adhesive layer of the tilt/slide sun-roof could delaminate.  
 As a result, the glass panel could become loose or even detach during vehicle operation.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car  
**Batch number / Barcode:** Specific Vehicles built between Date range 22/08/2017 to 14/12/2017  
**Country of origin:** Spain  
**Alert submitted by:** United Kingdom

**Alert number:** A12/1500/18  
**Product:** Passenger car  
**Name:** Ram  
**Risk type:** Fire  
**Category:** Motor vehicles  
**Brand:** Dodge  
**Type / number of model:** individual approval  
**Risk level:** Serious risk  
 Fracture of the fuel tank mounting may cause the tank to drop and come into contact with the road surface.  
 There is a risk of a fuel leak, which could cause a fire.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car. Company recall code: U04  
**Batch number / Barcode:** The vehicles concerned were produced between 28 May 2008 and 31 January 2012.  
**Country of origin:** United States  
**Alert submitted by:** Germany



**Alert number:** A12/1501/18  
**Product:** Passenger car  
**Name:** Liberty  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Jeep  
**Type / number of model:** EC type-approval: e4\*98/14\*0058\*04; type: KJ  
**Risk level:** Serious risk  
Corrosion on the rear transverse control arms may cause them to break.  
This can result in loss of driving stability.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car. Company recall code: U38  
**Batch number / Barcode:** The vehicles in question were produced between 29 April 2003 and 29 June 2007.  
**Country of origin:** Germany  
**Alert submitted by:** Germany  
**Products were found and measures were taken also in:** The Netherlands

**Alert number:** A12/1505/18  
**Product:** Passenger car  
**Name:** Compass  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Jeep  
**Type / number of model:** EC type-approval: e11\*2007/46\*4037\*00; type: MX  
**Risk level:** Serious risk  
A faulty rear seat-back locking mechanism could lead to the seat back folding forward unexpectedly in the event of rapid deceleration.  
As a consequence, luggage from the boot space may enter the passenger compartment, increasing the risk of injury.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car. Company recall code: U12  
**Batch number / Barcode:** The vehicles affected were produced between 27 October 2017 and 21 February 2018.  
**Country of origin:** United States  
**Alert submitted by:** Germany  
**Products were found and measures were taken also in:** The Netherlands

**Alert number:** A12/1507/18  
**Product:** Passenger car  
**Name:** 4008  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Peugeot  
**Type / number of model:** e2\*2007/46\*0115\*02, e2\*2007/46\*0115\*03, e2\*2007/46\*0115\*04, e2\*2007/46\*0115\*05, e2\*2007/46\*0115\*06  
**Risk level:** Serious risk  
The axle of the parking brake caliper has not been correctly sealed and might corrode.  
As a consequence, the parking brake may become less effective or fail completely.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car. Company recall code: JAT  
**Batch number / Barcode:** Vehicles manufactured between 1.10.2012 and 4.2.2016 — VIN: VF3BU9HDBDZ800101 to VF3BU9HDKGZ804035  
**Country of origin:** France  
**Alert submitted by:** France  
**Products were found and measures were taken also in:** Germany

**Alert number:** A12/1508/18  
**Product:** Passenger car  
**Name:** X5  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** BMW  
**Type / number of model:** Type-approval number: e1\*98/14\*0153\* Type: X53  
**Risk level:** Serious risk  
The software of the airbag control device has been incorrectly programmed.  
As a consequence, simultaneously switching off the engine and applying the handbrake may unintentionally activate the frontal airbag.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car. Company recall code 0065110300  
**Batch number / Barcode:** The vehicles in question were produced between 1 March 2001 and 28 February 2002.  
**Country of origin:** Germany  
**Alert submitted by:** Germany

**Alert number:** A12/1477/18

**Product:** Plastic doll

**Name:** Cute baby

**Risk type:** Chemical

**Category:** Toys

**Brand:** Ledy Toys

**Type / number of model:** K3 / LD66003A

**Risk level:** Serious risk

The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 2.9 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

**Measures ordered by public authorities (to: Importer):** Withdrawal of the product from the market

**Description:** A plastic doll in a cardboard box with transparent cover.

**Batch number / Barcode:** 6991203990141

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/1492/18

**Product:** Soft ball with spikes

**Name:** Unknown

**Risk type:** Choking

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** Unknown

**Risk level:** Serious risk

A small part (whistle) may easily detach from the toy.  
Small children might put it in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures ordered by public authorities (to: Retailer):** Ban on the marketing of the product and any accompanying measures

**Description:** Light blue ball with spikes, made of soft plastic material with a light and whistle (squeaking element) inside.

**Batch number / Barcode:** 7392870100335

**Country of origin:** China

**Alert submitted by:** Finland



**Alert number:** A12/1494/18

**Product:** Wooden toy set

**Name:** Hammer and nails game

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product emits high concentrations of formaldehyde into the ambient air (measured value up to 981 mg/kg).  
Formaldehyde can cause skin irritation when in contact with the skin and is carcinogenic.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-9.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Importer)

**Description:** Wooden toy consisting of flat wooden pieces in various colours and shapes, metal nails, a wooden hammer, rectangular particle board made of cardboard, supplied in a cardboard box.

**Batch number / Barcode:** 4012093692426

**Country of origin:** China

**Alert submitted by:** Germany



**Alert number:** A12/1506/18

**Product:** Plastic strings

**Name:** Fils de scoubidou

**Risk type:** Chemical

**Category:** Toys

**Brand:** Ammi

**Type / number of model:** reference 261059, model 1

**Risk level:** Serious risk

The strings contain bis (2-ethylhexyl) phthalate (DEHP) (measured value: up to 30% by weight).

This phthalate may harm the health of children, causing possible damage to the reproductive system.

The migration of organotin compounds of the materials is too high (measured value: up to 63mg/kg). Organotins are toxic and may harm human health.

The product does not comply with the REACH Regulation, with the requirements of the Toy Safety Directive and the relevant European standard 71-3.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Glittery plastic strings, two different packs of assorted colours.

**Batch number / Barcode:** 3700043010598

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/1509/18

**Product:** Illuminating wand

**Name:** Bacchetta luminosa

**Risk type:** Choking

**Category:** Toys

**Brand:** Carnival toys

**Type / number of model:** article 06403

**Risk level:** Serious risk

Small parts of the toy (screw) can easily be detached.

A child may put the small parts in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1 and EN 62115.

**Measures ordered by public authorities (to: Importer):** Withdrawal of the product from the market

**Description:** Battery-operated magic wand consisting of a handle with battery compartment, a pumpkin-shaped head containing an LED and a flexible metal (spring) connector.

**Batch number / Barcode:** batch 01-2017 -Barcode 8004761064037

**Country of origin:** China

**Alert submitted by:** Italy



**Alert number:** A12/1510/18

**Product:** Baby teether

**Name:** Animal Teether - Bunny

**Risk type:** Choking

**Category:** Toys

**Brand:** Fabelab

**Type / number of model:** Style Code: A - teether - CB17

**Risk level:** Serious risk

The wooden ring may break during use, generating small parts.

A small child may put the small parts in the mouth and choke on them.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Distributor)

**Measures ordered by public authorities (to: Distributor):** Recall of the product from end users

**Description:** Textile ears and wooden ring teether. Sold with in a plastic pack with a cardboard leaflet.

**Batch number / Barcode:** 5713034001701

**Country of origin:** India

**Alert submitted by:** Finland

