



🏠 [Safety Gate home \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/repository/content/pages/rapex/index\\_en.htm\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

☰ [Back to report listings \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.listNotifications&year=2020&lng=en\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2020&lng=en)

🔍 [Search alerts \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.search&lng=en\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search&lng=en)

👍 [IPSW 2018 \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=ipsw:home\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=ipsw:home)

## The Rapid Alert System for Non-Food Products (RAPEX)

### *RAPEX - Weekly overview report of notifications*

Week 18 - 2019

**Alert number:** A12/0681/19

**Product:** Round barbecue

**Name:** Dr Grill

**Risk type:** Burns, Fire

**Category:** Kitchen/cooking accessories

**Brand:** Planta

**Type / number of model:** 11935

**Type of alert:** Products with serious risks

The grill pit is insufficiently deep.

Burning parts of fuel (charcoal) can easily fall out of the barbecue grill causing fire or burns to users or children near the barbecue.

The product does not comply with the relevant European standard EN 1860-1.

Withdrawal of the product from the market

**Description:** Round metal barbecue, diameter: 35.6 cm, height: 44.5 cm. Packaging: cardboard box.

**Batch number / Barcode:** 5907516712869

**Country of origin:** China

**Alert submitted by:** Poland

Wyprodukowano dla Grupy Ogrodniczej Planta  
Współpraca 2002

**Planta**  
Grupa Ogrodnicza Planta

Importer i dystrybutor:  
PLANTA Sp. z o.o.  
ul. Wyszynskiego 16A, 33-100 Tamów  
POLAND  
tel: +48 14 63 95 500  
fax: +48 14 63 95 501  
biuro@planta.net.pl  
www.planta.net.pl

**Model: 11935**  
Wymiary: średnica 14" (35,6 cm)  
wys. 44,5 cm



**Alert number:** A12/0680/19

**Product:** Lighting chain

**Name:** LED 200 BOMBILLAS

**Risk type:** Electric shock

**Category:** Lighting chains

**Brand:** Unknown

**Type / number of model:** LED-GSK-200; REF: 1101370

**Type of alert:** Products with serious risks

The mains cable is not properly anchored and can detach.

As a consequence, live parts may become accessible, which could result an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Recall of the product from end users, Withdrawal of the product from the market

**Description:** Lighting chain with 200 non-replaceable blue LED lamps. Packaging: transparent plastic box with a colourful printed card inside.

**Batch number / Barcode:** 3 000011 013701

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/0696/19

**Product:** Lighting chain

**Name:** RPGT Noël guirlande lumineuse LED

**Risk type:** Electric shock

**Category:** Lighting chains

**Brand:** Foshan Youcheng Electric appliance

**Type / number of model:** model FSYC200L

**Type of alert:** Products with serious risks

The pin on the lighting chain plug (intended to be powered at extra-low safety voltages) fits into the network connector under dangerous voltage (low voltage).

The lighting chain may therefore be under a voltage for which the insulation is insufficient, which may cause an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European Standard 60598.

This product listing was removed by Amazon., Withdrawal of the product from the market

**Description:** Lighting chain with 200 multicoloured LED lights. The product was sold online, in particular via Amazon.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0685/19

**Product:** Passenger car

**Name:** C-Class, GLC F-Cell

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** Mercedes-Benz

**Type / number of model:** Type-approval numbers: e1\*2001/116\*0431\*47-\*50, e1\*2001/116\*0457\*38-\*41, e1\*2001/116\*0480\*31; types: 204, 204 K, 204 X

**Type of alert:** Products with serious risks

The sleep mode functionality of the electronic parking brake within the electronic stability programme (ESP) software may be defective.

As a result, the brake lights may be permanently activated or the ESP function could be deactivated, increasing the risk of an accident.

Recall of the product from end users

**Description:** Passenger car under Mercedes-Benz recall code: 5498904.

**Batch number / Barcode:** The affected vehicles were manufactured between June 2017 and November 2018.

**Country of origin:** Germany

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** Bulgaria, Croatia, Denmark, Finland, Iceland, Luxembourg, Poland, Portugal, Slovakia, Slovenia, Sweden

**Alert number:** A12/0686/19

**Product:** Passenger car

**Name:** Combo

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** Opel

**Type / number of model:** Type-approval numbers: e2\*2007/46\*0622\*00-\*04; e2\*2007/46\*0623\*02-\*04; Type: E

**Type of alert:** Products with serious risks

Possible misalignment of the ratchet on the handbrake lever latching mechanism.

As a result the handbrake may not engage or could disengage by itself, increasing the risk of an accident.

Recall of the product from end users

**Description:** Passenger car under Opel recall code: E19-190092.

**Batch number / Barcode:** The affected vehicles were manufactured between September 2017 and February 2019.

**Country of origin:** Spain

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** Bulgaria, Denmark, Finland, Luxembourg, Poland, Portugal, Slovakia, Slovenia

**Alert number:** A12/0687/19  
**Product:** Trailer  
**Name:** SB4003  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Stedele  
**Type / number of model:** Type-approval number: e1\*2007/46\*0159\*03; type: SA-U  
**Type of alert:** Products with serious risks  
The wheel nuts may be inadequate.  
As a result the wheels may come loose, increasing the risk of an accident.  
Recall of the product from end users  
**Description:** Trailer under Stedele recall code: Recall wheel screws.  
**Batch number / Barcode:** The affected vehicles were manufactured between 2017 and 2019.  
**Country of origin:** Germany  
**Alert submitted by:** Germany

**Alert number:** A12/0688/19  
**Product:** Passenger car  
**Name:** Giulia, Stelvio  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Alfa Romeo  
**Type / number of model:** Type-approval numbers: e3\*2007/46\*0382\*11, e3\*2007/46\*0435\*08; types: 952, 949  
**Type of alert:** Products with serious risks  
The seat guides may be inadequate and the seats may be wrongly positioned.  
As a result the seats could become detached in motion, increasing the risk of an accident.  
Recall of the product from end users  
**Description:** Passenger car under Alfa Romeo recall code: 8239.  
**Batch number / Barcode:** The affected vehicles were manufactured between 14 November 2018 and 7 February 2019.  
**Country of origin:** Italy  
**Alert submitted by:** Germany  
**Products were found and measures were taken also in:** Bulgaria, Denmark, Hungary, Luxembourg, Poland, Slovenia

**Alert number:** A12/0693/19  
**Product:** Passenger car  
**Name:** RAV4, Corolla, UX, ES  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Toyota, Lexus  
**Type / number of model:** Type-approval numbers: e6\*2007/46\*0289 (RAV4), e6\*2007/46\*0318 (Corolla), e6\*2007/46\*0263 (UX), e6\*2007/46\*0250 (ES)  
**Type of alert:** Products with serious risks  
The emergency calling system may not be correctly installed.  
As a consequence, the emergency calling system will not activate automatically in the case of an accident.  
Recall of the product from end users  
**Description:** Passenger car.  
**Batch number / Barcode:** The affected vehicles were manufactured in 2018 and 2019.  
**Country of origin:** Japan  
**Alert submitted by:** Portugal  
**Products were found and measures were taken also in:** Bulgaria, Croatia, Denmark, Finland, Hungary, Iceland, Poland, Slovakia, Slovenia, Sweden

**Alert number:** A12/0694/19  
**Product:** Passenger car  
**Name:** Crossland X  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Opel  
**Type / number of model:** Type-approval number: e4\*2007/46\*1194\*07  
**Type of alert:** Products with serious risks  
The rear axle bolts may be defective and could break.  
This could lead to loss of control over the vehicle, increasing the risk of an accident.  
Recall of the product from end users  
**Description:** Passenger car under Opel Recall code: 19-C-040 (E191901361).  
**Batch number / Barcode:** Model year: 2019.  
**Country of origin:** Spain  
**Alert submitted by:** Portugal  
**Products were found and measures were taken also in:** Bulgaria, Croatia, Denmark, Finland, Poland, Slovenia, Sweden

**Alert number:** A12/0695/19

**Product:** Passenger car

**Name:** Accord, Civic and Odyssey

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** Honda

**Type / number of model:** Model codes: Accord (CM5), Civic (ES1), Odyssey (RL1); VIN ranges: Accord (1HGCM5\*\*\*\*808193 to 1HGCM5\*\*\*\*23112), Civic (2HGES1\*\*\*\*585989 to 2HGES1\*\*\*\*915720), Odyssey (5FNRL18064B072434).

**Type of alert:** Products with serious risks

The replacement service parts from the previous recall may be defective.

In the event of the passenger frontal airbag being deployed, the excessive internal pressure may cause the inflator body to rupture and metal fragments may pass through the cushion material causing injury to the occupants.

Recall of the product from end users

**Description:** Vehicles that were previously recalled for the Takata driver's frontal airbag inflator. Honda recall code: 6KY.

**Batch number / Barcode:** Accord, model year 2004, 2005, 2006; Civic, model year 2001,2003,2005; Odyssey, model year 2004;

**Country of origin:** Canada

**Alert submitted by:** Portugal

**Products were found and measures were taken also in:** Croatia, Estonia, Finland, Sweden

**Alert number:** A12/0679/19

**Product:** Carbon monoxide and gas detector

**Name:** Gas & CO detector

**Risk type:** Asphyxiation

**Category:** Other

**Brand:** Cabletech

**Type / number of model:** URZ0409

**Type of alert:** Products with serious risks

The device is not sufficiently sensitive with respect to the detection of carbon monoxide.

The product poses a risk of CO poisoning.

The product does not comply with the relevant European standard EN 50291.

Withdrawal of the product from the market

**Description:** Carbon monoxide and gas detector, mains-powered. Packaging: cardboard box.

**Batch number / Barcode:** 5901890015479

**Country of origin:** China

**Alert submitted by:** Poland



**Alert number:** A12/0691/19

**Product:** Carbon monoxide and gas detector

**Name:** Gas & CO detector

**Risk type:** Asphyxiation

**Category:** Other

**Brand:** Cabletech

**Type / number of model:** URZ0407

**Type of alert:** Products with serious risks

The device is not sufficiently sensitive with respect to the detection of carbon monoxide.

The product poses a risk of CO poisoning.

The product does not comply with the relevant European standard EN 50291.

Withdrawal of the product from the market

**Description:** Carbon monoxide and gas detector, mains powered. Packaging: cardboard box.

**Batch number / Barcode:** 5901436752219

**Country of origin:** China

**Alert submitted by:** Poland



**Alert number:** A12/0683/19

**Product:** Baby carrier

**Name:** Sling Unlimited 4 in 1

**Risk type:** Injuries

**Category:** Childcare articles and children's equipment

**Brand:** Mini Monkey

**Type / number of model:** 180102

**Type of alert:** Products with serious risks

The attachment system can easily slip and the product can break. A child can consequently fall out of the carrier and suffer injuries.

Moreover, the product lacks a head support for the child which may lead to head injuries.

The product does not comply with the relevant European standard EN 13209.

Recall of the product from end users

**Description:** Baby carrier sling/soft baby carrier.

**Batch number / Barcode:** 8 7181444960037

**Country of origin:** The Netherlands

**Alert submitted by:** Iceland





**Alert number:** A12/0703/19

**Product:** Children's car seat

**Name:** Transformer X-Bag

**Risk type:** Injuries

**Category:** Childcare articles and children's equipment

**Brand:** Concord

**Type / number of model:** Approval No. E1-04301275

**Type of alert:** Products with serious risks

In the case of an impact, the back-rest could move down.

This could cause injury to the child's head or cervical spine. The child could consequently also slip through the safety belt and suffer injuries.

The product does not comply with Regulation UNECE No 44-04.

Recall of the product from end users, Withdrawal of the product from the market

**Description:** Children's car seat intended for weight 15-36kg (group II, III).

**Batch number / Barcode:** Unknown

**Country of origin:** Germany

**Alert submitted by:** Slovakia

**Products were found and measures were taken also in:** Slovenia



**Alert number:** A12/0704/19

**Product:** Children's car seat

**Name:** Unknown

**Risk type:** Injuries

**Category:** Childcare articles and children's equipment

**Brand:** Automax

**Type / number of model:** Approval No. E13-045132

**Type of alert:** Products with serious risks

The plastic shell of the base can break in the event of a car accident or sudden and violent braking of the vehicle, impairing the safety of the child. Moreover, the crack creates sharp edges that could damage the seat belt, preventing effective restraint of the child.

The product does not comply with Regulation UNECE No 44-04.

Recall of the product from end users, Withdrawal of the product from the market

**Description:** Children's car seat intended for weight 0-18kg (group 0+, 1).

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Slovakia



**Alert number:** A12/0677/19

**Product:** Spinning top

**Name:** Flash light spinning top

**Risk type:** Chemical

**Category:** Toys

**Brand:** Wonder kids

**Type / number of model:** Reference : A1300498

**Type of alert:** Products with serious risks

The toy's casing can easily break, causing the button batteries to become accessible.

A child may put the batteries in the mouth, which could cause damage to the child's gastrointestinal tract if swallowed.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115.

Recall of the product from end users

**Description:** Plastic spinning top with coloured lights.

**Batch number / Barcode:** 3437011211007; Lot : 2487

**Country of origin:** China

**Alert submitted by:** France

**Products were found and measures were taken also in:** Luxembourg



**Alert number:** A12/0678/19

**Product:** Toy slime

**Name:** CREEPY OOZE SLIME

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value up to 839 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Ban on the marketing of the product and any accompanying measures, Destruction of the product, Withdrawal of the product from the market

**Description:** Slime toy in a plastic yellow container, 24 packs in a display box.

**Batch number / Barcode:** 3858890635959

**Country of origin:** China

**Alert submitted by:** Croatia



**Alert number:** A12/0682/19

**Product:** Soft toy

**Name:** Zabawka Pluszowa

**Risk type:** Choking

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** Item N° HTJ1045

**Type of alert:** Products with serious risks

Small parts (elastic bands) can be easily detached from the toy.

A child may put the small part in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Making the marketing of the product subject to prior conditions

**Description:** Plush horse in a plush handbag. No packaging, label attached to the toy.

**Batch number / Barcode:** 8033113104503

**Country of origin:** China

**Alert submitted by:** Poland



**Alert number:** A12/0689/19

**Product:** Robot helmet

**Name:** Optimus prime

**Risk type:** Damage to hearing

**Category:** Toys

**Brand:** Transformers

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The sound pressure level of the helmet's speakers is too high.

It could cause damage to hearing.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Ban on the marketing of the products which are in the warehouse

**Description:** A grey and blue plastic robot helmet. There are three voice buttons above the helmet's ear. The product is sold in a cardboard box.

**Batch number / Barcode:** 5010993365371

**Country of origin:** China

**Alert submitted by:** Finland

**Products were found and measures were taken also in:** Germany, Slovenia



**Alert number:** A12/0697/19

**Product:** Toy slime

**Name:** ΠΙΤΖΑ - Slime

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** XXB-6062G

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value up to 499 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Withdrawal of the product from the market

**Description:** Green toy slime.

**Batch number / Barcode:** 0465547000034/ 20180401

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/0702/19

**Product:** Microwaveable soft toy

**Name:** Microwaveable toys

**Risk type:** Burns

**Category:** Toys

**Brand:** Kuddleez

**Type / number of model:** A/W16

**Type of alert:** Products with serious risks

When heated up, the material of the soft toy can easily smoulder.

The product can consequently cause burns if in contact with the skin.

The product does not comply with the requirements of the Toy Safety Directive.

Withdrawal of the product from the market

**Description:** Soft toy in the shape of a bear that can be heated up in the microwave and used as a hot water bottle. Sold without any packaging but with a label attached.

**Batch number / Barcode:** 5060016141765

**Country of origin:** United Kingdom

**Alert submitted by:** France



**Alert number:** A12/0706/19

**Product:** Plastic doll

**Name:** Beauty

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** No 8106

**Type of alert:** Products with serious risks

The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 32 % and 17 % by weight, respectively).

These phthalates may harm the health of children, causing possible damage to their reproductive system.

The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

**Description:** Plastic doll with long, brown artificial hair in a cardboard box with transparent window.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** Romania





**Alert number:** A12/0708/19

**Product:** Toy slime

**Name:** WHOOPEE PUTTY

**Risk type:** Chemical

**Category:** Toys

**Brand:** Toi-Toys

**Type / number of model:** 35793

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value: up to 2040 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Ban on the marketing of the product and any accompanying measures, Warning consumers of the risks, Withdrawal of the product from the market

**Description:** Slime toy, available in different colours, sold in a plastic container in the shape of a miniature toilet.

**Batch number / Barcode:** 8714627357936; Batch: 815315

**Country of origin:** China

**Alert submitted by:** Luxembourg

**Products were found and measures were taken also in:** Austria, Latvia



**Alert number:** A12/0684/19

**Product:** Leather shoes

**Name:** Halonen

**Risk type:** Chemical

**Category:** Clothing, textiles and fashion items

**Brand:** Create

**Type / number of model:** HM1706-Z1, col: 68 / HTL02-1, col: 87

**Type of alert:** Products with serious risks

There is an excessive amount of chromium (VI) in the leather insoles of both pair of shoes (measured value: 113.7 mg/kg and 19.7 mg/kg respectively).

Chromium (VI) is sensitising and may trigger allergic reactions.

The product does not comply with the REACH regulation.

Import rejected at border

**Description:** Men's blue or brown suede loafers. The insole is made of leather. The shoes have a buckle-decoration on the top.

**Batch number / Barcode:** 2001002418365 / 2001002418457

**Country of origin:** China

**Alert submitted by:** Finland



**Alert number:** A12/0698/19

**Product:** Children's trousers

**Name:** Unknown

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** Y-Clu

**Type / number of model:** Y11910

**Type of alert:** Products with serious risks

The product has drawstrings in the waist area, which are too long and unattached.

The drawstrings can become trapped during activities of the child and cause injuries.

The product does not comply with the applicable European Standard EN 14682.

Withdrawal of the product from the market

**Description:** Trousers in orange colour with a white stripe down the side intended for 8 year old girls. This garment bears very long functional cords with free ends in the waist area.

**Batch number / Barcode:** 8053017943497

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/0700/19

**Product:** Children's blouse

**Name:** Unknown

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** Y-Clu

**Type / number of model:** Y11914

**Type of alert:** Products with serious risks

The product has drawstrings in the waist area, which are too long and unattached.

The drawstrings can become trapped during activities of the child and cause serious injuries.

The product does not comply with the relevant European Standard EN 14682.

Withdrawal of the product from the market

**Description:** Orange blouse intended for 8 year old girls. The garment bears very long functional cords with free ends in the waist area.

**Batch number / Barcode:** 8053017946764

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/0701/19

**Product:** Children's blouse

**Name:** Unknown

**Risk type:** Injuries, Strangulation

**Category:** Clothing, textiles and fashion items

**Brand:** Y-Clu

**Type / number of model:** Y11906

**Type of alert:** Products with serious risks

The product has drawstrings in the neck and back area.

The drawstrings may become trapped during various activities of a child, leading to strangulation or injuries.

The product does not comply with the relevant European standard EN 14682.

Withdrawal of the product from the market

**Description:** Off-shoulder, sleeveless short top in orange colour intended for 8 year old girls . The product bears functional cords with free ends to be tied at the back of the neck.

**Batch number / Barcode:** 8053017935805

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/0705/19

**Product:** Girls' sleeveless t-shirt

**Name:** Strawberry

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** Y-Clu

**Type / number of model:** YB12344

**Type of alert:** Products with serious risks

There are decorative cords with free ends in the upper chest area.

These cords may become trapped during various activities of the child, leading to injuries.

The product does not comply with the relevant European Standard EN 14682.

Withdrawal of the product from the market

**Description:** White sleeveless t-shirt intended for 3 year old girls, with decorative cords attached in the shoulder area and a strawberry pattern on the front.

**Batch number / Barcode:** 8053017916651

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/0690/19

**Product:** USB Power Adapter

**Name:** USB Power Adapter

**Risk type:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Unknown

**Type / number of model:** A5224

**Type of alert:** Products with serious risks

The electrical insulation and the creepage/clearance distances are inadequate.

The user may receive an electric shock from live parts.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950.

Recall of the product from end users

**Description:** White USB adapter/charger for tablets.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Denmark



**Alert number:** A12/0699/19  
**Product:** Electrical socket adaptor  
**Name:** Unknown  
**Risk type:** Electric shock, Fire  
**Category:** Electrical appliances and equipment  
**Brand:** Unknown  
**Type / number of model:** BSP-02  
**Type of alert:** Products with serious risks  
 The product does not have shutters on live parts, nor a fuse.  
 A user could consequently touch live parts of the socket and receive an electric shock.

The product does not comply with the relevant national standards.

Withdrawal of the product from the market

**Description:** Electrical plug adaptor in white colour with 3 pins.

**Batch number / Barcode:** 47164888

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A11/0024/19  
**Product:** Airsoft goggles  
**Name:** NP Mesh Goggles  
**Risk type:** Injuries  
**Category:** Protective equipment  
**Brand:** NUPROL PMC  
**Type / number of model:** 6002 NP shades mesh eye pro -Tan, Ref. 6000 (colour: black), Ref. 6001 (colour: green), Ref. 6003 (colour: grey), Ref. 6010 (colour: black), Ref. 6011 (colour green), Ref. 6012 (colour: tan/cinnamon), Ref. 6013 (colour: grey)  
**Type of alert:** Products with other risk levels  
 The goggles do not provide sufficient protection from projectiles launched at high speed and the mesh can detach.  
 As a result, the user's eyes could get injured.

The product does not comply with the requirements of the Personal Protective Equipment Directive.

Withdrawal of the product from the market

**Description:** Protective mesh goggles for use when playing airsoft.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** France

