

The Rapid Alert System for Non-Food Products (RAPEX)

RAPEX - Weekly overview report of notifications**week 1 - 2015**

Level	Type	No. Ref.	Notifying country	Product	Risk	Measures adopted by notifying country	Products were found and measures were taken also in:
Serious risk	Consumer products	1 A12/2167/14	Germany	<p>Category: Motor vehicles</p> <p>Product: Passenger car</p> <p>Brand: Mercedes-Benz</p> <p>Name: A-, B-, C-, CLA-, CLS-, E-, GLA-, ML-, S-, SLK-class</p> <p>Type/number of model: Type: BR 176, BR 246, BR 204, BR 205, BR 117, BR 218, BR 207, BR 212; BR 156, BR 204, BR 166; BR 221, BR 222, BR 172 Models: A 180 CDI, A 200 CDI, A 200 CDI, A 200 CDI 4MATIC, A 220 CDI, A 220 CDI 4MATIC, B 180 CDI, B 180 CDI, B 200 CDI, B 200 CDI, B 200 CDI, B 200 CDI 4MATIC, B 220 CDI, B 220 CDI 4MATIC, C 180 CDI, 180 CDI, C 200 CDI, C 220 Bluetec, C 220 CDI, C 220 CDI 4MATIC, C 250 Bluetec, C 250 Bluetec 4Matic, C 250 CDI, C 250 CDI 4MATIC, C 300 Bluetec Hybrid, CLA 200 CDI, CLA 200 CDI 4MATIC, CLA 220 CDI, CLA 220 CDI 4MATIC, CLS 220 Bluetec, CLS 250 Bluetec, CLS 250 Bluetec 4MATIC, CLS 250 CDI, E 200 Bluetec, E 200 CDI, E 220 Bluetec, E 220 CDI, E 250 Bluetec, E 250 Bluetec 4MATIC E, E 250 CDI, E 250 CDI 4MATIC, E 300 CDI Hybrid, GLA 200 CDI, GLA 200 CDI 4MATIC, GLA 220 CDI, GLA 220 CDI 4MATIC, GLK 200 CDI, GLK 220 4MATIC, GLK 220 Bluetec 4MATIC, GLK 220 CDI, GLK 250 4MATIC, GLK</p>	<p>Injuries</p> <p>The gasket seal for the engine's chain tensioner may display incorrect settling behaviour. Over time, this may result in the chain tensioner detaching from the threaded hole on the cylinder head and the leakage of engine oil. The loss of large amounts of engine oil may contaminate the road, leading to a possible hazard for traffic following behind.</p>	<p>Voluntary measures: Recall of the product from end users</p>	

250 Bluetec 4MATIC,
 ML 250 Bluetec
 4MATIC, S 250 CDI,S
 300 Bluetec Hybrid,
 SLK 250 CDI ,
 EC type-approval
 number:
 e1*2007/46*1007*
 e1*2001/116*0470*
 e1*2001/116*0470*
 e1*2007/46*0598*
 e1*2007/46*0548*
 e1*2007/46*0928*
 e1*2001/116*0470*
 e1*2007/46*0928*
 e1*2001/116*0470*
 e1*2001/116*0480*
 e1*2001/116*0480*
 e1*2001/116*0431*
 e1*2001/116*0457*
 e1*2001/116*0431*
 e1*2001/116*0457*
 e1*2001/116*0431*
 e1*2001/116*0457*
 e1*2001/116*0431*
 e1*2001/116*0457*
 e1*2001/116*0431*
 e1*2001/116*0457*
 e1*2001/116*0431*
 e1*2001/116*0457*
 e1*2001/116*0431*
 e1*2001/116*0502*
 e1*2001/116*0501*
 e1*2007/46*0200*
 e1*2001/116*0501*
 e1*2007/46*0200*
 e1*2001/116*0501*
 e1*2007/46*0485*
 e1*2001/116*0335*
 e1*2001/116*0335*
 e1*2007/46*0751*
 e1*2001/116*0470*
 e1*2007/46*0751*
 e1*2001/116*0470*

Batch number/Barcode:
 Vehicles produced between February and November 2014 are affected.

OECD Portal Category: 77000000 - Automotive

Description:
 Passenger car

Country of origin:
 Germany

No pictures are available

<p>Serious risk</p>	<p>Consumer products</p>	<p>2 A12/2168/14</p>	<p>Luxembourg</p>	<p>Category: Toys Product: Loom bands with charms Brand: Unknown Name: DIY Loom bands Type/number of model: Unknown</p>	<p>Chemical The charms contain 45% by weight of di(2-ethylhexyl)phthalate (DEHP). This phthalate may harm the health of children, causing possible damage of the reproductive</p>	<p>Compulsory measures: Withdrawal of the product from the market</p>	
---------------------	--------------------------	---	-------------------	--	---	---	--

				<p>Batch number/Barcode: Unknown</p> <p>OECD Portal Category: 86000000 - Toys / Games</p> <p>Description: Hard transparent plastic box (21 cm x 16,5cm x 4 cm) containing colour loom rubber bands, charms and s-clips (stored in 14 subdivisions).</p> <p>Country of origin: China</p> 	<p>system.</p> <p>According to the REACH Regulation the phthalates DEHP, DBP and BBP are prohibited in all toys and childcare articles.</p>	
Serious risk	Consumer products	3 A12/2169/14	Germany	<p>Category: Motor vehicles</p> <p>Product: Van</p> <p>Brand: Mercedes-Benz</p> <p>Name: Sprinter, Vito, Viano, V-Klasse</p> <p>Type/number of model: Type: BR 906, BR 639, BR 447 , EC type approval numbers: e1*2007/46*0457*08 – 10, e1*2007/46*0458*06 – 08, e1*2007/46*0459*04 – 05, e1*2001/116*0353*12 – 13, e1*2001/116*0354*14 – 16, e1*2001/116*0424*09 – 11, e1*2007/46*0280*06 – 08, e1*2007/46*0300*07 – 08, e1*2007/46*0297*03 – 04, e1*2007/46*0557*03, e1*2007/46*0299*06 – 07, e1*2007/46*0294*03 – 04, e1*2007/46*1093*01, e1*2007/46*0312*06 – 07, e1*2007/46*0309*02 –</p>	<p>Injuries</p> <p>The gasket seal for the engine's chain tensioner may display incorrect settling behaviour. Over time, this may result in the chain tensioner detaching from the threaded hole on the cylinder head and the leakage of engine oil. The loss of large amounts of engine oil may contaminate the road, leading to a possible hazard for traffic following behind.</p>	<p>Voluntary measures: Recall of the product from end users</p>

04,
e1*2007/46*0311*05 –
06,
e1*2007/46*0308*02 –
03,
e1*2007/46*0279*06 –
08,
e1*2007/46*0301*08 –
10,
e1*2007/46*0298*04 –
06,
e1*2007/46*0295*06 –
07,
e1*2007/46*0296*03 –
05,
e1*2007/46*0305*05 –
07,
e1*2007/46*0310*02 –
04,
e1*2007/46*0307*05 –
06,
e1*2007/46*0304*02 –
03,
e1*2007/46*1076*02,
e1*2007/46*1075*01 -
02

Batch number/Barcode: The vehicles were manufactured between February and November 2014.

OECD Portal Category: 77000000 - Automotive



Description: Van

Country of origin: Germany

No pictures are available

Serious risk	Consumer products	4 A12/2170/14	Germany	<p>Category: Motor vehicles</p> <p>Product: Passenger car</p> <p>Brand: VW</p> <p>Name: Polo, e-up!</p> <p>Type/number of model: Type: 6C1, BL1 approval number: e1*2001/116*0510, e13*2007/46*1182</p> <p>Batch number/Barcode: The vehicles in question were manufactured between 6 February 2014 and 22 September 2014.</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Passenger car.</p>	<p>Injuries</p> <p>An unintended airbag release can occur without forewarning.</p>	<p>Voluntary measures: Recall of the product from end users</p>
--------------	-------------------	----------------------------------	---------	--	--	--

				<p>Country of origin: Germany</p> <p>No pictures are available</p>			
Serious risk	Consumer products	5 A12/2171/14	United Kingdom	<p>Category: Motor vehicles</p> <p>Product: Passenger car</p> <p>Brand: Chevrolet</p> <p>Name: Cruze, Orlando</p> <p>Type/number of model: Cruze 2.0 Diesel and Orlando 2.0 Diesel</p> <p>Batch number/Barcode: Cruze: AK500153 - AKI585519 - build dates: 28/11/08-27/2/11, Orlando: BK007979 - CK500160- build dates 15/9/10 - 30/3/11</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Diesel engine passenger car.</p> <p>Country of origin: Republic of Korea</p> <p>No pictures are available</p>	Injuries Vehicles may experience right hand drive shaft separation of the outer CV (constant velocity) joint during harsh cornering or U turns. If parked on an incline without the parking brake applied the vehicle could move unexpectedly and may result in a crash or injury.	Voluntary measures: Recall of the product from end users	
Serious risk	Consumer products	6 A12/2172/14	United Kingdom	<p>Category: Motor vehicles</p> <p>Product: Passenger car</p> <p>Brand: Chevrolet</p> <p>Name: Matiz and Spark</p> <p>Type/number of model: Matiz: VIN range from 9C642734 - AC526792, Spark: VIN range from 9C642734 - AC526792</p> <p>Batch number/Barcode: 1/12/08 - 24/10/09</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Passenger car.</p>	Injuries Vehicles may experience reduction in brake performance due to sticking of the valve within the ABS module (Anti-lock braking system). Brakes may feel spongy and stopping distances may become longer.	Voluntary measures: Recall of the product from end users	

				<p>Country of origin: Republic of Korea</p> <p>No pictures are available</p>			
Serious risk	Consumer products	7 A12/2173/14	Sweden	<p>Category: Jewellery</p> <p>Product: Bracelet</p> <p>Brand: C</p> <p>Name: AcW Bracelet Evy</p> <p>Type/number of model: 71360740001</p> <p>Batch number/Barcode: 7050216300831</p> <p>OECD Portal Category: 64000000 - Personal Accessories</p> <p>Description: Bracelet with different kind of chains and stones connected to two metal bars working as a lock. The chains are coloured metallic black. There are two chains with rhinestones, one with bigger stones and one with smaller stones. The bracelet has a white tag marked with a C.</p> <p>Country of origin: China</p>  	<p>Chemical</p> <p>The products contains excessive amounts of cadmium (measured value up to 15% by weight). Cadmium is classified as harmful if in contact with the skin.</p> <p>The product does not comply with the requirements of the REACH Regulation.</p>	<p>Voluntary measures: Withdrawal of the product from the market, Recall of the product from end users</p>	
Serious risk	Consumer products	8 A12/2174/14	Portugal	<p>Category: Motor vehicles</p> <p>Product: Passenger car</p> <p>Brand: Opel</p> <p>Name: Meriva</p> <p>Type/number of model: Meriva B</p> <p>Batch number/Barcode:</p>	<p>Injuries</p> <p>The latches of the rear safety belt buckles may open inadvertently in the event of a crash.</p>	<p>Voluntary measures: Recall of the product from end users</p>	

				<p>Model year: 2015.</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Passenger car.</p> <p>Country of origin: Spain</p> <p>No pictures are available</p>			
Serious risk	Consumer products	9 A12/2175/14	Portugal	<p>Category: Motor vehicles</p> <p>Product: Passenger car</p> <p>Brand: Opel</p> <p>Name: Astra</p> <p>Type/number of model: Astra J/GTC</p> <p>Batch number/Barcode: Production years: 2010 to 2012.</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Passenger car with petrol engine.</p> <p>Country of origin: Poland, Russia, United kingdom.</p> <p>No pictures are available</p>	Fire	In the event of a blockage of the radiator-cooling fan, an electrical short circuit could occur; this in turn could cause damage to the cooling fan module, in the worst case potentially resulting in a vehicle fire.	Voluntary measures: Recall of the product from end users
Serious risk	Consumer products	10 A12/2176/14	Malta	<p>Category: Motor vehicles</p> <p>Product: Peugeot</p> <p>Brand: Peugeot</p> <p>Name: 107</p> <p>Type/number of model: e11*2001/116*0237</p> <p>Batch number/Barcode: Manufactured from 20/06/2013 to 27/08/2013</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Passenger car</p> <p>Country of origin:</p>	Injuries	Breakage of the shock absorber rods could lead to loss of control of the vehicle and an accident.	Voluntary measures: Recall of the product from end users

				Czech Republic No pictures are available			
Serious risk	Consumer products	11 A12/2177/14	United Kingdom	<p>Category: Motor vehicles</p> <p>Product: Passenger car</p> <p>Brand: Jaguar</p> <p>Name: XJ</p> <p>Type/number of model: XJ Saloon</p> <p>Batch number/Barcode: Selected vehicles within VIN range: SAJAA20M9EPV67632 to SAJWA2GZ6F8V76050</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Passenger car</p> <p>Country of origin: United Kingdom</p> <p>No pictures are available</p>	Injuries The underbody brake pipe unions may not be to the correct torque specification. This may result in reduced braking performance, loss of brake fluid and the non-activation of the brake pressure switch, preventing initial vehicle start-up and potentially causing a vehicle crash.	Voluntary measures: Recall of the product from end users	
Serious risk	Consumer products	12 A12/2178/14	Sweden	<p>Category: Lighting equipment</p> <p>Product: Wall/ ceiling lamp</p> <p>Brand: OLIGO Lichttechnik</p> <p>Name: Mademoiselle Filou</p> <p>Type/number of model: 50-1490003</p> <p>Batch number/Barcode: Unknown</p> <p>OECD Portal Category: 78000000 - Electrical Supplies</p> <p>Description: Wall or ceiling-mounted lamp, in the shape of a fly with wings and a tea-strainer which is attached as a decorative element.</p> <p>Country of origin: Germany</p>	Electric shock, Fire The wings can catch fire if they touch the light source and the cable is not properly attached. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.	Compulsory measures: Withdrawal of the product from the market, Recall of the product from end users	



Serious risk	Consumer products	13 A12/2179/14	France	<p>Category: Electrical appliances and equipment</p> <p>Product: Travel adapter</p> <p>Brand: Drop Zone Energy</p> <p>Name: Unknown</p> <p>Type/number of model: DZ-12-150 / year of manufacture: 2011</p> <p>Batch number/Barcode: Batch No DZ 07-11-150 / 3760161131025</p> <p>OECD Portal Category: 78000000 - Electrical Supplies</p> <p>Description: 12v/220v adapter, blue in colour with cigarette lighter plug on one side and mains plug on the other.</p> <p>Country of origin: Taiwan</p> <p>No pictures are available</p>	<p>Electric shock</p> <p>The creepage distances and clearances are insufficient.</p> <p>The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950.</p>	<p>Compulsory measures: Withdrawal of the product from the market, Recall of the product from end users</p>	
Serious risk	Consumer products	14 A12/2180/14	United Kingdom	<p>Category: Motor vehicles</p> <p>Product: Motorcycle</p> <p>Brand: Triumph</p> <p>Name: Tiger Explorer</p> <p>Type/number of model: Tiger Explorer and Tiger Explorer XC</p> <p>Batch number/Barcode: Build dates are 01/11/11 – 01/06/14</p> <p>OECD Portal Category: 77000000 -</p>	<p>Injuries</p> <p>The side stand pivot bolt may fracture under abusive loads.</p>	<p>Voluntary measures: Recall of the product from end users</p>	

				Automotive Description: Motorcycle. Country of origin: United Kingdom No pictures are available			
Serious risk	Consumer products	15 A12/2181/14	Germany	Category: Toys Product: Plastic doll Brand: Jin Jian Name: Clever Baby's Type/number of model: Product ref. no: 3326 Batch number/Barcode: 1114004914 OECD Portal Category: 86000000 - Toys / Games Description: Battery powered plastic doll, in blue trousers, shirt, cap and bib. The packaging is a cardboard box with transparent window. Country of origin: China 	Chemical The head of the doll contains di-(2-ethylhexyl) phthalate (DEHP) (measured value: 9.1% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. According to the REACH Regulation the phthalates DEHP, DBP and BBP are prohibited in all toys and childcare articles.	Compulsory measures: Recall of the product from end users	
Serious risk	Consumer products	16 A12/2182/14	Germany	Category: Toys Product: Plastic doll Brand: Xin Ming Yue Name: Baby Lovely Type/number of model: XMY8038 Batch number/Barcode: 1114005014 OECD Portal Category: 86000000 - Toys / Games Description: Plastic	Chemical The head of the doll contains di-2-ethylhexylphthalate (DEHP) (measure value: 10.1% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. According to the REACH Regulation the phthalates DEHP, DBP and BBP are prohibited	Compulsory measures: Recall of the product from end users	



doll with arms made of stuffed fabric, movable eyes. The doll is battery operated and supplied in cardboard box with transparent window.

Country of origin:
China



in all toys and childcare articles

Serious risk	Consumer products	17 A12/2183/14	United Kingdom	<p>Category: Motor vehicles</p> <p>Product: Passenger car</p> <p>Brand: Aston Martin</p> <p>Name: DB9 (Coupe & Volante), DBS (Coupe & Volante), One-77, V12 Vantage (Coupe and Roadster), V12 Zagato, V8 Vantage (Coupe and Roadster), Virage (Coupe and Roadster)</p> <p>Type/number of model: Aston Martin: DB9 (Coupe & Volante), DBS (Coupe & Volante), One-77, V12 Vantage (Coupe and Roadster), V12 Zagato, V8 Vantage (Coupe and Roadster), Virage (Coupe and Roadster)</p> <p>Batch number/Barcode: Vehicles built between 15/06/2006 and 06/11/2014.</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Passenger car.</p> <p>Country of origin: United Kingdom</p> <p>No pictures are available</p>	<p>Burns</p> <p>The control module for the front heated seats may fail when the ignition is switched on. This could allow a permanent feed to the seat heater element(s) and it may not be possible to switch off the heating. This fault could cause the seat to overheat and in extreme circumstances the seat occupants may receive burns.</p>	<p>Voluntary measures: Recall of the product from end users</p>	
--------------	-------------------	--------------------------	----------------	---	---	--	--

Serious risk	Consumer products	18 A12/2184/14	Sweden	<p>Category: Jewellery</p> <p>Product: Bracelet</p> <p>Brand: NLY Accessories</p> <p>Name: Multi Colored Bracelet</p> <p>Type/number of model: 386280-0014-008 Colour: Black</p> <p>Batch number/Barcode: Unknown</p> <p>OECD Portal Category: 64000000 - Personal Accessories</p> <p>Description: Bracelet with several straps in various shapes and beads of different colours.</p> <p>Country of origin: Unknown</p> 	Chemical The metal back of the bead shaped like an eye contains up to 13 % by weight of cadmium. Cadmium is classified as harmful if swallowed, if inhaled or if in contact with the skin. The product does not comply with the REACH Regulation.	Voluntary measures: Withdrawal of the product from the market	
Other risk level	Consumer products	19 A11/0116/14	Germany	<p>Category: Chemical products</p> <p>Product: Foam glue</p> <p>Brand: Pichler</p> <p>Name: Devil</p> <p>Type/number of model: #C5140</p> <p>Batch number/Barcode: 4250718151402</p> <p>OECD Portal Category: 83000000 - Building Products</p> <p>Description: White tube of glue in a white cardboard box with a red sticker.</p> <p>Country of origin: Germany</p> 	Chemical The glue contains an excessive amount of toluene (measured value: 30% by weight). The product does not comply with the REACH Regulation.	Compulsory measures: Ban on the marketing of the product and any accompanying measures	



Other risk level	Consumer products	20 A11/0117/14	Germany	<p>Category: Chemical products</p> <p>Product: Vinyl spray</p> <p>Brand: Carlas</p> <p>Name: Colorful rubber spray film</p> <p>Type/number of model: C4 matt black, C6 red, C14 orange, C15 sky blue, C31 Yellow, C37 green, C82 violet, C313 pink, C130 pearl white, C188 gold, C190 lacquer, CB5 gold/red/violet, CB15 red/violet/blue, CB19 violet/blue/green, CB25 blue/green/gold, CB30 gold/green, CY1001 fluorescent red, CY1003 fluorescent green, CY1005 fluorescent yellow</p> <p>Batch number/Barcode: 4053029593172, 4053029593240, 4053029593196 and others</p> <p>OECD Portal Category: 58000000 - Cross Segment</p> <p>Description: Spray can with multicoloured label and clear plastic cap.</p> <p>Country of origin: China</p>	<p>Chemical</p> <p>The product contains an excessive amount of toluene (measured value: up to 30% by weight).</p> <p>The product does not comply with the Regulation on the classification, labelling and packaging of substances and mixtures (CLP) and with the REACH Regulation.</p>	<p>Compulsory measures: Withdrawal of the product from the market</p>	
Other risk level	Consumer products	21 A11/0118/14	France	<p>Category: Electrical appliances and equipment</p> <p>Product: Converter</p> <p>Brand: DZ-Energy</p> <p>Name: Unknown</p> <p>Type/number of</p>	<p>Electric shock</p> <p>The creepage and air distances between the live components in the secondary circuit and the earthed metal cover are too small.</p>	<p>Compulsory measures: Withdrawal of the product from the market, Recall of the product from end users</p>	



				<p>model: Year of manufacture: 2014</p> <p>Batch number/Barcode: DZ 03-14 / EAN : 3760161130219</p> <p>OECD Portal Category: 78000000 - Electrical Supplies</p> <p>Description: Converter 12 V/220 V 150W. Coloured cardboard box.</p> <p>Country of origin: Taiwan</p> <p>No pictures are available</p>	The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950.	
Other risk level	Consumer products	22 A11/0119/14	United Kingdom	<p>Category: Toys</p> <p>Product: Soft teddy bear</p> <p>Brand: Dunelm</p> <p>Name: CJ Bear</p> <p>Type/number of model: Unknown</p> <p>Batch number/Barcode: Small 505021923809, Large 5050210923823</p> <p>OECD Portal Category: 86000000 - Toys / Games</p> <p>Description: Traditional style stuffed toy bear with swing ticket fixed on ear. Only products supplied after October 2014 are affected.</p> <p>Country of origin: China</p> 	<p>Choking</p> <p>The seams of the toy may come apart exposing the inner filling material, which may cause choking to small children if put in the mouth and ingested.</p> <p>The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.</p>	Voluntary measures: Recall of the product from end users
Other risk level	Consumer products	23 A11/0120/14	Denmark	<p>Category: Childcare articles and children's equipment</p> <p>Product: Pushchair</p> <p>Brand: Mamas & Papas</p> <p>Name: Sola City pushchair</p> <p>Type/number of model: Sola City pushchair SC A23501</p>	<p>Injuries</p> <p>There is a risk of the child inside the pushchair getting its finger crushed in the opening where the hood moves inside the hinge when the parent pulls down the hood.</p> <p>There are no</p>	Compulsory measures: Withdrawal of the product from the market

158825300

Batch number/Barcode: Lot: 00813

OECD Portal Category: 54000000 - Baby Care

Description: Pushchair with swivel front wheels. The seat can be used facing front or back. Colour: black.

Country of origin: Unknown



Danish warnings or product information and therefore there is a risk of incorrect use of the pushchair.

Other risk level	Consumer products	24 A11/0121/14	United Kingdom	<p>Category: Electrical appliances and equipment</p> <p>Product: Laptop computer</p> <p>Brand: Lenovo, Ideapad</p> <p>Name: Ideapad: B460, B470, B560, B570, G460, G470, G475, G480, G560, G570, G575, G580, G770, S100, S10-3, S10-3c, S10-3N, S10- 3t, S110, S400, U160, U165, U260, U455, U460, V360, V370, V460, V560, V570, Y460, Y470, Y560, Y570, Z360, Z460, Z465, Z470, Z475, Z560, Z565, Z570, Z575, Z580. Lenovo: B460, B470, B470e, B475, B560, B570, B570e, B575, G455, G460, G465, G475, G480, V470c, G560, G565, G570, G575, V570, G580, G770, V370, V470, V560.</p> <p>Type/number of model: Power cord: LS-15</p>	<p>Fire</p> <p>Under certain environmental conditions, an electrical failure or a short circuit can occur in the power cord causing the power cord to overheat. The overheating may, in rare instances, lead to a fire.</p> <p>The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60320.</p>	<p>Voluntary measures: Recall of the product from end users</p>	
------------------	-------------------	--------------------------	----------------	---	--	--	--

Batch number/Barcode:
Power cord barcode: 145000600. The power cords were manufactured between February 2011 and December 2011.

OECD Portal Category: 78000000 - Electrical Supplies

Description: Laptop computer supplied with "LS-15" power cord. The power cord has "LS-15" moulded onto it and has a date code sticker.

Country of origin:
China



Serious risk

Professional products

25
A12/2165/14

Malta

Category: Chemical products

Product: Vehicle refinishing product

Brand: Kapci

Name: Grey Filler

Type/number of model: 2K HS Filler 633

Batch number/Barcode: P.D. 10/11.B.N.1290911019

OECD Portal Category: 77000000 - Automotive

Description: Product comes packaged in Cans. Product is the filling component in automotive car refinishing spray.

Country of origin:
Egypt



Environment

The product contains a higher level of volatile organic compounds (VOC) than the 420g/l limit. The presence of volatile organic compounds (VOC) above the permitted levels causes pollution as it contributes to the local and transboundary formation of photochemical oxidants in the boundary layer of the atmosphere. The product does not comply with the requirements of the Paints Directive.

Compulsory measures:
Withdrawal of the product from the market



Serious risk	Professional products	26 A12/2166/14	Malta	<p>Category: Chemical products</p> <p>Product: Vehicle refinishing product</p> <p>Brand: Kapci</p> <p>Name: Wash Primer 805 Yellow 1Kg Gross</p> <p>Type/number of model: Wash Primer 805 Yellow 1Kg Gross</p> <p>Batch number/Barcode: P.D04/12; Exp04/14.B.N. 1050412003</p> <p>OECD Portal Category: 77000000 - Automotive</p> <p>Description: Car refinishing product primer yellow colour 805 number</p> <p>Country of origin: Egypt</p>	<p>Environment</p> <p>The product contains a higher level of volatile organic compounds (VOC) than the 420g/l limit. The presence of volatile organic compounds (VOC) above the permitted levels causes pollution as it contributes to the local and transboundary formation of photochemical oxidants in the boundary layer of the atmosphere. The product does not comply with the requirements of the Paints Directive.</p>	<p>Compulsory measures: Withdrawal of the product from the market</p>	
--------------	-----------------------	--------------------------	-------	--	--	--	--