



## CONSUMERS

🏠 [Safety Gate home \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/repository/content/pages/rapex/index\\_en.htm\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

☰ [Back to report listings \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.listNotifications&year=2019&lng=en\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2019&lng=en)

🔍 [Search alerts \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.search&lng=en\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search&lng=en)

👍 [IPSW 2018 \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=ipsw:home\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=ipsw:home)

# The Rapid Alert System for Non-Food Products (RAPEX)

## *RAPEX - Weekly overview report of notifications*

Week 42 - 2019

Notification A12/1158/19 has been withdrawn from report 2019-31 of 02/08/2019 at the request of the notifying authority due to a reassessment of the product.

**Alert number:** A12/1545/19

**Product:** Portable table

**Name:** Unknown

**Risk type:** Injuries

**Category:** Furniture

**Brand:** Unknown

**Type / number of model:** HKTB-1028

**Type of alert:** Products with serious risks

The structure of the table can easily be deformed and the table could lose its stability.  
As a consequence, objects placed on the table may fall off and a user may suffer injuries.

Withdrawal of the product from the market

**Description:** Portable white table with no packaging.

**Batch number / Barcode:** 0000011458586

**Country of origin:** China

**Alert submitted by:** Lithuania



**Alert number:** A12/1527/19

**Product:** Bracelet

**Name:** Unknown

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Unknown

**Type / number of model:** N° 804

**Type of alert:** Products with serious risks

The product contains an excessive amount of lead (measured value: 6500 mg/kg).

Lead is harmful to human health, accumulates in the body and may damage fertility, breast-fed children or the unborn child.

The product does not comply with the REACH Regulation.

Ban on the marketing of the product and any accompanying measures

**Description:** Silver metal bracelets with heart-shaped pendant, each in transparent plastic packaging to which a label is affixed .

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Italy



**Alert number:** A12/1535/19

**Product:** Tiara

**Name:** Tiara "Cleopatra"

**Risk type:** Chemical

**Category:** Jewellery

**Brand:** Unknown

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The metal of the product contains an excessive amount of lead (measured value up to 3,76% by weight).

Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children.

The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

**Description:** Metal tiara with Egyptian theme.

**Batch number / Barcode:** Unknown

**Country of origin:** Egypt

**Alert submitted by:** Sweden



**Alert number:** A12/1546/19  
**Product:** Tyre repair set  
**Name:** DELUXE Tire Plug Kit  
**Risk type:** Chemical  
**Category:** Chemical products  
**Brand:** YANSHENG

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The glue from the set contains an excessive amount of toluene (measured value: 26% by weight).  
 Toluene is carcinogenic and toxic if inhaled or if it gets in contact with the skin.

The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

**Description:** Tyre repair set including screwdriver, pliers and glue, supplied in a blister packaging.

**Batch number / Barcode:** 4770364241741

**Country of origin:** China

**Alert submitted by:** Lithuania



**Alert number:** A12/1513/19

**Product:** Passenger car

**Name:** GLE

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** Mercedes-Benz

**Type / number of model:** Type-approval numbers: e1\*2007/46\*1885\*03-04 Type: H1GLE (BR 167)

**Type of alert:** Products with serious risks

The drain hose of the air conditioning system may not have been correctly installed.

Consequently, condensed water could enter the passenger compartment and damage or short-circuit several electric components, causing the engine to stop or run in emergency mode while driving, increasing the risk of accident.

Recall of the product from end users

**Description:** Passenger car under Mercedes-Benz Recall code: 8391101

**Batch number / Barcode:** The affected vehicles were manufactured between 23 August 2018 and 5 August 2019.

**Country of origin:** Germany

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** Poland

**Alert number:** A12/1514/19

**Product:** Passenger car

**Name:** S-Class

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** Mercedes-Benz

**Type / number of model:** Type-approval number: e1\*2001/116\*0335\*36-39, e1\*2001/116\*0396\*20 Type: 221, 221 AMG (BR 217, 222)

**Type of alert:** Products with serious risks

The A, B and C pillar trims may not have been correctly fastened.

In the event of an accident, the trims may impair the efficacy of the window airbags. If the window airbags are deployed, the trims might be detached and propelled into the passenger compartment, increasing the risk of injuries.

Recall of the product from end users

**Description:** Passenger car under Mercedes-Benz Recall code: 6391004

**Batch number / Barcode:** The affected vehicles were manufactured between 06 June 2018 and 04 September 2018.

**Country of origin:** Germany

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** Poland

**Alert number:** A12/1515/19

**Product:** Passenger car

**Name:** Mercedes-Benz

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** A-Class

**Type / number of model:** Type-approval number: e1\*2007/46\*1829\*00-02; type: F2A;

**Type of alert:** Products with serious risks

The strength of the material of the shielding plate under the spare wheel might not be appropriate.

Consequently, cracks could form on the plate, leading to its complete shear and loss of small parts of it, increasing the risk accident of following traffic.

Recall of the product from end users

**Description:** Passenger car under Mercedes-Benz Recall code: 6490002.

**Batch number / Barcode:** The affected vehicles were manufactured between 19/01/2018 and 18/07/2018.

**Country of origin:** Germany

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** Poland

**Alert number:** A12/1516/19

**Product:** Passenger car

**Name:** A4, A5

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** Audi

**Type / number of model:** Type-approval number: e1\*2001/116\*0430\*; type: B8

**Type of alert:** Products with serious risks

A damaged transistor may have been installed in the airbag control unit.

Consequently, it may not properly make contact leading to the passenger airbag not to be triggered in the event of an accident, increasing the risk of injuries.

Recall of the product from end users

**Description:** Passenger car under Audi Recall code: 69Z7.

**Batch number / Barcode:** The affected vehicles were manufactured in calendar weeks 21 and 22/2019.

**Country of origin:** Germany

**Alert submitted by:** Germany

**Alert number:** A12/1524/19

**Product:** Bus

**Name:** Lions City

**Risk type:** Fire

**Category:** Motor vehicles

**Brand:** MAN

**Type / number of model:** Type-approval numbers: e4\*2007/46\*0202\*31 - 33, e4\*2007/46\*0560\*24-\*25, e4\*2007/46\*0250\*31 - 33, e4\*2007/46\*0561\*25, e4\*2007/46\*0203\*32, e4\*2007/46\*0094\*33-\*35, Types: B.2007.46.010, B.2007.46.015, B.2007.46.012, B.2007.46.016, B.2007.46.011, B.2007.46.001 Sales description: Lions City

**Type of alert:** Products with serious risks

The gas pressure regulator could break at the angle bracket and become leaky as a result. Gas could then leak through this break and form an explosive gas mixture.

There is a risk that this gas mixture could ignite on hot components or other sources of ignition.

Recall of the product from end users

**Description:** Buses operating on compressed natural gas

**Batch number / Barcode:** The vehicles affected were produced between November 2017 and May 2019. The recall is being carried out under the code: T16886TR.

**Country of origin:** Germany

**Alert submitted by:** Germany

**Alert number:** A12/1525/19

**Product:** Bus

**Name:** Linkker

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** Linkker

**Type / number of model:** e17\*2007/46\*0046\*00, e17\*2007/46\*0046\*01

**Type of alert:** Products with serious risks

There is a possible fracture in the steering linkage. Material used to manufacture this linkage can prematurely wear out and cause a fracture.

If the steering linkage fails, driver will lose the control of the vehicle.

Recall of the product from end users

**Description:** Bus

**Batch number / Barcode:** Campaign code LIN-RC-002

**Country of origin:** Finland

**Alert submitted by:** Finland

**Alert number:** A12/1534/19

**Product:** Motorcycle

**Name:** CRF450L

**Risk type:** Injuries

**Category:** Motor vehicles

**Brand:** Honda

**Type / number of model:** - EC-type approval number: e4\*168/2013\*00089\*00; - Model year: 2019.

**Type of alert:** Products with serious risks

The horn stand might not be sufficiently strong.

Consequently, it may spontaneously break, causing the horn to detach while riding, increasing the risk of accidents.

Recall of the product from end users

**Description:** Motorcycle under Honda Recall code: 3KY.

**Batch number / Barcode:** The affected vehicles were manufactured between the 19th June 2018 and the 18th April 2019.

**Country of origin:** Japan

**Alert submitted by:** Portugal

**Products were found and measures were taken also in:** Poland

**Alert number:** A12/1536/19

**Product:** Steering wheel cover

**Name:** First Class PU

**Risk type:** Chemical

**Category:** Motor vehicles

**Brand:** CARTECH

**Type / number of model:** 18700

**Type of alert:** Products with serious risks

The plastic of the product contains an excessive amount of polycyclic aromatic hydrocarbons (PAHs), notably benzo[a]anthracene (BaA), chrysen (CHR), Benzo[a]pyrene (BaP), benzo[b]fluoranthene (BbFA), benzo[e]pyrene (BeP), benzo[k]fluoranthene (BkFA) and benzo[j]fluoranthene (BjFA) and (measured values: 75 mg/kg, 71 mg/kg, 15 mg/kg, 15 mg/kg, 13 mg/kg, 11 mg/kg and 9.3 mg/kg by weight respectively).

These PAHs may cause cancer and are also mutagenic and toxic for reproduction.

The product does not comply with the REACH regulation.

Withdrawal of the product from the market

**Description:** Black steering wheel cover.

**Batch number / Barcode:** 5202392187009

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/1511/19

**Product:** Warning triangle

**Name:** Výstražný trojúhelník/trojuholník

**Risk type:** Injuries

**Category:** Other

**Brand:** SHERON, YG

**Type / number of model:** Type-approval number n°: E11 27R033936 , YG-A001

**Type of alert:** Products with serious risks

The stability of the warning triangle is inadequate.

Consequently the triangle could easily overturn and oncoming vehicles would not be warned of the presence of an obstacle, increasing the risk of accidents.

The product does not comply with the relevant European Standard ECE27.

Recall of the product from end users, Warning consumers of the risks, Withdrawal of the product from the market

**Description:** Foldable warning triangle for motor vehicles, packed in a red plastic case.

**Batch number / Barcode:** 8594007994957

**Country of origin:** China

**Alert submitted by:** Slovakia





**Alert number:** A12/1512/19

**Product:** Warning triangle

**Name:** Unknown

**Risk type:** Injuries

**Category:** Other

**Brand:** FuDing

**Type / number of model:** RT611 , Type-approval n°: E4 27R032734

**Type of alert:** Products with serious risks

The stability of the warning triangle is inadequate and it does not sufficiently reflect the light.

Consequently, the triangle might not be seen or could easily overturn. Oncoming vehicles would not be warned of the presence of an obstacle, increasing the risk of accidents.

The product does not comply with the relevant European Standard ECE27.

Recall of the product from end users, Warning consumers of the risks, Withdrawal of the product from the market

**Description:** Foldable warning triangle for motor vehicles, packed in a red plastic case.

**Batch number / Barcode:** 8581173900059

**Country of origin:** China

**Alert submitted by:** Slovakia



**Alert number:** A12/1532/19

**Product:** Helium tank

**Name:** Ballon Gas

**Risk type:** Injuries

**Category:** Pressure equipment/vessels

**Brand:** Party Factory

**Type / number of model:** BR1C

**Type of alert:** Products with serious risks

The valve is not protected and in the event of fall or impact this may lead to significant pressure on the tank neck.

The neck of the bottle may consequently break and explode, causing a sudden liberation of the gas under pressure and a blast of metal parts.

The product does not comply with the requirements of the Transportable Pressure Equipments Directive , the European Agreement concerning the International Carriage of Dangerous Goods by Road (ADR 2017) and the relevant European Standard EN ISO 11118.

This product listing was removed by Amazon., Withdrawal of the product from the market

**Description:** Transportable helium tanks for inflating balloons. The product was (also) sold online, in particular via Amazon and other websites.

**Batch number / Barcode:** 4260432844047

**Country of origin:** China

**Alert submitted by:** France



NOT REFILLI XBN/CN 0.75L PH28 BAR -20°C UN1046 HELIUM

COMPRESSED EN ISO 12205 GR 1354



**Alert number:** A12/1542/19

**Product:** Ropes (equipment to protect against falls)

**Name:** Braided Safety Blue/Arbor Elite/Pottsblitz/CEclimb

**Risk type:** Injuries

**Category:** Protective equipment

**Brand:** Teufelberger

**Type / number of model:** Arbor Elite with slaiice® and pottsblitz with slaiice® 7350098-0099, 7350100-0103, 7341020-1026, 7350143-7350148, C5KBG1-16-00120/150/200, C5KBG8-16-00115/150/200, C5KBH1-16-00120/150/200, , Braided Safety Blue® with slaiice® 7350026-7350028, 7350087, 7361028-1045, 7361090-1091, C5QBG0-16-00120/150/200, C5QBG1-16-00150/200, C5QBG2-16-00120/150/200, C5QBG7-16-00120/150, C5QBGA-16-00120/150, C5QBG0-16-00120/150/200, C5QBG1-16-00150/200, C5QBG2-16-00120/150/200, C5QBG7-16-00120/150/200, C5QBGA-16-00120/150, C5QBH0-16-00120/150/200, C5QBH2-16-00120/150/200, C5QBH7-16-00120/150/200, C5QBH0-16-00150, C5QBH2-16-00150, C5QBHA-16-00150, C5QBHA-16-00120/150/200, CEclimb 12 (with Braided Safety Blue 12.7 with slaiice®) 7351330-1332

**Type of alert:** Products with serious risks

The eye of the rope might not have been properly spliced.

Consequently the eye might open during use, causing the climber to fall.

The product does not comply with the requirements of the Personal Protective Equipment Directive (since 21/04/2018 repealed by the Personal Protective Equipment Regulation) .

Recall of the product from end users

**Company recall page:** <https://www.teufelberger.com/en/> (<https://www.teufelberger.com/en/>)

**Description:** Ropes in different designs/colours with an eye at the end.

**Batch number / Barcode:** Serial numbers: 2014-xxxxxx to 19/09-yyy, The affected products were manufactured between January 2014 and September 2019.

**Country of origin:** Czech Republic

**Alert submitted by:** Austria



**Alert number:** A12/1531/19

**Product:** Children's high chair

**Name:** Unknown

**Risk type:** Injuries

**Category:** Childcare articles and children's equipment

**Brand:** Fillikid

**Type / number of model:** MÖ-6200; ZFJFR

**Type of alert:** Products with serious risks

The high chair is not sufficiently stable and can easily tip over sideways.

A sitting child may fall and suffer injuries.

The product does not comply with the relevant European Standard EN 14988.

Recall of the product from end users, Withdrawal of the product from the market

**Description:** Foldable high chair with green padded seat and green plastic tray. Packaging in a cardboard box.

**Batch number / Barcode:** 9009852395112

**Country of origin:** Germany

**Alert submitted by:** Hungary



**Alert number:** A12/1533/19

**Product:** Children's High chair

**Name:** Folding highchair

**Risk type:** Injuries

**Category:** Childcare articles and children's equipment

**Brand:** Comptine

**Type / number of model:** BB-06ST Simple high chair

**Type of alert:** Products with serious risks

The high chair is not sufficiently stable.

Consequently, it could tip over sideways while the child is still sitting on it, leading to injuries.

The product does not comply with the relevant European standard EN 14988.

Recall of the product from end users, Withdrawal of the product from the market

**Description:** Foldable high chair with light blue padded seat and gray plastic tray. Sold packed in a cardboard box. Recommended for children from 6-36 months of age. Maximum load capacity: 15 kg.

**Batch number / Barcode:** 3245670519347, Batch number 161221

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/1539/19

**Product:** Children's high chair set

**Name:** High chair

**Risk type:** Injuries, Strangulation

**Category:** Childcare articles and children's equipment

**Brand:** Faktum

**Type / number of model:** Botond Natural

**Type of alert:** Products with serious risks

The high chair is not sufficiently stable and can easily tip over backwards and sideways, causing injuries to the child.

Furthermore the child can slide out of the seat and get stuck with the head between the seat and armrest, leading to strangulation.

The product does not comply with the relevant European standard EN 14988.

Recall of the product from end users, Withdrawal of the product from the market

**Description:** Set consisting of a wooden table and a wooden high chair with tray, with multicoloured, foam-padded seat and backrest. The set is sold packed in a plastic bag.

**Batch number / Barcode:** 5999091704520

**Country of origin:** Hungary

**Alert submitted by:** Hungary



**Alert number:** A12/1523/19

**Product:** Pencil case

**Name:** Pencil case 3D

**Risk type:** Chemical

**Category:** Stationery

**Brand:** LiveLife

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The 3D plastic on the product contains an excessive amount cadmium (measured value up to 0,04 % by weight).

Cadmium is harmful to human health because it accumulates in the body, can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

**Description:** Pencil case made of fabric decorated with a 3d print with marine animals.

**Batch number / Barcode:** 5055727543243

**Country of origin:** China

**Alert submitted by:** Sweden



**Alert number:** A12/1510/19

**Product:** Plastic toy set

**Name:** Happy Day

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** CSJ43418-1186 ID: 18727

**Type of alert:** Products with serious risks

The plastic material of the toy contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: 32% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

**Description:** Set of two plastic ponies. Packaging: nylon bag.

**Batch number / Barcode:** 5 999057 799034

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/1517/19

**Product:** Toy slime

**Name:** Colorful Fluffy Mix-Up Slime

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** 2213-mix up

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value up to 733 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Withdrawal of the product from the market

**Description:** 150 grams of multicoloured slime in transparent plastic jar with lid. The product was also sold online.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Sweden



**Alert number:** A12/1518/19

**Product:** Toy slime

**Name:** Fluffy Squishy Lab Slime

**Risk type:** Chemical

**Category:** Toys

**Brand:** Pink Parrot Group

**Type / number of model:** 2213-green

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value up to 642 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Withdrawal of the product from the market

**Description:** 150 grams of green slime sold in a transparent plastic jar with lid. The product was also sold online.

**Batch number / Barcode:** 101089

**Country of origin:** China

**Alert submitted by:** Sweden



**Alert number:** A12/1519/19

**Product:** Toy slime

**Name:** Squishy Slime

**Risk type:** Chemical

**Category:** Toys

**Brand:** Free & Easy

**Type / number of model:** S34897030

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value up to 784 mg/kg)

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Withdrawal of the product from the market

**Description:** Light blue slime in transparent container sold in a blister on a cardboard. The product was also sold online.

**Batch number / Barcode:** 8719202637052

**Country of origin:** China

**Alert submitted by:** Sweden





**Alert number:** A12/1520/19

**Product:** Toy slime

**Name:** Dinosaur Poo

**Risk type:** Chemical

**Category:** Toys

**Brand:** HGL

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value up to 1098 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Withdrawal of the product from the market

**Description:** Brown slime with sparkles in a transparent plastic container. The product was also sold online.

**Batch number / Barcode:** 5021813145141

**Country of origin:** China

**Alert submitted by:** Sweden



**Alert number:** A12/1521/19

**Product:** Toy slime

**Name:** Neon slime vulcano with dinosaur

**Risk type:** Chemical

**Category:** Toys

**Brand:** HGL

**Type / number of model:** 41905849, SV13413

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value up to 1092 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Withdrawal of the product from the market

**Description:** Light blue neon slime with dinosaur toy in a transparent plastic container shaped like a Volcano. The product was also sold online.

**Batch number / Barcode:** 5021813134138, Batch n°: 9039/18

**Country of origin:** China

**Alert submitted by:** Sweden



**Alert number:** A12/1522/19

**Product:** Toy slime

**Name:** Green slime with frog

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** N14 313

**Type of alert:** Products with serious risks

The migration of boron from the toy slime is too high (measured value up to 881 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Withdrawal of the product from the market

**Description:** Transparent plastic container filled with green slime and a toy frog and eggs in plastic. The product was also sold online.

**Batch number / Barcode:** 5026619143131

**Country of origin:** China

**Alert submitted by:** Sweden



**Alert number:** A12/1529/19

**Product:** Plastic doll with accessories

**Name:** Super Surprise; HAIR GOALS

**Risk type:** Chemical

**Category:** Toys

**Brand:** L.O.L.

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: 11 % by weight) and dibutyl phthalate (DBP) (measured value: 3.6 % by weight).

These phthalates may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Destruction of the product, Import rejected at border

**Description:** Plastic doll with accessories. The product emits light and music. Packaged in a plastic cardboard box with transparent window.

**Batch number / Barcode:** 6928260038011

**THE PRODUCT IS COUNTERFEIT**

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/1530/19

**Product:** Plastic doll with accessories

**Name:** Surprise; HAIR GOALS

**Risk type:** Chemical

**Category:** Toys

**Brand:** L.O.L.

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The plastic material of the doll's head contains 2-ethylhexyl phthalate (DEHP) (measured value: 31 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Destruction of the product, Import rejected at border

**Description:** Plastic doll with accessories. Packaging: cardboard box with transparent window.

**Batch number / Barcode:** 6909462904106

**THE PRODUCT IS COUNTERFEIT**

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/1537/19

**Product:** Fancy-dress mask

**Name:** Wolf Mask/Masque Loup

**Risk type:** Burns

**Category:** Toys

**Brand:** SMIFFYS

**Type / number of model:** 55 EH, Product code: 46977

**Type of alert:** Products with serious risks

The fancy-dress mask is flammable, does not self-extinguish and the fire spreads rapidly on it.

If the mask catches fire, the child could suffer burns.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-2.

Recall of the product from end users, Withdrawal of the product from the market

**Description:** Wolf mask wrapped in transparent plastic bag. The product was also sold online.

**Batch number / Barcode:** 46977 -29-11-2016 VATNOGB129579528

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/1544/19

**Product:** Beach toy set

**Name:** Set SAND

**Risk type:** Choking

**Category:** Toys

**Brand:** FENG YU

**Type / number of model:** OC0340849

**Type of alert:** Products with serious risks

There are small parts in the toy that can get loose.

If a child puts the small parts in the mouth, they could block the child's airways.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Withdrawal of the product from the market

**Description:** Beach toy set consisting of a bucket with accessories, supplied in a plastic net.

**Batch number / Barcode:** 0000011573449

**Country of origin:** China

**Alert submitted by:** Lithuania



**Alert number:** A12/1528/19

**Product:** Children's tracksuit

**Name:** Unknown

**Risk type:** Strangulation

**Category:** Clothing, textiles and fashion items

**Brand:** Xtreme Boxing

**Type / number of model:** 0710 CB

**Type of alert:** Products with serious risks

There are drawstrings with free ends in the hood.

The drawstrings may become trapped during various activities of the child, leading to strangulation.

The product does not comply with the relevant European standard EN 14682.

Ban on the marketing of the product and any accompanying measures

**Description:** Hoodie sweatshirt with fluorescent green hood, for 10-year old.

**Batch number / Barcode:** article BFB-10Z, bar code 3176977100368 - 3176977120366 - 3176977140365

**Country of origin:** China

**Alert submitted by:** Italy



**Alert number:** A12/1541/19

**Product:** Children's tracksuit

**Name:** Unknown

**Risk type:** Strangulation

**Category:** Clothing, textiles and fashion items

**Brand:** MISS IMAGE

**Type / number of model:** LF 5155

**Type of alert:** Products with serious risks

The product contains drawstrings with free ends in the neck area.

These drawstrings can become trapped during various activities of a child, leading to strangulation.

The product does not comply with the relevant European standard 14682.

Withdrawal of the product from the market

**Description:** Tracksuit intended for 4-year old girls. The top part hooded sweatshirt bears functional elastic cords with a non fixed toggle.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Cyprus



**Alert number:** A12/1543/19

**Product:** Children's tracksuit

**Name:** Schoolmates schoolwear

**Risk type:** Injuries

**Category:** Clothing, textiles and fashion items

**Brand:** S

**Type / number of model:** 823L

**Type of alert:** Products with serious risks

The drawstrings in the waist area are too long.

They can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European Standard EN 14682.

Withdrawal of the product from the market

**Description:** Grey tracksuit intended for 6-year old boys, consisting of a hooded sweatshirt and trousers. The trousers bear drawstrings at the waist area, which are 20 cm each, but are not attached to the garment in at least one point positioned equidistant from the exit points.

**Batch number / Barcode:** 5290625016998

**Country of origin:** Pakistan

**Alert submitted by:** Cyprus



**Alert number:** A12/1538/19

**Product:** Napkin ring

**Name:** Servettring Krona

**Risk type:** Chemical

**Category:** Decorative articles

**Brand:** Unknown

**Type / number of model:** Unknown

**Type of alert:** Products with serious risks

The metal of the product contains an excessive amount of lead (measured value up to 5,45 % by weight).

Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children.

The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

**Description:** Dark metallic napkin ring shaped like a crown.

**Batch number / Barcode:** Unknown

**Country of origin:** India

**Alert submitted by:** Sweden



**Alert number:** A12/1540/19

**Product:** USB charger

**Name:** USB wall charger

**Risk type:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** GIGATECH

**Type / number of model:** G600

**Type of alert:** Products with serious risks

The clearance/creepage distances between the primary and accessible secondary circuits are not sufficient.

The user could touch accessible live parts and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950.

Recall of the product from end users, Withdrawal of the product from the market

**Description:** USB charger in white plastic, sold in a transparent plastic box.

**Batch number / Barcode:** 6911287249539

**Country of origin:** China

**Alert submitted by:** Croatia





**Alert number:** A11/0064/19

**Product:** Sliding compound mitre saw

**Name:** Sliding compound mitre saw

**Risk type:** Electric shock

**Category:** Machinery

**Brand:** Kity, Scheppach

**Type / number of model:** HM90SL (Scheppach) , KS216S and KS216S2 (Kitty)

**Type of alert:** Products with other risk levels

The power supply of the marking laser is defective.

Consequently,when plugged to the mains, the brass housing of the laser might become live, which if touched will lead the user to receive an electric shock.

The product does not comply with the requirements of the Machinery Directive.

Making the marketing of the product subject to prior conditions, Providing customers with repair kit, Recall of the product from end users

**Description:** Different models of mitre saw mounted on a sliding compound with a marking laser. The product was also sold online.

**Batch number / Barcode:** 4046664065791 and 4046664067870 (Kity), 4046664069119 and 4046664071686 (Scheppach)

**Country of origin:** Unknown

**Alert submitted by:** Germany

**Products were found and measures were taken also in:** France



Sliding Compound Mitre Saw HM90SL  
brand „Scheppach“  
EAN: 4046664069119  
(Sales mostly in Germany,  
to Holzmaster24 GmbH and Johannes Leifeld GmbH & Co.KG)

Sliding Compound Mitre Saw HM90SL  
brand „Scheppach“  
EAN: 4046664071686  
(Sales mostly in Sweden, Norway and Poland;  
Solely to Jula AB)



Sliding Compound Mitre Saw KS216S  
brand „Kity“  
EAN: 4046664065791  
(Sales mostly in France,  
to Leroy Merlin)

Sliding Compound Mitre Saw KS216S2  
brand „Kity“  
EAN: 4046664067870  
(Sales mostly in France,  
to Brico Prive SAS, Cdiscount.com)



Sliding Compound Mitre Saw KS216S  
brand „Kity“  
EAN: 4046664065791  
(Sales mostly in France,  
to Leroy Merlin)

Sliding Compound Mitre Saw KS216S2  
brand „Kity“  
EAN: 4046664067870  
(Sales mostly in France,  
to Brico Prive SAS, Cdiscount.com)



Sliding Compound Mitre Saw HM90SL  
brand „Scheppach“  
EAN: 4046664069119  
(Sales mostly in Germany,  
to Holzmaster24 GmbH and Johannes Leifeld GmbH & Co.KG)

Sliding Compound Mitre Saw HM90SL  
brand „Scheppach“  
EAN: 4046664071686  
(Sales mostly in Sweden, Norway and Poland;  
Solely to Jula AB)

**Alert number:** A11/0062/19

**Product:** Rope Wrench Kit

**Name:** Singing Tree Rope Wrench

**Risk type:** Injuries

**Category:** Protective equipment

**Brand:** ISC

**Type / number of model:** RP280XX+RT270C1, RP280XX+RT270B1

**Type of alert:** Products with other risk levels

The personal fall protection equipment has not been tested according to its intended use. The scope of the applied harmonised standards does not cover essential aspects of the system's scope. Furthermore, the instructions for use are incomplete.

This may lead to an increased risk of malfunction of the product, potentially leading to an accident.

The product does not comply with the Personal Protective Equipment Regulation.

Ban on the marketing of the product and any accompanying measures

**Description:** Guided type fall arrester for climbing and abseiling on a single rope. The product is made of aluminium with rope and rounded edges and is equipped with a quick-pin.

**Batch number / Barcode:** Unknown

**Country of origin:** United Kingdom

**Alert submitted by:** Germany



**Alert number:** A11/0063/19

**Product:** Children's high chair

**Name:** Highchair

**Risk type:** Injuries

**Category:** Childcare articles and children's equipment

**Brand:** Touragoo

**Type / number of model:** HC-61 Binge Green , Item N0: Touragoo Binge

**Type of alert:** Products with other risk levels

The high chair is not sufficiently stable.

Consequently, it could easily tip over backwards while the child is still sitting on it, leading to injuries.

The product does not comply with the relevant European Standard EN 14988.

Withdrawal of the product from the market

**Description:** High chair with removable green plastic tray and snap-on footrest, grey seatbelt, and backrest and lower basket, made in fabric.

The product is sold packed in a cardboard box.

**Batch number / Barcode:** 4918263216013

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A11/0065/19

**Product:** Toy slime

**Name:** Pâte Peteuse

**Risk type:** Chemical

**Category:** Toys

**Brand:** B&G international

**Type / number of model:** n°13038; yellow and orange

**Type of alert:** Products with other risk levels

The migration of boron from the toy slime is too high (measured value up to 469 mg/kg, yellow slime; 573 mg/kg orange slime). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Ban on the marketing of the product and any accompanying measures

**Description:** Toy slime in plastic containers; the colours yellow and orange are affected.

**Batch number / Barcode:** 3588270013038

**Country of origin:** France

**Alert submitted by:** Germany

