

A Safety Gate home (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

Back to report listings (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2020&Ing=er

Q Search alerts (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search&Ing=en)

IPSW 2018 (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=ipsw:home)

The Rapid Alert System for Non-Food Products (RAPEX)

RAPEX - Weekly overview report of notifications

Week 10 - 2020

Alert number: A12/00355/20 Product: Swimming gloves Name: AquaHandschuhe Risk type: Chemical Category: Hobby/sports equipment Brand: BECO Type / number of model: Art.: 9634, 9635, 9636, 9667 Type of alert: Products with serious risks The neoprene of the product contains an excessive amount of polycyclic aromatic hydrocarbons (PAHs), notably chrysene and benzo(e)pyrene (measured values: up to 3.17 mg/kg, and 4.48 mg/kg by weight respectively). These PAHs may cause cancer and are also mutagenic and toxic for reproduction. / The product does not comply with the REACH Regulation. Recall of the product from end users, Withdrawal of the product from the market Company recall page: https://www.beco-beermann.com/de/informationen/)

Description: Coloured gloves (depending on size S = turquoise, M = red, L = blue); padded web between the fingers; cuff with Velcro fastening; Articles 9634 and 9635: Upper: Textile (80% polyamide, 20% elastane), palm: 100% neoprene; Articles 9636 and 9667: Upper and palm: 100% neoprene

Batch number / Barcode: 4013368346709 Country of origin: People's Republic of China Alert submitted by: Germany



Alert number: A12/00345/20 Product: Laser engraving machine Name: Risk type: Damage to sight Category: Machinery Brand: Type / number of model: 20W

Type of alert: Products with serious risks

Unrestricted, invisible laser radiation can be emitted by the product. If reflected or diffused rays hit the eye, they may cause blindness or injuries. / The product does not comply with the requirements of the Machinery Directive and the relevant European standards EN 60825-1 and EN ISO 11553-1.

Ban on the marketing of the product and any accompanying measures

Description: Laser engraving machine, packed in wooden crate.

Batch number / Barcode: 6962375698616

Country of origin: People's Republic of China

Alert submitted by: Germany



Alert number: A12/00351/20 Product: Laser engraving machine Name: Risk type: Damage to sight Category: Machinery Brand:

Type / number of model: 40W

Type of alert: Products with serious risks

Unrestricted, invisible laser radiation can be emitted by the product. If reflected or diffused rays hit the eye, they may cause blindness or injuries. / The product does not comply with the requirements of the Machinery Directive and the relevant European standards EN 60825-1 and EN ISO 11553-1.

Ban on the marketing of the product and any accompanying measures

Description: Laser engraving machine, packed in cardboard box. The product was also sold online, in particular via eBay.

Batch number / Barcode: 6962375698197

Country of origin: People's Republic of China



Alert number: A12/00352/20 Product: Laser engraving machine Name: Risk type: Damage to sight Category: Machinery Brand:

Type / number of model: 130W KH9060

Type of alert: Products with serious risks

Unrestricted, invisible laser radiation can be emitted by the product. If reflected or diffused rays hit the eye, they may cause blindness or injuries / The product does not comply with the requirements of the Machinery Directive and the relevant European standards EN 60825-1 and EN ISO 11553-1.

Ban on the marketing of the product and any accompanying measures

Description: Laser engraving machine, packed in a wooden crate. the product was also sold online, in particular via eBay.

Batch number / Barcode: 6962375698364

Country of origin: People's Republic of China

Alert submitted by: Germany



Alert number: A12/00353/20 Product: Laser engraving machine Name: Risk type: Damage to sight Category: Machinery

Brand:

Type / number of model: 50W KH5030

Type of alert: Products with serious risks

Unrestricted, invisible laser radiation can be emitted by the product. If reflected or diffused rays hit the eye, they may cause blindness or injuries. / The product does not comply with the requirements of the Machinery Directive and the relevant European standards EN 60825-1 and EN ISO 11553-1.

Ban on the marketing of the product and any accompanying measures

Description: Laser engraving machine, packed in wooden crate. The product was also sold online, in particular via eBay.

Batch number / Barcode: 6962375698326

Country of origin: People's Republic of China

Alert submitted by: Germany



Alert number: A12/00342/20 Product: Passenger van / Light commercial vehicle Name: Partner/Rifter Risk type: Injuries Category: Motor vehicles Brand: Peugeot Type / number of model: Typ: E, Type-approval number: e2*2007/46*0623*05, e2*2007/46*0625*02 bis e2*2007/46*0625*08 Type of alert: Products with serious risks The front passenger seatbelt is defective. As a result, its restraining function will be impaired, increasing the risk of injury in the event of an accident. / Recall of the product from end users Description: Passenger van / Light commercial vehicle under Peugeot recall code: JUD. Batch number / Barcode: JUD Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Poland

Alert number: A12/00343/20 Product: Passenger car Name: 6 Risk type: Injuries Category: Motor vehicles Brand: Mazda Type / number of model: Type-approval number: e1*98/14*0188*, Type: GG/GY Type of alert: Products with serious risks A defect in the gas generator of the passenger airbag may cause uncontrolled inflation when the airbag is activated. As a result, small metal particles can be released, increasing the risk of injury to the occupants. / Recall of the product from end users Description: Passenger car under Mazda recall code: AF058A. Batch number / Barcode: AF058A Country of origin: Japan Alert submitted by: Germany Alert number: A12/00344/20 Product: Passenger car Name: Berlingo Risk type: Injuries Category: Motor vehicles Brand: Citroen Type / number of model: Type-approval numbers: e2*2007/46*0623*05, e2*2007/46*0625*02 to e2*2007/46*0625*08, Type: E Type of alert: Products with serious risks The front passenger seatbelt is defective. As a result, its restraining function will be impaired, increasing the risk of injury in the event of an accident. / Recall of the product from end users Description: Passenger car under Citroen recall code: HAZ. Batch number / Barcode: HAZ Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00346/20 Product: Passenger car Name: A-Class, B-Class, CLA Risk type: Injuries Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Model series: BR 176, BR 246, BR 117, Type-approval number: e1*2001/116*0470*15-*18, Type: 245 G Type of alert: Products with serious risks The occupant classification system for the front passenger seat may not be calibrated in accordance with the specifications. Consequently, an installed child seat may be identified as a person or a small, light person as a child seat. As a result, the passenger airbag could be activated despite the presence of a child seat or the passenger airbag could fail to activate despite the presence of a person on the passenger seat, increasing the risk of injuries. / Recall of the product from end users Description: Passenger car under Mercedes-Benz recall code: 9190204. Batch number / Barcode: 9190204 Country of origin: Germany Alert submitted by: Germany Alert number: A12/00347/20 Product: Passenger car Name: Clio, Captur Risk type: Fire Category: Motor vehicles Brand: Renault Type / number of model: Model series: X98, X87, Type-approval numbers: e2*2001/116*0327*87, e2*2001/116*0327*88, e2*2001/116*0327*89, e2*2007/46*0008*40, e2*2007/46*0008*41, e2*2007/46*0008*42 Type of alert: Products with serious risks The positive terminal of the battery can come into contact with the heat sink on the alternator. This can lead to an electrical short circuit and to increased risk of fire in the engine compartment. / Recall of the product from end users Description: Vehicles equipped with H4Bt engines, produced at Bursa, Valladolid and Novo Mesto under Renault recall code: 0D78. Batch number / Barcode: 0D78 Country of origin: France Alert submitted by: France Products were found and measures were taken also in: Ireland

Alert number: A12/00348/20 Product: Passenger car Name: Vivaro, Zafira Life Risk type: Fire, Injuries Category: Motor vehicles Brand: Opel Type / number of model: e2*2007/46*0532*10 to e2*2007/46*0533*08, Type: V Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia Risk type: Fire, Injuries
Name: Vivaro, Zafira Life Risk type: Fire, Injuries Category: Motor vehicles Brand: Opel Type / number of model: e2*2007/46*0532*10 to e2*2007/46*0533*08, Type: V Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Name: Vivaro, Zafira Life Risk type: Fire, Injuries Category: Motor vehicles Brand: Opel Type / number of model: e2*2007/46*0532*10 to e2*2007/46*0533*08, Type: V Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Risk type: Fire, Injuries Category: Motor vehicles Brand: Opel Type / number of model: e2*2007/46*0532*10 to e2*2007/46*0533*08, Type: V Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Category: Motor vehicles Brand: Opel Type / number of model: e2*2007/46*0532*10 to e2*2007/46*0533*08, Type: V Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Brand: Opel Type / number of model: e2*2007/46*0532*10 to e2*2007/46*0533*08, Type: V Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Type / number of model: e2*2007/46*0532*10 to e2*2007/46*0533*08, Type: V Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Type / number of model: e2*2007/46*0532*10 to e2*2007/46*0533*08, Type: V Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Type of alert: Products with serious risks There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
There is an increased risk of leak in the fuel line. Fuel may escape and ignitie, as well as leak into the road, causing a risk to trafic. / Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Recall of the product from end users Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Description: Passenger car Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Batch number / Barcode: E191902900 (20-C-001) Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Alert submitted by: Germany Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Products were found and measures were taken also in: Ireland, Poland Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Alert number: A12/00349/20 Product: Passenger car Name: Insignia
Product: Passenger car Name: Insignia
Product: Passenger car Name: Insignia
Name: Insignia
Rick type: Fire Injuries
Nisk type. The, injunes
Category: Motor vehicles
Brand: Opel
Type / number of model: Type: Z-B, e8*2007/46*0264*04 - 08
Type of alert: Products with serious risks
Engine oil from a crack-prone oil return pipe may come into contact with hot exhaust parts and cause a fire. Oil might also leak onto the road. /
Recall of the product from end users
Description: Passenger car
Batch number / Barcode: E19-1900420 (20-C-031)
Country of origin: Germany
Alert submitted by: Germany
Products were found and measures were taken also in: Ireland, Poland
Alert number: A12/00356/20
Product: Passenger car
Name: Charade
Risk type: Injuries
Category: Motor vehicles
Brand: Daihatsu
Type / number of model: Type: XP9F(a), e11*2001/116*0249*06
Type of alert: Products with serious risks
A defect in the gas generator of the passenger airbag may cause uncontrolled inflation and the release of metal fragments when the airbag is
activated, which can cause injuries to the occupants. /
Recall of the product from end users
Description: Passenger car
Batch number / Barcode: 201901
Country of origin: France
Alert submitted by: Germany
Alert number: A12/00358/20
Product: Lorry
Name: Actros, Arocs
Risk type: Injuries
Category: Motor vehicles
Brand: Mercedes- Benz
Brand: Mercedes- Benz
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743 Type of alert: Products with serious risks
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743 Type of alert: Products with serious risks
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743 Type of alert: Products with serious risks Faulty software may cause the ignition and associated systems to suddenly fail during driving. / Recall of the product from end users
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743 Type of alert: Products with serious risks Faulty software may cause the ignition and associated systems to suddenly fail during driving. / Recall of the product from end users Description: Lorry
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743 Type of alert: Products with serious risks Faulty software may cause the ignition and associated systems to suddenly fail during driving. / Recall of the product from end users Description: Lorry Batch number / Barcode: FREMDSTART
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743 Type of alert: Products with serious risks Faulty software may cause the ignition and associated systems to suddenly fail during driving. / Recall of the product from end users Description: Lorry Batch number / Barcode: FREMDSTART Country of origin: Germany
Brand: Mercedes- Benz Type / number of model: Models: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H, Type-approval numbers: e1*2007/46*0726 bis e1*2007/46*0743 Type of alert: Products with serious risks Faulty software may cause the ignition and associated systems to suddenly fail during driving. / Recall of the product from end users Description: Lorry Batch number / Barcode: FREMDSTART

Alert number: A12/00363/20 Product: Passenger van / Light commercial vehicle Name: Vivaro, Zafira Risk type: Injuries Category: Motor vehicles Brand: Opel Type / number of model: Type-approval numbers: e2*2007/46*0532*10; e2*2007/46*0533*, Type: V Type of alert: Products with serious risks Water may leak into the vehicle's interior. Consequently, the proper functioning of the airbags can be impaired, increasing the risk of injury in the event of an accident. / Recall of the product from end users Description: Passenger van / Light commercial vehicle under Opel recall code: E19-190444. Batch number / Barcode: E19-190444 Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Ireland Alert number: A12/00350/20 Product: Children's car seat Name: MINK Risk type: Injuries Category: Childcare articles and children's equipment Brand: Kinderkraft Type / number of model: KKFMINKBLK0000, KKFMINKBLK00BS, KKFMINKGRM0000, KKFMINKGRM00BS, KKFMINKGRY0000, KKFMINKGRY00BS, KKFMINKNAV0000, KKFMINKNAV00BS Type of alert: Products with serious risks One of the handle attachment components may become loose. The seat with child may detach from the handle while carrying it which would cause the a child fall and suffer injuries. / Recall of the product from end users Company recall page: https://kinderkraft.com/en/info (https://kinderkraft.com/en/info) Description: Children's car seat for children up to 13 kg Batch number / Barcode: Country of origin: People's Republic of China Alert submitted by: Poland

Alert number: A12/00339/20 Product: Plastic Doll Name: Beauty fashion icon Risk type: Chemical Category: Toys Brand:

Type / number of model: N0.20105

Type of alert: Products with serious risks

The doll contains an excessive amount of 2-ethylhexyl phthalate (DEHP) and di-'isononyl' phthalate (DINP) (measured value up to 34 % by weight and 20.45% by weight respectively). These phthalates may harm the health of children, causing possible damage to the reproductive system and the liver. / The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

Description: A plastic doll in a cardboard.

Batch number / Barcode: 6910154154501 Country of origin: People's Republic of China

Alert submitted by: Cyprus



Alert number: A12/00340/20 Product: Plastic doll with accessories Name: Beautiful Risk type: Chemical Category: Toys Brand: Type / number of model: N0.622

Type of alert: Products with serious risks

The doll contains an excessive amount of of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 21.7% by weight and 23.1% by weight respectively). These phthalates may harm the health of children, causing possible damage to the reproductive system. / The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

Description: A plastic doll with accssories in a cardboard.

Batch number / Barcode: 6900324555221

Country of origin: People's Republic of China

Alert submitted by: Cyprus



Alert number: A12/00341/20 Product: Plastic toy set Name: Game Set Police Risk type: Choking Category: Toys Brand:

Type / number of model: N0-1000641 Type of alert: Products with serious risks

The suction cups of the projectiles can easily detach. If a child puts the projectile in the mouth, the suction cup may detach and obstruct the airways. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Withdrawal of the product from the market

Description: Plastic toy police set, consists of plastic gun and projectiles with suction cups

Batch number / Barcode: 5902444006417

Country of origin: People's Republic of China

Alert submitted by: Poland







Alert number: A12/00357/20 Product: Toy gun set Name: katonai felszerelés / Military set Risk type: Chemical, Injuries Category: Toys Brand:

Type / number of model: Torch (on the label), Real Heroes Item No.C00314

Type of alert: Products with serious risks

The suction cups contain an excessive amount of di-(2-ethylhexyl) phthalate (DEHP) (up to 5.7 % by weight), and of dibutyl phthalate (DBP) (up to 13% by weight). These phthalates may harm the health of children causing possible damage to the reproductive system. The kinetic energy of the projectiles fired from the toy gun is too high and may lead to injuries. / The product does not comply with the REACH Regulation and the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Recall of the product from end users, Withdrawal of the product from the market

Description: Plastic toy gun set including 1 Pistol, 1 toy soldier, 1 hand grenade, 1 knife, 1 binoculars, 1 bottle and 1 identification tag and 3 projectiles with suction cups.

Batch number / Barcode: 5991800003146

Country of origin: People's Republic of China

Alert submitted by: Hungary









Alert number: A12/00359/20 Product: Hoverball Name: Amenon Hoverball 1 Risk type: Environment Category: Toys Brand: Amenon Type / number of model: Type of alert: Products with serious risks The solders and cables contain an excessive amount of lead (measured value up to 83%). Lead poses a risk to the environment. / The product does not comply with the requirements of the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive). Withdrawal of the product from the market Description: Toy in the shape of a flattened football with a lighting rim. Batch number / Barcode: Country of origin: People's Republic of China Alert submitted by: United Kingdom



Alert number: A12/00361/20 Product: Rattle toy Name: Baby Rattle Risk type: Choking Category: Toys Brand: BF

Type / number of model: Item N° 1401086

Type of alert: Products with serious risks

The product can easily break, releasing small parts. A child may put the small parts in the mouth and choke. / The product does not comply with the Toy Safety Directive and the relevant European standard EN 71-1.

Recall of the product from end users, Withdrawal of the product from the market

Description: Light green frog shaped rattle with a flexible, hemispherical frame at the bottom. The ball in the frame makes the rattling sound. There are three colored plastic beads on both sides of the yellow plastic arms. The rattle is available in the form of a mouse and a pig too. **Batch number / Barcode:** 8000014010868

Country of origin: People's Republic of China

Alert submitted by: Hungary









Alert number: A12/00360/20 Product: Leather shoes Name: Loafer Karlstad Risk type: Chemical Category: Clothing, textiles and fashion items Brand: OIS Type / number of model: art. 525115299OA Karlstad (both colors; black and pink) Type of alert: Products with serious risks The amount of chromium (VI) found in the leather is too high (measured value up to 21.1 mg/kg). Chromium (VI) is sensitising and may trigger allergic reactions. / The product does not comply with the REACH Regulation. Import rejected at border Description: Leather loafers with a leather bow with metallic tips on them, available in black and pink. Batch number / Barcode: 6413692308073 (black) Country of origin: People's Republic of China Alert submitted by: Finland 1218-L02A 0·i·s Alert number: A12/00362/20 Product: Girls' shoes Name: Risk type: Chemical Category: Clothing, textiles and fashion items Brand: BACIO & BACIO Type / number of model: Item N°: F3800 Navi Type of alert: Products with serious risks The leather insole of the shoes contains chromium VI (measured value: 14.8 mg/kg). Chromium (VI) is sensitising, can trigger allergic reactions and can cause cancer. / The product does not comply with the REACH Regulation. Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market Description: Girls' shoes in dark blue, with leather insole. Sample size: 21.

Batch number / Barcode: Country of origin: Unknown

Alert submitted by: Greece





Alert number: A12/00354/20 Product: USB charger Name: USB Charger Risk type: Electric shock Category: Electrical appliances and equipment Brand: Xenic Type / number of model: XC02 Black

Type of alert: Products with serious risks

The electrical insulation and the creepage/clearance distances are inadequate. The user may receive an electric shock from live parts. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950-1.

Withdrawal of the product from the market

Description: USB charger with 2 ports. 100 - 240 V

Batch number / Barcode: 5902721191294

Country of origin: People's Republic of China

Alert submitted by: Poland



Alert number: A12/00364/20
Product: Battery charger
Name: Battery Charger
Risk type: Electric shock
Category: Electrical appliances and equipment
Brand: EMOS
Type / number of model: BC SMART4 (N8168S)
Type of alert: Products with serious risks
The insulation of the product is inadequate. Parts of the product may consequently become live, leading to an electric shock if touched by the user. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335-1.
Withdrawal of the product from the market
Description: Battery charger, black plastic device, designed for NiMh:AA/AAA 4x.
Batch number / Barcode: 8592920033937

Country of origin: Czechia

Alert submitted by: Czechia





Alert number: INFO/00036/20 Product: Earrings Name: Risk type: Chemical Category: Jewellery Brand: Type / number of model: Type of alert: Products with other risk levels

The metal part of the product releases an excessive amount of nickel (measured value up to: 1,3 µg/cm2/week). / Nickel is a strong sensitiser and causes allergic reactions if present in articles that come into direct and prolonged contact with the skin. The product does not comply with the REACH Regulation.

Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market **Description:** Single pearl earrings.

Batch number / Barcode: Country of origin: Unknown Alert submitted by: Greece



Alert number: A11/00027/20 Product: ladder Name: HOUSEHOLD LADDERS Risk type: Injuries Category: Other Brand: STS Type / number of model: D05D/05 Type of alert: Products with other risk levels The ladder does not have sufficient mechanical strength and can bend during use, hence the user may fall from a height. / The product does not comply with the relevant European standard EN 131. Import rejected at border Description: Foldable aluminium step ladder with 4 steps and platform. The legs have yellow plastic non-slip end caps. Batch number / Barcode: 3871880001060 Country of origin: Bosnia and Herzegovina Alert submitted by: Hungary



Product: Plastic toy Name: Dinosaur Risk type: Choking Category: Toys Brand: PEPCO

Type / number of model: Item N0. 304848

Type of alert: Products with other risk levels

The toy's switch may not work properly and may cause batteries to overheat, get damaged and leak acid. The user could come into contact with the leaked corrosive acid and suffer chemical burns. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standards EN 71-1 and EN 62115.

Recall of the product from end users

Company recall page:

https://pepco.bg/magazini/informacija-za-klienti/info/igrachka-dinozavr-s-distancionno-upravlenie-talisman/ (https://pepco.bg/magazini/informacija-za-klienti/info/igrachka-dinozavr-s-distancionno-upravlenie-talisman/)

https://pepco.cz/prodejny/informace-pro-zakazniky/info/stazeni-z-prodeje-mazlicek-ruzova-kusadla-dinosaurus-na-dalkove-ovladani/ (https://pepco.cz/prodejny/informace-pro-zakazniky/info/stazeni-z-prodeje-mazlicek-ruzova-kusadla-dinosaurus-na-dalkove-ovladani/) https://pepco.ee/poed/pepco-teadaanne/info/puldiga-dinosaurus-roosade-naerimisrongastega-kaisuloomad/ (https://pepco.ee/poed/pepco-

nttps://pepco.ee/poed/pepco-teaddanne/info/puidiga-dinosaurus-roosade-naefimisrongastega-kaisuloomad/ (https://pepco.ee/poed/pepcoteaddanne/info/puldiga-dinosaurus-roosade-naerimisrongastega-kaisuloomad/)

https://pepco.hr/trgovine/informacije-za-korisnike/info/pepco-obavijest-15/ (https://pepco.hr/trgovine/informacije-za-korisnike/info/pepco-obavijest-15/)

https://pepco.hu/rolunk/uzleteink/vasarloi-tajekoztato/info/hivatalos-koezlemeny-1/ (https://pepco.hu/rolunk/uzleteink/vasarloi-tajekoztato/info/hivatalos-koezlemeny-1/)

https://pepco.lt/parduotuves/informacija/info/dinozaura-zaisla-valdoma-nuotoliniu-budu-minksti-zaislai-su-rausvais-kramtukais/ (https://pepco.lt/parduotuves/informacija/info/dinozaura-zaisla-valdoma-nuotoliniu-budu-minksti-zaislai-su-rausvais-kramtukais/) https://pepco.lv/veikali/pepco-pazinojums/info/milojamas-rotallietas-ar-roza-zobgrauzniem-talvadams-rotalu-dinozaurs/

(https://pepco.lv/veikali/pepco-pazinojums/info/milojamas-rotallietas-ar-roza-zobgrauzniem-talvadams-rotalu-dinozaurs/) https://pepco.pl/sklepy/informacje-dla-klientow/info/komunikat-firmy-pepco-1/ (https://pepco.pl/sklepy/informacje-dla-klientow/info/komunikat-firmy-pepco-1/)

https://pepco.ro/magazine/informatii-pentru-clienti/info/comunicat-pepco-3/ (https://pepco.ro/magazine/informatii-pentru-clienti/info/comunicat-pepco-3/)

https://pepco.si/trgovine/informacije-za-stranke/info/vrnitev-blaga-zivaliropotuljice-z-grizalom-igraca-dinozavra-na-daljinsko-vodenje/ (https://pepco.si/trgovine/informacije-za-stranke/info/vrnitev-blaga-zivaliropotuljice-z-grizalom-igraca-dinozavra-na-daljinsko-vodenje/) https://pepco.sk/predajne/informacie-pre-zakaznikov/info/dinosaurus-na-dialkove-ovladanie-maznacik-ruzove-hryzadla-stiahnutie-z-predaja/ (https://pepco.sk/predajne/informacie-pre-zakaznikov/info/dinosaurus-na-dialkove-ovladanie-maznacik-ruzove-hryzadla-stiahnutie-z-predaja/ (https://pepco.sk/predajne/informacie-pre-zakaznikov/info/dinosaurus-na-dialkove-ovladanie-maznacik-ruzove-hryzadla-stiahnutie-z-predaja/) Description: Remote controlled plastic toy dinosaur. Battery powered.

Batch number / Barcode:

Country of origin: People's Republic of China Alert submitted by: Poland



Alert number: A11/00028/20 Product: Baby teether Name: Baby Rattles Series Paradise Growth Risk type: Choking Category: Toys Brand: Cheng Li Type / number of model: ITM. N0. 00-65196

Type of alert: Products with other risk levels

The toy contains protruding parts (plastic rings). A child could put the protruding parts into the mouth, which could block the airways and cause choking. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1. Withdrawal of the product from the market

Description: A purple plastic teether in the shape of a dolphin.

Batch number / Barcode: 5906160265196

Country of origin: People's Republic of China

Alert submitted by: Poland



Alert number: A11/00030/20 Product: Battery-operated toy Name: Spiderman Risk type: Chemical Category: Toys Brand: Type / number of model: NO:3701

Type of alert: Products with other risk levels

The batteries compartment can easily be opened without the use of any tools, leaving batteries accessible. A child may take a damaged or leaking battery and suffer burns due to the leaking chemical products. The toy is operated with 2 AA batteries (batteries are easily accessible) which fit almost entirely in the small parts cylinder. AA batteries are relatively large, it would be hard to swallow them, therefore it is assumed that it may just get stuck in a child's throat and cause injuries. / Directive 2009/48/EC on safety of toys; standard EN 62115:2005+A2:2011+A2/2011/AC:2011++A11:2012+A11:2012/AC:2013+A12:2015 Electric toys - Safety Destruction of the product

Description: Plastic toy - telephone Spiderman. Toy is operated with 2 AA batteries (not included).

Batch number / Barcode: 9909050544254

Country of origin: People's Republic of China

Alert submitted by: Latvia



Alert number: A11/00031/20 Product: Battery-operated toy Name: Hero Risk type: Chemical Category: Toys Brand: Type / number of model: NO:616-6

Type of alert: Products with other risk levels

The batteries compartment can easily be opened without the use of any tools, leaving batteries accessible. A child may take a damaged or leaking battery and suffer burns due to the leaking chemical products. The toy is operated with 2 AA batteries (batteries are easily accessible) which fit almost entirely in the small parts cylinder. AA batteries are relatively large, it would be hard to swallow them, therefore it is assumed that it may just get stuck in a child"s throat and cause injuries. / Directive 2009/48/EC on safety of toys; EN 62115:2005+A2:2011+A2/2011/AC:2011+A11:2012+A11:2012/AC:2013+A 12:2015 Electric toys. Safety Destruction of the product

Description: Plastic toy - Hero in red colour. Toy is operated with 2 AA batteries (not included).

Batch number / Barcode:

Country of origin: People's Republic of China

Alert submitted by: Latvia



Alert number: A11/00032/20 Product: Battery-operated toy Name: Pepa Pig Risk type: Chemical Category: Toys Brand:

Type / number of model: NO:3696

Type of alert: Products with other risk levels

The batteries compartment can easily be opened without the use of any tools, leaving batteries accessible. A child may take a damaged or leaking battery and suffer burns due to the leaking chemical products. The toy is operated with 2 AA batteries (batteries are easily accessible) which fit almost entirely in the small parts cylinder. AA batteries are relatively large, it would be hard to swallow them, therefore it is assumed that it may just get stuck in a child's throat and cause injuries. / Directive 2009/48/EC on safety of toys; standard EN 62115:2005+A2:2011+A2/2011/AC:2011+A11:2012+A11:2012/AC:2013+A12:2015 Electric toys - Safety Destruction of the product

Description: Plastic toy - telephone Pepa Pig in pink and blue colour. Toy is operated with 2 AA batteries (not included).

Batch number / Barcode: 9909050565938

Country of origin: People's Republic of China

Alert submitted by: Latvia



Alert number: A11/00033/20 Product: Battery-operated toy Name: MUSIC STEERING WHEEL Risk type: Chemical Category: Toys Brand: Type / number of model: N°3190

Type of alert: Products with other risk levels

The batteries compartment can easily be opened without the use of any tools, leaving batteries accessible. A child may take a damaged or leaking battery and suffer burns due to the leaking chemical products. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115.

Destruction of the product

Description: Plastic toy wheel in red and blue colour. The toy is operated with 2 AA batteries (not included).

Batch number / Barcode: 9909050531902 Country of origin: People's Republic of China

Alert submitted by: Latvia



Alert number: A11/00034/20 Product: Battery-operated toy Name: Elephant Risk type: Chemical Category: Toys Brand:

Type / number of model: N°818-3; 92507

Type of alert: Products with other risk levels

The batteries compartment can easily be opened without the use of any tools, leaving batteries accessible. A child may take a damaged or leaking battery and suffer burns due to the leaking chemical products. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115.

Destruction of the product

Description: Plastic toy telephone in the shape of an elephant in yellow or green colour. The toy is operated with 2 AA batteries (not included). **Batch number / Barcode:** 8787247925076

Country of origin: People's Republic of China

Alert submitted by: Latvia



Alert number: INFO/00037/20 Product: Battery-operated toy Name: Frog Risk type: Chemical Category: Toys Brand: Type / number of model:

Type of alert: Products with other risk levels

The batteries compartment can easily be opened without the use of any tools, leaving batteries accessible. A child may take a damaged or leaking battery and suffer burns due to the leaking chemical products. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1 and EN 62115.

Withdrawal of the product from the market

Description: Soft musical toy frog in green with overalls and white boots. The toy is operated with 3 AA batteries (not included).

Batch number / Barcode:

Country of origin: People's Republic of China Alert submitted by: Latvia



Alert number: INFO/00038/20 Product: Rattle toy Name: Rattle Risk type: Choking Category: Toys Brand: Type / number of model: N°8088 Type of alert: Products with other risk levels The handle of the rattle is too long. A small ch

The handle of the rattle is too long. A small child could put it in the mouth, where it can get stuck and obstruct the airways. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.

Description: Plastic toy - baby rattle in pink and green or yellow colour.

Batch number / Barcode:

Destruction of the product

Country of origin: Unknown Alert submitted by: Latvia



Alert number: A11/00029/20 Product: Three-sockets extension Name: Bylectrica Risk type: Electric shock Category: Electrical appliances and equipment Brand: Type / number of model: PB16-259

Type of alert: Products with other risk levels

It is possible to open the adapter using a conventional screwdriver and access the live parts. A consumer could then receive an electric shock by touching said live parts. / Directive 2014/35/EU of the European Parliament and of the Council of 26 February 2014 on the harmonisation of the laws of the Member States relating to the making available on the market of electrical equipment designed for use within certain voltage limits Withdrawal of the product from the market

Description: Three-sockets extension with earthing PB16-259. The three sockets of the hub are arranged in a triangle with inscriptions max 16A and PB16-259 inside one socket. Plug-based inscriptions 16/250 ~, EAC and Belarusian inscription "Zrobliona u Belarusi".

Batch number / Barcode: 4810158000526

Country of origin: Belarus Alert submitted by: Lithuania





