



🏠 [Safety Gate home \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/repository/content/pages/rapex/index\\_en.htm\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

☰ [Back to report listings \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.listNotifications&year=2020&lng=en\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2020&lng=en)

🔍 [Search alerts \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.search&lng=en\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search&lng=en)

👤 [IPSW 2018 \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=ipsw:home\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=ipsw:home)

# The Rapid Alert System for Non-Food Products (RAPEX)

## *RAPEX - Weekly overview report of notifications*

Week 19 - 2020

Alert number: A12/00682/20

Product: Liquid for e-cigarettes

Name: Nic Salts

Risk type: Chemical

Category: Chemical products

Brand: Vampire Vape

Type / number of model: Heisenberg, Nicotine content 20 mg/ml

Type of alert: Products with serious risks

The product contains an excessive amount of nicotine (measured value: 24.3 mg/ml). Nicotine is acutely toxic and can endanger the user's safety, notably if the product comes into contact with the skin or is ingested. / The product does not comply with the requirements of the Tobacco Products Directive.

Withdrawal of the product from the market

Description: Refill container with 10 ml of blue liquid for electronic cigarettes.

Batch number / Barcode: 5060519668264

UNKNOWN

Country of origin: United Kingdom

Alert submitted by: Lithuania



Alert number: A12/00685/20

Product: LED tube

Name: T8 LED TUBE

Risk type: Electric shock

Category: Lighting equipment

Brand:

Type / number of model: NH20180910, T8-1.2m

Type of alert: Products with serious risks

During the insertion or re-insertion of the product, its live end can be touched. Moreover, the electrical insulation of the product is not sufficient. The user could touch live parts and receive an electric shock. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60968.

Withdrawal of the product from the market


Description: Fixed 1,2 meter long luminaire with 192 non-replaceable LEDs. The product is also sold online.

Batch number / Barcode:

NO

Country of origin: People's Republic of China

Alert submitted by: Hungary



Alert number: A12/00673/20

Product: Motorcycle

Name: TMAX XP530

Risk type: Injuries

Category: Motor vehicles

Brand: Yamaha

Type / number of model: Type-approval number: e13\*168/2013\*00047, Type: SJ14

Type of alert: Products with serious risks

The centre stand may be inadequately welded and could break. As a result, the motorcycle may fall, increasing the risk of an injury. /

Recall of the product from end users

Description: Motorcycle under Yamaha recall code: XP530A.

Batch number / Barcode: XP530A

NO

Country of origin: Japan

Alert submitted by: Germany

Products were found and measures were taken also in: Luxembourg

**Alert number:** A12/00674/20  
**Product:** Light commercial vehicle  
**Name:** Daily  
**Risk type:** Fire  
**Category:** Motor vehicles  
**Brand:** Iveco  
**Type / number of model:** Models: IS35CC2AA, IS35CI2AA, IS35SI2AA, IS56CC2BA, IS35SC2AA, IS52CI2BA, IS35SC2BA, IS52CI2AA, Type-approval numbers: e3\*2007/46\*0116\*07-\*13; e3\*2007/46\*0117\*07-\*11; e3\*2007/46\*0118\*08 -\*13; e3\*2007/46\*0119\*10; e3\*2007/46\*0120\*08 -\*15; e3\*2007/46\*0122\*10-\*12; , e3\*2007/46\*0138\*07+\*09; e3\*2007/46\*0151\*08-\*10  
**Type of alert:** Products with serious risks  
The regeneration of the particulate filter within an elevated temperature range may cause the vehicle to catch fire. /  
Recall of the product from end users  
**Description:**  
**Batch number / Barcode:** 02T, 2TA  
NO  
**Country of origin:** Italy  
**Alert submitted by:** Germany

**Alert number:** A12/00675/20  
**Product:** Motorcycle  
**Name:** YZF-R25, YZF-R3  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Yamaha  
**Type / number of model:** Type-approval number: e13\*168/2013\*00164\* , Type: RH12  
**Type of alert:** Products with serious risks  
The front brake pipe can be damaged by a loose connection to the front wheel fork and by getting into contact with a cable. This can lead to a sudden drop in braking pressure, increasing the braking distance and the risk of an accident. /  
Recall of the product from end users  
**Description:** Motorcycle under Yamaha recall code: YZF-R3/YZF-R25.  
**Batch number / Barcode:** YZF-R3/YZF-R25  
NO  
**Country of origin:** Indonesia  
**Alert submitted by:** Germany  
Products were found and measures were taken also in: Luxembourg

**Alert number:** A12/00676/20  
**Product:** Passenger car  
**Name:** A8  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Audi  
**Type / number of model:** Type-approval number: e1\*2007/46\*1751\* , Type: F8  
**Type of alert:** Products with serious risks  
The suspension forks on the rear axle may be defective. As a result, the tyres may come into contact with the wheelhouse, possibly leading to a loss of control over the vehicle and increased risk of an accident. /  
Recall of the product from end users  
**Description:** Passenger car under Audi recall code: 40P4.  
**Batch number / Barcode:** 40P4  
NO  
**Country of origin:** Germany  
**Alert submitted by:** Germany

**Alert number:** A12/00679/20  
**Product:** All-terrain vehicle  
**Name:** RANGER XP 1000, RANGER Diesel (Intl)  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Polaris  
**Type / number of model:** e8\*167/2013\*00003\*06  
**Type of alert:** Products with serious risks  
A stationary sheave of the drive clutch might be defective. Consequently, after deceleration the engine belt will remain engaged and the vehicle could unexpectedly continue to move, increasing the risk of accident. /  
Recall of the product from end users  
**Description:** All-terrain vehicle.  
**Batch number / Barcode:** R-20-02  
NO  
**Country of origin:** Poland  
**Alert submitted by:** United Kingdom



Alert number: A12/00686/20

Product: Passenger car

Name: Corsa

Risk type: Injuries

Category: Motor vehicles

Brand: Opel

Type / number of model: Type-approval number: e2\*2007/46\*0639\*, Type: U

Type of alert: Products with serious risks

The steering column is not manufactured according to the specifications. This may cause steering failure and lead to loss of control over the vehicle, increasing the risk of an accident. /

Recall of the product from end users

Description:

Batch number / Barcode: 200036-CO

NO

Country of origin: Spain

Alert submitted by: Germany

Alert number: A12/00687/20

Product: Motorcycle

Name: R NINE T, R1250GS, R1250RT, R1250R, R1250RS, K1600GT, K1600B

Risk type: Injuries

Category: Motor vehicles

Brand: BMW

Type / number of model: Type-approval numbers: e1\*168/2013\*00009\*, e1\*168/2013\*00071\*, e1\*168/2013\*00093\*, e1\*168/2013\*00094\*, e1\*168/2013\*00010\*, e1\*168/2013\*00011\*, Types: 1N12, 1G13, 1T13, 1R13, 2T16, 2T16r

Type of alert: Products with serious risks

Due to inappropriate materials' characteristics, components may come into contact with the spokes of the rear wheel. This may lead to loss of control over the vehicle, increasing the risk of an accident. /

Recall of the product from end users

Description:

Batch number / Barcode: 0000334500

NO

Country of origin: Germany

Alert submitted by: Germany

Alert number: A12/00688/20

Product: Passenger car

Name: Tiguan

Risk type: Injuries

Category: Motor vehicles

Brand: VW

Type / number of model: Type-approval number: e1\*2001/116\*0450\*##, Type: 5N

Type of alert: Products with serious risks

The roof-edge spoiler may not be secured enough due to an incorrect adhesive bond. As a result, the spoiler may become detached in motion, posing a risk to the following traffic. /

Recall of the product from end users

Description: Tiguan R-Line vehicles.

Batch number / Barcode: 66L5

UNKNOWN

Country of origin: Germany

Alert submitted by: Germany

Products were found and measures were taken also in: Slovakia

Alert number: A12/00689/20

Product: Passenger car

Name: A4, A5, A6, A7, Q5

Risk type: Fire

Category: Motor vehicles

Brand: Audi

Type / number of model: Type-approval number: e1 \* 2007/46 \* 1550 \*, Type: FY (Audi Q5), Type-approval number: e1 \* 2007/46 \* 1801 \*, Type: F2, (Audi A6, A7), Type-approval number: e1\*2001/116\*0430\*, Type: B8, (Audi A4/A5)

Type of alert: Products with serious risks

Moisture can penetrate into the belt starter generator. This can result in a short circuit, leading to local overheating and increased risk of fire. Due to the permanent power supply of the starter generator, this can occur when the vehicle has already been parked for a while. /

Recall of the product from end users

Description: Passenger cars equipped with 2.0 TFSI - engines and Mild-Hybrid systems.

Batch number / Barcode: 27H2

NO

Country of origin: Germany

Alert submitted by: Germany

Products were found and measures were taken also in: Slovakia

Alert number: A12/00690/20

Product: Passenger car

Name: TT

Risk type: Fire

Category: Motor vehicles

Brand: Audi

Type / number of model: Type-approval number: e1 \* 2001/116 \* 0369 \* .. , Type: 8J

Type of alert: Products with serious risks

A bracket mounted on the car body side can damage the fuel tank in the event of a crash. Consequently, fuel may leak close to a source of ignition, increasing the risk of fire. /

Recall of the product from end users

Description: Vehicles equipped with Quattro drive.

Batch number / Barcode: 20BX

NO

Country of origin: Germany

Alert submitted by: Germany

Products were found and measures were taken also in: Slovakia

Alert number: A12/00691/20

Product: Passenger car

Name: Bentayga

Risk type: Injuries

Category: Motor vehicles

Brand: Bentley

Type / number of model: Type-approval number: e11\*2007/46\*3609\*05, Type: 4V

Type of alert: Products with serious risks

The curtain airbags may be welded incorrectly. As a result, they may not properly inflate in the event of an accident, increasing the risk of injury. /

Recall of the product from end users

Description:

Batch number / Barcode: RE20/04

NO

Country of origin: United Kingdom

Alert submitted by: Germany

Alert number: A12/00692/20

Product: Bus

Name: Citaro, Conecto

Risk type: Injuries

Category: Motor vehicles

Brand: Evobus

Type / number of model: Models: 628 02, 628 03, 628B01, 628B02, Type-approval numbers: e1\*2007/46\*0087, e1\*2007/46\*0090, e1\*2007/46\*0036, e1\*2007/46\*0037

Type of alert: Products with serious risks

Cracks forming on the gas-pressure regulating device cause gas to leak. /

Recall of the product from end users

Description: Bus

Batch number / Barcode: 47.40M20080A

NO

Country of origin: Germany

Alert submitted by: Germany

Alert number: A12/00697/20

Product: All-terrain vehicle

Name: Phoenix 200

Risk type: Injuries

Category: Motor vehicles

Brand: Polaris

Type / number of model: 2018 and 2019 models

Type of alert: Products with serious risks

The stop of the throttle lever might have become damaged during shipping. Consequently, the throttle limiter might not properly work, leading to unexpected behaviour of the vehicle and increasing the risk of accident. /

Recall of the product from end users

Description: All-terrain vehicle.

Batch number / Barcode: A-20-01

NO

Country of origin: Taiwan

Alert submitted by: United Kingdom

Alert number: A12/00677/20

Product: Leather working gloves

Name: Buffalo leather gloves

Risk type: Chemical

Category: Protective equipment

Brand: Laatuhanaka

Type / number of model: art. 1025W

Type of alert: Products with serious risks

The product contains chromium VI (measured value: up to 31,5 mg/kg). Chromium (VI) is sensitising and can trigger allergic reactions and can cause cancer. / The product does not comply with the REACH and PPE Regulations.

Import rejected at border

Description: Working gloves made of white and light grey leather, red piping.

Batch number / Barcode:

NO

Country of origin: Pakistan

Alert submitted by: Finland



Alert number: A12/00696/20

Product: Particle filter mask

Name: Respirator Mask

Risk type: Health risk / other

Category: Protective equipment

Brand: Garry Galaxy

Type / number of model: N95

Type of alert: Products with serious risks

The particle/filter retention of the material is insufficient (measured value  $\leq 71\%$ ). Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures. / The product does not comply with the Personal Protective Equipment Regulation and the relevant European standard EN 149.

Recall of the product from end users

Description: Respiratory protective half-face filter mask of category KN95 (EN 149 FFP2), folded, with nose clip and elastic bands to secure it behind the ears.

Batch number / Barcode: 6972306630042

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Spain



Alert number: A12/00678/20

Product: Set of plastic dolls with accessories

Name: Angel

Risk type: Chemical

Category: Toys

Brand:

Type / number of model: 1247

Type of alert: Products with serious risks

The plastic material of the dolls contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 29.13% by weight) and dibutyl phthalate (DBP)(measured values: up to 20.67 % by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system. / The product does not comply with the REACH Regulation

Withdrawal of the product from the market

Description: Two plastic dolls with accessories.

Batch number / Barcode: 1230025300000

NO

Country of origin: People's Republic of China

Alert submitted by: Cyprus



Alert number: A12/00680/20

Product: Plastic doll with accessories

Name: BABY CUTE

Risk type: Chemical

Category: Toys

Brand: Angels

Type / number of model: 7091A

Type of alert: Products with serious risks

The head of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP)(measured value: 20.77 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. / The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

Description: Baby plastic doll with accessories.

Batch number / Barcode: 8989892723186

NO

Country of origin: People's Republic of China

Alert submitted by: Cyprus



Alert number: A12/00681/20

Product: Set of plastic doll with accessories

Name: Sparkle Girl

Risk type: Chemical

Category: Toys

Brand: My Dream

Type / number of model: 663

Type of alert: Products with serious risks

The plastic material of the dolls contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 29.54% by weight) and dibutyl phthalate (DBP)(measured values: up to 3.31 % by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system. / The product does not comply with the REACH Regulation.

Withdrawal of the product from the market

Description: Two plastic dolls with accessories.

Batch number / Barcode: 1230099888107

NO

Country of origin: People's Republic of China

Alert submitted by: Cyprus



Alert number: A12/00694/20

Product: Soft toy

Name: AT Panenka Rose

Risk type: Choking

Category: Toys

Brand: John Toy

Type / number of model: 27500

Type of alert: Products with serious risks

Small parts (the hook and loop fastener) can detach from the toy. A small child may put them in the mouth and choke on them. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Destruction of the productWithdrawal of the product from the market


Description: A soft body doll with plastic hands and feet and face, hair pulled into two braids. It has a hat with a green bow on its head.

Batch number / Barcode: 8711866275007

UNKNOWN

Country of origin: The Netherlands

Alert submitted by: Czechia



Alert number: A12/00695/20

Product: Toy slime

Name: Slimy Xtreme Glitterz

Risk type: Chemical

Category: Toys

Brand: Orb Slimy

Type / number of model:

Type of alert: Products with serious risks

The migration of boron from the toy slime is too high (measured value: 809 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Recall of the product from end users/Withdrawal of the product from the market


Description: Plastic jar containing toy slime. The slime is clear/gold-coloured containing gold-coloured stars. Yellow lid.

Batch number / Barcode: 622222136055

UNKNOWN

Country of origin: Switzerland

Alert submitted by: Norway



Alert number: A12/00683/20

Product: USB charging set

Name: Three-in-one charging kit

Risk type: Electric shock

Category: Electrical appliances and equipment

Brand: INKAX

Type / number of model: CD 43 type C

Type of alert: Products with serious risks

The electrical insulation is inadequate in the printed circuit and a transformer. The clearance and creepage distances between the primary and accessible secondary circuits are not sufficient. The user could receive an electric shock. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950-1.

Recall of the product from end users, Withdrawal of the product from the market

Description: Set comprising a car charger, a mains charger and a USB cable.

Batch number / Barcode: 6901004414326

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: France





Alert number: A12/00684/20

Product: USB charger

Name:

Risk type: Electric shock

Category: Electrical appliances and equipment

Brand: O mee

Type / number of model: JJH-069

Type of alert: Products with serious risks

The electrical insulation is inadequate in the printed circuit and the transformer. The clearance and creepage distances between the primary and accessible secondary circuits are not sufficient. The user could receive an electric shock. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950-1.

Recall of the product from end users, Withdrawal of the product from the market

Description: USB charger, 2 in 1, including a mains charger and a recharging/synchronisation cable, -2A/10W.

Batch number / Barcode: 3760264360698

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: France



Alert number: A12/00693/20

Product: Mobile phone battery

Name: Mobile Phone Battery

Risk type: Fire

Category: Electrical appliances and equipment

Brand: NX

Type / number of model: GML90252

Type of alert: Products with serious risks

The product is not resistant enough to temperature changes. Consequently, it could catch fire. / The product does not comply with the relevant European standard EN 62133-2.

Recall of the product from end users, Withdrawal of the product from the market



Description: Mobile phone battery, sold as replacement battery. The product is also sold online.

Batch number / Barcode: 3660766429841

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: France



Alert number: INFO/00053/20

Product: Particle filter mask

Name:

Risk type: Health risk / other

Category: Protective equipment

Brand:

Type / number of model: KN95

Type of alert: Products with other risk levels

The product bears a CE marking but is not certified as protective equipment by the relevant body. Consequently, the product might not fulfil the health and safety requirements and properly protect when combined with additional measures. / The product does not comply with the Personal Protective Equipment Regulation.

Ban on the marketing of the product and any accompanying measures

Description: Protective respiratory filtration half-face mask of category KN90 (EN 149) .

Batch number / Barcode: 6 930372 100012

NO

Country of origin: People's Republic of China

Alert submitted by: Denmark





Alert number: INFO/00055/20

Product: Particle filter mask

Name:

Risk type: Health risk / other

Category: Protective equipment

Brand: 3M (counterfeit)

Type / number of model: 9501V

Type of alert: Products with other risk levels

The product bears a CE marking but is not certified as protective equipment by the relevant body. Consequently, the product might not fulfil the health and safety requirements and properly protect when combined with additional measures. / The product does not comply with the Personal Protective Equipment Regulation.

Ban on the marketing of the product and any accompanying measures

Description: Protective respiratory filtration half-face mask of category KN95 (EN149).

Batch number / Barcode:

YES

Country of origin: People's Republic of China

Alert submitted by: Denmark



Alert number: INFO/00056/20

Product: Particle filter mask

Name:

Risk type: Health risk / other

Category: Protective equipment

Brand:

Type / number of model:

Type of alert: Products with other risk levels

The product bears a CE marking but is not certified as protective equipment by the relevant body. Consequently, the product might not fulfil the health and safety requirements and properly protect when combined with additional measures. / The product does not comply with the Personal Protective Equipment Regulation.

Ban on the marketing of the product and any accompanying measures


Description: Protective respiratory filtration half-face mask according to EN 149.

Batch number / Barcode:

NO

Country of origin: Denmark

Alert submitted by: Denmark



Alert number: INFO/00057/20

Product: Particle filter mask

Name: Protective mask

Risk type: Health risk / other

Category: Protective equipment

Brand: Sinpul

Type / number of model: KN95

Type of alert: Products with other risk levels

The product bears a CE marking but is not certified as protective equipment by the relevant body. Consequently, the product might not fulfil the health and safety requirements and properly protect when combined with additional measures. / The product does not comply with the Personal Protective Equipment Regulation.

Stop of sales

Description: Protective respiratory filtration half-face mask of category KN95 (EN 149).

Batch number / Barcode:

NO

Country of origin: People's Republic of China

Alert submitted by: Denmark

