



🏠 [Safety Gate home \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

☰ [Back to report listings \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2020&lng=en\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2020&lng=en)

🔍 [Search alerts \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search&lng=en\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search&lng=en)

👍 [IPSW 2018 \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=ipsw:home\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=ipsw:home)

The Rapid Alert System for Non-Food Products (RAPEX)

RAPEX - Weekly overview report of notifications

Week 33 - 2020

Alert number: A12/01137/20

Product: Hand disinfectant

Name: MissLife Hand Cleanser Gel

Risk type: Health risk / other

Category: Chemical products

Brand: MissLife

Type / number of model: 100ml Hand Cleanser

Type of alert: Products with serious risks

The product contains methanol (measured value: 11.6 %), which is acutely toxic to the central nervous system and to the eyes. Furthermore, the required hazard pictograms and warnings are missing. Users have therefore no information on the toxicity and flammability of the product. The packaging is not fitted with child-resistant fastening. Ingestion or contact with methanol may lead to blindness and death. / The product does not comply with the Biocidal Products and the Classification, Labelling and Packaging (CLP) Regulations.

Destruction of the product

Description: Transparent hand cleanser gel.

Batch number / Barcode: 8681734013256

NO

Country of origin: Turkey

Alert submitted by: Denmark



Alert number: A12/01138/20
Product: Passenger van / Light commercial vehicle
Name: Jumpy, Spacetourer
Risk type: Injuries
Category: Motor vehicles
Brand: Citroen
Type / number of model: Type: V, e2*2007/46*0530*00 to *10, e2*2007/46*0531*00 to *07
Type of alert: Products with serious risks
The rear brake hoses may have been incorrectly attached and can become damaged. This will impair the braking performance, increasing the risk of an accident. /
Recall of the product from end users
Description: Passenger van / Light commercial vehicle
Batch number / Barcode: GYJ
NO
Country of origin: Germany
Alert submitted by: Germany
Products were found and measures were taken also in: Ireland, Poland, Slovakia, Slovenia

Alert number: A12/01139/20
Product: Passenger van / Light commercial vehicle
Name: Expert, Traveller
Risk type: Injuries
Category: Motor vehicles
Brand: Peugeot
Type / number of model: Type-approval number: e2*2007/46*0532*00 to *09, e2*2007/46*0533*00 to *07, e2*2007/46*0533*10 , Type: V
Type of alert: Products with serious risks
The rear brake hoses may have been incorrectly attached and can become damaged. This will impair the braking performance, increasing the risk of an accident. /
Recall of the product from end users
Description: Passenger van / Light commercial vehicle
Batch number / Barcode: JRH
NO
Country of origin: France
Alert submitted by: Germany
Products were found and measures were taken also in: Denmark, Ireland, Poland, Slovakia, Slovenia

Alert number: A12/01140/20
Product: Passenger car
Name: CX-30
Risk type: Injuries
Category: Motor vehicles
Brand: Mazda
Type / number of model: e13*2007/46*2041*04
Type of alert: Products with serious risks
The brake caliper mounting bolts may be loose or missing. This may cause reduced braking performance and caliper interference with wheel rotation, resulting in loss of control over the vehicle and increased risk of an incident. /
Recall of the product from end users
Description: Passenger car
Batch number / Barcode: AL014A
UNKNOWN
Country of origin: Japan
Alert submitted by: Romania
Products were found and measures were taken also in: Poland, Slovenia

Alert number: A12/01141/20

Product: Passenger car

Name: CX-30

Risk type: Fire, Injuries

Category: Motor vehicles

Brand: Mazda

Type / number of model: e13*2007/46*2041*04

Type of alert: Products with serious risks

Due to an improper manufacturing process of the fuel tank, when fully refueling the vehicle, liquid fuel will eventually fill the charcoal canister resulting in a leak. A leak from the canister in the presence of an ignition source may increase the risk of fire. Additionally, the engine may stall while driving, increasing the risk of an accident. /

Recall of the product from end users

Description: Passenger car equipped with all-wheel drive.

Batch number / Barcode: AL015A

UNKNOWN

Country of origin: Japan

Alert submitted by: Romania

Products were found and measures were taken also in: Poland, Slovenia

Alert number: A12/01143/20

Product: Lorry

Name: F-Max

Risk type: Injuries

Category: Motor vehicles

Brand: Ford Trucks

Type / number of model: Model: CHK1, Type-approval number: e9*2007/46*0089*15-*16

Type of alert: Products with serious risks

The seat-back adjustment mechanism and potentially a seat locking bolt have been poorly fitted. This could lead to increased risk of injury in the event of an accident. /

Recall of the product from end users

Description: Lorry

Batch number / Barcode: FSA 201915A / FSA 201915B

NO

Country of origin: Turkey

Alert submitted by: Germany

Products were found and measures were taken also in: Slovenia

Alert number: A12/01145/20

Product: Passenger car

Name: A-Class, GLA

Risk type: Injuries

Category: Motor vehicles

Brand: Mercedes-Benz

Type / number of model: Type-approval number: e1*2001/116*0470*25, e1*2007/46*1829*08, Type: 245 G, F2A

Type of alert: Products with serious risks

The screws on the rear axle might not be tightened properly, which could lead to overloading of other screw connections. This can result in loss of wheel control and consequently to loss of control over the vehicle, increasing the risk of an accident. /

Recall of the product from end users

Description: Model series BR 156,177.

Batch number / Barcode: 3590006

NO

Country of origin: Germany

Alert submitted by: Germany

Products were found and measures were taken also in: Greece

Alert number: A12/01146/20

Product: Passenger car

Name: B-Class

Risk type: Injuries

Category: Motor vehicles

Brand: Mercedes-Benz

Type / number of model: Type-approval number: e1*2007/46*1909*00, Type: F2B

Type of alert: Products with serious risks

The welded joints fixing the frame of the front seats may not comply with the specifications. As a result they could fail in the event of a crash, causing the seat and its occupant to move more than expected, leading to increased risk of injuries. /

Recall of the product from end users

Description: Model series BR 247.

Batch number / Barcode: 9190013

NO

Country of origin: Germany

Alert submitted by: Germany

Alert number: A12/01147/20

Product: Passenger car

Name: EX, FX

Risk type: Injuries

Category: Motor vehicles

Brand: Infiniti

Type / number of model: Type-approval number: e1*2001/116*0477 , Type: J50

Type of alert: Products with serious risks

Wear on the upper steering column bearing could lead to increased friction during steering. Continued use of the damaged steering column could lead to full loss of steering power, increasing the risk of an accident. /

Recall of the product from end users

Description: Passenger car

Batch number / Barcode: R1501

NO

Country of origin: Japan

Alert submitted by: Germany

Alert number: A12/01148/20

Product: Passenger car

Name: Forester

Risk type: Injuries

Category: Motor vehicles

Brand: Subaru

Type / number of model: E13*2007/46*1305*04, E13*2007/46*1305*01, E13*2007/46*1305*05, E13*2007/46*1305*06, E13*2007/46*1305*07

Type of alert: Products with serious risks

An electrical connection that is part of the occupant detection system may become loose or unstable. As a result, the system will not be able to detect if the seat is occupied, and therefore may deactivate the airbag. /

Recall of the product from end users

Description: Passenger car

Batch number / Barcode: SRT280

NO

Country of origin: Japan

Alert submitted by: Poland

Products were found and measures were taken also in: Ireland, Slovakia

Alert number: A12/01149/20

Product: Passenger car

Name: Kuga

Risk type: Injuries

Category: Motor vehicles

Brand: Ford

Type / number of model: e13*2007/46*2188*02

Type of alert: Products with serious risks

The Fuel Operated Heater (FOH), could switch itself on when not programmed to do so by the driver. If this happens in a closed space, such as a garage, it could result in personal injury or death. /

Recall of the product from end users

Description: Vehicles, equipped with a Fuel Operated Heater (FOH).

Batch number / Barcode: 20S27

NO

Country of origin: Spain

Alert submitted by: United Kingdom

Alert number: A12/01150/20

Product: Passenger car

Name: Kuga PHEV

Risk type: Fire

Category: Motor vehicles

Brand: Ford

Type / number of model: e13*2007/46*2188*02

Type of alert: Products with serious risks

Internal or charging fault could cause the High Voltage (HV) battery pack to vent hot gas. As such gases have not been routed away from other components, they will cause them to exceed their designed working temperatures. Overheating of components such as the fuel tank and fuel lines will increase the risk of the vehicle catching fire. /

Recall of the product from end users

Description: Kuga Plug-In Hybrid Electric Vehicle (PHEV), fitted with a High Voltage (HV) battery pack.

Batch number / Barcode: 20S38

NO

Country of origin: Spain

Alert submitted by: United Kingdom

Products were found and measures were taken also in: Germany, Poland, Slovenia

Alert number: A12/01142/20

Product: Toy gun set

Name: SHOOT GUN

Risk type: Choking, Injuries

Category: Toys

Brand:

Type / number of model: NO.6699, 509102139/1PC

Type of alert: Products with serious risks

The suction cup of the projectile can easily detach. If a child puts the projectile in the mouth in order to wet it before shooting, the suction cup can detach leaving the airways obstructed by it. The bottom edge of the solid yellow plastic part of the toy gun is uneven and with sharpness and can cause injuries. / The product does not comply with the Toys Safety Directive and with the relevant European standard EN 71-1

Recall of the product from end users


Description: Plastic shooting toy gun set with two types of projectiles.

Batch number / Barcode: 4772013031536

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Latvia



Alert number: A12/01134/20

Product: Children's jacket

Name: JJSHALE NOOS

Risk type: Strangulation

Category: Clothing, textiles and fashion items

Brand: Jack & Jones Junior

Type / number of model: 12165551 - Size 128

Type of alert: Products with serious risks

There are drawstrings in the hood. They may become trapped during various activities of the child, leading to strangulation. / The product does not comply with the relevant European standard EN 14682.

Recall of the product from end users

Company recall page: <https://about.bestseller.com/sustainability/product-safety/product-recalls>

(<https://about.bestseller.com/sustainability/product-safety/product-recalls>)

Description: Mid-season jacket for children with drawstrings in hood. The product was sold online.

Batch number / Barcode:

NO

Country of origin: Myanmar

Alert submitted by: Denmark



12165551
JJESHALE JACKET



12165551
JJESHALE JACKET

Alert number: A12/01135/20

Product: Children's jacket

Name: JORFLEX JACKET JR

Risk type: Strangulation

Category: Clothing, textiles and fashion items

Brand: Jack & Jones Junior

Type / number of model: 12168224 - SIZE 128

Type of alert: Products with serious risks

There are drawstrings in the hood. They may become trapped during various activities of the child, leading to strangulation. / The product does not comply with the relevant European standard EN 14682.

Recall of the product from end users

Company recall page: <https://about.bestseller.com/sustainability/product-safety/product-recalls>

(<https://about.bestseller.com/sustainability/product-safety/product-recalls>)

Description: Mid-season jacket for children with drawstrings in hood. The product was sold online.

Batch number / Barcode:

NO

Country of origin: Myanmar

Alert submitted by: Denmark



12168224
JORFLEX JACKET



12168224
JORFLEX JACKET

Alert number: A12/01133/20
 Product: USB charger
 Name: USB Wall charger
 Risk type: Burns, Electric shock, Fire
 Category: Electrical appliances and equipment
 Brand:

Type / number of model: 144585, 4585_MKTO
 Type of alert: Products with serious risks

The electrical insulation is inadequate and the clearance/creepage distances between the primary and accessible secondary circuits are not sufficient, and the user could receive an electric shock. The product's enclosure is flammable, which can cause a fire. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950-1.

Recall of the product from end users

Description: Yellow-coloured USB charger 1000 mA

Batch number / Barcode:

NO

Country of origin: People's Republic of China

Alert submitted by: Denmark



Alert number: A12/01136/20
 Product: Power supply adaptor
 Name: AC/DC Adaptor
 Risk type: Electric shock
 Category: Electrical appliances and equipment
 Brand:

Type / number of model: JCY-1210 (12-PLM-1A-20-P)

Type of alert: Products with serious risks

The electrical insulation and the creepage/clearance distances are inadequate. The user may receive an electric shock from live parts. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950-1.

Recall of the product from end users

Description: Black power supply adapter.

Batch number / Barcode:

NO

Country of origin: People's Republic of China

Alert submitted by: Finland



Alert number: A12/01151/20

Product: Table lamp

Name: Bear

Risk type: Electric shock

Category: Electrical appliances and equipment

Brand: Markslojd

Type / number of model: Nr 105792

Type of alert: Products with serious risks

The product is child-appealing and is not supplied with a Safe Extra-Low Voltage (SELV) transformer. In case the lamp breaks, live parts can become accessible. A child could touch them and get an electric shock. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Withdrawal of the product from the market


Description: Bear-shaped table lamp, powered through the mains.

Batch number / Barcode: EAN 7330024549364

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Poland



Wydawca: Unipolmagazyni, Kasa Lubomirski, Markslojd AB	SV Tabela lampy: Kraj pochodzenia: Chiny Dystrybutor: Markslojd AB	EH Třech Leuchtöhren Herkunft: China Lieferant: Markslojd AB	DE
Lampa stolowa, kraj pochodzenia: Chiny, Dystrybutor: Markslojd AB, ul. Rakowiecka 24, 83-070 Igielna k. Poznania, Poland, Tel: +48 61 84 99 014, info@unipolmagazyni.com, unipolmagazyni.com	PL		

Alert number: A12/01152/20

Product: Table lamp

Name: Helge

Risk type: Electric shock

Category: Electrical appliances and equipment

Brand: Markslojd

Type / number of model: art. Nr 105311, typ Nr 105310

Type of alert: Products with serious risks

The product is child-appealing and is not supplied with a Safe Extra-Low Voltage (SELV) transformer. In case the lamp breaks, live parts can become accessible. A child could touch them and get an electric shock. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Withdrawal of the product from the market



Description: Owl-shaped table lamp, mains powered

Batch number / Barcode: EAN 7330024541474

UNKNOWN

Country of origin: People's Republic of China

Alert submitted by: Poland



Alert number: INFO/00117/20
 Product: Medical face mask
 Name: Medical Sterile Mask
 Risk type: Health risk / other
 Category: Protective equipment
 Brand:

Type / number of model:

Type of alert: Products with other risk levels

The product claims to meet the requirements of a surgical mask but it has not been certified as such by the relevant European body. Consequently, the product might not fulfil the health and safety requirements and thus not properly protect if not combined with additional measures. / The product does not comply with the requirements of the Medical Devices Directive and of the relevant European standard EN 14683.

Import rejected at border

Description: Medical face mask

Batch number / Barcode: EAN 6954295425540

NO

Country of origin: People's Republic of China

Alert submitted by: Poland



Alert number: A11/00070/20

Product: Baby pushchair

Name: Thule Sleek stroller

Risk type: Injuries

Category: Childcare articles and children's equipment

Brand: Thule

Type / number of model: 110000017/20/3 -1733

Type of alert: Products with other risk levels

Two screws are missing from the handlebar. The handlebar may easily detach and the pushchair may tip over. A child may consequently suffer injuries. / The product does not comply with the relevant European standard EN 1888.

Recall of the product from end users

Description: A black stroller designed to carry children.

Batch number / Barcode:

NO

Country of origin: Poland

Alert submitted by: Romania

Products were found and measures were taken also in: Austria, Croatia, Denmark, Poland

