

Alert number **[A12/01310/21](#)**

Product **Novelty Lighter**



Risk type **Burns
Fire**

The lighter is appealing to children and can easily be mistaken for a toy. Children may play with it and suffer burns or cause a fire. No lighter should be appealing to children.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 13869.

Category **Lighters**

Type **Consumer**

Description **Novelty lighter in the shape of a gun.**

Brand **AK**

Barcode **6600656000023**

Weekly report number **Report-2021-37**

Alert submitted by **Cyprus**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Retailer**

Date of entry into force **26/05/2021**



Alert number **[A12/01298/21](#)**

Product **Plush toy**



Risk type **Choking**

Small parts (the zipper handle) can easily detach from the toy. A small child may put them in the mouth and choke on them.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Pink colored plush animal in the shape of a lion. The product is also sold online.**

Brand **Funnies**

Name **Knuffel leeuw**

Weekly report number **Report-2021-37**

Alert submitted by **The Netherlands**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Recall of the product from end users
Other**

Date of entry into force **11/05/2021**

Alert number

[A12/01308/21](#)

Product

Space expedition toy set



Risk type

Injuries

The battery compartment of the torch of the set can be easily opened, leaving batteries accessible. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways, or could cause damages to the gastrointestinal tract.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 62115.

Category

Toys

Type

Consumer

Description

Space expedition toy set for kids. The product was also sold online.

Packaging description

Cardboard box.

Brand

Science4You

Name

Space Expedition Kit

Type / number of model

918922

Batch number

1013299001

Weekly report number

Report-2021-37

Alert submitted by

Ireland

Is the product counterfeit?

No

Country of origin

Portugal

Measures taken by economic operators

**Recall of the product from end users
Manufacturer**

Alert number

[A12/01311/21](#)

Product

Playground swing for two children



Risk type

Cuts

The product has protruding edges which are not protected. This can cause serious cuts on any part of the body which they come into contact with.

The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 1176.

Category

Hobby/sports equipment

Type

Consumer

Description

Steel swing for outdoor playgrounds. Two children (aged 6 and over) stand opposite each other and swing by exerting a force on the product through their weight.

Brand

Conradi Kaiser

Name

Seesaw sinio asto / Stainless steel

512519401

Type / number of model

Weekly report number **Report-2021-37**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Temporary ban on the supply, offer to supply and display of the product**
Other



Alert number

[A12/01305/21](#)


Product

Charcoal barbecue

Caractéristiques du produit

Couleurs	Noir
Références	603601
Dimensions (cm)	H 36 x larg. 42 x P 29 cm
Composant	Métal, bois
Produit en	Chine
Usage	 

[Afficher plus](#)



Risk type

**Burns
Fire**

The horizontal surface on which the barbecue is placed becomes too hot reaching a temperature of 102 degrees above the ambient temperature (the limit is 50 degrees). As a consequence, the user could suffer burns and the product could cause fire. Furthermore, labelling, warnings, pictograms and instructions are missing or do not respect the requirements.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 1860-1.

Category

Other

Type

Consumer

Description

Charcoal barbecue, dimensions H36 x L42 x D29 cm. The product is also sold online.

Brand

CASA

Name

Smokey BBQ

Batch number

111484.01

Weekly report number

Report-2021-37

Alert submitted by

France

Is the product counterfeit?

Unknown

Country of origin

Taiwan

Measures taken by economic operators

**Warning consumers of the risks
Distributor**

Measures taken by economic operators

**Withdrawal of the product from the market
Distributor**

Alert number **[A12/01302/21](#)**

Product **Motorcycle**

Risk type **Injuries**

The cam-follower shaft may be screwed incorrectly after the cylinder head has been replaced. As a result, oil may leak onto the rear tyre, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Motorcycle**

Brand **BMW**

Name **S 1000 RR**

EC-type approval/model **e1*168/2013*00091, Type: 2R99**

Production dates **12 February 2020 - 7 May 2020**

Company recall code **00 00 11 27 00**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Greece
Ireland
Poland
Slovenia**

Alert number **[A12/01309/21](#)**

Product **Sunscreen**



Risk type **Burns**

The actual protection factor of the suntan is lower than declared (measured value: 4.3) and lower than the required minimum protection level. Consequently, the user might be under-protected against UV radiation increasing the risk of sunburns or skin cancer.

The product does not comply with the Cosmetic Products Regulation.

Category **Cosmetics**

Type **Professional**

Description **Sunscreen lotion. The product was also sold online.**

Packaging description **Multi-coloured printed cardboard box. The product comes in a white opaque plastic tube. The product was also sold online.**

Brand **SolarTea**

Name **Sonnencreme SolarTea Bio SPF 30 100ml**

Batch number **6273**

Barcode **8010047194534**

Weekly report number **Report-2021-37**

Alert submitted by **Austria**

Is the product counterfeit?

No

Country of origin

Italy

Measures taken by economic operators

**Stop of sales
Retailer**

Products were found and measures were taken also in

Lithuania

Alert number **[A12/01301/21](#)**

Product **Lorry**

Risk type **Fire**

Mechanical stress associated with a weakness in the AHI (after-treatment hydrocarbon injection) pipe interconnector at the AHI injector. The stress may be attributed to strain caused by engine vibrations associated with low pipe strength. Engine vibrations may cause damage and a consequent increased risk of fire.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Professional**

Description **Lorry**

Brand **Volvo Trucks**

Name **FH16**

EC-type approval/model **Models: 2423C, 2433C, 2443C, 24A3C, 24B3C, 24G3C, 24J3C, 24K3C, 24L3C, 24Q3C, 24R3C, 24S3C, 24T3C, 24V3C VT23R VT43R, VTA3T, VTG3T, VTJ3R, VTJ3T, VTL3R, VTL3T, VTR3R, VTS3R, VTS3T, VTT3R ,VTV3R, VTY3R e11*2007/46*0271 e11*2007/46*3086 e11*2007/46*0272 e11*2007/46*3087 e5*2007/46*1014 e11*2007/46*0273 e11*2007/46*3261 e5*2007/46*1016 e11*2007/46*0274 e11*2007/46*3262 e11*2007/46*0278 e1*2007/46*1444 e11*2007/46*0279 e1*2007/46*1443 e11*2007/46*0282 e1*2007/46*1445 e1*2007/46*1413 e11*2007/46*3265 e5*2007/46*1020 e11*2007/46*0281 e11*2007/46*3445 e5*2007/46*1022 e11*2007/46*0283 e11*2007/46*3266 e5*2007/46*1021 e11*2007/46*0284 e11*2007/46*3088 e5*2007/46*1015 e5*2007/46*1017 e11*2007/46*0275 e11*2007/46*3263 e5*2007/46*1018 e11*2007/46*0276 e11*2007/46*3446 e5*2007/46*1023 e11*2007/46*0280 e11*2007/46*3264 e5*2007/46*1019 e11*2007/46*0899**

Production dates **01/2014 to May 2019**

Company recall code	C0172
Weekly report number	Report-2021-37
Alert submitted by	Germany
Is the product counterfeit?	No
Country of origin	Sweden
Measures taken by economic operators	Recall of the product from end users Manufacturer
Products were found and measures were taken also in	Sweden Slovenia

Alert number **[A12/01303/21](#)**

Product **Motorcycle**

Risk type **Burns
Injuries**

The fuel line may be defective. This could lead to a fuel leakage, increasing the risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Motorcycle**

Brand **Suzuki**

Name **Burgman 125, Burgman 200**

EC-type approval/model **e4*168/2013*00038, e4*168/2013*00039; Types: WC80, WC90**

Production dates **02.04.2018 - 05.06.2020**

Company recall code **97FW**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **France
Greece**

Alert number **[A12/01318/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 20,3% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Plastic doll.**

Packaging description **Cardboard box.**

Brand **HIT-CHIN**

Name **Beauty Girl**

Type / number of model **6869D**

Barcode **EAN 5907616608642**

Weekly report number **Report-2021-37**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators

**Destruction of the product
Importer**

Date of entry into force

28/07/2021

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force

28/07/2021

Alert number **[A12/01292/21](#)**

Product **Wristwatch**



Risk type **Chemical**

The product releases an excessive amount of nickel (measured value up to: 1.81 µg/cm²/week). Nickel is a strong sensitiser and causes allergic reactions if present in articles that come into direct and prolonged contact with the skin.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Men's wristwatch made of steel with steel links bracelet.**

Packaging description **The product is sold on a cardboard, packaged in a plastic blister with printed cardboard frame.**

Brand **Infinity accessoires**

Name **Herrenuhr**

Batch number **234441/00+01+02**

Barcode **2 000006 995612**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit?

Unknown

Country of origin

People's Republic of China

Measures taken by economic operators

**Warning consumers of the risks
Distributor**

Measures taken by economic operators

**Destruction of the product
Distributor**

Measures taken by economic operators

**Stop of sales
Distributor**

Measures taken by economic operators

**Recall of the product from end users
Distributor**

Alert number **[A12/01320/21](#)**

Product **Passenger car**

Risk type **Fire**

The connections to the injection valve's fuel-return line may not be fully secured and could become loose, which may cause the fuel-return-line to detach from the fuel-injection nozzle. As a result, fuel may leak and come in to contact with hot surfaces, increasing the risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Ford**

Name **Transit**

EC-type approval/model **e1*2007/46*1097*16, e1*2007/46*1096*19; Types: FFD, FED**

Production dates **8 June 2021 - 28 June 2021**

Company recall code **21S30**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Turkey**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **France
Slovenia**

Alert number **[A12/01307/21](#)**

Product **Toy telephone**



Risk type **Damage to hearing**

The sound level produced by the toy is too high (measured value: 86,1 dB), which could lead to permanent or partial hearing loss.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Plastic toy telephone, battery powered.**

Packaging description **Plastic blister with cardboard back.**

Brand **Pegaz Toys**

Name **Baby telephone**

Type / number of model **N0. CY1013-7C**

Barcode **EAN 5902385964791**

Weekly report number **Report-2021-37**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force


29/07/2021

Alert number

A12/01306/21

Product

Self-balancing scooter (hoverboard)



Risk type

**Burns
Fire
Injuries**

The battery does not have a device that monitors the cells temperature, hence it may overheat during charging, and the hoverboard cover may ignite. The product may cause a fire and the user may suffer burns. In addition, the power cords, which are exposed to movement between the two motors, are routed through a steel pipe with sharp edges at both ends. During the life of the product, the insulation of the power cords can be damaged by the sharp edges, the battery may short-circuit and explode during use. As a result, the user might lose control and fall off the scooter and suffer injuries.

The product does not comply with the requirements of the relevant European standards EN 60335 and EN 62133.

Category

Hobby/sports equipment

Type

Consumer

Description

Red self-balancing scooter for use as a personal transport

device for persons with lithium ion battery (36V, 2 Ah), and LED lighting and battery charger: HLT-118A-4200400E. The product was also sold online.

Packaging description	Brown and colourful cardboard box.
Brand	2Drive
Name	2Drive LED Series Balance Scooter
Type / number of model	2D-LED-R and SMART S (on the packaging label)
Barcode	82200823003033 / 5 999565 595050
Weekly report number	Report-2021-37
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	17/08/2021
Measures ordered by public authorities	Recall of the product from end users Distributor
Date of entry into force	17/08/2021

Alert number **[A12/01304/21](#)**

Product **Trailer**

Risk type **Injuries**

The tyres may be defective due to a manufacturing error. This could lead to a loss in tyre pressure or a burst tyre, potentially resulting in loss of control over the trailer.

Category **Motor vehicles**

Type **Consumer**

Description **Trailer**

Brand **Böckmann**

Name **-**

EC-type approval/model **Types: AB1C, AT1, ATP, KOM, AB3C, CH3
e1*2007/46*0083*06 , e1*2007/46*0088*05 ,
e1*2007/46*0104*05 , e1*2007/46*0176*04 ,
e1*2007/46*0786*05 , e1*2007/46*1872*00**

Production dates **15.03.2021 - 23.07.2021**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/01291/21](#)**

Product **Soft toy**



Risk type **Choking**

**A small part (plastic bow) may easily detach from the toy .
A small child may put it in the mouth and choke.**

**The product does not comply with the requirements of the
Toy Safety Directive and with the relevant European
standard EN 71-1.**

Category **Toys**

Type **Consumer**

Description **Squeezable orange bear with LED and a yellow bow. It has
printed black eyes and nose. It is approximately 8 cm in
size. The product is also sold online.**

Brand **Unknown**

Name **Knautschbär mit LED**

Type / number of model **Quetschspielzeug, Knautschspielzeug**

Barcode **4058411009392**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **Unknown**

Country of origin	Germany
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	31/08/2021
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Other
Date of entry into force	13/08/2021
Measures taken by economic operators	Ban on the marketing of the product and any accompanying measures Manufacturer
Date of entry into force	31/08/2021

Alert number **[A12/01300/21](#)**

Product **Bus/coach**

Risk type **Injuries**

The load-bearing structure of the roof superstructures may be too weak. This could lead to parts of the vehicle ending up on the road.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of Motor Vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Professional**

Description **Bus/coach**

Brand **Evobus**

Name **eCitaro, eCitaro G**

EC-type approval/model **e1*2007/46*1985*05, e1*2007/46*2083*02, Typ: 628 10, 628 11**

Production dates **13/03/2019 to 16/06/2021**

Company recall code **65.10M21165A**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Sweden**

Alert number **[A12/01321/21](#)**

Product **Passenger car**

Risk type **Fire**

Due to defective fixing, the electrical connection between the 48V or 12V wiring harness and the support point may be sporadically interrupted. This could result in electrical arcing, leading to increased risk of fire. Furthermore, if the electrical connection were completely interrupted, the vehicle could not be started.

Category **Motor vehicles**

Type **Consumer**

Description **Model series: BR 223.**

Brand **MERCEDES-BENZ**

Name **S-Class**

EC-type approval/model **Type: RS2
e1*2007/46*2115*00 -02**

Production dates **24.08.2020 - 24.02.2021**

Company recall code **1591014**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code - **<http://www.mercedes-benz>**

France

Products were found and
measures were taken also in

Poland



Alert number **[A12/01322/21](#)**

Product **Passenger car**

Risk type **Injuries**

The luggage net may be incorrectly affixed. As a result, luggage could end up in the passenger compartment, causing injury to the occupants.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **VW**

Name **Arteon, Golf, ID.4**

EC-type approval/model **Types: CDV, 3H, E2
e1*2007/46*2180, e1*2007/46*1725, e1*2018/858*00004**

Production dates **06/11/2019 - 06/05/2021**

Company recall code **68H5**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **France
Greece
Croatia
Sweden
Slovenia
Slovakia**

Alert number **[A12/01293/21](#)**

Product **Motorcycle**

Risk type **Injuries**

An insufficient amount of bearing grease might have been applied to the needle-bearings in the rear hub housing (roller bearings), during the manufacturing process. Consequently, the bearings might become damaged, leading to the blockage of the rear wheel while the vehicle is in motion, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Motorcycle**

Brand **KAWASAKI**

Name **Ninja H2 SX, Ninja SX SE, Ninja SX SE+**

EC-type approval/model **Type: ZXT02A
e4*168/2013*00073*00, 02**

Production dates **The affected vehicles were manufactured from 2018 to 2020.**

Company recall code **DAK52**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **France
Greece
Ireland**

**Poland
Sweden
Slovenia**



Alert number **[A12/01294/21](#)**

Product **Passenger car**

Risk type **Injuries**

The wiring harness of the driver's door might be defective. Consequently, the wiring of the airbag sensor might malfunction, impairing the functioning of the lateral and head airbags, increasing the risk of injuries in the event of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Toyota**

Name **Venza**

EC-type approval/model **Individual approval**

Production dates **The affected vehicles were manufactured from 05.11.2009 to 17.04.2015.**

Company recall code **21SMD-033**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Sweden**

Alert number **[A12/01299/21](#)**

Product **Earrings**



Risk type **Chemical**

The product contains an excessive amount of lead (measured value: 0.089% by weight). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may affect breast-fed or unborn children.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Hoop-shaped silver earrings set with a diameter of 8 mm, composed of a ball and a fantasy coil.**

Packaging description **The set is sold on a cardboard, packaged in a wooden box with various motifs and was also sold online.**

Brand **San Saru**

Type / number of model **Aalok 8 mm**

Weekly report number **Report-2021-37**

Alert submitted by **Spain**

Is the product counterfeit? **Unknown**

Country of origin **Thailand**

Measures ordered by public authorities

Ban on the marketing of the product and any accompanying measures
Importer



Alert number **[A12/01295/21](#)**

Product **Jockstrap**

Risk type **Chemical**

The leather in the product contains chromium VI (measured values up to: 13.9 mg/kg). Chromium (VI) is sensitising, can trigger allergic reactions and can cause cancer.

The product does not comply with the REACH Regulation.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Jockstrap made of black leather with black elastics on the sides.**

Packaging description **The product was also sold online.**

Brand **Rouge**

Name **Jock Straps**

Type / number of model **RJS1032BK**

Barcode **5 060404 810433**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United Kingdom**

Measures taken by economic operators **Recall of the product from end users
Distributor**

Measures taken by economic operators **Withdrawal of the product from the market
Distributor**

Company recall code - **<https://brunos.de/Produkttrueckruf/>**

Alert number

[A12/01296/21](#)

Product

Particle filter mask



Risk type

Health risk / other

The particle/filter retention of the material is insufficient (measured values: as low as 73%). Consequently, the product does not fulfil the health and safety requirements; thus, even if combined with other recommended measures, it may not properly protect.

The product does not comply with the Personal Protective Equipment Regulation and with the relevant European standard EN 149.

Category

Protective equipment

Type

Consumer

Description

Protective respiratory filtration half-face mask, of uniform white material and without valve. The mask had light whit straps that fit around the ears.


Packaging description

The product is sold in white/blue cardboard boxes, containing a total of 20 masks, reference: article LK-Z1510, EN 149:2001+A1:2009, FFP2 NR, CE 2163.

Brand	XIQUE
Name	Filtering half mask
Type / number of model	LK-Z1510
Batch number	Manufacturing date: 25/6/2020
Barcode	6971044297999
Weekly report number	Report-2021-37
Alert submitted by	Slovenia
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Withdrawal of the product from the market Importer
Date of entry into force	13/05/2021

Alert number **[A12/01290/21](#)**

Product **Ball game**



Risk type **Chemical**

The plastic material of the bolis contain bisphenol A (measured value up to 0,281 mg/l). Bisphenol A is toxic for reproduction.

The product does not comply with the requirements of the Toy Safety Directive.

Category **Toys**

Type **Consumer**

Description **Ball game for babies with 6 different coloured balls.**

Packaging description **Cardboard box.**

Brand **Happy World**

Name **Baby play balls**

Type / number of model **22269**

Batch number **20-398**

Barcode **8711866222698**

Weekly report number **Report-2021-37**

Alert submitted by **Belgium**

Is the product counterfeit? **No**

Country of origin **Unknown**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **26/08/2021**

Alert number **[A12/01297/21](#)**

Product **Night light**



Risk type **Burns
 Electric shock
 Fire**

The lamp is attractive to children. The dimensions of the flat plug are less than required. As a result, live parts are accessible and this could lead to an electric shock. The plastic part of the plug which holds the conductive parts in position is combustible. The lamp can catch fire during use causing burns to the user.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Category **Lighting equipment**

Type **Consumer**

Description **Owl-shaped, yellow, LED night light with switch. The product can be plugged directly into the socket.**

Packaging description **Transparent plastic blister with paper back.**

Brand	LE ROYAL
Name	Led Night Light
Type / number of model	R22614-5 / 243
Barcode	9 582261 400054
Weekly report number	Report-2021-37
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	30/08/2021
Measures ordered by public authorities	Recall of the product from end users Distributor
Date of entry into force	30/08/2021

Alert number **[A12/01313/21](#)**

Product **Passenger car**

Risk type **Injuries**

The IBS (Integrated Brake System) module may be defective. This may cause a failure of the ABS (anti-lock braking system), increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **FIAT**

Name **500e**

EC-type approval/model **e3*2018/858*00001*02, Type FA1**

Production dates **09.11.2020 - 03.12.2020**

Company recall code **6333**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/01312/21](#)**

Product **Passenger car**

Risk type **Injuries**

The IBS (integrated brake system) module may be defective. This may cause a failure of the ABS (anti-lock braking system), increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **ALFA ROMEO**

Name **Giulia, Stelvio**

EC-type approval/model **e3*2007/46*0382*15, e3*2007/46*0435*18; Types: 952, 949**

Production dates **16.01.2019 - 15.02.2021**

Company recall code **6334**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/01319/21](#)**

Product **Passenger car**

Risk type **Injuries**

Due to defective materials, the axle shafts could break. This could lead to driving power being lost without warning, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **FIAT**

Name **500**

EC-type approval/model **e3*2007/46*0064*56, Type: 312**

Production dates **09.09.2020 - 30.06.2021**

Company recall code **6343**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Croatia
Poland
Romania
Sweden
Slovenia**

Alert number **[A12/01317/21](#)**

Product **Mobile home / camper van**

Risk type **Fire**

The ground connection may be fitted incorrectly. This may result in a short circuit, increasing the risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Mobile home / camper van**

Brand **Dethleffs**

Name **Just**

EC-type approval/model **e1*2001/116*0416*31, Type: EG/DF 003**

Production dates **2020 - 2021**

Company recall code **54555**

Weekly report number **Report-2021-37**

Alert submitted by **Germany**

Is the product counterfeit? **No**


Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code - **<https://www.dethleffs.de>**

Alert number **[A12/01314/21](#)**

Product **Electric water heater**



Risk type **Electric shock**

The product is not correctly earthed, therefore accessible parts may become live. When touching them, users may receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and with the European standards EN 60335-1 and EN 60335-2-35.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Instant electric water heating, rated voltage 220 V, rated frequency 50 Hz, rated power 3000 W, type of operation - uninterruptible, power supply connection - non-disconnectable power cord, installation - fixed.**

Packaging description **Cardboard box.**

Brand **Unknown**

Name **Instant electric water heating faucet**

Type / number of model **Pro 1, ART. MS1976**

Barcode ***1804001***

Weekly report number **Report-2021-37**

Alert submitted by **Lithuania**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Importer**

Date of entry into force **09/09/2021**

Alert number **[A12/01315/21](#)**

Product **Whistle toy**



Risk type **Choking**

The toy is too small. A child can put it in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Plastic coloured whistle toy with a cord attached.**

Packaging description **Collective plastic packaging.**

Brand **Unknown**

Name **Brelok**

Type / number of model **TG 364911**

Barcode **5902280877684**

Weekly report number **Report-2021-37**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force

27/08/2021

Alert number **[A12/01316/21](#)**

Product **Toy putty**



Risk type **Chemical**

The migration of boron from the toy is too high: 323,71 mg/kg. Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-3.

Category **Toys**

Type **Consumer**

Description **Toy putty in a plastic imitation of an ice cream.**

Packaging description **Foil packaging.**

Brand **Unknown**

Name **Ice Cream Putty**

Barcode **7300009650279**

Weekly report number **Report-2021-37**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators

**Withdrawal of the product from the market
Distributor**

Date of entry into force

24/08/2021