
Alert number **[A12/01336/21](#)**

Product **Passenger car**

Risk type **Fire
Injuries**

The clutch pressure plate may be defective. This could lead to the loss of power transmission and to increased risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Jeep**

Name **Wrangler**

EC-type approval/model **Individual approval**

Production dates **30/08/2017 - 17/08/2020**

Company recall code **Y07**

Weekly report number **Report-2021-38**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**


Alert number	<u>A12/01333/21</u>
Product	Novelty Lighter



Risk type	Burns Fire
	The lighter is appealing to children and can easily be mistaken for a toy. Children may play with it and suffer burns or cause a fire. No lighter should be appealing to children.
	The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 13869.
Category	Lighters
Type	Consumer
Description	Novelty lighter in the shape of a toilet.
Brand	BD
Weekly report number	Report-2021-38
Alert submitted by	Cyprus
Is the product counterfeit?	Unknown
Country of origin	Unknown
Measures ordered by public authorities	Withdrawal of the product from the market Retailer
Date of entry into force	26/05/2021

Alert number **[A12/01334/21](#)**

Product **Novelty Lighter**



Risk type **Burns
Fire**

The lighter is appealing to children and can easily be mistaken for a toy. Children may play with it and suffer burns or cause a fire. No lighter should be appealing to children.

The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 13869.

Category **Lighters**

Type **Consumer**

Description **Novelty lighter in the shape of a grenade.**

Brand **ZHONG LONG**

Name **FUZE M217 ME175B 008-803**

Type / number of model **803**

Barcode **6600080170125**

Weekly report number **Report-2021-38**

Alert submitted by **Cyprus**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

26/05/2021

Alert number **[A12/01324/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 47,5% by weight). This phthalates may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Set of two plastic dolls of 28cm and 10cm tall with accessories.**

Packaging description **Cardboard box with transparent window.**

Brand **Unknown**

Name **HAPPY PARTNER! FASHION Beauty Girl**

Type / number of model **NO. 1805
Q889-30; Q889T2H168K**

Barcode **8591920008891**

Weekly report number **Report-2021-38**

Alert submitted by **Czechia**

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

16/08/2021

Alert number **[A12/01327/21](#)**

Product **Toy Slime**



Risk type **Chemical**

The migration of boron from the toy slime is too high (measured value up to 3708,38 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

Category **Toys**

Type **Consumer**

Description **Toy slime in bomb-shaped container.**

Packaging description **Cardboard box.**

Brand **Unknown**

Name **Ancient Bomb Slime**

Type / number of model	Item N0: C63603
Barcode	EAN 5906245224209
Weekly report number	Report-2021-38
Alert submitted by	Poland
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Withdrawal of the product from the market Importer
Date of entry into force	24/06/2021

Alert number **[A11/00076/21](#)**

Product **Soft toy**



Risk type **Choking**

Due to the weakness of certain seams, the fibrous stuffing material of the toy is easily accessible. A child may put the stuffing in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **A frog-shaped soft toy, plastic ring with plastic toy keys attached.**

Packaging description **Cardboard label.**

Brand **BABY TOYS**

Name **Funny Toy**

Type / number of model **NO. 00-43668**

Barcode **EAN 5906160243668**

Weekly report number **Report-2021-38**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market
Importer**

Date of entry into force **08/07/2021**

Alert number **[A12/01343/21](#)**

Product **Passenger car**

Risk type **Injuries**

When the manually adjustable front seats are moved as far forward as possible, for example, when moving the front seats forward rapidly to allow access to the second row seats, the front seat slide end supports may become deformed over time. As a result, the seats could be positioned too far and the driver may not be able to touch the pedals, increasing the risk of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **LAND ROVER**

Name **Defender**

EC-type approval/model **e5*2007/46*0092, e5*2007/46*0125**

Production dates **4 December 2020 - 9 April 2021**

Company recall code **N609**

Weekly report number **Report-2021-38**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **United Kingdom**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **16/08/2021**

Company recall code - <https://topix.jaguar.jlrext.com>

Products were found and
measures were taken also in
Croatia
Poland
Sweden

Alert number **[A12/01344/21](#)**

Product **Baby pushchair**



Risk type **Injuries**

The pushchair is not stable enough and the seat restraint system might break . A child may consequently suffer injuries.

The product does not comply with the General Product Safety Directive and the European standard EN 1888-1.

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Baby stroller, size: 102x45x72**

Packaging description **Cardboard box. The product sold online.**

Brand **Kikka boo**

Name **Baby pushchair**

Type / number of model **model CLOE, art.No. 31001030108, 31001030109, 31001030110, 3100103111**

Barcode **Баркод 3801001031102**

Weekly report number **Report-2021-38**

Alert submitted by **Bulgaria**

Is the product counterfeit? **No**


Country of origin **People's Republic of China**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures
Importer**

Date of entry into force **02/08/2021**

Alert number **[A11/00077/21](#)**

Product **USB charger**



Risk type **Electric shock**

The insulation of the product is inadequate. The user could receive an electric shock from accessible live parts.

The product does not comply with the requirements of the Low Voltage Directive and the European standard EN 62368.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **White battery charger with 2 USB port and 1 lightning port.**

Packaging description **Packaging: blister and cardboard box.**

Brand **hoco.**

Name **CHARGER 2USB**

Type / number of model **C59A**

Barcode	6 931474 707949
Weekly report number	Report-2021-38
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	04/06/2021
Products were found and measures were taken also in	Lithuania

Alert number **[A11/00078/21](#)**

Product **USB charger**



Risk type	Electric shock
	The insulation of the product is inadequate. The user could receive an electric shock from accessible (live) parts.
	The product does not comply with the requirements of the Low Voltage Directive and the European standard EN 62368.
Category	Electrical appliances and equipment
Type	Consumer
Description	White battery charger with 2 USB ports.
Packaging description	Cardboard box with transparent plastic window.
Brand	OnePlus
Name	USB Wall Charger
Type / number of model	A6199 / Art: 2002141

Barcode	8 944870 161992
Weekly report number	Report-2021-38
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	03/08/2021

Alert number **[A12/01335/21](#)**

Product **Passenger car**

Risk type **Injuries**

Due to manufacturing defect, the support wire grid between the inner and outer layers of the fuel injector rubber return pipe may not provide sufficient support, which may cause the pipe to bend and break over time. As a result, fuel could leak into the cold side of the motor compartment and onto the road surface, posing a risk to the following traffic.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Land Rover**

Name **Discovery Sport, Range Rover Evoque, Range Rover Velar**

EC-type approval/model **e5*2007/46*1058, e5*2007/46*0076, e5*2007/46*1057**

Production dates **8.01.2020 - 5.05.2021**

Company recall code **N590**

Weekly report number **Report-2021-38**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **United Kingdom**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force

25/06/2021

Products were found and
measures were taken also in

**Ireland
Poland
Slovenia**

Alert number **[A12/01348/21](#)**

Product **Passenger car**

Risk type **Injuries**

The starter battery ground stud in the boot area may provide insufficient contact. This may cause various electrical faults, such as the vehicle not starting, stalling while in motion, losing all electrical power and the exterior lights going out without warning to the driver, increasing the risk of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **LAND ROVER**

Name **Discovery**

EC-type approval/model **e5*2007/46*1054**

Production dates **6.11.2019 - 12.03.2021**

Company recall code **N607**

Weekly report number **Report-2021-38**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Slovakia**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force

01/07/2021

Products were found and
measures were taken also in

**Croatia
Ireland
Poland
Sweden
Slovenia**

Alert number **[A12/01349/21](#)**

Product **Passenger car**

Risk type **Injuries**

Due to manufacturing defect, the support wire grid between the inner and outer layers of the fuel injector rubber return pipe may not provide sufficient support, which may cause the pipe to bend and break over time. As a result, fuel could leak into the cold side of the motor compartment and onto the road surface, posing a risk to the following traffic.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Jaguar**

Name **E-PACE, F-PACE, XE, XF**

EC-type approval/model **e5*2007/46*1050, e5*2007/46*1047, e5*2007/46*1049, e5*2007/46*1048**

Production dates **27.11.2019 - 28.04.2021**

Company recall code **H359**

Weekly report number **Report-2021-38**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **United Kingdom**

Measures taken by economic **Recall of the product from end users**

operators

Manufacturer

Date of entry into force

25/06/2021

Products were found and
measures were taken also in

**Croatia
Ireland
Poland
Sweden**

Alert number **[A12/01330/21](#)**

Product **Extension cord**



Risk type	<p>Burns Electric shock Fire</p> <p>The cable inside the mains power cord is too thin. When the cable extension kit is used with class I devices, the user might suffer burns or an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>
Category	Electrical appliances and equipment
Type	Consumer
Description	Orange, single-socket mains extension lead with 30 m cable.
Packaging description	Transparent plastic bag with label.
Brand	ICON
Name	LENGŐHOSSZABITÓ

Type / number of model	EP10001-30
Barcode	1 000131 003009
Weekly report number	Report-2021-38
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Import rejected at border Importer
Date of entry into force	06/08/2021

Alert number **[A12/01329/21](#)**

Product **Laser pointer**




Risk type	<p>Damage to sight</p> <p>The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.</p> <p>The product does not comply with the relevant European standard EN 60825.</p>
Category	Laser pointers
Type	Consumer
Description	Pen-shaped black and silver laser pointer with the inscription LASER POINTER on the clip, powered by 2 x AAA batteries. Size: length: 16.7 cm, diameter 1.4 cm
Packaging description	Bubble wrap.
Brand	Unknown
Name	LASER POINTER

Weekly report number	Report-2021-38
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Import rejected at border Importer
Date of entry into force	31/08/2021

Alert number **[A12/01325/21](#)**

Product **WET WIPES**



Risk type **Chemical
Health risk / other**

The product contains a mixture of the preservatives methylchloroisothiazolinone (MCI) and methylisothiazolinone (MI). Measured values: MCI 0,00007% and MI 0,00004%, which are forbidden in leave-on cosmetics. Dermal contact with MCI and MI containing products can provoke allergic contact dermatitis to sensitised persons.

The product does not comply with the Cosmetic Products Regulation.

Category **Cosmetics**

Type **Consumer**

Description **Wet wipes for delicate and normal skin.**

Packaging description **Plastic packaging of 100 wipes.**

Brand **OTPIMAL**

Name **Wet Wipes Chamomile**

Batch number **Lot 009 Manufacturing Date 9/1/2021, Expiry Date 9/1/2024
(3Months after opening)**

Barcode **5304000204396**

Weekly report number **Report-2021-38**

Alert submitted by	Cyprus
Is the product counterfeit?	No
Country of origin	Albania
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	13/07/2021

Alert number

[A12/01326/21](#)

Product

WET WIPES



Risk type

**Chemical
Health risk / other**

The product contains a mixture of the preservatives methylchloroisothiazolinone (MCI) and methylisothiazolinone (MI) (measured values: MCI 0,0001% and MI 0,00004%), which are forbidden in leave-on cosmetics. Dermal contact with MCI and MI containing products can provoke allergic contact dermatitis to sensitised persons.

The product does not comply with the Cosmetic Products Regulation.

Category

Cosmetics

Type

Consumer

Description

Wet wipes for delicate and normal skin.

Packaging description

Plastic package of 100 wipes.

Brand

Optimal

Name

Wet Wipes Aloe Vera

Batch number

Lot 042 Manufacturing Date 11/02/2021, Expiry Date 11/02/2024 (3 Months after opening)

Barcode

5304000204372

Weekly report number

Report-2021-38

Alert submitted by	Cyprus
Is the product counterfeit?	No
Country of origin	Albania
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	13/07/2021

Alert number

A12/01323/21

Product

WET WIPES



Risk type

**Chemical
Health risk / other**

The product contains a mixture of the preservatives methylchloroisothiazolinone (MCI) and methylisothiazolinone (MI). Measured values: MCI 0,0009% and MI 0,0005 %, which are forbidden in leave-on cosmetics. Dermal contact with MCI and MI containing products can provoke allergic contact dermatitis to sensitised persons.

The product does not comply with the Cosmetic Products Regulation.

Category

Cosmetics

Type

Consumer

Description

Wet wipes for delicate and normal skin.

Packaging description

Plastic packaging of 100 wipes.

Brand

Optimal

Name

Wet Wipes Lavender

Batch number

Lot 330 Manufacturing Date 25/11/2020, Expiry Date 25/11/2023 (3 Months after opening)

Barcode

5304000204389

Weekly report number

Report-2021-38

Alert submitted by	Cyprus
Is the product counterfeit?	No
Country of origin	Albania
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	13/07/2021

Alert number **[INFO/00152/21](#)**

Product **Passenger car**

Risk type **Injuries**

The reversing camera software may not display an image during reversing, although this has been activated in the settings. This could increase the risk of injury to bystanders.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Dodge**

Name **Charger**

EC-type approval/model **Individual approval**

Production dates **07.05.2018 - 29.08.2020**

Company recall code **W62**

Weekly report number **Report-2021-38**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/01347/21](#)**

Product **Passenger car**

Risk type **Injuries**

The fuel tank may not be leak-proof. As a result, fuel could escape and leak onto the road, posing a risk to the following traffic.

Category **Motor vehicles**

Type **Consumer**

Description **Model series: BR 223**

Brand **Mercedes-Benz**

Name **S-Class**

EC-type approval/model **e1*2007/46*2115*02-03, Type: RS2**

Production dates **08.02.2021 - 24.03.2021**

Company recall code **4790014**

Weekly report number **Report-2021-38**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code - **<https://www.Mercedes-Benz.de>**

Alert number **[A12/01338/21](#)**

Product **Rocket**



Risk type **Damage to sight**

The product may explode at too low altitude and can burst too close to the ground. Bystanders can be hit by parts of the firework and damage the eyes.

The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

Category **Pyrotechnic articles**

Type **Consumer**

Description **Rocket with stik**

Packaging description **Black box with two red dragons pictured on it.**

Brand **Fyrværkerieksperten A/S**

Name **Bomberaket**

Type / number of model **0163-F2-5226
07336.6005**

Batch number **20-15163**

Weekly report number **Report-2021-38**

Alert submitted by **Denmark**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures
Manufacturer**



Date of entry into force **02/07/2021**

Alert number

[A11/00071/21](#)

Product

Battery toy piano



Risk type

**Chemical
Environment**

The solders in the toy contain lead (measured value up to 0.28% by weight) and cadmium (measured value up to 0.0016% by weight) in concentrations above limit values. Lead and cadmium pose a risk to the environment.

The product does not comply with the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category

Toys

Type

Consumer

Description

Battery-operated toy consisted of a blue piano with the head of a lion, which, when the keys are pressed, makes sounds.

Packaging description

Label affixed to the product bearing identification information.

Brand

GAZELOtoys

Name

Piánko lev modrý na baterie

Type / number of model

G116909-855-35A-5874

Barcode

5900949403519

Weekly report number

Report-2021-38

Alert submitted by	Czechia
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Retailer
Date of entry into force	28/08/2021

Alert number **[A11/00073/21](#)**

Product **Audio sensor**



Risk type **Environment**

The metal (solders) in the product contains an excessive amount of lead (measured value up to: 53% by weight). Lead poses a risk to the environment.

The product does not comply with the requirements of Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category **Electrical appliances and equipment**

Type **Consumer**

Description **The product is labelled with the following information: VTV, Zvonek, Country of origin - P.R.C, Importer for the Czech Republic, Unsuitable for children under 3 years, Zadd: VTV s.r.o. Libušská 319, Prague 4, EAN 6930323540805.**

Packaging description **Cardboard box bearing instructions for use and for inserting batteries.**

Brand **Intelligent**

Name **Zvukové čidlo Intelligent**

Type / number of model **101**

Batch number **Model 101**

Barcode **6930323540805**

Weekly report number	Report-2021-38
Alert submitted by	Czechia
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	28/08/2021

Alert number

[A11/00075/21](#)

Product

Battery-operated toy piano



Risk type

Environment

The solders of the toy contain an excessive amount of lead (measured value: 8% by weight). Lead is harmful to human health, accumulates in the body and can cause developmental neurotoxicity.

The product does not comply with the requirements of the Directive 2011/65/EU on the restriction of hazardous substances (RoHS) and the relevant European standard EN 62321-5.

Category

Toys

Type

Consumer

Description

Battery-operated toy piano.

Packaging description

The product was distributed in cardboard packaging.

Brand

JIN BO

Name

Piánko na baterie JIN BO

Type / number of model

49506119

Barcode

28811495061190

Weekly report number

Report-2021-38

Alert submitted by

Czechia

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Distributor**


Date of entry into force **28/08/2021**

Alert number

A12/01328/21

Product

Portable LED lamp



Risk type

**Burns
Electric shock
Fire**

The cables inside the mains power cord are too thin and could overheat during use. The plastic part of the luminaire's integrated plug is made of combustible material. The mains plug and output connector's pins' insulation and size are inappropriate and the USB port's insulation is inadequate, leaving live parts accessible. Live parts could also become accessible without the use of any tools. User may consequently suffer burns, receive an electric shock or the product may cause a fire.

The product does not comply with the requirements of the Low Voltage Directive and the European Standards EN 60598 and EN 60335.

Category

Lighting equipment

Type

Consumer


Description

Rechargeable and portable camping LED lamp with USB port, which can be operated directly from the mains,

	batteries or by the solar module. It is supplied with a charger cable.
Packaging description	The product is packaged in a colourful cardboard box.
Brand	YX (on the box); LE ROYAL (on the label)
Name	RECHARGEABLE CAMPING LANTERN
Type / number of model	YX-5655COB (on the box); R2614-22 (on the label)
Barcode	9 580261 400227
Weekly report number	Report-2021-38
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Recall of the product from end users Distributor
Date of entry into force	30/08/2021
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	30/08/2021

Alert number **[A12/01342/21](#)**

Product **Fireworks**



Risk type **Damage to sight**

The product may explode at too low altitude and can burst too close to the ground. Bystanders can be hit by parts of the firework, causing injuries or damage to the eye region. The sound pressure level is too high and may cause damage to hearing.

The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

Category **Pyrotechnic articles**

Type **Consumer**

Description **Rocket with stick.**

Packaging description **Rocket with stick. Black colour background with purple stripes.**

Brand **Fyrværkerieksperten**

Name **Dark Spirit - Night Ball 2**

Type / number of model **07022.0736
CE registration number: 0163-F2-5226**

Batch number **20-11012**

Weekly report number **Report-2021-38**

Alert submitted by	Denmark
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Other : The article must not be sold on the Danish market Manufacturer
Date of entry into force	02/07/2021

Alert number **[A12/01341/21](#)**

Product **Fireworks**



Risk type **Damage to hearing
Damage to sight
Injuries**

The product may explode at too low altitude and can burst too close to the ground. Bystanders can be hit by parts of the firework, causing injuries or damage to the eye region. The sound pressure level is too high and may cause damage to hearing.

The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

Category **Pyrotechnic articles**

Type **Consumer**

Description **Rocket with stick.**

Packaging description **Rocket with stick. Blue background with "FireArt" written with flames.**

Brand **Fyrværkerieksperten**

Name **FireArt - Wildfire 1**

Type / number of model **07036.6185
CE registration number: 0163-F2-5226**

Batch number **20-15085**

Weekly report number **Report-2021-38**

Alert submitted by	Denmark
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Manufacturer
Date of entry into force	02/07/2021

Alert number **[A12/01340/21](#)**

Product **Fireworks**



Risk type **Damage to hearing
Damage to sight
Injuries**

The product may explode at too low altitude and can burst too close to the ground. Bystanders can be hit by parts of the firework, causing injuries or damage to the eye region. The sound pressure level is too high and may cause damage to hearing.

The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

Category **Pyrotechnic articles**

Type **Consumer**

Description **Rocket**

Packaging description **Rocket with stick. Dark Background with coloured effects.**

Brand **Fyrværkerieksperten A/S**

Name **Dark Spirit - Golden Sky 10**

Type / number of model **07022.1079
CE registration number: 0163-F2-5226**

Batch number **20-11024**

Weekly report number **Report-2021-38**

Alert submitted by	Denmark
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Manufacturer
Date of entry into force	02/07/2021

Alert number **[A12/01339/21](#)**

Product **Fireworks**



Risk type **Damage to hearing
Damage to sight
Injuries**

The product may explode at too low altitude and can burst too close to the ground. Bystanders can be hit by parts of the firework, causing injuries or damage to the eye region. The sound pressure level is too high and may cause damage to hearing.

The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

Category **Pyrotechnic articles**

Type **Consumer**

Description **Rocket**

Packaging description **Rocket with stick. Black colour with two red dragons.**

Brand **Fyrværkerieksperten A/S**

Name **Bomberaket**

Type / number of model **07336.6006
CE registration number: 0163-F2-5226**

Batch number **20-15164**

Weekly report number **Report-2021-38**

Alert submitted by	Denmark
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Manufacturer
Date of entry into force	02/07/2021

Alert number **[A11/00074/21](#)**

Product **Soother holder**



Risk type **Choking**

In case of impact, the wooden shield of the product may easily break generating small parts. A small child may put them in the mouth and choke.

The product does not comply with the requirements of the General Product Safety Directive and with the European standard EN 12586.

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Wood with metal clip for making a soother holder.**

Packaging description **Plastic bag.**

Brand **Wibra**

Name **Clip voor speenkoord**

Type / number of model **2667.0042**

Batch number **6309096**

Weekly report number **Report-2021-38**

Alert submitted by **The Netherlands**

Is the product counterfeit? **No**

Country of origin	The Netherlands
Measures ordered by public authorities	Withdrawal of the product from the market Other
Date of entry into force	02/08/2021
Measures ordered by public authorities	Warning consumers of the risks Other
Date of entry into force	02/08/2021
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Other
Date of entry into force	02/08/2021

Alert number **[A12/01337/21](#)**

Product **Firework**



Risk type **Fire**

The flames caused by the operation of the battery do not extinguish. The battery and flammable material nearby may consequently catch fire.

The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

Category **Pyrotechnic articles**

Type **Consumer**

Description **Set of 25 shot of firework batteries.**

Packaging description **Black and purple colours with firework images. Big box is written in silver and "9" in black on a orange background.**

Brand **Fyrværkerieksperten A/S**

Name **Big Box 9**

Type / number of model **CE registration number: 0163-F2-5214**

Batch number **20-26027**

Weekly report number **Report-2021-38**

Alert submitted by **Denmark**

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Recall of the product from end users
Manufacturer**

Date of entry into force

12/04/2021

Alert number **[A11/00072/21](#)**

Product **Extension cord**



Risk type **Burns
Electric shock**

The cable inside the mains power cord is too thin. When the cable extension kit is used with class I devices, the user might suffer burns or an electric shock.

The product does not comply with the requirements of the Low Voltage Directive.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Orange, single-socket mains extension lead with 10 m cable.**

Packaging description **Transparent plastic bag with label.**

Brand **ICON**

Name **LENGÖHOSSZABITÓ**

Type / number of model **EP10001-10**

Barcode **1 000131 001005**

Weekly report number **Report-2021-38**

Alert submitted by **Hungary**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Import rejected at border
Importer**

Date of entry into force

06/08/2021

Alert number **[A12/01351/21](#)**

Product **Soft toy**



Risk type **Choking**

Due to the weakness of certain seams on the head of the toy, small parts (the mane of the pony) are easily detachable. A child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Soft toy little pony**

Packaging description **No packaging, label attached to the toy.**

Brand **Hasbro**

Name **Hasbro - my little pony**

Type / number of model **HSHB9819**

Batch number **CO106/B9819Asst**

Barcode **010993388707**

Weekly report number **Report-2021-38**

Alert submitted by **Croatia**

Is the product counterfeit? **Unknown**

Country of origin **The Commonwealth of Dominica**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures
Distributor**

Date of entry into force **22/07/2021**

Alert number **[A12/01331/21](#)**

Product **Plastic hooks**



Risk type **Chemical**

The product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP), (measured value up to 34%). This phthalate may harm the health by causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Other**

Type **Consumer**

Description **Transparent plastic hooks with suction cup. Dimensions: 12x18 cm, cc 45 g.**

Packaging description **4 products per pack, fixed on cardboard with plastic foil.**

Brand **Unknown**

Name **GANCHO DE VENTOSA**

Type / number of model **089502**

Barcode **8686860089502**

Weekly report number **Report-2021-38**

Alert submitted by **Hungary**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures
Distributor**

Date of entry into force **26/08/2021**

Alert number

A12/01332/21

Product

Lighting chain



Risk type

**Burns
Electric shock
Fire**

The cross-sectional area of the external and internal wires is too thin and they can overheat, leading to burns or fire. In the event of damage of the base-insulated wires, the active parts may become accessible, which may cause an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Category

Lighting chains

Type

Consumer

Description

Icicle-shaped lighting chain with 140 non-replaceable, white LED lamps. The product includes a socket outlet that allows the connection of another lighting chain.

Packaging description

Transparent plastic box.

Brand	Unknown
Name	5M LED MERRY CHRISTMAS
Type / number of model	XM-140-R-I-LN
Barcode	6 902104 579021
Weekly report number	Report-2021-38
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Import rejected at border Importer
Date of entry into force	11/08/2021

Alert number **[A12/01350/21](#)**

Product **Motorcycle**

Risk type **Injuries**

In the ABS (Antilock Braking System) modulator, excessive grease was applied to the O-ring of the reservoir piston due to improper management of the equipment for applying grease to components. During continued use in this condition, foreign matter adheres to the grease that has moved to the out valve, and it may become pinched in the check valve during braking, causing input pressure leak, and increasing the braking distance.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of two- or three-wheel vehicles and quadricycles.

Category **Motor vehicles**

Type **Consumer**

Description **Model Code: CBR500RA (PC62), CB500FA (PC63), CB500XA (PC64); Model year: 2019.**

Packaging description **VIN's: CBR500RA (from MLHPC62A4K5002707 to MLHPC62A3K5003704), CB500FA (from MLHPC63A4K5006643 to MLHPC63A4K5009235), CB500XA (from MLHPC64A4K5006012 to MLHPC64A7K5012158).**

Brand **Honda**

Name **CB500FA/XA & CBR500RA**

EC-type approval/model **CBR500RA - e13*168/2013*00507*00, CB500FA - e13*168/2013*00508*00, CB500XA - e13*168/2013*00523*00**

Production dates **CBR500RA - 26.08.19 - 20.12.19, CB500FA - 31.07.19 - 15.12.19, CB500XA - 20.06.19 -17.01.20**

Company recall code **3M5**

Weekly report number **Report-2021-38**

Alert submitted by **Portugal**

Is the product counterfeit?

No

Country of origin

Thailand

Measures taken by economic operators

**Recall of the product from end users
Importer**

Products were found and measures were taken also in

**Estonia
Greece
Ireland
Poland
Romania
Sweden
Slovenia
Slovakia**

Alert number **[A12/01345/21](#)**

Product **Lighting chain**



Risk type **Burns
Electric shock
Fire**

The cross-sectional area of the external and internal wires is too thin and they can overheat, leading to burns or fire. In the event of damage of the base-insulated wires, the active parts may become accessible, which may cause an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the European standard EN 60598.

Category **Lighting chains**

Type **Consumer**

Description **Icicle-shaped lighting chain with 180 non-replaceable, blue LED lamps. The product includes a socket outlet that allows the connection of another lighting chain.**

Packaging description **Transparent plastic box.**

Brand **Unknown**

Name **6.6M LED MERRY CHRISTMAS**

Type / number of model **XM-180-R-I-LN**

Barcode **6 902104 579014**

Weekly report number **Report-2021-38**

Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Import rejected at border Importer
Date of entry into force	11/08/2021

Alert number **[A12/01346/21](#)**

Product **Plastic toy**



Risk type **Chemical
Choking**

The battery compartment can be easily opened, leaving the button cell batteries accessible. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways, or could cause damages to the gastrointestinal tract.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115.

Category **Toys**

Type **Consumer**

Description **Plastic toy truck, battery powered (button cell batteries).**

Packaging description **Cardboard box with plastic window.**

Brand **GAZELO toys**

Name **Oil Tanker**

Type / number of model **G122761-WY783A/B-6339 (on attached label)
WY783B (on packaging)**

Barcode **5900949409580**

Weekly report number **Report-2021-38**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market
Importer**

Date of entry into force **07/09/2021**