

Alert number

**A11/00084/21**

Product

**Cosmetics**



Risk type

**Health risk / other**

**This product was not manufactured according to the required good manufacturing practices and lacks the adequate evaluations before entry on the market. Furthermore, these products were lacking the adequate production and product information. Consequently, safe use cannot be guaranteed.**

**The product does not comply with the Cosmetic Products Regulation.**

Category

**Cosmetics**

Type

**Consumer**

Description

**Various cosmetic products from the brand Mamita Botanical, to be used for different purposes: Aceite revitalizante de cuerpo y pelo; Crema Super Linda; Contorno de ojos reparador; Exfoliante facial; Serum Super Linda; Tónico Elixir; Limpiador Alisante y Reafirmante; Limpiador Nutritivo y Calmante.**

Packaging description	<b>The products are packaged in coloured bottles and in small silver-coloured tubes. The bottles may have a normal cap, a squeeze-cap, or a drop-distributor cap.</b>
Brand	<b>Mamita Botanical</b>
Name	<b>Mamita Botanical (varios productos)</b>
Type / number of model	<b>Aceite revitalizante de cuerpo y pelo Contorno de ojos reparador Crema Super Linda Exfoliante facial Limpiador Alisante y Reafirmante Limpiador Nutritivo y Calmante Serum Super Linda Tónico Elixir</b>
Batch number	<b>All</b>
Weekly report number	<b>Report-2021-40</b>
Alert submitted by	<b>Spain</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>Spain</b>
Measures taken by economic operators	<b>Ban on the marketing of the product and any accompanying measures Manufacturer</b>
Date of entry into force	<b>16/04/2021</b>
Measures taken by economic operators	<b>Withdrawal of the product from the market Manufacturer</b>
Date of entry into force	<b>16/04/2021</b>

Alert number **[A12/01409/21](#)**

Product **Necklace**



Risk type **Chemical**

**The product releases an excessive quantity of nickel (measured values: up to 86 µg/cm<sup>2</sup>/week) and contains an excessive amount of lead (measured value: up to 65% by weight). Nickel is a strong sensitiser and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin. Lead is harmful to human health, accumulates in the body, and may also affect breast-fed or unborn children. The product also contains an excessive amount of cadmium (measured value up to 0,013% by weight). Cadmium is harmful to human health because it accumulates in the body, can damage the kidneys and bones, and it may cause cancer.**

**The product does not comply with the REACH Regulation.**

Category **Jewellery**

Type **Consumer**

Description **Pink pendant necklace consisting of a chain, a ring and a heart set with crystals.**

Packaging description **Black jewellery box marked with “VanCrystals”. There is a guarantee certificate in the box with the pendant necklace. Product sold online.**

Brand **Vancrystals**

Name **Arais Rosado necklace with Swarovski crystals**

Barcode **8435441802135**

Weekly report number **Report-2021-40**

Alert submitted by **Spain**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures  
Distributor**

Measures taken by economic operators **Removal of this product listing by the online marketplace  
Retailer**

Alert number **[A11/00083/21](#)**

Product **Extension cord**



Risk type **Burns  
Electric shock  
Fire**

**The cable inside the mains power cord is too thin. When the cable extension kit is used with class I devices, the user might suffer burns or an electric shock.**

**The product does not comply with the requirements of the Low Voltage Directive.**

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Orange, single-socket mains extension lead with 20 m cable.**

Packaging description **Transparent plastic bag with label.**

Brand **ICON**

Name **LENGŐHOSSZABITÓ**

Type / number of model	<b>EP10001-20</b>
Barcode	<b>1 000131 002002</b>
Weekly report number	<b>Report-2021-40</b>
Alert submitted by	<b>Hungary</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>People's Republic of China</b>
Measures ordered by public authorities	<b>Import rejected at border Importer</b>
Date of entry into force	<b>06/08/2021</b>

Alert number **[A12/01395/21](#)**

Product **Folding stool**



Risk type **Injuries**

**The stool has no locking device and the user can consequently suffer injuries with the clamping points.**

**The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12520.**

Category **Furniture**

Type **Consumer**

Description **Folding stool with metal leg frame and plastic seat. Seat is made of plastic, hollow, external dimensions - 330x295x28 mm.**

Brand **Unknown**

Name **Folding stool**

Type / number of model **HM-D33**

Barcode **0000011493600**

Weekly report number **Report-2021-40**

Alert submitted by **Lithuania**

Is the product counterfeit? **No**

Country of origin

**People's Republic of China**

Measures ordered by public  
authorities

**Withdrawal of the product from the market  
Importer**

Date of entry into force

**08/09/2021**



Alert number

**[A12/01391/21](#)**

Product

**Crystal Creations Hair Accessories**



Risk type

**Damage to sight**

**Due to inadequate warning on the packaging and inadequate instructions on how to use the glue applicator, glue might come in contact with the user's eye, causing eye injuries.**

**The product does not comply with the CLP Regulation nor with the requirements of the Toy Safety Directive.**

Category

**Clothing, textiles and fashion items**

Type

**Consumer**

Description

**Hair accessories set.**

Packaging description

**Cardboard box.**

Brand

**Crystal Creations**

Name

**Crystal Creations Hair Accessories**

Type / number of model

**Style N0 6272653**

Weekly report number

**Report-2021-40**

Alert submitted by

**Ireland**

Is the product counterfeit?


**No**

Country of origin

**People's Republic of China**

Measures taken by economic operators

**Recall of the product from end users  
Distributor**



Alert number **[A12/01403/21](#)**

Product **Passenger car**

Risk type **Fire**

**A short circuit in the hydraulic electronic control unit (HECU) housing may occur. This could cause a fire in the engine compartment.**

**The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Model code: DH**

Brand **HYUNDAI**

Name **Geness**

EC-type approval/model **e4\*KS07/46\*0018\*, e4\*2007/46\*1030\***

Production dates **09.06.2013 - 09.03.2020**

Company recall code **11D054**

Weekly report number **Report-2021-40**

Alert submitted by **France**

Is the product counterfeit? **Unknown**

Country of origin **Republic of Korea**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Date of entry into force **15/07/2021**

Products were found and  
measures were taken also in

**Ireland**  
**Poland**




Alert number

**[A11/00085/21](#)**

Product

**Soft toy**



Risk type

**Choking**

**Due to the weakness of certain seams, the fibrous stuffing material of the toy is easily accessible. A child may put it in the mouth and choke.**

**The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.**

Category

**Toys**

Type

**Consumer**

Description

**Soft-filled toy in the shape of an animal, in a pink colour.**

Packaging description

**No packaging, label attached to the toy.**

Brand

**Unknown**

Name

**PINK FONG - Soft toy**

Type / number of model

**PFPT-04001-01**

Barcode

**8809456151623**

Weekly report number

**Report-2021-40**

Alert submitted by

**Croatia**

Is the product counterfeit?

**Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures  
Distributor**

Date of entry into force **17/08/2021**

---

Alert number **[A12/01402/21](#)**

Product **Passenger car**

---

Risk type **Fire**

**Adverse tolerances combined with external force may cause the lower section of the maintenance bonnet to come into contact with the fuel inlet connector on the fuel delivery unit flange. As a result, damage to the fuel inlet connector may occur and lead to fuel leakage, increasing the risk of fire.**

**The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **PORSCHE**

Name **Macan (S. GTS. Turbo)**

EC-type approval/model **e13\*2007/46\*1165\*02 - e13\*2007/46\*1165\*08**

Production dates **7.11.2013 - 27.3.2018**

Company recall code **ALA2**

Weekly report number **Report-2021-40**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Date of entry into force **28/03/2020**

Products were found and  
measures were taken also in **Greece  
Sweden**



---

Alert number **[A12/01393/21](#)**

Product **Vehicle component - seat**

---

Risk type **Injuries**

**The seat support brace may be defective and could fail. This will lead to increased risk of injury in the event of an accident**

Category **Motor vehicles**

Type **Consumer**

Description **Vehicle component**

Brand **Braun-Ability**

Name **Turny Evo Bis**

Production dates **1.8.2020 - 1.3.2021**

Weekly report number **Report-2021-40**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Sweden**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Alert number **[A12/01399/21](#)**

Product **Bracelets**



Risk type **Chemical**

**The product contains an excessive amount of cadmium (82.5% by weight). Cadmium is harmful to health. It accumulates in the body and can damage the kidneys and bones and may be carcinogenic.**

**The product does not comply with the REACH Regulation.**

Category **Jewellery**

Type **Consumer**

Description **Three bracelets with various silver or gold-coloured metal pendants.**

Packaging description **Cardboard jewellery box with labelling**

Brand **TEDi**

Name **Armband 3 Stück**

Type / number of model **35969001751000000150  
39646001751000000150**

Batch number **121  
DNP 263**

Weekly report number **Report-2021-40**

Alert submitted by **Germany**

Is the product counterfeit?	<b>Unknown</b>
Country of origin	<b>People's Republic of China</b>
Measures ordered by public authorities	<b>Recall of the product from end users Importer</b>
Date of entry into force	<b>03/09/2021</b>
Measures ordered by public authorities	<b>Stop of sales Importer</b>
Date of entry into force	<b>03/09/2021</b>
Products were found and measures were taken also in	<b>Poland</b>

Alert number **[A11/00086/21](#)**

Product **Soft toy**



Risk type **Choking**

**The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the stuffing material in the mouth and choke.**

**The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.**

Category **Toys**

Type **Consumer**

Description **Yellow and orange plush duck, height: 25 cm.**

Brand **Unknown**

Name **Plush duck**

Type / number of model **MRT-180**

Weekly report number **Report-2021-40**

Alert submitted by **Croatia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public **Import rejected at border**

authorities

**Importer**

Date of entry into force

**02/08/2021**

Alert number **[A12/01404/21](#)**

Product **Baby stroller**



Risk type **Injuries**

**The handlebar is not resistant enough and may break causing a loss of control of the stroller. As a consequence, there could be an accident causing injuries.**

**The product does not comply with the General Product Safety Directive and the European standard EN 1888-1.**

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Baby stroller/buggy in green and black. The product is also sold online.**

Packaging description **Brown cardboard box with a picture of the unfolded baby stroller, model name, article number, EAN and customer name 'XXXLutz'. The term 'baby stroller' is displayed on the top of the cardboard box in various European languages.**

Brand **Jimmylee**

Name **Sporty**

Type / number of model **9009852542059**

Batch number **87040015/01**

Weekly report number **Report-2021-40**

Alert submitted by	<b>Austria</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>Austria</b>
Measures taken by economic operators	<b>Recall of the product from end users Manufacturer</b>
Date of entry into force	<b>22/09/2021</b>

Alert number **[A12/01401/21](#)**

Product **Passenger transport vehicle**

Risk type **Environment**

**The open circuit of the bus bar generating a vehicle malfunction producing a DTC. The bus bar is the large socket which is fixed by screws on the injection computer (ECU) the loose plug can lead to injection faults, hence the risk of pollution emission at the exhaust.**

**The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Open circuit of the bus bar**

Brand **KIA**

Name **Soul EV (SK3) Niro EV (DE)**

EC-type approval/model **Niro de e4\*2007/46\*1139\*09 à e4\*2007/46\*1139\*09 Soul de e4\*2007/46\*1365\*02 à e4\*2007/46\*1365\*02**

Production dates **Soul EV: from 7 January 2020 to 11 January 2020 Niro EV: from 8 January 2020 to 17 January 2020**

Company recall code **211069**

Weekly report number **Report-2021-40**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Republic of Korea**

Measures taken by economic operators **Recall of the product from end users  
Distributor**



Date of entry into force **07/08/2021**

Products were found and  
measures were taken also in **Sweden  
Slovakia**

Alert number **[A12/01400/21](#)**

Product **Passenger car**

Risk type **Injuries**

**The NADI (non-azide driver inflator) type airbag may have improper sealing that could allow moisture to enter into the propellant. If the propellant afterwards dries out, it could lead to decreased density resulting in a too high burn rate. Consequently the airbag may not deploy as designed and provide less protection, increasing the risk of injury.**

**The product does not meet the requirements set out in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles**

Category **Motor vehicles**

Type **Consumer**

Description **Model series E46.**

Brand **BMW**

Name **3**

EC-type approval/model **e1\*97/27\*0097\*01 e1\*97/27\*0097\*02 e1\*97/27\*0097\*03  
e1\*97/27\*0097\*04 e1\*98/14\*0097\*05 e1\*98/14\*0097\*06  
e1\*98/14\*0097\*07  
e1\*98/14\*0112\*00 e1\*98/14\*0112\*01 e1\*98/14\*0112\*02  
e1\*98/14\*0112\*03 e1\*98/14\*0112\*04**

Production dates **23.10.1997 - 03.07.2000**

Company recall code **0032200300**

Weekly report number **Report-2021-40**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators

**Recall of the product from end users  
Manufacturer**

Date of entry into force

**20/05/2021**

Products were found and measures were taken also in


**Estonia  
Greece  
Ireland  
Poland  
Romania  
Sweden  
Slovenia**

Alert number

**[A12/01397/21](#)**

Product

**Electronic controlgear for LED module**



Risk type

**Electric shock**

**The electrical insulation is inadequate and the clearance /creepage distances between the primary and accessible secondary circuits as well as between the live circuit and the earthing circuit on the PCB are not sufficient. Accessible parts can become live and the user could receive an electric shock from them.**

**The product does not comply with the requirements of the Low Voltage Directive and the European standard EN 61347-2.**

Category

**Electrical appliances and equipment**

Type

**Consumer**

Description

**Led power supply, 170-264V, 47/63Hz, 1,8A, 24VDC / 8,3A, class I**

Brand

**eurolite**

Name

**Electronic transformer 24V 8,3A**

Type / number of model

**No. 51402263**

Barcode

**4026397688801**

Weekly report number

**Report-2021-40**

Alert submitted by

**Finland**

Is the product counterfeit? **Unknown**

Country of origin **Germany**

Measures ordered by public authorities **Recall of the product from end users  
Distributor**


Date of entry into force **21/06/2021**

Alert number

**[INFO/00157/21](#)**

Product

**Particle filter mask**



Risk type

**Health risk / other**

**The product bears a CE marking but its filtering capacity has not been tested by a relevant competent European conformity assessment body. Consequently, it is not proven that the product fulfils the health and safety requirements; thus, even if combined with other recommended measures, it may not properly protect.**

**The product does not comply with the Personal Protective Equipment (PPE) Regulation.**

Category

**Protective equipment**

Type

**Consumer**

Description

**White flat foldable mask without valve. With ear straps. The product is also sold online.**

Packaging description

**White plastic bag with light blue marking. With sign "EU CE certified" and "5 layer structure"**

Brand

**mezorizon**

Name

**KN95 Protective Mask**

Batch number

**202004**

Barcode

**4260657782711**

Weekly report number

**Report-2021-40**

Alert submitted by	<b>Estonia</b>
Is the product counterfeit?	<b>Unknown</b>
Country of origin	<b>People's Republic of China</b>
Measures taken by economic operators	<b>Removal of this product listing by the online marketplace Retailer</b>
Date of entry into force	<b>23/09/2021</b>
Measures taken by economic operators	<b>Withdrawal of the product from the market Retailer</b>
Date of entry into force	<b>23/09/2021</b>

Alert number **[A12/01394/21](#)**

Product **Passenger car**

Risk type **Injuries**

**Due to incorrect programming, the electronic control unit (ECU) of the hybrid vehicle may incorrectly determine the position of the transmission selector lever which could cause the hybrid system to shut down. This could result in a loss of power, increasing the risk of an accident.**

**The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of Motor Vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **TOYOTA**

Name **Prius, Prius PHEV**

EC-type approval/model **Toyota Prius PHEV: e6\*2007/46\*0340\*04  
Toyota Prius: e6\*2007/46\*0339\*06**

Production dates **31.05.2021 - 02.08.2021**

Company recall code **21SMD-076**

Weekly report number **Report-2021-40**

Alert submitted by **Bulgaria**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users  
Importer**

**Greece**



Products were found and  
measures were taken also in

**Ireland**  
**Poland**



Alert number **[A12/01396/21](#)**

Product **Particle filter mask**



Risk type **Health risk / other**

**The particle/filter retention of the material is insufficient (measured values: as low as 28%) and the total filtration capacity of the mask is insufficient (measured mean values: as low as 64%). Consequently, the product does not fulfil the health and safety requirements; thus, even if combined with other recommended measures, it may not properly protect.**

**The product does not comply with the Personal Protective Equipment (PPE) Regulation and with the relevant European standard EN 149.**

Category **Protective equipment**

Type **Consumer**

Description **Masks are white, disposable non-woven, cup-shaped, which are attached to the ears with rubber bands. Marking on the mask: Gram Minkang 9001-KN95 Mask, FFP2 Nr. D, EN 149:2001+A1 2009, CE.**

Packaging description **Soft plastic packaging. Marking on the packaging: Apsauginė veido kaukė KN95, 1 vnt., 5 sluoksnių, b/k 8050043166234, sertifikato Nr. OP200328S.PHM0S21, platintojas UAB „TITANIKA“ Servėčės g. 1, Vilnius.**

Brand **Gram**

Name **Protective face masks GRAM KN95 (5 layers, 1 pc.)**

Type / number of model **Minkang 9001-KN95 Mask**


Barcode	<b>8050043166234</b>
Weekly report number	<b>Report-2021-40</b>
Alert submitted by	<b>Lithuania</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>People's Republic of China</b>
Measures ordered by public authorities	<b>Withdrawal of the product from the market Importer</b>

Alert number

**A12/01398/21**

Product

**Lighting chain**



Risk type

**Burns  
Electric shock  
Fire**

**The cable is not properly anchored and is too thin; it could overheat, leading to a risk of fire or burns. The accessible wires have inadequate insulation. The user could touch accessible live parts, which may cause an electric shock.**

**The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.**

Category

**Lighting chains**

Type

**Consumer**

Description

**Lighting chain with 99 non-replaceable red LED lamps. Product also sold online.**

Packaging description

**Packaging: transparent plastic box with a colourful printed card inside**

Brand	<b>Unknown</b>
Name	<b>LED 100 BOMBILLAS / beltéri LED karácsonyi égősor</b>
Type / number of model	<b>LED-GSK-100; REF: 1101379</b>
Barcode	<b>8 000011 013794</b>
Weekly report number	<b>Report-2021-40</b>
Alert submitted by	<b>Hungary</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>People's Republic of China</b>
Measures ordered by public authorities	<b>Recall of the product from end users Distributor</b>
Date of entry into force	<b>17/09/2021</b>
Measures ordered by public authorities	<b>Withdrawal of the product from the market Distributor</b>
Date of entry into force	<b>17/09/2021</b>

Alert number **[A12/01410/21](#)**

Product **Mirror**



Risk type **Cuts**

**Due to insufficient glue attaching the glass mirror to the backing, the mirror may fall off and break, resulting in glass shards which can cause cuts.**

**The product does not comply with the requirements of the General Product Safety Directive.**

Category **Decorative articles**

Type **Consumer**

Description **Mirror on a wooden backing and with a wood shelf. The product was also sold online.**

Brand **Next**

Name **Oakley Mirror**

Type / number of model **688055**

Weekly report number **Report-2021-40**

Alert submitted by **Ireland**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures taken by economic **Recall of the product from end users**

operators **Distributor**

Date of entry into force **11/06/2021**

Company recall code - <https://www.nextdirect.com/help/en/ie/Section.aspx?ItemId=31100>

Alert number **[A12/01408/21](#)**

Product **Plastic doll**



Risk type **Chemical**

**The toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 19.4% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.**

**The product does not comply with the REACH Regulation.**

Category **Toys**

Type **Consumer**

Description **Plastic doll.**

Packaging description **Plastic blister with cardboard back.**

Brand **Unknown**

Name **Ballet Twinkle Toes**

Type / number of model **LY-2310**

Weekly report number **Report-2021-40**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**



Measures taken by economic operators

**Withdrawal of the product from the market  
Distributor**

Date of entry into force

**15/09/2021**

Alert number

**[A12/01407/21](#)**

Product

**Toy slime**



Risk type

**Chemical**

**The migration of boron from the toy slime is too high (measured value up to 2273.18 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.**

**The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.**

Category

**Toys**

Type

**Consumer**

Description

**Toy slime with glitter.**

Packaging description

**Plastic pill-shaped packaging.**

Brand

**Unknown**

Name

**Slime M**

Type / number of model

**7262  
BPLA 3024**

Barcode

**5902719733024**

Weekly report number

**Report-2021-40**

Alert submitted by

**Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market  
Importer**

Date of entry into force **01/09/2021**

Measures taken by economic operators **Destruction of the product  
Importer**

Date of entry into force **01/09/2021**

Alert number **[A12/01406/21](#)**

Product **Toy slime**



Risk type **Chemical**

**The migration of boron from the toy slime is too high (measured value up to 721.08 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.**

**The product does not comply with requirements of the Toy Safety Directive and the relevant European standard EN 71-3.**

Category **Toys**

Type **Consumer**

Description **Toy slime.**

Packaging description **Plastic packaging.**

Brand **Unknown**

Name **Masa galaktyczna w beczce**

Type / number of model **61936  
BZES 9111**

Barcode **5902719709111**

Weekly report number **Report-2021-40**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market  
Importer**

Date of entry into force **01/09/2021**

Measures taken by economic operators **Destruction of the product  
Importer**

Date of entry into force **01/09/2021**

Alert number **[A12/01405/21](#)**

Product **Plastic doll**



Risk type **Chemical**

**The plastic material of the head of the doll contains di-(2-ethylhexyl) phthalate (DEHP) (measured value up to 38.3% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.**

**The product does not comply with the REACH Regulation.**

Category **Toys**

Type **Consumer**

Description **Plastic doll about 30 cm tall with accessories.**

Packaging description **Cardboard box with transparent window, CE marking and +3 as indication for the age.**

Brand **Unknown**

Name **FASHION**

Type / number of model **LY350**

Batch number **bm1226K76**

Barcode **8595500012261**

Weekly report number **Report-2021-40**

Alert submitted by **Czechia**

Is the product counterfeit?

**No**

Country of origin

**People's Republic of China**

Measures ordered by public authorities

**Withdrawal of the product from the market  
Retailer**

Date of entry into force

**29/09/2021**