

Alert number **[A12/01472/21](#)**

Product **Passenger car**

Risk type **Injuries**

The wheel hubs may not be sufficiently tightened to the rear axle, which may cause a wheel to detach from the rear suspension crossbar. This could result in a loss of control over the vehicle, increasing the risk of an accident.

The product does not comply with the requirements set out in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **CITROEN**

Name **C4 (C41)**

EC-type approval/model **e9*2007/46*6816*01, e9*2007/46*6816*02, e9*2007/46*6816*03, e9*2007/46*6816*04**

Production dates **20.10.2020 -- 23.04.2021**

Company recall code **HTP**

Weekly report number **Report-2021-43**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Spain**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **02/07/2021**

Alert number **[A12/01477/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The head and arms of the doll contains contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 29.7% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **A plastic doll with accessories.**

Packaging description **Packed in a cardboard box with transparent window.**

Brand **Unknown**

Name **Heartable girl**

Type / number of model **PS81-8**

Barcode **6908553153157**

Weekly report number **Report-2021-43**

Alert submitted by **Cyprus**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

31/08/2021

Alert number **[A12/01478/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 29.5% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Set of two plastic dolls with accessories.**

Packaging description **Cardboard box with transparent window.**

Brand **Unknown**

Name **Beauty summer magic**

Type / number of model **8881**

Barcode **6920190288818**

Weekly report number **Report-2021-43**

Alert submitted by **Cyprus**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

31/08/2021

Alert number **[A12/01479/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 26.4% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **A plastic doll with accessories.**

Packaging description **Packed in a cardboard with transparent cover.**

Brand **Unknown**

Name **JEWELRY BEAUTIFUL SET**

Type / number of model **TRH45140**

Barcode **1815000451405**

Weekly report number **Report-2021-43**

Alert submitted by **Cyprus**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

31/08/2021

Alert number **[INFO/00159/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 21,5% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Plastic mermaid doll.**

Packaging description **Plastic bag.**

Brand **Unknown**

Weekly report number **Report-2021-43**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures taken by economic operators **Withdrawal of the product from the market
Distributor**

Date of entry into force **15/09/2021**

Alert number **[A12/01469/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The head of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 26,3% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Plastic doll.**

Packaging description **Cardboard box with plastic window.**

Brand **Unknown**

Name **Beauty / My style love**

Type / number of model **668D**

Barcode **7460801017202**

Weekly report number **Report-2021-43**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators

**Destruction of the product
Importer**

Date of entry into force

21/09/2021

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force

21/09/2021

Alert number **[A12/01461/21](#)**

Product **LED light lamp**



Risk type **Electric shock**

The accessible wires have inadequate insulation. Live parts can become accessible. A user could touch a live part and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and of the relevant European standards EN 60598-1 and EN 60598-2.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Mp3 LED Magic ball light, Homra, DB5, LDJ-Prime Edition.**

Packaging description **LED Magic ball light.**

Brand **Homra**

Name **Mp3 LED Magic ball light**

Type / number of model **DB5, LDJ-Prime Edition**

Weekly report number **Report-2021-43**

Alert submitted by **The Netherlands**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**



Alert number **[A12/01460/21](#)**

Product **Hot water bottle**



Risk type **Burns**

The seams of the hot water bottle may easily tear open when in use. The rubber bottle can therefore leak hot water and cause burns.

The product does not comply with the requirements of the General Product Safety Directive.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **A soft, flexible baby bottle that is factory filled and sealed with liquid and never needs to be refilled. The product was sold online.**

Packaging description **ZENSY CARE SOFT BABYWARMER**

Brand **Ardes**

Name **ARDES ZENSY CARE**

Type / number of model **12811500 met EAN code: 8004032111095
12811501 met EAN code: 8004032112177
16901540 met EAN code: 8004032112474**

Weekly report number **Report-2021-43**

Alert submitted by **The Netherlands**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Distributor**

Date of entry into force

23/08/2021

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force

24/10/2021

Alert number **[A12/01458/21](#)**

Product **Passenger car**

Risk type **Injuries**

Due to a specific software update error that can cause an abrupt reset, the Data Communication Module (DCM) may become damaged. As a result, it will no longer be possible to initiate an emergency call using the eCall system.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of Motor Vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Vehicles manufactured in Pitesti plant.**

Brand **DACIA**

Name **Logan III**

EC-type approval/model **e19*2007/46*0026*02, e19*2007/46*0026*03, e19*2007/46*0026*04**

Production dates **2021/03/11 - 2021/05/11**

Company recall code **ODN3**

Weekly report number **Report-2021-43**

Alert submitted by **Romania**

Is the product counterfeit? **No**

Country of origin **Romania**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**


Date of entry into force **12/10/2021**

Products were found and
measures were taken also in

Poland

Alert number **[INFO/00160/21](#)**

Product **Earrings**



Risk type **Chemical**

The product releases an excessive amount of nickel (measured value 1,384 µg/cm²/week). Nickel is a strong sensitiser and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Round-shaped metal earrings in silver with embedded clear rhinestones.**

Packaging description **Transparent plastic bag.**

Brand **Unknown**

Batch number **11154589**

Weekly report number **Report-2021-43**

Alert submitted by **Slovakia**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities

**Import rejected at border
Importer**

Date of entry into force

30/09/2021



Alert number

A12/01459/21

Product

USB mains charger



Risk type

Electric shock

The electrical insulation is inadequate and the clearance /creepage distances between the primary and accessible secondary circuits are not sufficient. The user could receive an electric shock from accessible (live) parts. Furthermore, the product can overheat.

The product does not comply with the requirements of the Low Voltage Directive and the European standard EN 60950.

Category

Electrical appliances and equipment

Type

Consumer

Description

Charger with a two-pole plug without a protective contact integrated into the charger body, equipped with two USB input ports, and sold without connecting cable. Product sold online.

Packaging description

Outer cardboard box and inner plastic cover.



Brand	C-tech
Name	Universal 2-ports USB Charger
Type / number of model	UC-02
Barcode	8594125010393
Weekly report number	Report-2021-43
Alert submitted by	Czechia
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Retailer
Date of entry into force	12/03/2021

Alert number

A12/01481/21

Product

Robot vacuum cleaner



Risk type

Electric shock

The product is supplied with a non-EU plug (US plug) that leave high-voltage live parts accessible when plugged in. Furthermore, the earthing protection is inadequate and the product insulation is inappropriate, leaving live parts accessible. The user could touch the accessible live parts and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive (LVD), the Radio Equipment Directive and the relevant European standard EN 60335.


Category	Electrical appliances and equipment
Type	Consumer
Description	Robot vacuum cleaner with laser navigation and radio remote control; includes charging station. Weight 4 kg/Diameter 330 mm/Height 101 mm/14.4 V Dust receptacle 600/ml Lithium Battery 25000mAh in obsidian blue colour. The product was also sold online, in particular, via Amazon.
Brand	TESVOR
Name	Robotic vacuum cleaner S6
Weekly report number	Report-2021-43
Alert submitted by	Germany
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Other
Date of entry into force	01/10/2021
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	01/10/2021

Alert number

[A11/00090/21](#)

Product

Scissor lift jack



Risk type

Injuries

The device is not sufficiently resistant to load. It may break down and cause the user to fall increasing the risk of injuries.

The product does not comply with the requirements of the Machinery Directive the relevant European standard EN 1494.

Category

Machinery

Type

Consumer

Description

Metal scissor jack, maximum weight: 1,5 t.

Packaging description

Cardboard box.

Brand

GEKO

Name

Podnosnik trapezowy

Type / number of model	G01061 1,5t JFM-1.5T
Batch number	Manufactured in 2019
Barcode	5901477106699
Weekly report number	Report-2021-43
Alert submitted by	Poland
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Withdrawal of the product from the market Manufacturer
Date of entry into force	24/09/2021
Products were found and measures were taken also in	Lithuania

Alert number **[A12/01457/21](#)**

Product **Toy gun, bow and arrow set**



Risk type **Choking**

The arrows' suction cups can be easily detached. A child may put them in the mouth and choke on them.

The product does not comply with the requirements of the Toy Safety Directive and of the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Toy set consisting of a plastic toy rifle, a plastic toy bow, and matching arrows with suction cups at their end.**

Packaging description **The set is sold in a transparent plastic packaging with a coloured cardboard back.**

Brand **Unknown**

Name **MASK**

Type / number of model **3193A
3193B
3193C**

Batch number **1809G378**

Barcode **5291410141901**

Weekly report number **Report-2021-43**

Alert submitted by	Cyprus
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	15/06/2021
Measures taken by economic operators	Withdrawal of the product from the market Importer
Date of entry into force	15/06/2021

Alert number **[A12/01456/21](#)**

Product **Toy set**



Risk type **Choking**

The arrows' suction cups can be easily detached. A child may put them in the mouth and choke on them.

The product does not comply with the requirements of the Toy Safety Directive and of the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Plastic toy set including a bow and three matching arrows, a plastic knife, as well as an axe and a spear.**

Packaging description **The set is sold in a transparent plastic packaging with a coloured cardboard back.**

Brand **RS toys / RSTA /**

Name **INDIANI APACHE**

Type / number of model **9445**

Batch number **01/9445**

Barcode **8004817094452**

Weekly report number **Report-2021-43**

Alert submitted by	Cyprus
Is the product counterfeit?	Unknown
Country of origin	Hong Kong
Measures ordered by public authorities	Withdrawal of the product from the market Retailer
Date of entry into force	15/06/2021

Alert number

[A12/01454/21](#)

Product

UV equipment for gel nails



Risk type

Electric shock

The electrical insulation of the charger is inadequate and the clearance /creepage distances between the primary and accessible secondary circuits are not sufficient. The user could receive an electric shock from accessible (live) parts.

The product does not comply with the requirements of the Low Voltage Directive and the European standards EN 60335-1 and EN 60335-2-23.

Category

Electrical appliances and equipment

Type

Consumer

Description

Hardener for gel nails, supplied with a charger. Product sold online.

Packaging description

Cardboard packaging.

Brand

SUN2C

Name

UV LED nail lamp

Type / number of model

TSL-2424

Weekly report number

Report-2021-43

Alert submitted by

Finland

Is the product counterfeit?

Unknown

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Recall of the product from end users
Distributor**

Date of entry into force

05/07/2021

Alert number **[A12/01480/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The head of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 45.9% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Plastic doll about 30 cm tall.**

Packaging description **Cardboard box with transparent window.**

Brand **Unknown**

Name **Fashion models**

Type / number of model **9293**

Batch number **HA1531, 5-200-14**

Barcode **8419293250566**

Weekly report number **Report-2021-43**

Alert submitted by **Czechia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Retailer**

Date of entry into force **30/09/2021**

Alert number **[A12/01463/21](#)**

Product **Toy scooter**



Risk type **Injuries**

The scooter direction tube may break. As a consequence, a kid riding it can suffer injuries.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Scooter for children available in different colours. The product was sold online.**

Brand **OXELO**

Name **LEARN 500 BLUE, LEARN 500 PINK, LEARN 500 YELLOW**

Type / number of model **LEARN 500 BLUE (model code : 855206 ; article code : 2939387)
LEARN 500 PINK (model code : 855207 ; article code : 2939388)
LEARN 500 YELLOW (model code : 855205 ; article code : 2939386)**

Weekly report number **Report-2021-43**

Alert submitted by **Romania**

Is the product counterfeit? **No**

Country of origin	People's Republic of China
Measures taken by economic operators	Recall of the product from end users Distributor
Date of entry into force	14/10/2021
Company recall code	- https://www.decathlon.ro/static/rechemare-produse/trotinete-rechemare.pdf
Products were found and measures were taken also in	Austria Poland Slovakia

Alert number

[A12/01468/21](#)

Product

Pendant luminaire



Risk type

Electric shock

The live parts of the lamp cap are accessible when the lamp is partially screwed into the lamp holder of the luminaire, and the lamp cap is not fully insulated. Furthermore, water can enter the connection compartment via the membrane seal and via the holes of the mounting screws. A user can get an electric shock when touching the metal threads of the lamp holder.

The product does not comply with the requirements of the Low Voltage Directive and the European standards EN 60598-2-1, EN 60598-1 and EN 60061-3.

Category

Lighting equipment

Type

Consumer

Description

Pendant luminaire with indications 100V-240V and 50Hz/60Hz. Product sold online.

Packaging description

Carboard packaging

Brand

Faro Barcelona

Name

Pendant luminaire with LED lamp Riippuvalaisin, LE

Type / number of model

**73696
Honey**

Batch number

SL B-58087479

Barcode

8421776169579

Weekly report number	Report-2021-43
Alert submitted by	Finland
Is the product counterfeit?	No
Country of origin	Spain
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	14/07/2021
Products were found and measures were taken also in	Lithuania

Alert number **[A12/01475/21](#)**

Product **Lorry**

Risk type **Injuries**

Under dynamic load, a crack in the forged parts of the steering-shaft adapter may spread further over the service life of the vehicle and ultimately lead to breakage. If the steering-shaft adapter were to break, the steering would immediately fail, increase the risk of a crash.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles

Category **Motor vehicles**

Type **Professional**

Description **Lorry**

Brand **Mercedes-Benz**

Name **Actros, Arocs**

EC-type approval/model **Type: 963-0-A, 963-4-A, 963-2-A, 963-0-B, 963-4-B, 963-2-B, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 963-2-E, 963-0-F, 963-4-F, 963-2-F, 963-8-G, 963-8-H
e1*2018/858*00039*00-01, e1*2018/858*00040*00-01,
e1*2018/858*00041*00-01, e1*2018/858*00042*00-01,
e1*2018/858*00043*00-01, e1*2018/858*00044*00-01,
e1*2018/858*00045*00-01, e1*2018/858*00046*00-01
e1*2018/858*00047*00-01, e1*2018/858*00048*00-01,
e1*2018/858*00049*00-01, e1*2018/858*00050*00-01,
e1*2018/858*00051*00-01, e1*2018/858*00052*00-01,
e1*2018/858*00053*00-01,
e1*2018/858*00054*00-01, e1*2018/858*00055*00-01,
e1*2018/858*00056*00-01**

Production dates **From 23.4.2021 to 19.8.2021**

Company recall code **LSPADAPTER**

Weekly report number **Report-2021-43**

Alert submitted by **Germany**

Is the product counterfeit?

No

Country of origin

Germany

Measures taken by economic operators

**Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in

Poland

Alert number **[A12/01455/21](#)**

Product **Rattle toy**



Risk type **Choking**

A small plastic part (squeaking element) may easily detach from the toy. A small child may put it in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **A neon yellow whistling and rattle toy with a teddy bear shape that emits a flashing light.**

Packaging description **The product was sold without packaging.**

Brand **Tengda**

Name **játékszer/ hračka**

Type / number of model **YE20873**

Barcode **5680150208737**

Weekly report number **Report-2021-43**

Alert submitted by **Hungary**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Recall of the product from end users
Other**

Date of entry into force **25/06/2021**

Measures ordered by public authorities **Withdrawal of the product from the market
Distributor**

Date of entry into force **25/06/2021**

Alert number **[A12/01467/21](#)**

Product **Necklace**



Risk type **Chemical**

The product's closing contains lead (measured values: 0,17% by weight). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Necklace described as "copper", with a weight of 34,3 g and a size of 42 cm. Product sold online.**

Packaging description **The product is sold in a plastic pouch with cardboard tags and stickers.**

Brand **Yehwang**

Type / number of model **0595320**

Batch number **0215907**

Weekly report number **Report-2021-43**

Alert submitted by **The Netherlands**

Is the product counterfeit? **No**

Country of origin


People's Republic of China

Measures ordered by public
authorities

Withdrawal of the product from the market
Other

Alert number **[A12/01464/21](#)**

Product **Wooden puzzle**



Risk type **Choking**

The toy contains small elements. A child may put in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Colourful wooden snake-shaped jigsaw puzzle. One side of the elements is marked with numbers and the other side with letters.**

Packaging description **Packaging: transparent plastic foil, with sticker.**

Brand **Unknown**

Name **játékszer / Toy**

Type / number of model **YE31081**

Barcode **5680480310810**

Weekly report number **Report-2021-43**

Alert submitted by **Hungary**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Distributor**


Date of entry into force **27/07/2021**

Measures ordered by public authorities **Recall of the product from end users
Distributor**

Date of entry into force **27/07/2021**

Alert number **[A12/01482/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 20.9% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system.

The doll does not comply with the REACH regulation.

Category **Toys**

Type **Consumer**

Description **Plastic doll with long brown hair and dressed in a short formal dress and bracelets on both hands of gold colour.**

Packaging description **Cardboard box with transparent window.**

Brand **Unknown**

Name **Plastic doll Fashion doll**

Type / number of model **NO. BL 858, ITEM NO: B3820-528862**

Barcode **EAN: 8599330038200**

Weekly report number **Report-2021-43**

Alert submitted by **Slovakia**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Distributor**

Date of entry into force

15/10/2021

Measures taken by economic operators

**Recall of the product from end users
Distributor**

Date of entry into force

15/10/2021

Measures taken by economic operators

**Warning consumers of the risks
Distributor**

Date of entry into force

15/10/2021

Alert number **[A12/01476/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The plastic material of the head of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 38.3 ± 15.3 % by weight). These phthalates may harm the health of children, causing possible damage to their reproductive system.

The product does not comply with the REACH regulation (1907/2006) annex XVII, No 51.

Category **Toys**

Type **Consumer**

Description **Plastic doll for hanging in a red or lilac tulle dress and pink shoes, 17cm high, without markings (hanging ring located in the doll's head)**

Packaging description **Without packaging**

Brand **Unknown**

Weekly report number **Report-2021-43**

Alert submitted by **Czechia**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public **Withdrawal of the product from the market**

authorities

Retailer

Date of entry into force

12/10/2021

Alert number **[A12/01466/21](#)**

Product **Portable mini fan**



Risk type **Environment**

The solders contain an excessive amount of lead (measured value up to 51% by weight). Lead poses a risk to the environment.

The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category **Electrical appliances and equipment**

Type **Consumer**

Description **The mini fan consists of a blue plastic body with black plastic fan blades and a black plastic string.**

Packaging description **No packaging**

Brand **Out Of The Blue KG**

Name **Mini fan portable**

Type / number of model **617012**

Barcode **4029811127108**

Weekly report number **Report-2021-43**

Alert submitted by **Sweden**

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Retailer**

Date of entry into force

11/10/2021

Alert number **[A12/01484/21](#)**

Product **Doll**



Risk type **Chemical**

The doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 14% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Small doll dressed in colourful clothes and drawn on face.**

Packaging description **Pink cardboard box packaging with transparent window.**

Brand **Unknown**

Name **Doll „Fashion Angel“**

Type / number of model **NO. 7785**

Weekly report number **Report-2021-43**

Alert submitted by **Lithuania**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**



Alert number **[A12/01470/21](#)**

Product **Plastic doll**



Risk type **Chemical**

The doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 35% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system.

The doll does not comply with the REACH regulation.

Category **Toys**

Type **Consumer**

Description **Plastic doll with colourful hair.**

Packaging description **Cardboard box packaging with see-through front.**

Brand **Unknown**

Name **Doll „Bearby“**

Type / number of model **YP8316**

Weekly report number **Report-2021-43**

Alert submitted by **Lithuania**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**



Alert number **[A12/01465/21](#)**

Product **Mixer with bowl**



Risk type **Fire**

Due to inadequate thermal protection, the windings of the motor could overheat leading to a fire.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **White mixer with bowl.**

Brand **Kaito**

Type / number of model **HS-9601SP**

Barcode **3856022619266**

Weekly report number **Report-2021-43**

Alert submitted by **Croatia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Warning consumers of the risks
Importer**

Date of entry into force **28/09/2021**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures
Importer**

Date of entry into force **28/09/2021**

Measures ordered by public authorities **Withdrawal of the product from the market
Importer**

Date of entry into force **28/09/2021**

Alert number **[A12/01473/21](#)**

Product **Motorcycle**

Risk type **Injuries**

The rear brake hoses on affected motorcycles may be susceptible to heat damage, which may cause a sudden loss of rear brake function and increase the risk of a crash.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of two- or three-wheel vehicles and quadricycles

Category **Motor vehicles**

Type **Consumer**

Description **Ducati motorcycles, models: Monster 821, Monster 1200/1200S, Monster 1200R.**

Brand **DUCATI**

Name **Monster 821; Monster 1200/1200S; Monster 1200R**

EC-type approval/model **e49*168/2013*00006*00; e49*168/2013*00006*01; e49*168/2013*00006*02; e49*168/2013*00006*03; e49*168/2013*00006*04; e49*168/2013*00006*05; e49*168/2013*00034*00; e49*168/2013*00034*01 e49*168/2013*00034*02**

Production dates **Monster 1200/1200S, Model Year: 2014-2021
Monster 1200R, Model Year: 2016-2019
Monster 821, Model Year: 2015-2021**

Company recall code **CR217**

Weekly report number **Report-2021-43**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Italy**

Measures taken by economic **Recall of the product from end users**

operators

Manufacturer

Products were found and
measures were taken also in

**Greece
Croatia**

Alert number **[A11/00091/21](#)**

Product **Motorcycle**

Risk type **Injuries**

The side stand may be improperly welded, potentially causing the stand to break. A broken side stand could result in the motorcycle falling down, increasing the risk of injury.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of two- or three-wheel vehicles and quadricycles

Category **Motor vehicles**

Type **Consumer**

Description **Ducati motorcycle, model: Hypermotard 950 SP**

Brand **DUCATI**

Name **Hypermotard 950 SP**

EC-type approval/model **e49*168/2013*00070*00**

Production dates **Model Year: 2019**

Company recall code **CR220**

Weekly report number **Report-2021-43**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Germany
Greece**

Alert number **[A12/01471/21](#)**

Product **Fireworks**



Risk type **Burns
Injuries**

The ignition fuse burns too fast. As a result, the user may get injured or burnt.

The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947-5.

Category **Pyrotechnic articles**

Type **Consumer**

Description **Flash bangers, class F3.**

Packaging description **Cardboard box containing 6 pieces of product.**

Brand **Unknown**

Name **Bangers**

Type / number of model **1008-F3-69259883
P06-30**

Barcode **5901363700673**

Weekly report number **Report-2021-43**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force

11/08/2021

Measures taken by economic operators

**Destruction of the product
Importer**

Date of entry into force

11/08/2021