

Alert number

[**A12/00268/22**](#)

Product

Professional teeth whitening kit

Risk type

Chemical

The product contains hydrogen peroxide (measured concentration 6,8% by weight). Hydrogen peroxide at high concentrations causes skin irritation and is harmful if swallowed.

This product does not comply with the Cosmetic Products Regulation.

Category

Cosmetics

Type

Consumer

Description

Teeth whitening kit consisting on whitening gel, soothing gel, dental floss and gum shield. The product was also sold online, in particular via Amazon and eBay.

Packaging description

White cardboard box.

Brand

Glamador

Name

Teeth whitening set

Batch number

202110128A

Weekly report number

Report-2022-7

Alert submitted by

France

Is the product counterfeit?

Unknown

Country of origin

Unknown

Measures taken by economic operators

**Removal of this product listing by the online marketplace
Other**

Alert number **[A12/00269/22](#)**

Product **SOFT TOY**



Risk type **Choking**

Small parts may detach. In addition, the fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the small parts or the stuffing material in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive nor the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Soft toy in the shape of a rabbit.**

Brand **Unknown**

Type / number of model **XW-752**

Barcode **3858887901647**

Weekly report number **Report-2022-7**

Alert submitted by **Croatia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public **Import rejected at border**

authorities

Importer

Date of entry into force

15/12/2021

Alert number **[A12/00270/22](#)**

Product **Bath product**



Risk type **Choking**

Due to the characteristic form, appearance, colour and size, this product may be mistaken for a foodstuff. The product has small parts that can be easily detached. A small child/vulnerable user may put them in the mouth and choke on them.

The product does not comply with the requirements of the Food Imitating Directive.

Category **Cosmetics**

Type **Consumer**

Description **1piece/180g, bath product in a shape of donut. The product was also sold online.**

Packaging description **The products are wrapped in a cardboard box (16 pieces in one box).**

Brand **Bath Donuts**

Name **Bath Donuts**

Type / number of model **01 Blueberry
02 Raspberry
03 Toffe & Caramel
04 Stawberry & Banana
05 Chocolate & Coconut
06 Lemonmeringue
07 Cinnamom & Vanilla
08 Blackberry & Almond**

10/1/214DON

Batch number	10/13/212DON 10/15/215DON 10/19/213DON 10/20/217DON 10/22/212DON 10/22/216DON 9/28/218DON
Barcode	5056422985222
Weekly report number	Report-2022-7
Alert submitted by	Slovakia
Is the product counterfeit?	Unknown
Country of origin	United Kingdom
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Importer
Date of entry into force	22/11/2021

Alert number

[A12/00287/22](#)

Product

Inflatable Swimming ring flamingo

Risk type

Chemical

The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 11% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category

Hobby/sports equipment

Type

Consumer

Description

Inflatable swimming ring toy in the shape of a flamingo. The product was also sold online.

Packaging description

Transparent plastic bag.

Brand

Unknown

Name

Simring med flamingo och frukt

Type / number of model

MF008/ SKU: swbecacc18210507722

Barcode

B210707055832

Weekly report number

Report-2022-7

Alert submitted by

Sweden

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures taken by economic operators

Removal of this product listing by the online marketplace Distributor

Alert number

[**A12/00279/22**](#)

Product

Transparent plastic camera bag

Risk type

Chemical

The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 0,31% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The plastic also contains short-chain chlorinated paraffins (SCCPs) (measured value up to 0.61% per weight). SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bioaccumulate in wildlife and humans, posing a risk to human health and the environment.

The product does not comply with the Regulation on persistent organic pollutants (POP Regulation) nor with the REACH Regulation.

Category

Clothing, textiles and fashion items

Type

Consumer

Description

Transparent plastic camera bag.

Packaging description

Plastic transparent bag. The product was also sold online, in particular, via Amazon.com.

Brand

VALICLUD

Name

VALICLUD kraftig klar ryggsäck stadion godkänd transparent tygväska PVC stor kapacitet

Type / number of model

602095/05-25

Weekly report number	Report-2022-7
Alert submitted by	Sweden
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Removal of this product listing by the online marketplace Other
Date of entry into force	09/09/2021

Alert number **[A12/00265/22](#)**

Product **Light string**



Risk type **Electric shock**

The product is improperly designed, the electrical insulation is inadequate and the clearance /creepage distances between the primary and accessible secondary circuits are not sufficient, and live parts are accessible on the socket outlet. Furthermore, the product is recommended for outdoor use but the plug of the light string is not protected against splashing or leaking water. The user could consequently touch live parts and receive an electric shock from them.

The product does not comply with the requirements of the Low Voltage Directive nor the European standards EN 60432-1, EN 60598-1 and EN 60598-2-20.

Category **Lighting chains**

Type **Consumer**

Description **Light string for outdoor use, with 25 glass lightbulbs in tungsten. G40, 7.65M, 5W, Warm white, 3500K Voltage: 220V - Watertight: IP54.**

Packaging description **The product is sold with white protection elements and protective bubblewrap for lightbulbs. Product sold online in particular on CDiscount with URL <https://www.cdiscount.com/maison/lampes/guirlande-lumineuse-exterieure-7-65m-25pcs-5w-g40/f-117022224-mum6556887243664.html?idOffre=481011015#mpos=0>**

Brand **ELINKUME**


Name **ELINKUME Guirlande Lumineuse Extérieure 7,65M 5W avec**

25 G40 Ampoules Étanche Décoration pour ext.

Type / number of model	E12
Weekly report number	Report-2022-7
Alert submitted by	France
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Removal of this product listing by the online marketplace Other

Alert number **[A12/00271/22](#)**

Product **Soother holder**



Risk type **Strangulation**

The strap is too long and may lead to strangulation of a child.

The product does not comply with the relevant European standard EN 12586.

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Handmade soother holders made from leather and with a clip. The product was also sold online.**

Brand **Mavies**

Name **Pacifier Cord**

Type / number of model **Black leather; brown leather; Fringe Camel; Grey Paint; Leopard Grey; Navy Blue; Sand Paint; Speckle Sand; Speckle white; Taupe Paint; Zebra**

Weekly report number **Report-2022-7**

Alert submitted by **The Netherlands**

Is the product counterfeit? **Unknown**


Country of origin **The Netherlands**

Measures ordered by public **Withdrawal of the product from the market**

authorities	Other
Date of entry into force	05/10/2021
Measures ordered by public authorities	Warning consumers of the risks Other
Date of entry into force	05/10/2021
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Other
Date of entry into force	05/10/2021

Alert number **[A12/00273/22](#)**

Product **Soother holder**



Risk type **Choking**

The soother holder breaks easily and generates small parts. A small child could put them in the mouth and choke. In addition, the strap is too long and may lead to strangulation of the child.

The product does not comply with the relevant European standard EN 12586.

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **Handmade soother holder with wooden colourful beads. The product was also sold online.**

Brand **Mushie**

Name **Clip Cleo Blush and Cleo Dried Thyme**

Batch number **7426999778592
7426999778639**

Weekly report number **Report-2022-7**

Alert submitted by **The Netherlands**

Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators

**Ban on the marketing of the product and any accompanying measures
Distributor**

Date of entry into force

04/10/2021

Alert number **[A12/00305/22](#)**

Product **Bicycle handle**



Risk type **Chemical
Environment**

The product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP), di-isobutyl phthalate (DIBP) and di-n-butyl phthalate (DBP) (measured values up to 3.3% and 0.8%% by weight respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. It also contains polycyclic aromatic hydrocarbons (PAHs) (measured value up to: 368 mg/kg) which may cause cancer and short-chain chlorinated paraffins (SCCPs) (measured value up to 0.6% by weight) as well as an excessive amount of lead (measured values: 0.24%). SCCPs and lead persist in the environment, are toxic to aquatic organisms at low concentrations and bio accumulate in wildlife and humans, posing a risk to human health and the environment.

The product does not comply with REACH Regulation, the Regulation on persistent organic pollutants (POP Regulation), nor with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category **Hobby/sports equipment**

Type **Consumer**

Description **Black bicycle handle. The product was also sold online, in particular, via AliExpress.**

Packaging description **Transparent plastic bag.**

Brand **Unknown**

Name	2pcs/1 Pair Mountain Road Cycling Bike Bicycle MTB Handlebar Cover Grips Smooth Soft Rubber Anti-sli
Type / number of model	H0126E28468
Batch number	20210315
Weekly report number	Report-2022-7
Alert submitted by	Sweden
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Removal of this product listing by the online marketplace Other
Date of entry into force	10/09/2021

Alert number

[**A12/00276/22**](#)

Product

Plastic handbag toy

Risk type

**Chemical
Environment**

The toy contains an excessive amount of short chain chlorinated paraffin (SCCPs), di- (2-ethylhexyl) phthalate (DEHP) and di-n-butyl phthalate (DBP) (measured values up to 0,4%, 22% and 1% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bioaccumulate in wildlife and humans.

The product does not comply with the Persistent Organic Pollutants (POPs) Regulation nor with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category

Clothing, textiles and fashion items

Type

Consumer

Description

Transparent plastic bag in the shape of a pineapple in PVC. The product was also sold online.

Packaging description

Plastic transparent handbag.

Brand

Unknown

Name

Transparent Jelly Package Crossbody Väska Färsk Ananas Shape Chain Handy Messenger Shoulder Bag

Type / number of model

8719949177057


Weekly report number	Report-2022-7
Alert submitted by	Sweden
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Removal of this product listing by the online marketplace Other
Date of entry into force	06/09/2021

Alert number

[A12/00277/22](#)

Product

Electrical soccer game



Risk type

Chemical

The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured values: 27 %). This phthalate may harm the health of children, causing possible damage to their reproductive system.

The product does not comply with the REACH Regulation.

Category

Toys

Type

Consumer

Description

Electrical football game with ball.

Packaging description

Cardboard box.

Brand

Unknown

Name

Hover Soccer Ball LED Hover Soccer Ball Racketleksaker

Type / number of model

999-2

Barcode

S656949400

Weekly report number

Report-2022-7

Alert submitted by

Sweden

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures taken by economic operators

**Removal of this product listing by the online marketplace
Other**

Date of entry into force

13/09/2021

Alert number **[A12/00272/22](#)**

Product **Immersion heater**



Risk type	Electric shock The grip that insulates the connection between power supply cord and the metallic heating element is too small. A user might touch the metallic live part of the product and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.
Category	Electrical appliances and equipment
Type	Consumer
Description	Coffee immersion heater; nominal voltage marked on the product: 220V- 240V; 500W.
Packaging description	The product is packed in cardboard box.
Brand	RJE
Name	Coffee heater
Weekly report number	Report-2022-7
Alert submitted by	Romania
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

30/12/2021

Alert number

[A11/00029/22](#)

Product

Electric swing for babies



Risk type

Injuries

The swing is not stable enough. As a result, it can tip over and fall, leading to injuries to a child.

The product does not comply with the requirements of the General Product Safety Directive nor the European standard EN 1273.

Category

Childcare articles and children's equipment

Type

Consumer

Description

Portable baby swing (electric).

Packaging description

Cardboard Box.

Brand

Lorelli

Name

Portofino Baby Electric Swing Portofino Baby Elect

Batch number

033502

Barcode

3800151995272

Weekly report number

Report-2022-7

Alert submitted by

Malta

Is the product counterfeit?

No

Country of origin **Bulgaria**

Measures taken by economic operators **Withdrawal of the product from the market
Distributor**

Date of entry into force **18/01/2022**

Alert number **[A12/00289/22](#)**

Product **Plush toy**



Risk type **Choking**

A small part (the suction cup) may be easily detached from the toy. A small child may put it in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive nor the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **The toy is made of soft plush with a soft fibre filling in the form of a panda bear with a suction cup attached to the top of the head by a textile cord. The toy is black and white with an embroidered nose, mouth and eyes.**

Packaging description **Sold without packaging.**

Brand **Unknown**

Name **PANDA with a suction cup**

Type / number of model **70331-1**

Barcode **6905070331013**

Weekly report number **Report-2022-7**

Alert submitted by **Slovakia**

Is the product counterfeit? **Unknown**





Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market
Distributor**

Date of entry into force **30/11/2021**

Alert number **[A11/00030/22](#)**

Product **Glue**



Risk type **Chemical**

The product lacks the appropriate labelling and language. The user therefore does not have the necessary information on the dangers posed by the product in terms of skin sensitization.

The product does not comply with the classification, labelling and packaging (CLP) Regulation.

Category **Chemical products**

Type **Consumer**

Description **Tubes of strong glue. The product is sold online, in particular via AliExpress, Cdiscount, Alibaba and Amazon.**

Packaging description **Blister packaging**

Brand **UV-LOCA**

Weekly report number **Report-2022-7**

Alert submitted by	France
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Removal of this product listing by the online marketplace Other
Measures taken by economic operators	Recall of the product from end users Distributor

Alert number **[A12/00275/22](#)**

Product **Earrings**



Risk type **Chemical**

The product contains cadmium (measured value 0,0624%). Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Dangling metal earrings adorned with metal beads.**

Packaging description **The product is attached to a paper label with information "The best accessories! Auskarai 4230-18070".**

Brand **No 1**

Name **Earrings**

Type / number of model **4230-18070**

Barcode **2000000097206**

Weekly report number **Report-2022-7**

Alert submitted by **Lithuania**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

21/01/2022

Alert number **[A12/00306/22](#)**

Product **Chainsaw**



Risk type **Cuts**

When installing a lever in the chainsaw, there are discrepancies that can have an influence on the triggering sensitivity of the automatic chain brake. This may lead to risk of injuries in the event of a kickback.

The product does not comply with the requirements of the Machinery Directive.

Category **Machinery**

Type **Consumer**

Description **Chainsaw MS 391. The product is also sold online.**

Brand **STIHL**

Type / number of model **MS 391**

Batch number **190993963 - 190994982**

Weekly report number **Report-2022-7**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Unknown**

Measures taken by economic **Recall of the product from end users**

operators

Manufacturer

Date of entry into force


19/01/2022

Alert number

[A11/00028/22](#)

Product

Toy panda with battery



Risk type

Chemical

The battery compartment of the toy can be easily opened, leaving batteries accessible. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways, or could cause injuries to the gastrointestinal tract.

The product does not comply with the requirements of the Toy Safety Directive nor the European standard EN 62115.

Category

Toys

Type

Consumer

Description

Black and white plastic moving, musical panda toy figure with flashing coloured light. The toy is powered by 3 AA batteries.

Packaging description

Colourful cardboard box.

Brand

Haoteng Toys / ABABABY

Name	Sound & light cartoon toy set
Type / number of model	2026-1
Barcode	5212888900388
Weekly report number	Report-2022-7
Alert submitted by	Hungary
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	04/01/2022
Measures ordered by public authorities	Recall of the product from end users Distributor
Date of entry into force	04/01/2022

Alert number **[A12/00274/22](#)**

Product **Children's sweater**



Risk type **Choking**

The small decorative elements (beads) can easily be detached from the sweater. A small child may put them in the mouth and choke on them.

The product does not comply with the requirements of the General Product Safety Directive.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **White knitted girls' sweater, decorated with rows of beads that were placed in knitted covers and separated from each other by knotts.**

Brand **Dong**

Type / number of model **DH-96**

Weekly report number **Report-2022-7**

Alert submitted by	Hungary
Is the product counterfeit?	Unknown
Country of origin	Unknown
Measures ordered by public authorities	Withdrawal of the product from the market Other
Date of entry into force	23/11/2021
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	23/11/2021
Measures taken by economic operators	Recall of the product from end users Distributor
Date of entry into force	23/11/2021
Measures taken by economic operators	Withdrawal of the product from the market Distributor
Date of entry into force	23/11/2021

Alert number **[A12/00303/22](#)**

Product **Fireworks**



Risk type

**Burns
Damage to hearing**

The noise level is too high (measured values: up to 122 dB). Consequently it can cause damage to hearing. Furthermore, burning pieces fall off from the product at too low altitude and within the safety distance on the ground. As a result, the user may get burnt.

The product does not comply with the requirements of the Pyrotechnics Directive nor the European standard EN 15947-5.

Category

Pyrotechnic articles

Type

Consumer

Description

100 shot compound battery


Packaging description

Black and orange colours with firework images. "The Kraken" is written in yellow and "100 shot compound" in white. The front side has a image of a pirate skeleton head.

Brand	Fyrværkerieksperten A/S
Name	The Kraken - 100 shot compound
Type / number of model	1008-F2-69258817
Batch number	116.9270 21-13021
Weekly report number	Report-2022-7
Alert submitted by	Denmark
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	14/12/2021

Alert number **[A12/00304/22](#)**

Product **Fireworks**



Risk type **Burns
Fire**

The product leaves smoldering embers just after function. These may start a fire, and a user may get burnt.

The product does not comply with the requirements of the Pyrotechnics Directive nor the European standard EN 15947-5.

Category **Pyrotechnic articles**

Type **Consumer**

Description **36 shot battery**

Packaging description **The product is sold in a package with a coloured background and an illustration of a ship on the front.**

Brand **JORGE Fireworks**

Name **Galeon**

Type / number of model **2463-F2-0235**

Batch number **JW308**

Weekly report number **Report-2022-7**

Alert submitted by **Denmark**

Is the product counterfeit? **No**

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Distributor**

Date of entry into force

06/12/2021

Alert number **[A12/00290/22](#)**

Product **Snowmobile**



Risk type **Fire**

The tank can expel fuel from the vent when the cooling system efficiency is reduced, thereby landing on hot components of the vehicle if flipped on the right side or parked. Fire could occur and, in some situations, cause serious injury, even death and and/or property damages

The product does not comply with the requirements of the Machinery Directive

Category **Machinery**

Type **Professional**

Description **Snowmobile**

Brand **Ski-Doo and Lynx**

Name **Ski-Doo, Lynx**

Type / number of model **models equipped with 900 ACE Turbo engine.**

Batch number **2020 - 2021 - 2022**

Weekly report number **Report-2022-7**

Alert submitted by **Belgium**

Is the product counterfeit? **Unknown**

Country of origin **Canada**

Measures ordered by public authorities **Recall of the product from end users
Distributor**

Date of entry into force **27/01/2022**

Alert number **[A12/00286/22](#)**

Product **Passenger car**

Risk type **Injuries**

The correct deployment of the passenger airbag cannot be guaranteed if the airbag is activated below -15 ° C inside the vehicle. Due to faulty seams in the airbag's protective cover in the dashboard, the component detached from the dashboard may break the windscreen. Glass fragments may damage the airbag, increasing the risk of injuries in the event of an accident.

The product does not comply with the requirements of the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **VW**

Name **Polo**

EC-type approval/model **AW
e1*2007/46*1783***

Production dates **21.8.2020 - 29.10.2020**

Company recall code **70I4**

Weekly report number **Report-2022-7**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **South Africa**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and
measures were taken also in

Croatia
Denmark
France
Ireland
The Netherlands
Slovenia
Sweden



Alert number **[A12/00285/22](#)**

Product **Passenger car**

Risk type **Injuries**

Incorrect tightening torque for the wheel bolts may cause a wheel to detach, leading to a loss of control of the vehicle. This could increase the risk of an accident.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Dodge**

Name **RAM**

EC-type approval/model **Individual approval**

Production dates **26.4.2011 - 21.5.2021**

Company recall code **Y26**

Weekly report number **Report-2022-7**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **The Netherlands**

Alert number **[A12/00307/22](#)**

Product **Motorcycle**

Risk type **Injuries**

When extending the center stand and pushing the seat base handle upwards incorrectly, the threaded insert on one or more of the attachment points may not be securely held. If the handle on the seat base breaks in use in a running vehicle, this may increase the risk of injury.

The product does not comply with the Regulation on the approval and market surveillance of two- or three wheel vehicles and quadricycles.

Category **Motor vehicles**

Type **Consumer**

Description **Motorcycle**

Brand **Harley-Davidson**

Name **Pan America**

EC-type approval/model **e4*168/2013*00131*01, RA1**

Production dates **8.08.2020 - 16.11.2021**

Company recall code **0178**

Weekly report number **Report-2022-7**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Denmark
Sweden**

Alert number **[A12/00284/22](#)**

Product **Passenger car**

Risk type **Injuries**

When the vehicle stops the airbag control unit may deactivate the passenger airbag. This could increase the risk of injury in the event of an accident.

The product does not comply with the requirements of the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **MERCEDES-BENZ**

Name **S Class**

EC-type approval/model **e1*2007/46*2115*01**

Production dates **1.11.2020 - 1.06.2021**

Company recall code **5499009**

Weekly report number **Report-2022-7**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Importer**

Date of entry into force **29/10/2021**

Products were found and
measures were taken also in


Greece
The Netherlands
Poland
Slovenia
Sweden

Alert number

[INFO/00009/22](#)

Product

Jewellery set



Risk type

Chemical

Two parts of the set contain an excessive quantity of cadmium (each 90% by weight). Cadmium is harmful to human health because it accumulates in the body, can damage the kidneys and bones, and it may cause cancer.

The product does not comply with the REACH Regulation.

Category

Jewellery

Type

Consumer

Description

45 piece children's jewellery set for girls with ear clips, rings, necklaces and pendants for crafting. Product sold online, in particular via Amazon.

Packaging description

Individual parts in three pink plastic trays, packaged in transparent plastic foil.

Brand

Tacobear

Name	Kinderschmuck-Set für Mädchen
Weekly report number	Report-2022-7
Alert submitted by	Germany
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Removal of this product listing by the online marketplace Other

Alert number **[INFO/00008/22](#)**

Product **Necklace**



Risk type **Chemical**

The product contains an excessive quantity of cadmium (50% by weight). Cadmium is harmful to human health because it accumulates in the body, can damage the kidneys and bones, and it may cause cancer.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Wolf necklace for men with silver metal alloy chain, an amulet pendant and leather cord. Product sold online, in particular via Amazon.**

Packaging description **Chain packaged in a transparent plastic bag**

Brand **PikaLF**

Name **Wolf-Halskette für Männer**

Weekly report number **Report-2022-7**

Alert submitted by **Germany**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators

Removal of this product listing by the online marketplace
Other

Alert number **[A12/00283/22](#)**

Product **Passenger car**

Risk type **Injuries**

A short circuit may occur in the injector control circuit that could stop the engine and the braking assistance is reduced. Those could increase the risk of injury in the event of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Mazda**

Name **Mazda CX-5 (KE), Mazda 6 (GJ, GL), Mazda 3 (BM, BN)**

EC-type approval/model **e1*2001/116*0262*10 e1*2001/116*0262*11
e1*2001/116*0262*12 e1*2001/116*0262*13
e1*2001/116*0262*14
e1*2001/116*0448*18 e1*2001/116*0448*19
e1*2001/116*0448*20 e1*2001/116*0448*21
e1*2001/116*0448*22 e1*2001/116*0448*23
e1*2001/116*0448*24 e1*2001/116*0448*25
e11*2007/46*1247*01 e1*2001/116*0448*14
e1*2001/116*0448*15 e1*2001/116*0448*16
e1*2001/116*0448*17 e1*2001/116*0448*18
e1*2001/116*0448*19 e1*2001/116*0448*20
e1*2001/116*0448*21 e1*2001/116*0448*22**

Production dates **26.01.2012 - 21.01.2016**

Company recall code **AJ024A
AJ024E**

Weekly report number **Report-2022-7**

Alert submitted by **France**

Is the product counterfeit?	No
Country of origin	Japan
Measures taken by economic operators	Recall of the product from end users Manufacturer
Date of entry into force	10/12/2021
Products were found and measures were taken also in	Germany The Netherlands Slovakia Slovenia Sweden

Alert number **[A12/00291/22](#)**

Product **Passenger car**

Risk type **Fire**

Improperly welded non-return valve on the fuel tank may rupture when the vehicle is in use. This can result in fuel leaks, increasing the risk of fire.

The product does not comply with the requirements of the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Mazda**

Name **Mazda 3**

EC-type approval/model **e11*2001/116*0262*15**

Production dates **1.07.2015 - 18.09.2015**

Company recall code **AG021A**

Weekly report number **Report-2022-7**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **15/12/2021**

Products were found and
measures were taken also in

Croatia
The Netherlands
Slovakia
Slovenia
Sweden



Alert number **[A12/00292/22](#)**

Product **Passenger car**

Risk type **Fire**

Due to possible deformation of the fuel tank, the pipes may not be properly welded onto the tank and this weld may break. A fuel leak may occur, increasing the risk of fire.

The product does not comply with the requirements of the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Mazda**

Name **Mazda 3**

EC-type approval/model **e11*2001/116*0262*14**

Production dates **24.09.2015 - 16.10.2015**

Company recall code **AG020A**

Weekly report number **Report-2022-7**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **15/12/2021**

Products were found and
measures were taken also in

Croatia
The Netherlands
Slovakia
Sweden



Alert number **[A12/00282/22](#)**

Product **Passenger car**

Risk type **Injuries**

Water entering into the ball joint could lead to corrosion, causing the joint to block, so the articulated arm can separate from the lower arm. This may lead to loss of control over the vehicle, increasing the risk of an accident.

The product does not comply with the requirements of the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Professional**

Description **Passenger car**

Brand **Mazda**

Name **CX7**

EC-type approval/model **"e11*2001/116*0308*00 e11*2001/116*0308*01 e11*2001/116*0308*02 e11*2001/116*0308*03 e11*2001/116*0308*04 e11*2001/116*0308*05 e11*2001/116*0308*06 e11*2001/116*0308*07"**

Production dates **8.05.2007 - 7.08.2012**

Company recall code **AG012D**

Weekly report number **Report-2022-7**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force


15/12/2021

Products were found and
measures were taken also in

The Netherlands
Slovakia
Slovenia
Sweden

Alert number **[A11/00031/22](#)**

Product **Varnish**



Risk type **Chemical**

The product's labelling and packaging lack warning indications and have inadequate pictograms. In the absence of hazard statements, the user is not informed that the product contains methylisotiazolinone, which is a skin sensitiser.

The product does not comply with the Classification, Labelling and Packaging (CLP) Regulation.

Category **Chemical products**

Type **Consumer**

Description **Varnish for modelling**

Packaging description **Small round plastic bottle with screw cap**

Brand **MICROSCAL INDUSTRIES**

Name **MICRO GLOSS**

Weekly report number **Report-2022-7**

Alert submitted by **France**

Is the product counterfeit? **Unknown**

Country of origin **United States**

Measures taken by economic operators

**Recall of the product from end users
Retailer**



Alert number

[A12/00293/22](#)

Product

Screw-D-ring for climbing harnesses



TREECORE TRIPLE LOCK



CORE PLUS TRIPLE LOCK



TREECORE TRIPLE LOCK



CORE PLUS TRIPLE LOCK



Risk type

Injuries

The screw placed in the D-ring eyelets of the climbing harness can break, resulting in a fall leading to injuries to the user.

The product does not comply with the Personal Protective Equipment (PPE) Regulation.

Category

Protective equipment

Type

Consumer

Description

Screw-D-ring, either fitted to climbing harnesses or marketed individually.

Brand

Edelrid

Name

Screw-D-Ring to Harnesses

Type / number of model

**CORE PLUS TRIPLE LOCK 88037
CORE SCREW D-SINGLE / CORE SCREW D-KIT 88062 / 88054
RADIALIS PRO 71610**

TRECORE TRIPLE LOCK / CORE SLIDING D_KIT 88036 / 88052

Batch number	From October 2019
Weekly report number	Report-2022-7
Alert submitted by	Germany
Is the product counterfeit?	No
Country of origin	Germany
Measures taken by economic operators	Recall of the product from end users Manufacturer
Date of entry into force	01/02/2022
Measures taken by economic operators	Recall of the product from end users Manufacturer
Date of entry into force	01/02/2022
Company recall code	- https://www.edelrid.de/de/service/recalls/aufruf-zur-nachruestung-von-screw-d-ring-schrauben.php

Alert number **[A12/00281/22](#)**

Product **Passenger car**

Risk type **Injuries**

The latching of the electrical connector of the left acceleration crash sensor onto the cross beam may not be in line with specifications, so the electrical connector of the crash sensor might become detached as a result of vibration while the vehicle is driven or in an accident with multiple impacts. As restraint systems will not be triggered, this could reduce the restraint effect, increasing the risk of injury.

The product does not comply with the requirements of the Regulation on the approval and market surveillance of Motor Vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **MERCEDES-BENZ**

Name **Class C, Class E**

EC-type approval/model **204, R1EC
e1*2001/116*0431*61, e1*2007/46*1666*17 bis *18**

Production dates **28.09.2020 - 28.09.2020**

Company recall code **6192002**

Weekly report number **Report-2022-7**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic **Recall of the product from end users**

operators




Manufacturer

Products were found and
measures were taken also in

The Netherlands

Alert number **[A12/00266/22](#)**

Product **Stacking cups**



Risk type **Suffocation**

The cups are large enough to cover a young child's mouth and nose, and some of the cups lack the necessary openings to allow an inflow of air. A young child may suffocate when placing the product on its mouth and nose.

The product does not comply with the requirements of the Toy Safety Directive nor the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Set of plastic stacking cups in assorted colors for toddlers. Product sold online, in particular via Wish.**

Packaging description **Plastic net packaging with an attached label with Chinese characters, a bar code and a sticker with a product reference.**

Brand **Unknown**

Name	New Baby Kleinkind ungiftige Spielzeuge pädagogische Stapelbecher Random Style
Type / number of model	A F10-C-3 B2089 SI
Barcode	6938560800072
Weekly report number	Report-2022-7
Alert submitted by	Luxembourg
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Removal of this product listing by the online marketplace Other
Date of entry into force	23/11/2021

Alert number **[A11/00027/22](#)**

Product **Glue**



Risk type **Chemical**

The product's labelling and packaging lack warning indications and have inadequate pictograms. In the absence of hazard statements, the user is not informed that the product contains cyclohexane (32.6% by weight), which can cause skin irritation.

The product does not comply with the Classification, Labelling and Packaging (CLP) Regulation.

Category **Chemical products**

Type **Consumer**

Description **Tube of special acrylic and jewellery liquid adhesive. Product sold online, in particular via Amazon.**

Packaging description **Cardboard packaging**

Brand **T9000 - ELEpure"**

Name **Colle Spéciale Acrylique et bijoux bricolage adhésif**

Weekly report number **Report-2022-7**

Alert submitted by **France**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators



**Removal of this product listing by the online marketplace
Other**

Date of entry into force

21/09/2021

Alert number **[A12/00263/22](#)**

Product **Puffer ball with light**



Risk type **Environment**

The solders of the toy contain an excessive amount of lead (measured value up to 13.8 % by weight). Lead poses a risk to the environment.

The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category **Toys**

Type **Consumer**

Description **A battery operated puffer ball made of soft plastic with light. The product is also sold online.**

Packaging description **No packaging**

Brand **Johntoy**

Name **Fluffy stressboll med ljus**

Type / number of model **24295**

Batch number **18-644
24/288**


Barcode **8711866242955**

Weekly report number **Report-2022-7**

Alert submitted by	Sweden
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Withdrawal of the product from the market Retailer
Date of entry into force	08/11/2021

Alert number **[A12/00259/22](#)**

Product **Toy fire fighter helmet**



Risk type **Environment**

The solders of the product contain an excessive amount of lead and cadmium (measured value up to 64.1 and 0.11 % by weight, respectively). Lead and cadmium pose a risk to the environment.

The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category **Toys**

Type **Consumer**

Description **A battery operated toy fire fighter helmet made of hard plastic with sound and light functions. The product is also sold online.**

Packaging description **No packaging**

Brand **Nugar**

Name **Brandmanshjälm med ljus och ljud**

Type / number of model **14963B
8461**

Batch number **1900324**

Barcode **8719905149630**


Weekly report number	Report-2022-7
Alert submitted by	Sweden
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Withdrawal of the product from the market Retailer
Date of entry into force	08/11/2021

Alert number

A12/00264/22

Product

Flying disk toy



Risk type

Environment

The solders of the toy contain an excessive amount of lead (measured value up to 0.19 % by weight). Lead poses a risk to the environment.

The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category

Toys

Type

Consumer

Description

A battery operated flying disk with launcher and light function. The product is also sold online.

Packaging description

Cardboard and transparent plastic.

Brand

Air max

Name

Flying disk launcher

Type / number of model

**26924
7487**

Batch number

20-310

Barcode

8711866269242

Weekly report number

Report-2022-7

Alert submitted by	Sweden
Is the product counterfeit?	No
Country of origin	Unknown
Measures taken by economic operators	Withdrawal of the product from the market Retailer
Date of entry into force	08/11/2021

Alert number **[A12/00280/22](#)**
 Product **Body and face lotion**



Risk type **Chemical**

The product contains hydroxyisohexyl 3-cyclohexene carboxaldehyde (INCI), which is a skin sensitiser and triggers allergic reactions or contact dermatitis.

The product does not comply with the Cosmetic Products Regulation.

Category **Cosmetics**

Type **Consumer**

Description **Body and face lotion containing hydroxyisohexyl 3-cyclohexene carboxaldehyde (Lyral), as declared in the list of ingredients.**

Packaging description **The product is sold in a 150 ml, mostly white, cylindrical container, with a dark green cap. IA label with indications in Swedish was attached over these.**

Brand **ARKO Classic**

Name **Natural Krem Ekstra**

Barcode **86906654**

Weekly report number **Report-2022-7**

Alert submitted by **Sweden**

Is the product counterfeit? **Unknown**

Country of origin

Turkey

Measures taken by economic operators

**Stop of sales
Distributor**

Alert number

[A11/00034/22](#)

Product

Laser engraving machine



Risk type

Damage to sight

The product is not equipped with protective casing, while the protective cap on the laser head always leaves an open gap between the laser head cover and the workpiece when the laser head is at either its highest or lowest possible position. The user's eyes or a bystander may be exposed to the laser when this is reflected by the workpiece, resulting in damages to the eyes.

The product does not comply with the requirements of the Machinery Directive.

Category

Machinery

Type

Consumer

Description

Small laser engraving machine (table frame without protective casing). Product sold online, in particular via Amazon, with ASIN number B08NDG3P66.

Packaging description

Corrugated board box

Brand	Two Trees
Name	Two Trees TT-5.5S / TOTEM S 40W
Type / number of model	TT-5.5S / TOTEM S
Barcode	C03202105220267
Weekly report number	Report-2022-7
Alert submitted by	Germany
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Ban on the marketing of the product and any accompanying measures Other
Date of entry into force	26/01/2022
Measures taken by economic operators	Recall of the product from end users Other
Date of entry into force	01/02/2022

Alert number **[A12/00278/22](#)**

Product **Desk lamp**



Risk type **Electric shock
Fire**

The product is improperly designed and could easily overturn, while the supply cable is not correctly anchored. Furthermore, the accessible basic insulated wires can come into contact with sharp edges, and it is not resistant to fire. The user could consequently touch live parts and receive an electric shock, and the product may start a fire.

The product does not comply with the requirements of the Low Voltage Directive nor European standards EN 60598-1 and EN 60598-2-4.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Green desk lamp for children, plastic construction 220-240 Vac; 50 Hz; max. 24 W E27; IP20 -Protection class II.**

Packaging description **The lamp is packed in a cardboard box.**

Brand **OZCAN**

Type / number of model **6315-15,07**

Barcode **8698522546490**

Weekly report number **Report-2022-7**

Alert submitted by **Croatia**

Is the product counterfeit?

No

Country of origin

Turkey

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

13/10/2021

Alert number **[A12/00262/22](#)**

Product **Office chair**



Risk type **Injuries**

The rolling resistance is too low. The chair can consequently easily overturn, leading to that the user falls and suffers injuries.

The product does not comply with the requirements of the General Product Safety Directive nor the European standard EN 1335-2.

Category **Furniture**

Type **Consumer**

Description **Office chair swivels around a vertical axis, with a soft seat and backrest, with a metal regular five-beam star-shaped base and a gas lift. External dimensions of the chair - width 430 mm, maximum height 1050 mm, height of the base with wheels 170 mm.**

Brand **Unknown**

Name **Office chair PORTO**

Type / number of model **HLM K**

Barcode **2010001054214**

Weekly report number **Report-2022-7**

Alert submitted by **Lithuania**

Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Products were found and measures were taken also in	Slovenia

Alert number

[A11/00033/22](#)

Product

Electric chainsaw



Risk type

**Cuts
Injuries**

The front handle is placed above the motor body and attached directly to the side of the body above the guide axis. This solution causes the lack of the required clearance between the handle and the side of the motor body and makes it impossible to hold the saw securely when it is controlled during horizontal cutting. The user may suffer cuts or injuries.

The product does not comply with the requirements of the Machinery Directive nor with European standard EN 60745-2-13.

Category

Machinery

Type

Consumer

Description

Electric chainsaw.

Packaging description

Cardboard box.

Brand

GARDENX

Name

Elektryczna pilarka lancuchowa

Type / number of model

SF7J153WS-2

Barcode

5901694463711

Weekly report number

Report-2022-7

Alert submitted by	Poland
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Withdrawal of the product from the market Importer
Date of entry into force	24/01/2022

Alert number **[A11/00032/22](#)**

Product **Electric chainsaw**



Risk type **Cuts
Injuries**

The chain catcher is not durable enough. In the event that the chain breaks, the chain catcher could fail, increasing the risk of injury or cuts.

The product does not comply with the requirements of the Machinery Directive nor with European standard EN 60745-2-13.

Category **Machinery**

Type **Consumer**

Description **Electric chainsaw.**

Packaging description **Cardboard box.**

Brand **BESTGREEN PRO**

Name **Pila lancuchowa elektryczna**

Type / number of model **CS 2400-16**

Barcode **3505390998021**

Weekly report number **Report-2022-7**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Manufacturer**

Date of entry into force

14/01/2022

Alert number

A12/00288/22

Product

Electric scooter



Risk type

**Burns
Fire**

The battery does not have a device that monitors the cells temperature. Hence during charging it may overheat, leading to burns or fire.

The product does not comply with the requirements of the Machinery Directive nor with the European standard EN 62133-2.

Category

Machinery

Type

Consumer

Description

Black electric scooter with battery charger with model: GJS150-2940200.

Packaging description

Packaging: brown cardboard box

Brand

MS ENERGY

Name

NEUTRON n1 Electric Scooter

Type / number of model	ES-8-2508 N1
Barcode	3856005173006
Weekly report number	Report-2022-7
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	22/12/2021
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	22/12/2021

Alert number **[A12/00267/22](#)**

Product **Toy set**



Risk type **Choking
Suffocation**

The plastic foil packaging bag is too thin and poses a suffocation risk. In addition, the toy contains small parts (surprise toys). The product lacks the appropriate age warning, therefore a small child could be given the toy, put it in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive nor European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Set of 12 plastic eggs in various colours containing each a surprise toy. Product sold online, in particular via eBay.**

Packaging description **Plastic bag with a zipper.**

Brand **Unknown**

Type / number of model **@2671734@ 07-30 / 191225HS01 RUK39 22268778**

Barcode **191225HS01 RUK39**

Weekly report number **Report-2022-7**

Alert submitted by **Luxembourg**

Is the product counterfeit? **Unknown**

Country of origin	People's Republic of China
Measures taken by economic operators	Removal of this product listing by the online marketplace Other
Date of entry into force	23/11/2021
Measures taken by economic operators	Other : For buyers who bought the toy more than 90 days ago, sellers are asked to warn & organize recall Other
Date of entry into force	23/11/2021
Measures taken by economic operators	Warning consumers of the risks Other
Date of entry into force	23/11/2021

Alert number **[A12/00260/22](#)**

Product **Children's dress**



Risk type **Choking**

The small decorative elements (beads) can easily detach from the dress. A small child may put them in the mouth and choke on them.

The product does not comply with the requirements of the General Product Safety Directive.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **White, sleeveless casual dress for little girls. The product is decorated with beads. Size: 2**

Packaging description **The product was sold without packaging.**

Brand **YanBin**

Type / number of model **A58175**

Barcode **2106160102**

Weekly report number **Report-2022-7**

Alert submitted by **Hungary**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public authorities

**Withdrawal of the product from the market
Other**

Date of entry into force

02/12/2021

Measures taken by economic operators

**Withdrawal of the product from the market
Distributor**

Date of entry into force

02/12/2021

Measures taken by economic operators

**Recall of the product from end users
Distributor**

Date of entry into force

02/12/2021

Alert number **[A12/00301/22](#)**

Product **Pull toy**



Risk type **Strangulation**

The cord of the toy is too long. It may get wrapped around the child's neck and lead to strangulation.

The product does not comply with the requirements of the Toy Safety Directive nor the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **The toy is made of various colored wooden parts of various shapes in the form of a vehicle on wheels and ducks. A red textile drawstring is attached to the toy. Pulling the toy creates a movement of the ducks, which they take out of the bowl.**

Packaging description **Plastic bag with a paper label attached. The product is marked on the affixed paper label with the number P29989, the barcode and the CE marking.**

Brand **Unknown**

Name **Ducks for pulling**

Type / number of model **P29989**

Barcode **8586022429989**

Weekly report number **Report-2022-7**

Alert submitted by	Slovakia
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Stop of sales Importer
Date of entry into force	03/02/2022
Measures taken by economic operators	Recall of the product from end users Importer
Date of entry into force	03/02/2022
Measures taken by economic operators	Warning consumers of the risks Importer
Date of entry into force	03/02/2022

Alert number **[A12/00299/22](#)**

Product **Motorcycle**

Risk type **Injuries**

If driven on the 1st gear and at high RPM, the surface of the resin hose of the oil cooler may over-heat from the radiant heat of the exhaust pipe. The resin hose may crack and engine oil may leak. This may cause a fire, or the oil may adhere to the rear tyre, causing the rider to fall.

The product does not comply with the Regulation on the type-approval and market surveillance of two- or three-wheel vehicles and quadricycles.

Category **Motor vehicles**

Type **Consumer**

Description **Model year: 2020 and 2022; Model code (Type): CBR1000SPL/STL (SC82).**

Brand **Honda**

Name **CBR 1000 SPL/STL**

EC-type approval/model **e4*168/2013*00126*00, e4*168/2013*00126*01**

Production dates **9.12.2019 - 25.10.2021**

Company recall code **3MF**

Weekly report number **Report-2022-7**

Alert submitted by **Portugal**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Importer**

Products were found and **Greece
The Netherlands**

measures were taken also in

Poland
Slovenia
Sweden



Alert number **[A12/00302/22](#)**

Product **Toy slime**



Risk type **Chemical**

The migration of boron from the toy slime is too high (measured value up to 2044 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.

The product does not comply with the requirements of the Toy Safety Directive nor the European standard EN 71-3.

Category **Toys**

Type **Consumer**

Description **Black slime wrapped in a bomb-shaped plastic container with a plastic cap and a textile wick.**

Brand **Unknown**

Name **Bomb - black slime**

Type / number of model **P00837**

Barcode **8586021000837**

Weekly report number **Report-2022-7**

Alert submitted by **Slovakia**

Is the product counterfeit? **Unknown**

Country of origin **Hong Kong**

Measures taken by economic operators **Recall of the product from end users
Distributor**

Date of entry into force **27/01/2022**

Alert number **[A12/00261/22](#)**

Product **Children's shoes**



Risk type **Choking**

The small decorative elements (bow with rhinestones) can easily be detached from the product. A small child may put them in the mouth and choke on them.

The product does not comply with the requirements of the General Product Safety Directive.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Pink shoes with a velcro strap and a bow-shaped decoration with golden rhinestones on it. Size: 22**

Packaging description **Cardboard box**

Brand **CSCK.S**

Name **Children's shoes**

Type / number of model **X-5226**

Weekly report number **Report-2022-7**

Alert submitted by **Hungary**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities

**Withdrawal of the product from the market
Distributor**

Date of entry into force

03/01/2022

Measures ordered by public authorities

**Recall of the product from end users
Distributor**

Date of entry into force

03/01/2022



Alert number **[A12/00295/22](#)**

Product **False nails**



Risk type **Chemical**

According to the list of ingredients, the glue contains dibutyl phthalate (DBP), which use is forbidden in cosmetic products. The phthalate maybe harmful to human health, causing possible damage to the reproductive system or the unborn child.

The product does not comply with the Cosmetic Products Regulation.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Set of plastic nails (12 - 24 pieces) in different designs, supplied with glue in an orange tube.**

Packaging description **Cardboard box.**

Brand **Splendid Nail**

Type / number of model **XS 708**

Weekly report number **Report-2022-7**

Alert submitted by **Romania**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public
authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

09/02/2022

Alert number **[A12/00294/22](#)**

Product **Hair dye**



Risk type **Microbiological**

The product contains an excessive level of aerobic mesophilic bacteria (measured value: 680 000 cfu/g), yeast (measured value: 4000 cfu/g) and mould (measured value: 20 000 cfu/g). If used on damaged skin, or if it comes into contact with the eyes, the product may cause infection or irritation.

The product does not comply with the Cosmetic Products Regulation.

Category **Cosmetics**

Type **Consumer**

Description **Henna-based hair dye powder.**

Packaging description **Powder is packed in a 200 g golden plastic pouch. There is a sketch of a woman with red hair in front of the package.**

Brand **Brite**

Name **Herbal Henna**

Batch number **11
11/2020**

Barcode **890602200016**

Weekly report number **Report-2022-7**

Alert submitted by	Finland
Is the product counterfeit?	Unknown
Country of origin	India
Measures ordered by public authorities	Import rejected at border Importer
Date of entry into force	04/02/2022

Alert number **[A12/00309/22](#)**

Product **swim ring**



Risk type **Chemical**

The plastic material of the product (swim ring and inflation valve) contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP), (measured values: up to 14.62% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Inflatable swim ring with watermelon motif. Size „60“. Intended for children older than 3 years old.**

Packaging description **Plastic bag.**

Brand **Unknown**

Name **SWIM RING**

Batch number **L455**

Barcode **8595500004556**

Weekly report number **Report-2022-7**

Alert submitted by **Czechia**

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

07/02/2022

Alert number **[A12/00296/22](#)**

Product **False nails**



Risk type **Chemical**

According to the list of ingredients, the glue contains dibutyl phthalate (DBP), which use is forbidden in cosmetic products. The phthalate may be harmful to human health, causing possible damage to their reproductive system or the unborn child.

The product does not comply with the Cosmetic Products Regulation.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Set of plastic nails (12 - 24 pieces), supplied with glue in an orange tube.**

Packaging description **Cardboard box.**

Brand **Beauty Secret**

Name **Unghie Finite**

Weekly report number **Report-2022-7**

Alert submitted by **Romania**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public
authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

09/02/2022

Alert number **[A12/00308/22](#)**

Product **Children's cardigan**



Risk type	Strangulation
	The product has cords in the neck area. These cords can become trapped during various activities of a child, leading to strangulation.
	The product does not comply with the requirements of the General Product Safety Directive nor with European standard EN 14682.
Category	Clothing, textiles and fashion items
Type	Consumer
Description	Pink cardigan with cord and pompom in the neck area.
Brand	EAC
Type / number of model	6456
Weekly report number	Report-2022-7
Alert submitted by	Austria
Is the product counterfeit?	Unknown
Country of origin	Turkey
Measures taken by economic operators	Stop of sales Retailer

Alert number **[A12/00300/22](#)**

Product **Plastic ball**



Risk type **Chemical**

The toy contains an excessive amount of diisobutyl phthalate (DIBP) (measured value up to 39,3%). This phthalate may harm the health of children, causing possible damage to their reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Plastic ball.**

Packaging description **Net bag.**

Brand **GAZELO TOYS**

Name **Pilka**

Type / number of model **Z6416-Z6416-3409**

Barcode **5900949428444**

Weekly report number **Report-2022-7**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators


**Withdrawal of the product from the market
Importer**

Date of entry into force

28/10/2021

Alert number **[A12/00298/22](#)**

Product **Plastic toy**



Risk type **Choking
Cuts**

The product has small plastic parts (tentacle, wheels) that can be easily detached. A child may put them in the mouth and choke. The toy has accessible sharp elements (metal axle), which could cause cuts.

The product does not comply with the requirements of the Toy Safety Directive nor with European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Plastic toy.**

Packaging description **No packaging, label attached to the toy.**

Brand **midex**

Name **Zwierzatko**

Type / number of model **D34763**

Barcode **5900733587111**

Weekly report number **Report-2022-7**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators

**Withdrawal of the product from the market
Importer**

Date of entry into force

03/01/2022

Company recall code

- <https://midex.pl/d34763/>

Alert number **[A12/00297/22](#)**

Product **Toy telephone**



Risk type **Damage to hearing**

The sound level pressure is too high (measured value: up to 75.0 dB). This could lead to permanent or temporary hearing loss.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Plastic toy telephone, battery powered.**

Packaging description **Paper box with transparent plastic window.**

Brand **Unknown**

Name **Music Mobile Phone**

Type / number of model **BTEL4092
CY1013-2**

Barcode **5902719714092**

Weekly report number **Report-2022-7**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market
Importer**

Date of entry into force **05/01/2022**

Company recall code - <http://bigtoys.pl/?id=Komunikaty>