
Alert number **[A12/00848/22](#)**

Product **Lighting chains**



Risk type **Electric shock**

The product does not have adequate mechanical strength and insulation. Live parts may easily become accessible and a user may receive an electric shock. Moreover, the product lacks the required labelling and instructions for safe use.

The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598-2-20.

Category **Lighting chains**

Type **Consumer**

Description **LED lighting chain with 8 programs and a mini controller, with CE marking. Product sold online, in particular via eBay.**

Packaging description **Packed in a plastic bag**

Brand **Unknown**

Name **LED lighting chain Ziemassvētku virtene**

Type / number of model **EK-04, EMC, LVD IP44**

Weekly report number **Report-2022-23**

Alert submitted by **Latvia**

Is the product counterfeit?

Unknown

Country of origin

People's Republic of China

Measures taken by economic operators

**Ban on the marketing of the product and any accompanying measures
Other**

Date of entry into force

24/02/2022

Alert number **[A12/00817/22](#)**

Product **Passenger car**

Risk type **Injuries**

The head airbags are improperly installed, which causes an increased risk of injury in the event of an accident.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **DS**

Name **DS4**

EC-type approval/model **F
e2*2007/46*0628*17, e2*2007/46*0628*18**

Production dates **01.03.2022 - 06.04.2022**

Company recall code **JEU**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Poland
Slovenia**

Alert number **[A12/00818/22](#)**

Product **Passenger car**

Risk type **Injuries**

The front seat belt tensioners may be defective. This could lead to improper activation during a collision, increasing the risk of injury to occupants.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **KIA models: Ceed, Ceed Station Wagon (PHEV), Proceed (CD), XCeed (PHEV) (CDCUV), Sorento (PHEV) (MQ4)**

Brand **KIA**

Name **Passenger car**

EC-type approval/model **e4*2007/46*1299*15; e4*2007/46*1299*16**

Production dates **Ceed, Ceed Station Wagon, Proceed, XCeed: 10.11.2021 - 02.02.2022
Sorento: 05.07.2021 - 17.08.2021**

Company recall code **220S14**

Weekly report number **Report-2022-23**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Republic of Korea**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and **France
Portugal**

measures were taken also in **Slovenia**



Alert number **[A12/00847/22](#)**

Product **Lighting chains**



Risk type **Electric shock**

The product does not have adequate mechanical strength and insulation. Live parts may easily become accessible and a user may receive an electric shock. Moreover, the product lacks the required labelling and instructions for safe use.

The product does not comply with the requirements of the Low Voltage Directive, nor with the European standard EN 60598 part 1 and part 2-20.

Category **Lighting chains**

Type **Consumer**

Description **Lighting chain, sold online, in particular via Ali Express.**

Packaging description **Plastic packaging.**

Brand **Unknown**

Name **Christmas Light Ziemassvētku virtenes**

Type / number of model **EK-04**

Weekly report number **Report-2022-23**

Alert submitted by **Latvia**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures taken by economic operators

**Ban on the marketing of the product and any accompanying measures
Other**

Date of entry into force

05/01/2022

Alert number **[A12/00833/22](#)**

Product **Puffer toy**



Risk type **Choking**

Small parts (eyes) can easily detach from the toy. A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Puffer toy in the shape of a stretchy centipede (orange or neon yellow or blue) with eyes.**

Packaging description **No packaging, one label attached.**

Brand **Trendhaus**

Name **Monster Würmer 6-Fach sort.**

Type / number of model **947406**

Batch number **CH26855**

Barcode **4032722947406**

Weekly report number **Report-2022-23**

Alert submitted by **Austria**

Is the product counterfeit?	No
Country of origin	Germany
Measures taken by economic operators	Marking the product with appropriate warnings on the risks Importer
Date of entry into force	25/05/2022
Measures taken by economic operators	Stop of sales Importer
Date of entry into force	25/05/2022
Products were found and measures were taken also in	Lithuania

Alert number **[A12/00831/22](#)**

Product **Passenger car**

Risk type **Injuries**

The locking nut of the steering gear rod may be insufficiently tightened. This may lead to steering loss, increasing the risk of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Fiat**

Name **Fiat 500**

EC-type approval/model **312
e3*2007/46*0064*63-*64**

Production dates **21.03.2022 - 30.03.2022**

Company recall code **6450**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Croatia
The Netherlands
Slovenia**

Alert number **[A12/00829/22](#)**

Product **Passenger car**

Risk type **Injuries**

The locking nut of the steering gear rod may be insufficiently tightened. This may lead to steering loss, increasing the risk of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Abarth**

Name **500 Abarth**

EC-type approval/model **312
e3*2007/46*0064*63-*64**

Production dates **21.03.2022 - 30.03.2022**

Company recall code **6451**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **The Netherlands
Poland**

Alert number **[A12/00827/22](#)**

Product **Passenger car**

Risk type **Injuries**

The locking nut of the steering gear rod may be insufficiently tightened. This may lead to the steering loss, increasing the risk of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Lancia**

Name **Ypsilon**

EC-type approval/model **402
individual approval**

Production dates **21.03.2022 - 30.03.2022**

Company recall code **6452**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **The Netherlands**

Alert number **[A12/00840/22](#)**

Product **Puffer toy**



Risk type **Choking**

Small parts (eyes) can easily detach from the toy. A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Puffer toy in the shape of a stretchy centipede (orange, purple, or green) with eyes, 30 cm long.**

Packaging description **No packaging, one label attached.**

Brand **TEDI**

Name **Stretch Centipede**

Batch number **21-638**

Barcode **55626001241000000200**

Weekly report number **Report-2022-23**

Alert submitted by **Austria**

Is the product counterfeit? **No**

Country of origin	The Netherlands
Measures taken by economic operators	Marking the product with appropriate warnings on the risks Importer
Date of entry into force	25/05/2022
Measures taken by economic operators	Withdrawal of the product from the market Importer
Date of entry into force	25/05/2022
Products were found and measures were taken also in	Croatia

Alert number **[A12/00824/22](#)**

Product **Electric scooter**



Risk type **Injuries**

The cable brake can suddenly break during usage. A user may be unable to stop and suffer injuries.

The product does not comply with the requirements of the Machinery Directive.

Category **Machinery**

Type **Consumer**

Description **Electric scooter with a speed limit of 25km/h.**

Brand **OXELO**

Type / number of model **8577081
SC RIDE 900E**

Barcode **3583784016865**

Weekly report number **Report-2022-23**

Alert submitted by **Romania**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market
Manufacturer**

Measures taken by economic operators

**Recall of the product from end users
Distributor**

Date of entry into force

24/05/2022

Company recall code

- https://www.decathlon.ro/landing/rechemare-produse/_/R-a-rechemare-produse

Products were found and measures were taken also in

**Poland
Portugal**

Alert number **[A12/00838/22](#)**

Product **Battery operated toy**



Risk type **Environment**

The solder contains an excessive amount of lead (measured value up to 65.5% by weight). Lead poses a risk to the environment.

The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).

Category **Toys**

Type **Consumer**

Description **Battery (2 x 1.5 V AA) driven toy in the shape of an iron, for children older than 3 years.**

Packaging description **Cardboard box with transparent window.**

Brand **SPARKYS**

Name **Žehlička**

Type / number of model **28BB-100541**

Barcode **8592525058298**

Weekly report number **Report-2022-23**

Alert submitted by **Czechia**

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Stop of sales
Distributor**

Date of entry into force

12/05/2022

Alert number **[A12/00819/22](#)**

Product **Wet wipes for babies**



Risk type **Chemical**

The product contains propylparaben, which use is forbidden in leave-on products designed for application on the nappy area of children under three years of age. Propylparaben may have an endocrine disrupting activity. The product also contains phenoxyisopropanol, which use is forbidden in leave-on cosmetics.

The product does not comply with the Cosmetic Products Regulation.

Category **Cosmetics**

Type **Consumer**

Description **Wet wipes for babies.**

Packaging description **Blue plastic package with colorful images of a woman and a baby. Each package contains 100 pieces.**

Brand **cotton club**

Name **Wet wipes for babies „AURA ultra comfort“**

Batch number **10.07.21 07 R**

Barcode **4607068626911**

Weekly report number **Report-2022-23**

Alert submitted by **Lithuania**

Is the product counterfeit?

No

Country of origin

Russian Federation

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

26/05/2022

Alert number **[A12/00828/22](#)**

Product **Passenger car**

Risk type **Injuries**

In the event of a collision the two frontal impact sensors may separate. This can affect the deployment of the airbag, increasing the risk of injury.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Kia**

Name **Soul**

EC-type approval/model **PS
e4*2007/46*0825***

Production dates **21.07.2013 - 01.06.2015**

Company recall code **221040**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**


Is the product counterfeit? **No**

Country of origin **Republic of Korea**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Ireland
Poland
Portugal**

Slovenia



Alert number **[A12/00830/22](#)**

Product **Passenger car**

Risk type **Injuries**

Severe corrosion may lead to a leakage of the brake booster, thus reducing the braking force, leading to an increase in brake pedal force required to decelerate the vehicle, resulting in a possible increase in stopping distance. Moreover, due to severe corrosion, a particularly strong or severe braking manoeuvre may cause mechanical damage to the brake booster, preventing the vehicle from decelerating through the service brake and thus increasing the risk of an accident.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Mercedes Benz**

Name **GL, ML, R-Class**

EC-type approval/model **164, 164 G, 251
e1*2001/116*0315*00 - *17, e1*2001/116*0340*00 - *14,
e1*2001/116*0341*00 - *17**

Production dates **14.01.2004 - 31.08.2015**

Company recall code **4290005, 4290006**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators

**Recall of the product from end users
Manufacturer**

Company recall code

- <https://www.mercedes-benz.de>

Products were found and measures were taken also in

**Bulgaria
France
Croatia
The Netherlands
Portugal
Slovakia**

Alert number **[A12/00826/22](#)**

Product **Passenger van/light commercial vehicle**

Risk type **Fire**

The coolant pump, which is controlled via vacuum, may have a leak between the coolant and vacuum circuits so the coolant may enter the vacuum circuit. If the electric switchover valves are exposed to coolant, due to an electrochemical reaction, this can lead to a continuous increase in the temperature of the component part, which could cause fire.

The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van/light commercial vehicle**

Brand **Mercedes-Benz**

Name **Vito, V-Class**

EC-type approval/model **639/2, 639/4, 639/5
e1*2007/46*0457*23-*25, e1*2007/46*0458*20-*22,
e1*2007/46*0459*13-*15**

Production dates **23.11.2020 - 06.11.2021**

Company recall code **VS2KU20MPE**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Spain**

Measures taken by economic operators

**Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in

**France
Poland**

Alert number **[A12/00823/22](#)**

Product **Plastic toy**



Risk type **Choking**

The suction cups detach easily from the projectiles. A child playing with the toy may put the projectile in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Set of plastic toys with gun and projectiles with suction cups.**

Packaging description **Plastic packaging.**

Brand **Unknown**

Name **Game Policemen**

Type / number of model **1014**

Barcode **5902666699282**

Weekly report number **Report-2022-23**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Warning consumers of the risks
Importer**

Date of entry into force **13/05/2022**

Measures ordered by public authorities **Withdrawal of the product from the market
Importer**

Date of entry into force **13/05/2022**

Measures ordered by public authorities **Destruction of the product
Importer**

Date of entry into force **13/05/2022**

Alert number **[A12/00821/22](#)**

Product **Passenger car**

Risk type **Injuries**

The curtain airbag may be improperly fastened. This could lead to that the curtain airbag is not properly deployed in the event of an accident, increasing the risk of injuries.

The product does not comply with the Regulation on the approval and market surveillance of motor Vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car.**

Brand **Opel**

Name **Astra**

EC-type approval/model **F
e2*2007/46*0628*17-*18**

Production dates **10.03.2022 - 27.04.2022**

Company recall code **KA6**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code **- <https://www.opel.de/owners/pruefung-ihres-fahrzeugs-auf-rueckrufaktionen>**

Alert number **[A12/00845/22](#)**

Product **Passenger van/light commercial vehicle**

Risk type **Injuries**

The locking mechanism of the front headrests to the seats may be missing and could eject in the event of a collision, increasing the risk of injury.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van/light commercial vehicle**

Brand **OPEL**

Name **ZAFIRA / VIVARO**

EC-type approval/model **e2*2007/46*0533*19
e2*2007/46*0533*20**

Production dates **16.11.2021 - 16.12.2021**

Company recall code **08F (22-C-061)**

Weekly report number **Report-2022-23**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **11/03/2022**

Products were found and
measures were taken also in

The Netherlands
Poland



Alert number **[A12/00834/22](#)**

Product **Earrings**



Risk type **Chemical**

The pins of the earrings release an excessive amount of nickel (measured values: up to 1.48 µg/cm²/week). Nickel is highly sensitising and may lead to allergic reactions through skin contact.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Gold-coloured earrings with a grooved surface**

Packaging description **The product is sold attached to a printed cardboard.**

Brand **Fashion Jewelry**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **Unknown**

Country of origin **Turkey**

Measures ordered by public authorities **Withdrawal of the product from the market
Retailer**

Alert number **[A12/00822/22](#)**

Product **Hair dryer**



Risk type **Burns
Electric shock
Fire**

The hair dryer does not have a thermal cut-out device. The plastic material of the casing is combustible. The hair dryer can overheat and catch fire during use causing burns to the user. The distance between the heater and the safety grille is less than required. The wire ends are not adequately protected against pulling and twisting. The internal conductor of the mains connection cable, which is too thin, may be broken. The dimensions of the mains plug are substantially less than required. The user could touch accessible live parts, which may cause an electric shock.

The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Black foldable hair dryer.**

Packaging description **Colourful cardboard box**

Brand **LEOVIN**

Name **PROFESSIONAL HAIR DRYER**

Type / number of model **LE-880**

Barcode **6920160008804**

Weekly report number	Report-2022-23
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures ordered by public authorities	Import rejected at border Importer
Date of entry into force	27/05/2022

Alert number **[A12/00835/22](#)**

Product **Earrings**



Risk type **Chemical**

The earrings release an excessive amount of nickel (measured values: up to 14.61 µg/cm²/week) and contain an excessive amount of lead (measured values: up to 64.6%). Nickel is highly sensitising and may lead to allergic reactions through skin contact. Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Gold or silver pendant earrings with a black stone.**

Packaging description **The product is sold attached on a printed cardboard.**

Brand **Azize Accessory**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **Unknown**

Country of origin **Turkey**

Measures ordered by public authorities

**Withdrawal of the product from the market
Retailer**



Alert number **[A12/00837/22](#)**

Product **Toy bow and arrows set**



Risk type **Choking**

The suction cups detach easily from the arrows. A child playing with the toy may put an/the arrow(s) in the mouth and choke with on a/the suction cup(s).

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Toy set consisting of plastic bow and three arrows with suction cups. The cardboard back of the packaging has a target depicted.**

Packaging description **The product is sold in a plastic blister with a colourful cardboard back.**

Brand **GAZELO toys**

Name **Target Game Play Set**

Type / number of model **G137675-3502-7284**

Barcode **5900949424033**

Weekly report number **Report-2022-23**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Importer**

Date of entry into force **28/02/2022**

Measures ordered by public authorities **Warning consumers of the risks
Importer**

Date of entry into force **28/02/2022**

Alert number **[A12/00843/22](#)**

Product **Toy slime**



Risk type **Chemical**

The migration of boron from the toy is too high (measured value up to 1228,7 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive nor with the relevant European standard EN 71-3.

Category **Toys**

Type **Consumer**

Description **Orange toy slime.**

Packaging description **Plastic packaging.**

Brand **midex**

Name **Slime crystal mud**

Type / number of model **D37424**

Barcode **5900733599787**

Weekly report number **Report-2022-23**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Importer**

Date of entry into force **03/03/2022**

Measures ordered by public authorities **Warning consumers of the risks
Importer**

Date of entry into force **03/03/2022**

Measures ordered by public authorities **Destruction of the product
Importer**

Date of entry into force **03/03/2022**

Alert number **[A12/00836/22](#)**

Product **Expandable toy**



Corrigendum **Notification A12/00836/22: at the request of the notifying authority the notification has been updated with additional information on the product identification.**

Risk type **Choking Injuries**

The flamingo figurine expands 50% in size when in contact with water. If child puts it in the mouth or swallows it, the contact with saliva or stomach liquids will cause the figurine to expand, which can result in occlusion of the respiratory track or intestinal blockage.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **An egg (size of 60 mm) containing a flamingo figurine.**

Packaging description **Plastic blister inside paper packaging.**

Brand **Unknown**

Name **Growing pet flamingo**

Type / number of model **BZES7155**

Barcode **5902496133710
5902719707155**

Weekly report number	Report-2022-23
Alert submitted by	Poland
Is the product counterfeit?	Unknown
Country of origin	Unknown
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	11/03/2022
Measures ordered by public authorities	Destruction of the product Importer
Date of entry into force	11/03/2022
Measures ordered by public authorities	Warning consumers of the risks Importer
Date of entry into force	11/03/2022

Alert number **[A12/00844/22](#)**

Product **Toy slime**



Risk type **Chemical**

The migration of boron from the toy is too high (measured value up to 2499,15 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.

Category **Toys**

Type **Consumer**

Description **Set of toy slime in the shape of ice cream.**

Packaging description **Plastic blister with cardboard packaging.**

Brand **Qiaoyi**

Name **Ice Cream Cone DIY Slime**

Type / number of model **D34468**

Barcode **5900733584950**

Weekly report number **Report-2022-23**

Alert submitted by **Poland**

Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Recall of the product from end users Importer
Date of entry into force	11/03/2022
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	11/03/2022
Measures ordered by public authorities	Destruction of the product Importer
Date of entry into force	11/03/2022
Measures ordered by public authorities	Warning consumers of the risks Importer
Date of entry into force	11/03/2022

Alert number **[A12/00842/22](#)**

Product **Toy slime**



Risk type **Chemical**

The migration of boron from the toy is too high (measured value up to 3118,32 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system.

The product does not comply with the requirements of the Toy Safety Directive nor with the relevant European standard EN 71-3.

Category **Toys**

Type **Consumer**

Description **Set of toy slime in colourful plastic packaging in the shape of macarons.**

Packaging description **Plastic blister in a cardboard packaging.**

Brand **Qiaoyi**

Name **Large makaron DIY**

Type / number of model **D34466**

Barcode **5900733584936**

Weekly report number **Report-2022-23**

Alert submitted by **Poland**

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

11/03/2022

Measures ordered by public authorities

**Warning consumers of the risks
Importer**

Date of entry into force

11/03/2022

Measures ordered by public authorities

**Destruction of the product
Importer**

Date of entry into force

11/03/2022

Alert number	<u>A12/00839/22</u>
Product	Telescopic ladder



Risk type	Injuries The horizontal distance between the top rung of the ladder and a wall is less than the minimum required. When climbing the top of the ladder, the user may lose balance and could fall from a considerable height, which can lead to injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN131-6.
Category	Hand tools
Type	Consumer
Description	Telescopic ladder of 2.6 meters.
Packaging description	Red and black cardboard box.
Brand	Diggers Tools
Name	Telescopic ladder 2.6m
Type / number of model	DIGL26
Barcode	5425009851128
Weekly report number	Report-2022-23
Alert submitted by	Belgium

Is the product counterfeit?

No

Country of origin

Unknown

Measures taken by economic operators

**Recall of the product from end users
Manufacturer**

Alert number **[A11/00075/22](#)**

Product **Toy telephone**



Risk type **Damage to hearing**

The sound pressure level is too high (measured value up to 76.2 dB). This could lead to permanent or partial hearing loss when the product is used.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Plastic toy telephone, battery powered.**

Packaging description **Cardboard box with plastic window.**

Brand **HUANGER Happy World**

Name **Phone Touch**

Type / number of model **BTEL0947
HE8001**

Barcode **5902719740947**

Weekly report number **Report-2022-23**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin	People's Republic of China
Measures ordered by public authorities	Warning consumers of the risks Importer
Date of entry into force	28/02/2022
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	28/02/2022

Alert number **[A12/00841/22](#)**

Product **Plastic doll**



Risk type **Chemical**

The toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 19,6% by weight). This phthalate may harm the health of children, possibly causing damage to the reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Plastic doll.**

Packaging description **Plastic blister with cardboard back.**

Brand **Unknown**

Name **Lalka Syrenka**

Type / number of model **HAK 088
NO.ZY88288**

Barcode **2010000004425**

Weekly report number **Report-2022-23**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Importer**


Date of entry into force **25/03/2022**

Measures ordered by public authorities **Destruction of the product
Importer**

Date of entry into force **25/03/2022**

Alert number **[A12/00846/22](#)**

Product **Solder paste**



Risk type **Chemical**

The product contains a high amount of lead. Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children. The product should be used only by, or under the direction of, technically qualified personnel who are aware of the hazards involved and the necessity for reasonable care in handling.

The product does not comply with the REACH regulation.

Category **Chemical products**

Type **Professional**

Description **White translucent cartridge with red lid and stopper containing 600g of soldering paste. The product is also sold online to the general public, in particular via eBay.**

Packaging description **-**

Brand **Kester**

Name **Kester HM531 WS solder paste**

Type / number of model **SN63PB37 T3 / 7010020511**

Batch number **IP101270**

Weekly report number **Report-2022-23**

Alert submitted by	Ireland
Is the product counterfeit?	No
Country of origin	United States
Measures taken by economic operators	Other : Voluntary withdrawal of the product from sale to general public and takedown from eBay processed Retailer
Date of entry into force	31/05/2022

Alert number

[A12/00820/22](#)

Product

Track light



Risk type

Electric shock

The end piece of the track is not properly anchored, hence live parts can easily be accessed. Furthermore, the contact pressure is transmitted through insulating material in the internal connections (phase and protective earth) of the luminaire. Hence, the product is improperly designed and does not adequately protected against electric shock. Finally, the screw connection of the protective earth is not adequately locked against loosening, hence the product could go live. The user could consequently touch live parts and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60598-1 and EN 60570.

Category

Lighting equipment

Type

Consumer

Description

The product consists of a black metal track with five black spotlights. Product sold online.

Brand	Qazqa
Name	Gissi SL 5 black track
Type / number of model	92822
Barcode	8718881046872
Weekly report number	Report-2022-23
Alert submitted by	Sweden
Is the product counterfeit?	Unknown
Country of origin	The Netherlands
Measures taken by economic operators	Stop of sales Manufacturer
Date of entry into force	09/05/2022

Alert number **[A12/00850/22](#)**

Product **Toy whistle**



Risk type **Damage to hearing**

The sound pressure level is too high (measured value up to 121.4 dB). This could lead to permanent or partial hearing loss when the product is used.

The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Yellow, red and white-purple whistles**

Packaging description **The product is suspended on a cord with a label attached.**

Brand **Unknown**

Weekly report number **Report-2022-23**

Alert submitted by **Austria**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Withdrawal of the product from the market
Other**

Date of entry into force **20/05/2022**

Measures taken by economic operators **Destruction of the product
Retailer**

Date of entry into force **20/05/2022**

Alert number **[A12/00849/22](#)**

Product **Toy whistle**



Risk type **Choking
Damage to hearing**

The sound pressure level is too high (measured value up to 123.5 dB). This could lead to permanent or partial hearing loss when the product is used. Moreover, the weather vane can be easily detached. A child may put it in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Whistle (red-blue, white-blue or yellow-white) with weather vane and cockerel or squirrel.**

Packaging description **The product is hanging on a cord with a label attached to it.**

Brand **Unknown**

Weekly report number **Report-2022-23**

Alert submitted by **Austria**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators

**Withdrawal of the product from the market
Other**

Date of entry into force

20/05/2022

Measures taken by economic operators

**Destruction of the product
Distributor**

Date of entry into force

20/05/2022

Alert number **[A12/00816/22](#)**

Product **Passenger car**

Risk type **Injuries**

The thickness of the gas tank walls could be reduced to below the requirements, by corrosion. Gas tanks may burst, increasing the risk of injury.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Touran vehicles for gas operation (CNG)**

Brand **Volkswagen, VW**

Name **Touran**

EC-type approval/model **1T
e1*2001/116*0211***

Production dates **07.09.2005 - 21.05.2015**

Company recall code **20DP**

Weekly report number **Report-2022-23**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **France
Iceland
Slovenia**

Alert number **[A12/00825/22](#)**

Product **Winter jacket**



Risk type **Injuries**

The drawstrings in the waist and on the back of the jacket may become trapped during various activities of a child. This could lead to strangulation or other injuries.

The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14682.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Red winter jacket with hood and zipper, size 4 (18-28). The product has cords with free ends at the waist and on the back.**

Packaging description **The product is sold without packaging.**

Brand **BF&GF Fashion**

Name **Winter jacket for children**

Type / number of model **Size 4, (18 - 28)**

Weekly report number **Report-2022-23**

Alert submitted by **Romania**

Is the product counterfeit? **Unknown**

Country of origin

People's Republic of China

Measures ordered by public
authorities

**Withdrawal of the product from the market
Retailer**

Date of entry into force

24/05/2022