

Alert number **[A11/00092/22](#)**

Product **Fireworks**



Risk type **Burns  
Fire  
Injuries**

**The product may explode at too low altitude and can burst too close to the ground. Bystanders can be hit by parts of the firework, causing burns.**

**The product does not comply with the requirements of the Pyrotechnics Directive nor with the European standard EN 15947-5.**

Category **Pyrotechnic articles**

Type **Consumer**

Description **Battery of 13 shot tubes, (category F2).**

Packaging description **The product is sold wrapped in a black paper background with fireworks depicted.**

Brand **Liyang Pyroshine Fireworks Co. Ltd.**

Name **Big Bang 13 Shots**

Type / number of model **23.1305**

Batch number **21-25010**

Barcode **5704777044179**

Weekly report number **Report-2022-29**

Alert submitted by	<b>Denmark</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>People's Republic of China</b>
Measures taken by economic operators	<b>Recall of the product from end users Importer</b>
Date of entry into force	<b>22/04/2022</b>

Alert number **[INFO/00109/22](#)**

Product **Hair dye**



Risk type **Chemical**

**The product contains 2-nitro-p-phenylenediamine (measured value: 1,6%), which is a strong skin sensitiser.**

**The product does not comply with the Cosmetic Products Regulation.**

Category **Cosmetics**

Type **Consumer**

Description **Hair dye (brown powder). Product also sold online.**

Packaging description **Black plastic bag**

Brand **Neha Herbals**

Name **Herbal color black**

Batch number **NHBL.65**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**

Is the product counterfeit? **Unknown**

Country of origin **India**

Measures ordered by public **Other : Not yet been done**

authorities **Other**



Alert number **[A12/01052/22](#)**

Product **Children's head band**



Risk type **Chemical**

**The battery compartment can be easily opened/broken, leaving the button batteries accessible. A child could put them in the mouth, which could cause damage to the child's gastrointestinal tract.**

**The product does not comply with the requirements of the Toy Safety Directive nor with the relevant European standard EN 62115.**

Category **Toys**

Type **Consumer**

Description **Children's head band in red color with red hearts on top. At the back of the headband, there is a small box which contains button batteries.**

Brand **Unknown**

Name **HAPPY VALENTIN'S DAY**

Type / number of model **PHB-4**

Barcode **0490202000036**

Weekly report number **Report-2022-29**

Alert submitted by **Cyprus**

Is the product counterfeit? **No**

Country of origin

**People's Republic of China**

Measures ordered by public  
authorities

**Withdrawal of the product from the market  
Retailer**

Date of entry into force

**28/02/2022**

Alert number **[A12/01053/22](#)**

Product **Children's head band**



Risk type **Chemical**

**The battery compartment can be easily opened/broken, leaving the button batteries accessible. A child could put them in the mouth, which could cause damage to the child's gastrointestinal tract.**

**The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 62115.**

Category **Toys**

Type **Consumer**

Description **Children's head band in pink color with a big pink bow on top. At the back of the headband, there is a small box which contains button batteries.**

Brand **Unknown**

Name **JUMBO CARNIVAL**

Type / number of model **PHB-1**

Barcode **0478000000038**

Weekly report number **Report-2022-29**

Alert submitted by **Cyprus**

Is the product counterfeit? **No**

Country of origin

**People's Republic of China**

Measures ordered by public  
authorities

**Withdrawal of the product from the market  
Retailer**

Date of entry into force

**28/02/2022**



Alert number **[A12/01041/22](#)**

Product **Skin cream/soap**



Risk type **Chemical**

**According to the list of ingredients, the product contains hydroquinone. Hydroquinone is a skin sensitiser and may cause allergic contact dermatitis.**

**The product does not comply with the Cosmetic Products Regulation.**

Category **Cosmetics**

Type **Consumer**

Description **Lightening beauty cream and lightening beauty soap.**

Packaging description **The cream is sold in white and orange bottles or jars of 30 ml, 50 ml and 120 ml. The soap is sold in a pack of 180 g in a white and orange cardboard box.**

Brand **Dream Cosmetics**

Name **Caro White**

Barcode **6 18100 530094  
6 181100 530063  
6 181100 530070  
6 181100 531008**

Weekly report number **Report-2022-29**

Alert submitted by **Italy**

Is the product counterfeit? **Unknown**

Country of origin **Ivory Coast**

Measures ordered by public authorities **Withdrawal of the product from the market  
Importer**

Date of entry into force **23/03/2022**

Alert number **[A12/01048/22](#)**

Product **Shower mat**



Risk type **Chemical**

**The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 26% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system.**

**The product does not comply with the REACH Regulation.**

Category **Furniture**

Type **Consumer**

Description **Black non-slip shower mat. Product sold online, in particular via Cdiscount**

Packaging description **no packaging**

Brand **Unknown**

Name **Tapis de douche antidérapant noir**

Weekly report number **Report-2022-29**

Alert submitted by **Luxembourg**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public  
authorities

**Ban on the marketing of the product and any  
accompanying measures  
Other**

Date of entry into force

**25/05/2022**

Alert number **[INFO/00107/22](#)**

Product **Visibility vest**



Risk type **Injuries**

**The vest does not have a sufficient retroreflective surface. As a result, the user is not sufficiently visible in situations where high visibility is essential.**

**The product does not comply with the Personal Protective Equipment Regulation nor with the European standard EN 1150.**

Category **Protective equipment**

Type **Consumer**

Description **High visibility yellow waistcoat vest in fluorescent fabric, with one horizontal band of retro-reflective tape around the torso.**

Packaging description **Cardboard card with the product fixed on the bottom of the card.**

Brand **Pure**

Name **Pure reflective vest**

Type / number of model **255583**

Barcode **871940045850**

Weekly report number **Report-2022-29**

Alert submitted by **Iceland**

Is the product counterfeit? **Unknown**

Country of origin **The Netherlands**

Measures taken by economic operators **Stop of sales  
Importer**

Date of entry into force **14/02/2022**

Alert number

**A12/01057/22**

Product

**Children's clothing set**



Risk type

**Strangulation**

**The functional cords close to the neck and in the back area may become trapped during various activities of a child, leading to strangulation.**

**The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14682.**

Category

**Clothing, textiles and fashion items**

Type

**Consumer**

Description

**Girls set of trousers and long sleeve sweatshirt. This set is a velvet outfit made for 6 years old girls.**

Brand

**EMERY KIDS**

Type / number of model

**12-1321**

Barcode

**1213210106**

Weekly report number	<b>Report-2022-29</b>
Alert submitted by	<b>Cyprus</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>Greece</b>
Measures ordered by public authorities	<b>Withdrawal of the product from the market Distributor</b>
Date of entry into force	<b>15/03/2022</b>



Alert number

**[A12/01055/22](#)**

Product

**Children's clothing set**



Risk type

**Injuries**

**The product contains decorative cords that can be tied around the waist. The cords may become trapped during various activities of a child, leading to injuries.**

**The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14682.**

Category

**Clothing, textiles and fashion items**

Type

**Consumer**

Description

**Young girls set of skirt and short sleeve blouse. This floral set is designed for 2 years old girls. The blouse bears long cords with free ends in the waist area.**

Brand

**Fanny Look**

Type / number of model

**7682**

**1032220467682**

Barcode

Weekly report number **Report-2022-29**

Alert submitted by **Cyprus**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market  
Retailer**

Date of entry into force **18/04/2022**

---

Alert number **[A12/01056/22](#)**

Product **Plastic baby doll**

---



Risk type **Chemical**

**The plastic material of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured values: up to 24,44% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system**

**The product does not comply with the REACH Regulation.**

Category **Toys**

Type **Consumer**

Description **A doll in a cardboard with transparent cover.**

Packaging description **Cardboard with transparent cover.**

Brand **KL**

Name **Cute baby doll**

Type / number of model **K688**

Barcode **6900018831280**

Weekly report number **Report-2022-29**

Alert submitted by **Cyprus**

Is the product counterfeit? **Unknown**

Country of origin

**People's Republic of China**

Measures ordered by public  
authorities

**Withdrawal of the product from the market  
Retailer**

Date of entry into force

**02/03/2022**

Alert number **[A12/01054/22](#)**

Product **Plastic dolls**



Risk type **Chemical**

**The head of the three dolls contains up to 32,15% by weight of bis(2-ethylhexyl) phthalate (DEHP). This phthalate may harm the health of children, possibly causing damage to the reproductive system.**

**The product does not comply with the REACH Regulation.**

Category **Toys**

Type **Consumer**

Description **Three dolls in a cardboard with transparent cover.**

Brand **Unknown**

Name **Happy Partner**

Type / number of model **1807973**

Barcode **6900018079736**

Weekly report number **Report-2022-29**

Alert submitted by **Cyprus**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public  
authorities


**Withdrawal of the product from the market  
Importer**

Date of entry into force

**03/02/2022**

Alert number **[A12/01040/22](#)**

Product **Wood saw blade for angle grinder**



Risk type **Cuts**

**The circular saw blade may be mounted on an angle grinder and could therefore, against its intended use, be used as a hand-held circular saw. As a consequence, this could cause kickback or loss of control over the tool, resulting in injuries.**

**The product does not comply with the requirements of the Machinery Directive nor with the European standard EN 60745-2-3.**

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Saw blade for wood, with a diameter of 125 mm, advertised for use with angle grinders. Product sold online, in particular via eBay.**

Brand **speedcutter**

Name **Kreissägeblatt für Winkelschleifer beworben**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators

**Other : The platform operator has stopped supplying/displaying the article.  
Other**

Date of entry into force


**06/04/2022**



Alert number

[\*\*A12/01039/22\*\*](#)

Product

**Chainsaw attachment**

Risk type

**Cuts**

**The chainsaw attachment may be mounted on an angle grinder and could therefore, against its intended use, be used as a hand-held circular saw. As a consequence, this could cause kickback or loss of control over the tool, resulting in injuries.**

**The product does not comply with the requirements of the Machinery Directive nor with the European standard EN 60745-2-3.**

Category

**Electrical appliances and equipment**

Type

**Consumer**

Description

**Chainsaw attachment as an accessory for angle grinders; 1 500 watts, 12 inch. Product sold online, in particular via eBay.**

Brand

**Unknown**

Name

**CHAIN SAW 12", Kettensägeblatt für Winkelschleifer beworben**

Weekly report number

**Report-2022-29**

Alert submitted by

**Germany**

Is the product counterfeit?

**Unknown**

Country of origin

**People's Republic of China**

Measures taken by economic operators


**Removal of this product listing by the online marketplace  
Other**

Date of entry into force

**06/04/2022**

Alert number **[A12/01038/22](#)**

Product **Circular saw blade**



Risk type	<b>Cuts</b>
	<b>The circular saw blade may be mounted on an angle grinder and could therefore, against its intended use, be used as a hand-held circular saw. As a consequence, this could cause kickback or loss of control over the tool, resulting in injuries.</b>
	<b>The product does not comply with the requirements of the Machinery Directive nor with the European standard EN 60745-2-3.</b>
Category	<b>Electrical appliances and equipment</b>
Type	<b>Consumer</b>
Description	<b>125 mm chainsaw blade with a bore of 22 mm for mounting on an angle grinder. Product sold online, in particular via eBay</b>
Brand	<b>Unknown</b>
Name	<b>Kettensägeblatt 125 mm für Winkelschleifer beworben</b>
Weekly report number	<b>Report-2022-29</b>
Alert submitted by	<b>Germany</b>
Is the product counterfeit?	<b>Unknown</b>
Country of origin	<b>Germany</b>

Measures taken by economic operators

**Removal of this product listing by the online marketplace  
Other**

Date of entry into force



**22/10/2018**

Alert number

**[A12/01037/22](#)**

Product

**Circular saw blade**



Risk type

**Cuts**

**The circular saw blade may be mounted on an angle grinder and could therefore, against its intended use, be used as a hand-held circular saw. As a consequence, this could cause kickback or loss of control over the tool, resulting in injuries.**

**The product does not comply with the requirements of the Machinery Directive nor with the European standard EN 60745-2-3.**

Category

**Electrical appliances and equipment**

Type

**Consumer**

Description

**125 mm chainsaw blade with a bore of 22 mm for mounting on an angle grinder. Product sold online, in particular via eBay.**

Brand

**Unknown**

Name

**Kettensägeblatt 125 mm für Winkelschleifer beworben/FT12514**

Weekly report number

**Report-2022-29**

Alert submitted by

**Germany**

Is the product counterfeit?

**Unknown**

Country of origin

**Germany**

Measures taken by economic operators

**Removal of this product listing by the online marketplace  
Other**

Date of entry into force

**22/10/2022**

Alert number **[A12/01064/22](#)**

Product **Disposable electronic cigarette**

Risk type **Chemical**

**This product contains 14ml of nicotine-containing liquid (maximum permitted volume is 2ml). It also lacks the required information leaflet allowing the consumer to make informed choices regarding the safe use of the product. Nicotine is acutely toxic in high concentrations or volumes and can endanger the user's safety, notably if the product comes into contact with the skin or is ingested.**

**The product does not comply with the requirements of the Tobacco Products Directive.**

Category **Chemical products**

Type **Consumer**

Description **Aroma King 7000 20mg/ml, volume 14ml Disposable electronic cigarette.**

Packaging description **Rectangular box in various colours depending on the flavour.**

Brand **Aroma King**

Name **Aroma King 7000 2% NIC Salt (20mg/ml nicotine) 14ml**

Type / number of model **Flavourings: Mixed Berries, Strawberry Watermelon, Blueberry Pomegranate, Cool Mint, Banana Ice, Pina Colada Rum, Blueberry Bubblegum, Strawberry Donut, Blueberry on Ice, Grape Ice, Apple Peach Pear, Pineapple Ice, Lush Ice, Mr. Blue, Pink Lemonade, Cotton Candy, Strawberry Ice, Gummy Bear, Strawberry Banana, Blue Sour Raspberry**

Weekly report number **Report-2022-29**

Alert submitted by **Ireland**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public  
authorities

**Withdrawal of the product from the market  
Importer**

Date of entry into force

**25/05/2022**



---

Alert number **[A12/01036/22](#)**

Product **Passenger car**

---

Risk type **Injuries**

**The front seat belt tensioners may be defective. This could lead to improper activation during a collision, increasing the risk of injury to occupants.**

**The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **HYUNDAI**

Name **i30**

EC-type approval/model **PDE  
e5\*2007/46\*1075**

Production dates **25.5.2020 - 6.10.2020**

Company recall code **11DC45**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Republic of Korea**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Company recall code **- <http://www.hyundai.de/>**

Products were found and **The Netherlands**

measures were taken also in **Poland**



Alert number

**[A12/01035/22](#)**

Product

**Vehicle part / Replacement wheels**

Risk type

**Injuries**

**Insufficient structural durability can lead to the formation of structural cracks and fractures in the spokes and at the base of the rim and may cause the wheel to break. This leads to loss of control over the vehicle equipped with the those wheels, increasing the risk of an accident.**

**The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category

**Motor vehicles**

Type

**Consumer**

Description

**Special wheels for passenger cars.**

Brand

**D-CARS Performance GmbH**

Name

**ROOKIE 10520**

EC-type approval/model

**KBA 53510  
ROOKIE 10520**

Production dates

**1.03.2020 - 30.11.2020**

Weekly report number

**Report-2022-29**

Alert submitted by

**Germany**

Is the product counterfeit?

**No**

Country of origin

**People's Republic of China**

Measures taken by economic operators

**Recall of the product from end users  
Manufacturer**

Alert number **[A12/01049/22](#)**

Product **Plush Toy**



Risk type **Choking**

**Small parts (eyes) can easily detach from the toy. Small children may put them in the mouth and choke.**

**The product does not comply with the requirements of the Toy Safety Directive.**

Category **Toys**

Type **Consumer**

Description **Stuffed animals/plush pink and blue toys. The product is only sold in the gift shops of the theme park (Toverland).**

Packaging description **The product is labeled.**

Brand **Toverland**

Name **Dwervelknuffel**

Type / number of model **"Dwervelknuffels" pink and blue**

Batch number **21-TL-20**

Weekly report number **Report-2022-29**

Alert submitted by **The Netherlands**

Is the product counterfeit? **No**

Country of origin

**People's Republic of China**

Measures taken by economic operators

**Recall of the product from end users  
Distributor**

Date of entry into force

**15/06/2022**

Company recall code

- <https://www.toverland.com/attractiepark/terugroepactie-dwerveknuffels>

Alert number **[A12/01062/22](#)**

Product **Pickup truck/light commercial vehicle**

Risk type **Injuries**

**The side airbag inflatable curtain inflator may break due to internal corrosion and may deploy spontaneously in the absence of an accident or commanded deployment. As a result, the metal fragments may pass through the cushion material causing injury to the occupants.**

**The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Pickup truck/light commercial vehicle**

Brand **Dodge**

Name **RAM: 1500 Pickup, 2500 Pickup, 3500 Pickup, 3500 10K LB Cab, RAM Truck**

EC-type approval/model **Individual approvals**

Production dates **09.04.2015 - 03.11.2015**

Company recall code **Y55**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**


Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Products were found and  
measures were taken also in

## **The Netherlands**





Alert number **[A12/01034/22](#)**

Product **Pickup truck/light commercial vehicle**

Risk type **Injuries**

**The side airbag inflatable curtain inflator may break due to internal corrosion and may deploy spontaneously in the absence of an accident or commanded deployment. As a result, the metal fragments may pass through the cushion material causing injury to the occupants.**

**The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Pickup truck/light commercial vehicle**

Brand **Dodge**

Name **RAM: 1500 Pickup, 2500 Pickup, 3500 Pickup, 3500 10K LB Cab, RAM Truck**

EC-type approval/model **Individual approval**

Production dates **27.03.2015 - 31.08.2020**

Company recall code **Y63**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**


Is the product counterfeit? **No**

Country of origin **United States**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Products were found and  
measures were taken also in

## **The Netherlands**



---

Alert number **[A12/01042/22](#)**

Product **Passenger car**

---

Risk type **Fire  
Injuries**

**The controllable coolant pump may have a leak between the coolant and vacuum circuit via negative pressure and allow coolant to enter it. If the electric switchover valves are exposed to coolant, a continuous increase in the component part temperature may occur and cause fire. In addition, the brake booster may become damaged over time and reduce brake performance that could lead to an accident.**

**The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Mercedes-Benz**

Name **Vito, V-Class**

EC-type approval/model **639/2, 639/4, 639/5  
e1\*2007/46\*0457\*21-\*25, e1\*2007/46\*458\*14, \*20-\*22,  
e1\*2007/46\*0459\*13-\*15**

Production dates **16.01.2019 - 13.11.2021**

Company recall code **VS2KUMIPU**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Spain**

Measures taken by economic operators

Products were found and measures were taken also in

**Recall of the product from end users  
Manufacturer**

**France  
Greece  
Croatia  
The Netherlands**

Alert number **[A12/01060/22](#)**

Product **Scuba-diving compressor**



Risk type **Electric shock  
Fire**

**The pins of the water-pump power socket (live parts) are accessible. A user could touch them and receive an electric shock. Moreover, the product is lacking a sensing device on the cooling system which could trigger an appropriate response from the control unit. This could increase the risk of fire.**

**The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60204-1.**

Category **Machinery**

Type **Consumer**

Description **Blue high-pressure mini compressor for filling mini scuba-diving tanks with air.**

Packaging description **Cardboard packaging.**

Brand **MiniDive**

Name **Minicomp**

Type / number of model **YH-QB01**

Barcode **3770008734159**

Weekly report number **Report-2022-29**

Alert submitted by	<b>France</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>People's Republic of China</b>
Measures taken by economic operators	<b>Withdrawal of the product from the market Importer</b>
Measures taken by economic operators	<b>Recall of the product from end users Importer</b>
Date of entry into force	<b>07/06/2022</b>
Company recall code	- <a href="https://rappel.conso.gouv.fr/fiche-rappel//7226/interne">https://rappel.conso.gouv.fr/fiche-rappel//7226/interne</a>

---

Alert number **[A12/01059/22](#)**

Product **Passenger car**

---

Risk type **Injuries**

**A malfunction in the electrical shift control unit can cause the parking lock to be released. As a result, the vehicle can roll away when parked, increasing the risk of injury.**

**The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Hyundai**

Name **IONIQ 5 (NE EV)**

EC-type approval/model **e9\*2018/858\*11054\*  
NE**

Production dates **10.09.2020 - 03.05.2022**

Company recall code **21D064**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Republic of Korea**


Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Company recall code **- <https://www.hyundai.de/>**

Products were found and **Denmark**

measures were taken also in

**Estonia**  
**France**  
**The Netherlands**  
**Poland**  
**Romania**  
**Slovenia**





Alert number

**[A12/01043/22](#)**

Product

**Particle filter mask**



Risk type

**Health risk / other**

**The particle/filter retention of the material is insufficient (measured values: as low as 77%). Consequently, the product does not fulfil the health and safety requirements; thus, even if combined with other recommended measures, it may not properly protect.**

**The product does not comply with the Personal Protective Equipment Regulation nor with the European standard EN 149.**

Category

**Protective equipment**

Type

**Consumer**

Description

**Masks in black (6), grey (6), red (6), light blue (6) and dark blue (6), with the indication FFP2 and the CE marking printed on it. Each mask is individually packaged. Product sold online, in particular via Amazon.**

Packaging description

**Each mask is individually packaged, then sold in a cardboard box containing 30 masks, marked with FFP2.**

Brand	<b>HUHETA</b>
Type / number of model	<b>NQX-2001</b>
Batch number	<b>20220210</b>
Weekly report number	<b>Report-2022-29</b>
Alert submitted by	<b>Germany</b>
Is the product counterfeit?	<b>Unknown</b>
Country of origin	<b>People's Republic of China</b>
Measures taken by economic operators	<b>Removal of this product listing by the online marketplace Other</b>

Alert number **[A12/01051/22](#)**

Product **Puffer toy**



Risk type **Choking**

**Small parts (the bow and the arms) can easily detach from the toy. A small child may put them in the mouth and choke.**

**The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.**

Category **Toys**

Type **Consumer**

Description **Orange puffer bear with moulded face, bow and short ribbon with loop and light inside.**

Packaging description **None**

Brand **Fluffy Bär Flashing**

Barcode **8590004134587**

Weekly report number **Report-2022-29**

Alert submitted by **Austria**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures taken by economic operators

**Destruction of the product  
Retailer**

Date of entry into force

**06/07/2022**

Alert number

**[A12/01044/22](#)**

Product

**Children's bikini**



Risk type

**Injuries**

**The product bears cords with free ends that can become trapped, during various activities of a child, leading to injury.**

**The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14682.**

Category

**Clothing, textiles and fashion items**

Type

**Consumer**

Description

**Bikini bathing suit set in pink colour, intended for 9-10 years old girls. The top part bears functional cords with free ends to be tied at the back.**

Brand

**YES! DO KID'S**

Type / number of model

**A-9106**

Weekly report number	<b>Report-2022-29</b>
Alert submitted by	<b>Cyprus</b>
Is the product counterfeit?	<b>Unknown</b>
Country of origin	<b>People's Republic of China</b>
Measures ordered by public authorities	<b>Withdrawal of the product from the market Retailer</b>
Date of entry into force	<b>05/07/2022</b>

Alert number **[A12/01045/22](#)**

Product **Children's bikini**



Risk type **Injuries**

**The product has functional cords with free ends to be tied around the back area. The cords may become trapped during various activities of a child, leading to injuries.**

**The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14682.**

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Children's bikini bathing suit set, intended for 9-10 years old girls.**

Brand **YES! DO KID'S**

Type / number of model **A-9096**

Weekly report number **Report-2022-29**

Alert submitted by **Cyprus**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market  
Retailer**

Date of entry into force **05/07/2022**





Alert number **[A11/00093/22](#)**

Product **Fireworks**



Risk type **Burns**

**When the article is ignited, burning or incandescent material may fall to the ground at more than 1 meter distance. As a consequence, the user may suffer burns.**

**The product does not comply with the requirements of the Pyrotechnics Directive nor with the European standard EN 15947-5.**

Category **Pyrotechnic articles**

Type **Consumer**

Description **Category F1 handheld sparkler in different red, white and dark red colours. Product sold online.**

Packaging description **Red and white packaging with sparkles from sparklers**

Brand **DEKORA**

Name **Bengalas Palillo 17 cm**

Type / number of model **316003**

Batch number **20524701**

Barcode **8435599746701**

Weekly report number **Report-2022-29**

Alert submitted by	<b>Denmark</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>Spain</b>
Measures taken by economic operators	<b>Withdrawal of the product from the market Retailer</b>
Date of entry into force	<b>06/07/2022</b>

Alert number **[INFO/00110/22](#)**

Product **Earrings**



Risk type **Chemical**

**The product contains an excessive amount of cadmium (measured value 0,0143 % by weight ). Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer.**

**The product does not comply with the REACH Regulation.**

Category **Jewellery**

Type **Consumer**

Description **Earrings in different shapes of brown colour with different colour patterns fixed on one paper pad.**

Brand **Unknown**

Name **La Tienda del Colombiano**

Weekly report number **Report-2022-29**

Alert submitted by **Slovakia**

Is the product counterfeit? **No**

Country of origin **Peru**

Measures ordered by public authorities **Import rejected at border  
Importer**

Date of entry into force **06/06/2022**



Alert number **[A12/01047/22](#)**

Product **Earrings**



Risk type **Chemical**

**The product contains an excessive amount of cadmium (measured value 0,016 % by weight ). Cadmium is harmful to human health, because it accumulates in the body and can damage organs and it may cause cancer. The product contains an excessive amount of lead (measured value 15,78 % by weight). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children. The product releases an excessive amount of nickel (measured value 0,2783 µg/cm<sup>2</sup>/week). Nickel is a strong sensitizer and can cause various allergic reactions if it occurs in objects that come into direct and prolonged contact with the skin.**

**The product does not comply with the REACH Regulation.**

Category **Jewellery**

Type **Consumer**

Description **Gold-coloured hanging earrings, consisting of a flat circle on which hangs a teardrop decorated with rhinestones with a plastic stand with the following information: Zirconia JVYN, JY logo, price and product code.**

Brand **Unknown**

Name **Zirconia JVYS**

Weekly report number **Report-2022-29**

Alert submitted by	<b>Slovakia</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>Unknown</b>
Measures taken by economic operators	<b>Warning consumers of the risks Retailer</b>
Date of entry into force	<b>27/06/2022</b>
Measures taken by economic operators	<b>Stop of sales Retailer</b>
Date of entry into force	<b>27/06/2022</b>

Alert number **[A12/01046/22](#)**

Product **Earrings**



Risk type **Chemical**

**The product releases an excessive amount of nickel (measured value up to 1,4 µg/cm<sup>2</sup>/week). Nickel is a strong sensitizer and causes allergic reactions if present in articles that come into direct and prolonged contact with the skin.**

**The product does not comply with the REACH Regulation.**

Category **Jewellery**

Type **Consumer**

Description **Earrings in the shape of a gold-coloured circle with a diameter of approx. 1,40 cm and pebbles in the front part. The product is offered to consumers on a plastic stand.**

Brand **Unknown**

Name **Groove earrings with rhinestones in the shape of a circle, gold**

Type / number of model **2481**

Barcode **6925510276582**

Weekly report number **Report-2022-29**

Alert submitted by **Slovakia**

Is the product counterfeit?

**No**

Country of origin

**People's Republic of China**

Measures taken by economic operators

**Stop of sales  
Retailer**

Date of entry into force

**29/06/2022**

Measures taken by economic operators

**Warning consumers of the risks  
Retailer**

Date of entry into force

**29/06/2022**



Alert number

**[A12/01069/22](#)**

Product

**Cleaning and degreasing agent**

Risk type

**Chemical**

**The product is extremely alkaline (measured pH value > 12.8) and corrosive but lacks the appropriate precautionary statements and a child-resistant fastening, required for these kind of products. Users have therefore no information on the dangers incurred when the product comes into contact with the skin and eyes or if it is ingested.**

**The product does not comply with the Regulation on the classification, labelling and packaging of substances and mixtures (CLP).**

Category

**Chemical products**

Type

**Consumer**

Description

**Cleaning and degreasing spray**

Packaging description

**500 ml spray**

Brand

**Lynx expert**

Name

**Nettoyant dégraissant superpuissant spécial barbecue et plancha**

Barcode

**3701159001906**

Weekly report number

**Report-2022-29**

Alert submitted by

**France**

Is the product counterfeit? **No**

Country of origin **Poland**

Measures taken by economic operators **Withdrawal of the product from the market  
Importer**

Date of entry into force **13/06/2022**

Measures taken by economic operators **Recall of the product from end users  
Importer**

Date of entry into force **13/06/2022**

Company recall code - <https://rappel.conso.gouv.fr/fiche-rappel//7329/interne>

---

Alert number **[A12/01068/22](#)**

Product **Descaler**

---



Risk type **Chemical**

**The product is extremely acid (measured pH value = 0.75) and corrosive but lacks the appropriate precautionary statements and a child-resistant fastening, required for these kind of products. Users have therefore no information on the dangers incurred when the product comes into contact with the skin and eyes or if it is ingested.**

**The product does not comply with the Regulation on the classification, labelling and packaging of substances and mixtures (CLP).**

Category **Chemical products**

Type **Consumer**

Description **Descaler spray**

Packaging description **500 ml spray**

Brand **Lynx expert**

Name **Détartrant surpuissant - salle de bain, cuisine**

Barcode **3701159001906**

Weekly report number **Report-2022-29**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Poland**

Measures taken by economic operators **Withdrawal of the product from the market  
Importer**

Date of entry into force **14/06/2022**

Measures taken by economic operators **Recall of the product from end users  
Importer**

Date of entry into force **17/07/2022**

Company recall code - <https://rappel.conso.gouv.fr/fiche-rappel//7330/interne>

Alert number

**[A12/01067/22](#)**

Product

**Cleaning and degreasing agent**

Risk type

**Chemical**

**The product is extremely alkaline (measured pH value > 12.6) and corrosive but lacks the appropriate precautionary statements and a child-resistant fastening, required for these kind of products. Users have therefore no information on the dangers incurred when the product comes into contact with the skin and eyes or if it is ingested.**

**The product does not comply with the Regulation on classification, labelling and packaging of substances and mixtures (CLP).**

Category

**Chemical products**

Type

**Consumer**

Description

**Cleaning and degreasing spray**

Packaging description

**500 ml spray**

Brand

**Lynx expert**

Name

**Nettoyant dégraissant multi-usages extrême**

Barcode

**3701159001920**

Weekly report number

**Report-2022-29**

Alert submitted by

**France**

Is the product counterfeit? **No**

Country of origin **Poland**

Measures taken by economic operators **Recall of the product from end users  
Importer**

Date of entry into force **14/06/2022**

Measures taken by economic operators **Withdrawal of the product from the market  
Importer**

Date of entry into force **13/06/2022**

Company recall code - <https://rappel.conso.gouv.fr/fiche-rappel//7332/interne>

Alert number **[A11/00091/22](#)**

Product **Fireworks**



Risk type **Burns**

**When the ground spinner is ignited, it may move too far away from its initial position and laterally projects debris for more than 1 m. As a consequence, bystanders can be hit by parts of the debris and suffer burns.**

**The product does not comply with the requirements of the Pyrotechnics Directive nor with the European standard EN 15947-5.**

Category **Pyrotechnic articles**

Type **Consumer**

Description **Ground Spinner in the shape of a blue cylinder with green fuse (Category F1)**

Packaging description **Blue package with animation of a rocket**

Brand **Jorge Fireworks**

Name **Kolorowe Zwariowane**

Type / number of model **JM04-CL**

Barcode **5901583640049**

Weekly report number **Report-2022-29**

Alert submitted by **Denmark**

Is the product counterfeit? **No**

Country of origin **Poland**

Measures ordered by public authorities **Stop of sales  
Retailer**

Date of entry into force **08/07/2022**



Alert number **[A12/01058/22](#)**

Product **Battery pack**



lithium pack rcB 1200 insole  
 Model: LZ Type 030  
 7.4V 1200mAh 8.88Wh  
 2/CP7/34/48



Lenz Ges.m.b.H.  
 Staudachstrasse 3  
 6868 Schwarzach, Austria  
 www.lenzproducts.com



**USE OF THIS DEVICE MAY CAUSE BURNS!**  
**PLEASE READ THE INSTRUCTIONS CAREFULLY**

Risk type **Burns**

**The faulty electrical insulation may result in a thermal reaction during the charging process. The battery may self-ignite posing a risk of burns.**

**The product does not comply with the requirements of General Product Safety Directive.**

Category **Electrical appliances and equipment**

Type **Consumer**

Description **Battery pack for heatable products.**

Brand **LENZ**

Name **lithium pack rcB 1200 insole**

Type / number of model **LZ Type 030**

Weekly report number **Report-2022-29**

Alert submitted by **Austria**


Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures taken by economic operators **Recall of the product from end users  
Importer**

Products were found and  
measures were taken also in

**Ireland**



Alert number **[A12/01065/22](#)**

Product **Lighting chain**



Risk type **Chemical**

**The product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 0,17 %). This phthalate may harm the health of children, causing possible damage to their reproductive system.**

**The product does not comply with the REACH Regulation.**

Category **Decorative articles**

Type **Consumer**

Description **Lighting chain with 10 warm white LED in the shape of watermelons. Product also sold online.**

Packaging description **Plastic box**

Brand **ROXAN**

Name **Guirlande lumineuse "Pastèque"**

Type / number of model **22900**

Batch number **260024**

Barcode **4029811364053**

Weekly report number **Report-2022-29**

Alert submitted by **Luxembourg**

Is the product counterfeit?

**Unknown**

Country of origin

**People's Republic of China**

Measures ordered by public authorities

**Ban on the marketing of the product and any accompanying measures  
Other**

Date of entry into force

**24/03/2022**

Measures taken by economic operators

**Recall of the product from end users  
Distributor**

Date of entry into force

**24/03/2022**

Alert number

**[A12/01063/22](#)**

Product

**Battery operated toy**



Risk type

**Environment**

**The solder joint in the toy has an excessive concentration of lead (measured value up to 63.9 % by weight). Lead poses a risk to the environment.**

**The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).**

Category

**Toys**

Type

**Consumer**

Description

**Electronic children's game with digital display, buttons and with case for 2 x AA 1.5 V batteries. The toy is not suitable for children under 3 years of age.**

Packaging description

**Paper box**

Brand

**Unknown**

Name

**Dětská hra Brick Game 9999**

Type / number of model

**E-9999**

Batch number

**HA1512**

Barcode

**8416387017876**

Weekly report number

**Report-2022-29**

Alert submitted by	<b>Czechia</b>
Is the product counterfeit?	<b>Unknown</b>
Country of origin	<b>People's Republic of China</b>
Measures ordered by public authorities	<b>Withdrawal of the product from the market Retailer</b>
Date of entry into force	<b>22/06/2022</b>

Alert number **[A12/01079/22](#)**

Product **Magnetic balls**



Risk type	<p><b>Injuries</b></p> <p><b>The toy is made of small parts (balls) with a high magnetic flux. If a child swallows them, they could attract one another causing intestinal blockage or perforation.</b></p> <p><b>The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.</b></p>
Category	<b>Toys</b>
Type	<b>Consumer</b>
Description	<b>Ball cube consisting of 216 magnetic balls with a size of 3 mm each, with 36 balls per side; all the balls are attracted to each other by magnetic force. The product is sold online.</b>
Packaging description	<b>The product folded into a cube shape is wrapped in plastic film and placed in a foam case. This case is placed in a tin box with a lid, in the middle of which there is a transparent window so that the toy inside can be clearly seen.</b>
Brand	<b>Unknown</b>
Name	<b>Magnetické kuličky Neocube 3mm, 216 ks</b>
Weekly report number	<b>Report-2022-29</b>
Alert submitted by	<b>Czechia</b>
Is the product counterfeit?	<b>No</b>

Country of origin

**People's Republic of China**

Measures ordered by public  
authorities

**Withdrawal of the product from the market  
Retailer**

Date of entry into force

**22/06/2022**



---

Alert number **[A12/01050/22](#)**

Product **Passenger car**

---

Risk type **Injuries**

**The top cover of the trunk spoiler may get loose due to assembly issues and adhesive failures. This can lead to the spoiler detaching from the main body of the trunk spoiler and fall onto the road, increasing the risk of an accident.**

**The product does not comply with the requirements laid down in the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car, affected cars belong to the cars with “Range Rover Sport Non-Autobiography” specifications.**

Brand **Land Rover**

Name **Range Rover Sport**

EC-type approval/model **LS  
e11\*2001/116\*0243\***

Production dates **20.05.2009 - 28.03.2011**

Company recall code **N700**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **United Kingdom**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

**The Netherlands**

Products were found and  
measures were taken also in



---

Alert number **[A12/01061/22](#)**

Product **Personal watercraft**

---

Risk type **Drowning  
Injuries**

**The passenger seat is not adequately latched to the watercraft. As a result it could inadvertently unlatch, causing the passenger to unexpectedly fall in the water, increasing the risk of injuries or drowning.**

**The product does not comply with the requirements of the Recreational Craft and Personal Watercraft Directive.**

Category **Recreational crafts**

Type **Consumer**

Description **Personal watercraft**

Brand **Sea-Doo**

Name **Sea-Doo**

Type / number of model **Fish Pro Scout  
GTI  
GTR  
RXP  
Wake 170**

Weekly report number **Report-2022-29**

Alert submitted by **Belgium**

Is the product counterfeit? **No**

Country of origin **Mexico**

Measures taken by economic operators **Recall of the product from end users  
Importer**

Date of entry into force **08/07/2022**

Products were found and measures were taken also in **Croatia**

Alert number **[A12/01072/22](#)**

Product **Passenger car**

Risk type **Injuries**

**A coding of a control unit may not match the individual vehicle equipment so that the affected control units may malfunction. As a result, some functions of the electronic stability program control unit may not be fully available, thus changing the braking and control behavior, increasing the risk of an accident.**

**The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Mercedes-Benz**

Name **Sprinter, Vito, Viano, V-Class**

EC-type approval/model **e1\*2007/46\*0294\*15-16, e1\*2007/46\*0299\*07, e1\*2007/46\*0300\*18, e1\*2007/46\*0301\*18+20, e1\*2007/46\*0304\*09, e1\*2007/46\*0305\*14, e1\*2007/46\*0308\*08-10, e1\*2007/46\*1760\*04, 906BA50, 906BA35, 906BB35, 906BB50/4x4, 906BB35/4x4, 906BA50/4x4, KL3A4, FL3A4, FL3A5, 639/2, 639/4, 639/5, 639, e1\*2007/46\*1761\*04, e1\*2007/46\*1763\*04, e1\*2007/46\*0457\*27, e1\*2007/46\*0458\*06, \*11, e1\*2007/46\*1459\*14, e9\*2001/116\*0048\*06**

Production dates **14.01.2005 - 10.06.2021**

Company recall code **VS2CSBAS3, VS3CSBAS3, VS3CSBSTA, VS3CSBEZS, VS2CSBHU, VS2CSBSAM, VS2CSBKI, VS2CSBAS1, VS2CSBAS2, VS3CSBSAM, NC2CSBKI, NC2CSBEZS, NC3CSBKI,**

Weekly report number **Report-2022-29**

Alert submitted by **Germany**

Is the product counterfeit?

**No**

Country of origin

**Germany**

Measures taken by economic operators

**Recall of the product from end users  
Manufacturer**

Products were found and measures were taken also in

**The Netherlands**

Alert number **[A12/01074/22](#)**

Product **Soft toy**



Risk type **Choking**

**Small parts can easily detach (ears) from the toy. As a consequence, a small child may put them in the mouth and choke.**

**The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71.**

Category **Toys**

Type **Consumer**

Description **Soft toy dog (white, pink) with black plastic eyes and a black plastic nose; battery compartment in the belly, lid without screws (for 2 x 1.5V batteries; not included)**

Brand **Unknown**

Name **bellender Plüschhund**

Weekly report number **Report-2022-29**

Alert submitted by **Austria**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Stop of sales  
Retailer**

---

Alert number	<b><u><a href="#">A12/01078/22</a></u></b>
Product	<b>Skin-lightening cream</b>

---



Risk type	<b>Chemical</b>  <b>According to the list of ingredients, the product contains hydroquinone. Hydroquinone is a skin sensitiser and may cause allergic contact dermatitis.</b>  <b>The product does not comply with the Cosmetic Products Regulation.</b>
Category	<b>Cosmetics</b>
Type	<b>Consumer</b>
Description	<b>Cosmetic product, cream with skin-lightening and skin-conditioning effect</b>
Packaging description	<b>White, printed plastic pot with red screw top; container wrapped in plastic film, quantity 500 ml, production date 5.2.2022, best-before date February 2027, other marking: NAFDAC 02-5156</b>
Brand	<b>SKIN LIGHT</b>
Name	<b>La Crème éclaircissante traitante</b>
Batch number	<b>GB0335</b>
Weekly report number	<b>Report-2022-29</b>
Alert submitted by	<b>Germany</b>
Is the product counterfeit?	<b>Unknown</b>

Country of origin **Ivory Coast**

Measures taken by economic operators **Recall of the product from end users  
Retailer**

Date of entry into force **13/06/2022**



Alert number

[\*\*A12/01077/22\*\*](#)

Product

**Skin-lightening body lotion**

Risk type

**Chemical**

**According to the list of ingredients, the product contains hydroquinone. Hydroquinone is a skin sensitizer and may cause allergic contact dermatitis.**

**The product does not comply with the Cosmetic Products Regulation.**

Category

**Cosmetics**

Type

**Consumer**

Description

**Cosmetic product, lotion with skin-lightening and skin-conditioning effect**

Packaging description

**White plastic bottle with purple flip-top, hinged cap and dosage spout, completely enclosed in a brightly coloured, printed plastic film, quantity 250 ml, production date February 2021, best-before date February 2023**

Brand

**Clair-Liss Gènia**

Name

**Lightening Body Lotion**

Batch number

**L3667**

Barcode

**6181100322514**

Weekly report number

**Report-2022-29**

Alert submitted by

**Germany**

Is the product counterfeit? **Unknown**

Country of origin **Ivory Coast**

Measures taken by economic operators **Recall of the product from end users  
Retailer**

Date of entry into force **13/06/2022**

Alert number **[A12/01080/22](#)**

Product **Magnetic balls**



Risk type **Injuries**

**The toy is made of small parts (balls) with a high magnetic flux. If a child swallows them, they could attract one another causing intestinal blockage or perforation.**

**The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.**

Category **Toys**

Type **Consumer**

Description **Ball cube consisting of 216 black magnetic balls with a size of 5 mm each, with 36 balls per side. The product is sold online.**

Packaging description **For the product with serial number 20200401, the balls are sealed in plastic, for the product with serial number 20200601, the cube is inserted in a plastic box with a hinged lid. Furthermore, both models are placed in a foam case in a tin box with a lid with a transparent window.**

Brand **Unknown**

Name **Magnetické kuličky Neocube 5 mm, 216 ks - černá**

Type / number of model **00009033**

Batch number **20200601; 20200401**

**5902802913302**

Barcode

Weekly report number **Report-2022-29**

Alert submitted by **Czechia**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market  
Retailer**

Date of entry into force **18/06/2022**

Alert number **[A12/01071/22](#)**

Product **Beach sandals**



Risk type **Chemical**

**The plastic material of the product contains an excessive amount of dibutyl phthalate (DBP) (measured value up to 0.31% by weight). This phthalate may harm the health by causing possible damage to the reproductive system.**

**The product does not comply with the REACH Regulation.**

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Black sandals**

Packaging description **Transparent plastic bag**

Brand **NOIXX**

Name **Lady Flip Flop**

Type / number of model **79433**

Barcode **6419860836201**

Weekly report number **Report-2022-29**

Alert submitted by **Finland**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Import rejected at border  
Importer**

Date of entry into force **04/07/2022**

Alert number **[A12/01070/22](#)**

Product **Plush toy**



Risk type **Choking**

**The plush toy has small parts (eyes). Small children may put them in the mouth and choke.**

**The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.**

Category **Toys**

Type **Consumer**

Description **Grey or dark brown sitting plush donkey with key ring**

Brand **Clip-On Crew**

Name **Key ring**

Type / number of model **442051**

Barcode **5050565480392**

Weekly report number **Report-2022-29**

Alert submitted by **Finland**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public  
authorities

**Import rejected at border  
Importer**

Date of entry into force

**04/07/2022**



Alert number **[A12/01073/22](#)**

Product **Plastic chair**



Risk type **Injuries**

**The chair has insufficient stability and strength, as a result the backrest can break under load, injuring the user.**

**The product does not comply with the requirements of the General Product Safety Directive nor with the European standards EN 12520 and EN 1728.**

Category **Furniture**

Type **Consumer**

Description **Plastic chair**

Brand **Pro Bürosim**

Weekly report number **Report-2022-29**

Alert submitted by **Bulgaria**

Is the product counterfeit? **Unknown**


Country of origin **Turkey**

Measures ordered by public authorities **Import rejected at border  
Importer**

Date of entry into force **01/07/2022**

Alert number **[INFO/00111/22](#)**

Product **Candle**



Risk type **Choking**

**Due to their characteristic appearance, form, colour and size, the candles may be mistaken for food stuff. A small child can put them in the mouth and choke on it. A part from that the muffin shaped candle has decorative parts that can be easily detached.**

**The product does not comply with the requirements of the Food Imitating Directive nor with the requirements of the Toy Safety Directive.**

Category **Decorative articles**

Type **Consumer**

Description **A candle in a ceramic cup imitating cream A candle in plastic packaging imitating a muffin with cream frosting, sprinkled with chocolate sticks and a chocolate heart**

Brand **Unknown**

Weekly report number **Report-2022-29**

Alert submitted by	<b>Bulgaria</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>Bulgaria</b>
Measures ordered by public authorities	<b>Recall of the product from end users Manufacturer</b>
Date of entry into force	<b>01/07/2022</b>

Alert number

**[A12/01075/22](#)**

Product

**Hair dryer**



Risk type

**Burns  
Electric shock  
Fire**

**The hair dryer does not have a thermal cut-out device. The plastic material of the casing is combustible. The hair dryer can overheat and catch fire during use causing burns to the user. The mains cable is not properly protected against pulling and twisting. Live (active) parts can be touched if the internal too thin conductor of the mains connection cable is broken or become free. The user may touch the live parts and receive an electric shock.**

**The product does not comply with the requirements of the Low Voltage Directive nor with the European Standard EN 60335.**

Category

**Electrical appliances and equipment**

Type

**Consumer**

Description

**Black and pink hair dryer with 2 detachable nozzles.**

Packaging description

**Colourful cardboard box**


Brand	<b>BEST</b>
Name	<b>PROFESSIONAL ASCIUGACAPELLI</b>
Type / number of model	<b>FH-307, ART:190043</b>
Barcode	<b>6916766190043</b>
Weekly report number	<b>Report-2022-29</b>
Alert submitted by	<b>Hungary</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>People's Republic of China</b>
Measures ordered by public authorities	<b>Import rejected at border Importer</b>
Date of entry into force	<b>24/06/2022</b>

Alert number

**[A11/00094/22](#)**

Product

**Portable wall lamp**



Risk type

**Electric shock**

**The insulation of the lamp socket cables is inadequate and the mains supply cable may become damaged at the cable entry opening. As a result, live parts may become accessible and the user may consequently receive an electric shock.**

**The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.**

Category

**Lighting equipment**

Type

**Consumer**

Description

**Shell-shaped, portable wall lamp with a halogen bulb placed in a G9 socket, enclosed in a picture frame.**

Packaging description

**Packaging: white cardboard box with color picture of the product.**

Brand

**Unknown**

Name

**kagyló lámpa / Shell Light**

Type / number of model

**SHELL LIGHT-003**

Barcode

**5998982310611**

Weekly report number

**Report-2022-29**

Alert submitted by	<b>Hungary</b>
Is the product counterfeit?	<b>No</b>
Country of origin	<b>People's Republic of China</b>
Measures ordered by public authorities	<b>Withdrawal of the product from the market Distributor</b>
Date of entry into force	<b>03/03/2022</b>