

Alert number **[A12/01368/22](#)**

Product **Fireworks**



Risk type **Burns
Fire
Injuries**

The battery tubes are not stable, hence the product may fall over and shoot in unintended directions. A user or bystander may be hit and suffer injuries. Burning pieces may fall off from the fireworks, and cause injury, burns and/or damage.

The product does not comply with the requirements of the Pyrotechnics Directive nor with the European standard EN 15947-5.

Category **Pyrotechnic articles**

Type **Consumer**

Description **Battery of shot tubes, containing 8 shots.**

Packaging description **Black paper background with fireworks depicted.**

Brand **Liuyang Yihelong Trade Co. Ltd**

Name **Familie Batteri XL**

Type / number of model **07336.9605**

Batch number **21-29005**

Weekly report number **Report-2022-40**

Alert submitted by **Denmark**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures taken by economic operators **Withdrawal of the product from the market
Importer**

Date of entry into force **22/04/2022**

Alert number **[A11/00114/22](#)**

Product **Motorboat**



Risk type **Drowning**

The sealing of plugs in the air-tight compartments of the boat may be defective. This can cause the boat to sink, creating a risk of drowning for passengers.

The product does not comply with the requirements of the Recreational Craft and Personal Watercraft Directive.

Category **Recreational crafts**

Type **Consumer**

Description **Open boat with 4 meters in length and with a centre console**

Packaging description **Not applicable**

Brand **Karel**

Type / number of model **400**

Weekly report number **Report-2022-40**

Alert submitted by **Malta**

Is the product counterfeit? **No**

Country of origin **Greece**

Measures ordered by public authorities **Withdrawal of the product from the market
Other**

Date of entry into force **14/07/2022**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **14/07/2022**

Alert number **[A12/01369/22](#)**

Product **Winch brake for lifeboat**

Risk type **Injuries**

The winch break may malfunction. This could prevent proper lowering of the lifeboat and evacuation of a vessel. Further, passengers/evacuees may suffer severe harm or death due to uncontrolled motion of the lifeboat when lowered.

The product does not comply with the requirements of the Marine Equipment directive

Category **Protective equipment**

Type **Professional**

Description **Winches for survival craft and rescue boats**

Brand **Zhenjiang DH Marine Equipment Co., Ltd.**

Type / number of model **dw34f**

Weekly report number **Report-2022-40**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Recall of the product from end users
Distributor**

Date of entry into force **03/08/2022**

Measures ordered by public authorities **Ban on the marketing of the product and any accompanying measures
Distributor**

Date of entry into force **03/08/2022**

Measures ordered by public authorities **Withdrawal of the product from the market
Distributor**

Date of entry into force **03/08/2022**

Alert number **[A12/01351/22](#)**

Product **Passenger car**

Risk type

Fire

Improper high voltage wiring harness could cause temperature rise and burning of contacts inside the connector. This defect can cause significant damage to the power supply system, increasing the risk of fire.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category

Motor vehicles

Type

Consumer

Description

Passenger car

Brand

OPEL

Name

Vivaro, Zafira

EC-type approval/model

**V
e2*2007/46*0532*18, e2*KS18/858*00004*00**

Production dates

15.03.2022-30.04.2022

Company recall code

O7P

Weekly report number

Report-2022-40

Alert submitted by

Germany

Is the product counterfeit?

No

Country of origin

France

Measures taken by economic operators

**Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in

**France
Poland
Sweden**

Alert number **[A11/00113/22](#)**

Product **Motorboat**



Risk type **Drowning**

The boat does not have enough buoyancy to float when flooded with water. The boat may sink, increasing the risk of drowning for users.

The product does not comply with the requirements of the Recreational Craft and Personal Watercraft Directive.

Category **Recreational crafts**

Type **Consumer**

Description **Open boat with 4.5 meters length**

Packaging description **none**

Brand **Marino**

Type / number of model **Atom 2000/450**

Weekly report number **Report-2022-40**

Alert submitted by **Malta**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures ordered by public authorities **Withdrawal of the product from the market
Other**

Date of entry into force **14/07/2022**

Alert number **[A12/01373/22](#)**

Product **Plush toy**



Risk type **Choking**

Small parts (nose, zipper puller) can easily detach from the toy. A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Puppy dog and tiger plush toys.**

Packaging description **Vacuum bag, plastic bag inside covering plush toy.**

Brand **Unknown**

Name **Plushie puppy**

Type / number of model **2991
2992**

Barcode **6430080070435
6430080070473**

Weekly report number **Report-2022-40**

Alert submitted by **Finland**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Measures ordered by public
authorities

**Import rejected at border
Importer**

Date of entry into force

16/09/2022

Alert number **[A12/01384/22](#)**

Product **Skin-lightening oil**



Risk type **Chemical**

According to the list of ingredients, the product contains hydroquinone. Hydroquinone is a skin sensitiser and may cause allergic contact dermatitis.

The product does not comply with the Cosmetic Products Regulation.

Category **Cosmetics**

Type **Consumer**

Description **Skin-lightening oil**

Packaging description **50 ml white plastic bottle**

Brand **Dream Cosmetics**

Name **Caro White**

Batch number **13/29905-B**

Barcode **6181100530070**

Weekly report number **Report-2022-40**

Alert submitted by **Italy**

Is the product counterfeit? **Unknown**

Country of origin **Ivory Coast**

Measures ordered by public
authorities

**Withdrawal of the product from the market
Importer**

Date of entry into force

04/02/2022

Alert number [**A12/01367/22**](#)

Product **Lubricant**



Risk type **Chemical**

The packaging is not fitted with child-resistant fastenings, nor a tactile warning. Moreover, the label does not include the signal word "Danger", nor the hazard statement "May be fatal if swallowed and enters airways". The user is not properly informed that this product is dangerous by aspiration.

The product does not comply with the classification, labelling and packaging (CLP) Regulation.

Category **Chemical products**

Type **Consumer**

Description **Water resistant lubricant presented as an anti-corrosion agent. Product sold online.**

Packaging description **The product is marketed in five different packages: 29 ml can / 118 ml can / 118 ml aerosol / 355 ml aerosol / 3.7 liter canister**

Brand **Boeshield**

Name **Boeshield T9**

Barcode
370083160000
3700831600017
3700831600024
3700831600031
3700831600048

Weekly report number **Report-2022-40**

Alert submitted by **France**

Is the product counterfeit?	No
Country of origin	United States
Measures taken by economic operators	Recall of the product from end users Importer
Date of entry into force	01/09/2022
Measures taken by economic operators	Withdrawal of the product from the market Importer
Date of entry into force	01/09/2022
Company recall code	- https://rappel.conso.gouv.fr/fiche-rappel/7983/interne

Alert number **[A12/01383/22](#)**

Product **Expandable toy**



Risk type **Choking**

Small part may easily detach from the fish figurine. Further, the toy expands more than 50% in size when in contact with water. If child puts it in the mouth or swallows it, the contact with saliva or stomach liquids will cause the figurine to expand, which can result in occlusion of the respiratory tract or intestinal blockage.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **An egg (size 60 mm) made of easily breaking material, containing a fish figurine made of expandable material.**

Packaging description **Blister and cardboard packaging.**

Brand **CLOWN POLSKA**

Name **Fish Egg Growing Pet**

Type / number of model **C5702**

Barcode **5902510217020**

Weekly report number **Report-2022-40**

Alert submitted by **Poland**

Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Warning consumers of the risks Importer
Date of entry into force	26/08/2022
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	26/08/2022

Alert number **[A12/01374/22](#)**

Product **Children's swimsuit**



Risk type **Strangulation**

The product bears functional cords close to the neck and in the back area. The cords may become trapped during various activities of a child, leading to strangulation.

The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14682.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Children's one-piece swimsuit with girl image in front of the swimsuit with functional cords at the neck and back area.**

Brand **Unknown**

Name **Same game - Let's go my friends**

Type / number of model **6311**

Weekly report number **Report-2022-40**


Alert submitted by **Bulgaria**

Is the product counterfeit? **Unknown**

Country of origin **Unknown**

Measures ordered by public authorities **Withdrawal of the product from the market
Retailer**

Date of entry into force **03/10/2022**



Alert number **[A11/00116/22](#)**

Product **Soft toy**



Risk type **Choking
Suffocation**

The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the stuffing material in the mouth and choke. Moreover, the plastic of the packaging is too thin. If a child plays with the packaging, the plastic can cover the mouth and nose, causing the child to suffocate.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Doll made of textile material, fibrous stuffing.**

Packaging description **Plastic bag.**

Brand **Mega Creative**

Name **Lalka szmaciana**

Type / number of model **INDEX 482482**

Barcode **5908275173809**

Weekly report number **Report-2022-40**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin	People's Republic of China
Measures ordered by public authorities	Warning consumers of the risks Importer
Date of entry into force	31/08/2022
Measures ordered by public authorities	Withdrawal of the product from the market Importer
Date of entry into force	31/08/2022

Alert number

[A11/00115/22](#)

Product

Inflatable boat/dinghy



Risk type

Drowning

The boat does not have enough buoyancy to float when flooded with water. The boat may sink, increasing the risk of drowning for users. Moreover the required warnings and re-boarding instructions are missing in the user manual.

The product does not comply with the requirements of the Recreational Craft and Personal Watercraft Directive.

Category

Recreational crafts

Type

Consumer

Description

Product is an inflatable boat of 2.7 metres with the label GT Inflatables

Brand

GT Inflatables

Name

TMG270

Type / number of model

TMG270

Weekly report number

Report-2022-40

Alert submitted by

Malta

Is the product counterfeit?

No

Country of origin

People's Republic of China

Measures ordered by public authorities

**Withdrawal of the product from the market
Other**

Date of entry into force **14/07/2022**



Alert number **[A12/01365/22](#)**

Product **Rattle toy**



Risk type	<p>Choking</p> <p>A small part can easily detach (sticker mirror). Small children may put it in the mouth and choke.</p> <p>The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.</p>
Category	Toys
Type	Consumer
Description	Helicopter-shaped rattle with a handle
Brand	Unknown
Name	OBALL O-COPTER
Type / number of model	10556
Barcode	074451105560
Weekly report number	Report-2022-40
Alert submitted by	Lithuania
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Importer

Products were found and
measures were taken also in

Estonia
Luxembourg



Alert number **[A12/01375/22](#)**

Product **Plastic toy**



Risk type	<p>Choking</p> <p>The plastic pieces of the toy can easily break, generating small parts. A child may put them in the mouth and choke.</p> <p>The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.</p>
Category	Toys
Type	Consumer
Description	Plastic money box in the shape of a ball, which consists of six different-coloured pieces. The toy is sold disassembled. Product sold online.
Packaging description	Plastic transparent bag with blue cuff. Inside the package there is a paper label with instructions for the composition of the toy.
Brand	Unknown
Name	Ball money box

Barcode	2000590864660
Weekly report number	Report-2022-40
Alert submitted by	Czechia
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	07/09/2022

Alert number **[A12/01371/22](#)**

Product **Plastic doll**



Risk type **Chemical**

The plastic material of the head of the doll contains an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 13.9 % by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Plastic doll about 20 cm tall with accessories (plastic comb in the shape of a starfish). The doll is barefoot. For children older than 3 years of age.**

Packaging description **Cardboard box with transparent window.**

Brand **HAPPY PARTNER !**

Name **L.OL. SURPRISE, LIL SISTERS**

Type / number of model **1886**

Batch number **HD-5162, 3-324-26**

Barcode **8590861770317**

Weekly report number **Report-2022-40**

Alert submitted by **Czechia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Retailer**

Date of entry into force **05/09/2022**

Alert number **[A12/01382/22](#)**

Product **Trailer**

Risk type **Injuries**

Too large tolerances of the installed axle unit in combination with the installed tyre and rim tolerances can cause the tyre to collide with the mudguard support plate when the axle compresses, damaging the inside of the tyre. This can lead to a sudden loss of tyre pressure while driving, increasing the risk of an accident.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Trailer**

Brand **STEMA**

Name **ST O2-1 ww./opt. SySTEMA, Basic**

EC-type approval/model **ST O2-1
e1*2007/46*0112*04**

Production dates **01.06.2022 - 06.09.2022**

Company recall code **STL - Achsvariante AL-KO**

Weekly report number **Report-2022-40**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **The Netherlands**

Alert number **[A12/01381/22](#)**

Product **Passenger car**

Risk type **Injuries**

Improper folding of the airbag may impede the deployment of the passenger side airbag in the event of an accident. A rip could occur in the airbag leading to insufficient protection, increasing the risk of injury.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Audi**

Name **A3, RS 3**

EC-type approval/model **GY
e1*2007/46*2060*, e1*2007/46*2144***

Production dates **09.02.2021 - 28.04.2022**

Company recall code **69DZ**

Weekly report number **Report-2022-40**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Ireland**

Alert number **[A12/01364/22](#)**

Product **Rattle toy**



Risk type **Choking**

The rattle can easily break, generating small parts. A child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Colorful, plastic pram rattle consisting of 4 stringed elephant figurines with hanging rings at the ends.**

Packaging description **Cardboard box with window**

Brand **My Baby**

Name **My Baby Toys**

Type / number of model **5018**

Barcode	1000015205246
Weekly report number	Report-2022-40
Alert submitted by	Hungary
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China
Measures taken by economic operators	Withdrawal of the product from the market Distributor
Date of entry into force	24/05/2022
Measures taken by economic operators	Recall of the product from end users Distributor
Date of entry into force	24/05/2022

Alert number **[A12/01380/22](#)**

Product **Passenger car**

Risk type **Injuries**

Due to a software error, the warning function for malfunctioning blinkers does not work. This can cause an accident.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **OPEL**

Name **Corsa F**

EC-type approval/model **U
e2*2007/46*0639*05-*15**

Production dates **15.07.2019 - 04.06.2021**

Company recall code **E212102140 (22-C-049) O6B**

Weekly report number **Report-2022-40**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Croatia
France
Iceland
Luxembourg
Poland
Slovakia
Sweden**

Alert number **[A12/01366/22](#)**

Product **Power supply**



Risk type	Environment
	The solder has an excessive concentration of lead (Pb) (measured value up to 61.4%). Lead poses a risk to the environment.
	The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).
Category	Electrical appliances and equipment
Type	Consumer
Description	Antenna power supply.
Packaging description	Plastic bag
Brand	LAMEX
Name	Zasilacz antenowy regulowany
Type / number of model	LXG03A
Barcode	5902270748284
Weekly report number	Report-2022-40
Alert submitted by	Poland
Is the product counterfeit?	Unknown
Country of origin	People's Republic of China

Measures ordered by public
authorities

**Warning consumers of the risks
Manufacturer**

Date of entry into force

29/08/2022

Measures ordered by public
authorities

**Withdrawal of the product from the market
Manufacturer**

Date of entry into force

29/08/2022

Alert number **[A12/01386/22](#)**

Product **Laser pointer**



Risk type	<p>Damage to sight</p> <p>The laser beam is too powerful. Direct viewing of the laser beam could cause damage to sight.</p> <p>The product does not comply with the European standard EN 60825.</p>
Category	Laser pointers
Type	Consumer
Description	The metal laser pointer has a cylindrical body of 11.5 cm long and a diameter of 1.60 cm. It can be recharged via a USB plug, which is located at one end. The product emits UV light, LED light and five patterns.
Packaging description	Metal box and cardboard box
Brand	PUTEKCO
Name	LED TRAINING POINTER
Type / number of model	X001E534SN
Weekly report number	Report-2022-40
Alert submitted by	Hungary
Is the product counterfeit?	No
Country of origin	People's Republic of China

Measures ordered by public
authorities

**Import rejected at border
Importer**

Date of entry into force

06/05/2022

Alert number [**A12/01376/22**](#)

Product **Passenger car**

Risk type **Injuries**

The material of the passenger airbag inflator may degrade over time. If deployed, the airbag can be ruptured and metal fragments can pass through the airbag, causing injury to occupants.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Jaguar Land Rover Limited**

Name **XF (X250)**

EC-type approval/model **e11*2001/116*0323***

Production dates **19.11.2007 - 16.03.2018**

Company recall code **H361**

Weekly report number **Report-2022-40**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **United Kingdom**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **20/09/2022**

Alert number **[A12/01370/22](#)**Product **Light commercial vehicle**Risk type **Injuries**

The ball joint head that connects the front suspension arms from its housing can detach. This can lead to a loss of control of the vehicle, increasing the risk of an accident.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**Type **Professional**Description **Light commercial vehicle**Brand **Iveco**Name **Daily**

EC-type approval/model **IS35CC2AA, IS35CI2AA, IS35SC2AA, IS35SI2AA, IS52CC2AA, IS52CI2BA, IS56CC2BA, IS70CC2BA, IS70CI2BA, e3*2007/46*0116*21, e3*2007/46*0117*20, e3*2007/46*0120*21-22, e3*2007/46*0118*22-23, e3*2007/46*0152*19-20, e3*2007/46*0122*20-21, e3*2007/46*0119*21-22, e3*2007/46*0123*18, e3*2007/46*0115*18-19**

Production dates **03.05.2022 - 27.05.2022**Company recall code **49T**Weekly report number **Report-2022-40**Alert submitted by **Germany**Is the product counterfeit? **No**Country of origin **Italy**Measures taken by economic operators **Recall of the product from end users
Manufacturer**Company recall code **- <https://www.iveco.com>**

Products were found and
measures were taken also in

Ireland
The Netherlands
Sweden

Alert number **[A12/01385/22](#)**

Product **Electric kettle**



Risk type **Electric shock**

The metal housing parts of the kettle is only separated from the active heating element with basic insulation and the mains lead has no protective conductor. If the basic insulation or the heat protection device fails, the metal housing parts of the kettle may become live, and the user may receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335.

Category **Electrical appliances and equipment**

Type **Consumer**

Description **White electric kettle. Capacity: 2.3 liters**

Packaging description **Colourful cardboard box.**

Brand **CiaoBosi**

Name **BOLLITORE ELETTRICO**

Type / number of model **TX-9552**

Barcode **6972785795522**

Weekly report number **Report-2022-40**

Alert submitted by **Hungary**

Is the product counterfeit? **No**

Country of origin	People's Republic of China
Measures ordered by public authorities	Recall of the product from end users Distributor
Date of entry into force	02/08/2022
Measures ordered by public authorities	Withdrawal of the product from the market Distributor
Date of entry into force	02/08/2022

Alert number **[A12/01379/22](#)**

Product **Passenger car**

Risk type **Injuries**

Trim parts of the backrest on both front seats can detach during rear airbag deployment in the event of an accident. The airbag deployment may be impaired and the airbag itself may be damaged, increasing the risk of injury to rear occupants.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Maybach S-Class (model series 223)**

Brand **MERCEDES-BENZ**

Name **S-Class**

EC-type approval/model **R2S
e1*2007/46*2115*04, e1*2007/46*2115*05, e1*2007/46*2115*06**

Production dates **11.09.2020 - 16.12.2021**

Company recall code **9190016**

Weekly report number **Report-2022-40**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code **- <https://www.mercedes-benz.de>**

Alert number **[A12/01372/22](#)**

Product **Plastic doll**



Risk type **Chemical**

The plastic material of the head of the doll contains an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 30.2% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system.

The product does not comply with the REACH Regulation.

Category **Toys**

Type **Consumer**

Description **Plastic doll about 25 cm tall, for children above three years of age.**

Packaging description **Cardboard box with transparent window**

Brand **My First Fashion Perfect**

Name **my first**

Type / number of model **958**

Batch number **TT5338K33**

Barcode **8592021053384**

Weekly report number **Report-2022-40**

Alert submitted by **Czechia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Retailer**

Date of entry into force **13/09/2022**

Alert number **[A12/01378/22](#)**

Product **Passenger car**

Risk type **Fire**

Defects in the winding of cell-internal foils in the high-voltage batteries can lead to the occurrence of increased self-discharge. This can cause high voltage cell modules to overheat, increasing the risk of fire.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **MINI**

Name **MINI Cooper Countryman SE ALL4**

EC-type approval/model **FMX
e1*2007/46*1682***

Production dates **20.11.2020 - 26.05.2021**

Company recall code **0061110700**

Weekly report number **Report-2022-40**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **The Netherlands**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code **- <https://www.bmw.de/de/topics/service-zubehoer/bmw-service/rueckrufe.html>**

Alert number **[A12/01377/22](#)**Product **Passenger car**Risk type **Fire**

Defects in the winding of cell-internal foils in the high-voltage batteries can lead to the occurrence of increased self-discharge. This can cause high voltage cell modules to overheat, increasing the risk of fire.

The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.

Category **Motor vehicles**Type **Consumer**Description **Passenger car**Brand **BMW**Name **X2, X1, X3, X5, 5 Limousine, 3 Touring, 3 Limousine, 7**EC-type approval/model **F2X, F1X, G3X, G5X, G5L, G3K, G3L, 7L
e1*2007/46*1824*, e1*2007/46*1676*, e1*2007/46*1797*,
e1*2007/46*1918*, e1*2007/46*1688*, e1*2007/46*2017*,
e1*2007/46*1947*, e1*2007/46*0276***Production dates **02.12.2019 - 22.09.2022**Company recall code **0061100700**Weekly report number **Report-2022-40**Alert submitted by **Germany**Is the product counterfeit? **No**Country of origin **Germany**Measures taken by economic operators **Recall of the product from end users
Manufacturer**Company recall code **- <https://www.bmw.de/de/topics/service-zubehoer/bmw-service/rueckrufe.html>**

Alert number **[A12/01388/22](#)**

Product **Plastic doll**



Risk type **Chemical**

The plastic material of the head of the doll contains an excessive concentration of di-(2-ethylhexyl) phthalate (DEHP).(up to 11.4 % by weight). This phthalate may harm the health of children by possibly causing damage to the reproductive system.

The product does not comply with the requirements of the Toy Safety Directive.

Category **Toys**

Type **Consumer**

Description **Plastic doll (baby), about 13 cm tall with accessories: bathtub, shower set, balloon, pacifier and cap. With the indication that it is for children older than 3 years of age.**

Packaging description **In a plastic packaging with a paper cardboard label.**

Brand **Unknown**

Name **Lovely DOLL**

Type / number of model **TNBL8919-22**

Barcode **6999200015942**

Weekly report number **Report-2022-40**

Alert submitted by **Czechia**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Withdrawal of the product from the market
Retailer**

Date of entry into force **07/09/2022**

Alert number

[A12/01387/22](#)

Product

Children's digital camera



Risk type

Chemical

The charging cable, the plug and the plug top of the product contain an excessive concentration of Dibutyl phthalate (DBP), of bis (2-ethylhexyl) phthalate (DEHP) and Di-'isodecyl' phthalate (DINP) (up to 2.9% by weight). These phthalates may harm the health of children by possibly causing damage to the reproductive system and liver.

The product does not comply with the requirements of the Toy Safety Directive.

Category

Toys

Type

Consumer

Description

Digital camera for children in a child attractive design of a pet. Different pet designs available (penguin, panda, rabbit, chicken, bear, ...). Product also sold online, in particular via AliExpress.

Packaging description

Cardboard packaging.

Brand

Unknown

Name

KIDS CAM - Children's Camera / Design for Children

Type / number of model

YT010

Weekly report number

Report-2022-40

Alert submitted by

Luxembourg

Is the product counterfeit?

Unknown

Country of origin	People's Republic of China
Measures ordered by public authorities	Stop of sales Other
Date of entry into force	30/09/2022
Measures ordered by public authorities	Ban on the marketing of the product and any accompanying measures Other
Date of entry into force	30/09/2022
Measures ordered by public authorities	Recall of the product from end users Other
Date of entry into force	30/09/2022

Alert number **[A11/00112/22](#)**
 Product **Air compressor**



Risk type

Injuries

The product has a valve which does not correspond to the safety requirements. As a result, the valve can malfunction and cause excessive pressure on the tank, which could burst. Furthermore, the materials are too thin to withstand pressure, and the purging device has been installed in a place where it may not perform adequately. Consequently, the product may explode, injuring the users.

The product does not comply with the requirements of the Pressure Equipment Directive nor with the European standard EN 286-1.

Category

Pressure equipment/vessels

Type

Consumer

Description

Simple pressure vessel with the indication CFL-50. PS = 10 bar / PT = 15 bar. Volume: 50 L TS = -10/+90 °C fitted to the SCHEPPACH HC55-8 air compressor. Product sold online.

Brand

Ningbo Huasheng Co. Ltd - SCHEPPACH

Name

Air compressor Ningbo Huasheng (HSNB) - SCHEPPACH

Type / number of model

**CFL-50
HC55-8**

Batch number

201912001

Barcode

4046664066804

Weekly report number

Report-2022-40

Alert submitted by	France
Is the product counterfeit?	No
Country of origin	People's Republic of China
Measures taken by economic operators	Stop of sales Importer
Date of entry into force	04/03/2021