



European Commission (http://ec.europa.eu/index_en.htm) Consumers (http://ec.europa.eu/consumers/index_en.htm)

Consumers safety (http://ec.europa.eu/consumers/consumers_safety/index_en.htm)

Safety products (http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/index_en.htm)

🏠 [Rapid Alert System home \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

☰ [Back to report listings \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2018\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2018)

🔍 [Search alerts \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search)

👍 [Safe Products Online \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline)

The Rapid Alert System for Non-Food Products (RAPEX)

RAPEX - Weekly overview report of notifications

week 9 - 2018

Corrigendum : Notification A12/1829/17 from Report 2017-051 has been temporarily removed while the risk is re-assessed.

Alert number: A12/0298/18

Product: Home perfume

Name: Extrait de parfum

Risk type: Chemical

Category: Chemical products

Brand: Atmosphaera

Type / number of model: 10ml - 130900 F

Risk level: Serious risk

The graphic representation of fruits on the product packaging might be attractive to children.

Because of the product's similarity to a foodstuff, a child could unscrew it and swallow the content, which is harmful to humans.

The product does not comply with the Regulation on the classification, labelling and packaging of substances and mixtures (CLP) and the requirements of the Directive 87/357/EEC on products which, appearing to be other than they are, endanger the health or safety of consumers.

Measures taken by economic operators: Recall of the product from end users (By: Importer)

Description: Perfume extract for indoor use, 10 ml, to be used in conjunction with an incense burner.

Batch number / Barcode: 01 15 417 221 - 2015010086

Country of origin: China

Alert submitted by: France



Alert number: A12/0311/18

Product: Soother holder

Name: Soother Clip

Risk type: Choking

Category: Childcare articles and children's equipment

Brand: Dr Brown's

Type / number of model: No. AC037-INTL

Risk level: Serious risk

The soother holder breaks easily, generating small parts.

A small child may put the small parts in the mouth and choke.

The product does not comply with the relevant European Standard EN 12586.

Measures ordered by public authorities: Recall of the product from end users, Warning consumers of the risks, Withdrawal of the product from the market

Description: Pink or blue coloured soother holders attached to a cardboard with instructions; sold in a blister package.

Batch number / Barcode: 072239301722 - Batch code: SD041615

Country of origin: China

Alert submitted by: The Netherlands

Products were found and measures were taken also in: Iceland



Alert number: A12/0289/18

Product: False nails

Name: Deng Deng

Risk type: Chemical

Category: Clothing, textiles and fashion items

Brand: Unknown

Type / number of model: a) Fashion 100% Security - No S 502 b) 12 PCS Nails - No S 611

Risk level: Serious risk

The glue contains dibutyl phthalate (DBP), which is toxic to reproduction.

The product does not comply with the Cosmetic Products Regulation.

Measures ordered by public authorities: Ban on the marketing of the product and any accompanying measures

Description: Two sets of plastic nails (12 pcs) in different designs and supplied with glue in an orange tube. Packed in a cardboard bag. The notifying authority qualifies the product as a cosmetic.

Batch number / Barcode: a) 6932448262006; b) 6264454898550

Country of origin: China

Alert submitted by: Romania



Alert number: A12/0291/18
Product: Ladies' leather belt
Name: Unknown
Risk type: Chemical
Category: Clothing, textiles and fashion items
Brand: Lili
Type / number of model: Article No 50011001185

Risk level: Serious risk
 The amount of chromium (VI) in the leather is too high.
 Chromium (VI) is sensitising and may trigger allergic reactions.

The product does not comply with the REACH regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Distributor)

Description: Leather belt for women with animal-print textile fabric on the outside.

Batch number / Barcode: 4250980300126

Country of origin: China

Alert submitted by: Germany



Alert number: A12/0312/18

Product: Leather jacket

Name: Celine

Risk type: Chemical

Category: Clothing, textiles and fashion items

Brand: Werner Christ

Type / number of model: Article: 71 2310

Risk level: Serious risk

The amount of chromium (VI) in the leather is too high (measured value: up to 11 mg/kg).
 Chromium (VI) is sensitising and may trigger allergic reactions.

The product does not comply with the REACH Regulation.


Measures taken by economic operators: Withdrawal of the product from the market (By: Importer)

Description: Beige leather jacket with zip fasteners at the front, on the pocket and on the sleeve, metal buckles on the side, beige backstitched seams and fabric lining.

Batch number / Barcode: Bar code: 4054246377217 and 0004719110

Country of origin: Unknown

Alert submitted by: Germany



Alert number: A12/0318/18

Product: Children's swim outfit

Name: Sokisahtel Mermaid

Risk type: Drowning, Injuries, Strangulation

Category: Clothing, textiles and fashion items

Brand: Unknown

Type / number of model: Unknown

Risk level: Serious risk

The bikini has drawstrings in the neck and waist areas.

These can become trapped during various activities of a child, leading to injuries or strangulation.

The product does not comply with the relevant European Standard EN 14682.

The mermaid tail also reduces the child's ability to swim, which poses a risk of drowning.


Measures taken by economic operators: Withdrawal of the product from the market (By: Importer)

Description: Children's bikini set (top and bottom) with mermaid tail (costume and monofin) packed in transparent plastic bag.

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Estonia



Alert number: A12/0325/18

Product: Adult novelty product

Name: Le Body XL

Risk type: Chemical

Category: Clothing, textiles and fashion items

Brand: Zado /Orion

Type / number of model: 020.20007501050

Risk level: Serious risk

The amount of chromium (VI) in the leather parts is too high (measured value up to 26 mg/kg):

Chromium (VI) is sensitising and may trigger allergic reactions.

The product does not comply with the REACH Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Retailer)

Description: Black leather body harness with several leather straps, various buckles, silver-coloured metal rivets and black textile insets, with a zip at the back.

Batch number / Barcode: 20007501050

Country of origin: Turkey

Alert submitted by: Germany

Products were found and measures were taken also in: The Netherlands



Alert number: A12/0327/18

Product: Children's sweatshirt

Name: Unknown

Risk type: Strangulation

Category: Clothing, textiles and fashion items

Brand: Best Kid's

Type / number of model: style MRO-525

Risk level: Serious risk

There are drawstrings in the neck area.

These can become trapped during various activities of a child, leading to strangulation.

The product does not comply with the relevant European Standard EN 14682.

Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market

Description: Children's sweatshirt with hood and drawstrings, inscription "LEGEND 75 Futbol Real"

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Italy



Alert number: A12/0328/18

Product: Children's trousers

Name: Unknown

Risk type: Injuries

Category: Clothing, textiles and fashion items

Brand: Franky Village

Type / number of model: Article FKT-82

Risk level: Serious risk

The drawstrings in the waist area are too long and not fixed to the garment.

They can become trapped during various activities of a child, leading to injuries.

The product does not comply with the relevant European Standard EN 14682.

Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market

Description: Grey jogging bottoms for girls, with drawstring in the waist area.

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Italy



Alert number: A12/0329/18
Product: Children's sweatshirt
Name: Unknown
Risk type: Strangulation
Category: Clothing, textiles and fashion items
Brand: Diamond

Type / number of model: art.0951

Risk level: Serious risk

There are drawstrings in the neck area.

These can become trapped during various activities of a child, leading to strangulation.

The product does not comply with the relevant European Standard EN 14682.


Measures ordered by public authorities (to: Manufacturer): Withdrawal of the product from the market

Description: Children's sweatshirt with zip fastening and drawstrings in the neck area

Batch number / Barcode: size 12Y

Country of origin: Italy

Alert submitted by: Italy



Alert number: A12/0330/18

Product: Children's sweatshirt

Name: Unknown

Risk type: Strangulation

Category: Clothing, textiles and fashion items

Brand: URKIN

Type / number of model: art. HM-316

Risk level: Serious risk

There are drawstrings in the neck area.

These can become trapped during various activities of a child, leading to strangulation.

The product does not comply with the relevant European Standard EN 14682.

Measures ordered by public authorities (to: Importer): Withdrawal of the product from the market

Description: Children's camouflage sweatshirt with hood.

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Italy



Alert number: A12/1424/17

Product: False nails

Name: Dudustrong

Risk type: Chemical

Category: Clothing, textiles and fashion items

Brand: Unknown

Type / number of model: Dudustrong No S627 (Other names : a) Miss Seven; b) Splendid Nail; c) DengDeng)

Risk level: Serious risk

The product contains di-butyl phthalate (DBP), which is toxic to reproduction.

The product does not comply with the Cosmetic Products Regulation.

Measures ordered by public authorities: Withdrawal of the product from the market

Description: Sets of plastic nails in different colours and design. The packaging consists of a plastic blister with 12 pcs of nails and with glue in an orange tube.

Batch number / Barcode: 6958864456270

Country of origin: China

Alert submitted by: Romania





Alert number: A12/0324/18

Product: Thermal insulation

Name: EPS 120 Ignifugat

Risk type: Fire

Category: Construction products

Brand: ADEPLAST

Type / number of model: Unknown

Risk level: Serious risk

The actual reaction to fire class is lower than the declared reaction to fire class.

In case of fire, this could lead to a lower level of safety than expected.

The product does not comply with the requirements of the Construction Products Regulation and the relevant European standard EN 13163.

Measures taken by economic operators: Withdrawal of the product from the market

Description: Thermal insulation with plastic packaging.

Batch number / Barcode: Lot: 010-2017; date of manufacture: 07.06.2017

Country of origin: Romania

Alert submitted by: Bulgaria



Alert number: A12/0290/18

Product: Nail polish

Name: Super Nail Hardner

Risk type: Chemical

Category: Cosmetics

Brand: BNC manicure Miss Rou /, DAEWON Cosmetics

Type / number of model: Unknown

Risk level: Serious risk

The product contains dibutyl phthalate which is toxic to reproduction.

The product does not comply with the Cosmetic Products Regulation.

Measures ordered by public authorities: Withdrawal of the product from the market

Description: Nail polish, available in different colours.

Batch number / Barcode: Unknown

Country of origin: Unknown

Alert submitted by: Romania



Alert number: A12/0304/18

Product: Manicure mask

Name: Manicure Mask

Risk type: Chemical

Category: Cosmetics

Brand: Bellitas Limited / , Strictly Professional

Type / number of model: SPB 0564

Risk level: Serious risk

The product contains the preservative methyl-dibromo glutaronitrile. This substance may cause skin irritation, an allergic skin reaction and respiratory irritation.

The cream also contains isobutylparaben, as indicated in the list of ingredients on the packaging. This paraben has a potential endocrine disrupting activity.

The product does not comply with the Cosmetic Products Regulation.

Measures ordered by public authorities (to: Distributor): Ban on the marketing of the product and any accompanying measures

Description: White plastic 100 ml tube.

Batch number / Barcode: Batch BF 09, 5033940004659

Country of origin: United Kingdom

Alert submitted by: Lithuania

Products were found and measures were taken also in: Latvia



Alert number: A12/0331/18

Product: Candle

Name: Lauakuunal Patina

Risk type: Fire

Category: Decorative articles

Brand: Flora

Type / number of model: 70 x 370 mm table candle

Risk level: Serious risk

Due to its shape of the candle is not stable and may fall over.

As a consequence, it may cause a fire risk.

The product does not comply with the requirements of the European Standard EN 15493

Measures taken by economic operators: Withdrawal of the product from the market (By: Distributor)

Measures ordered by public authorities (to: Distributor): Ban on the marketing of the product and any accompanying measures

Description: Table candle

Batch number / Barcode: 4740005007135

Country of origin: Estonia

Alert submitted by: Finland

Products were found and measures were taken also in: Estonia



Alert number: A12/0297/18

Product: Curling iron

Name: Professional Curling Iron

Risk type: Electric shock

Category: Electrical appliances and equipment

Brand: GEMEI

Type / number of model: model GM-2908

Risk level: Serious risk

The electrical insulation between the live parts of the heating element and the accessible metal parts is inadequate. Accessible parts could therefore become live.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335.

Measures taken by economic operators: Recall of the product from end users (By: Distributor)

Description: Electric hair curling iron supplied in cardboard box.

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: France



Alert number: A12/0321/18

Product: Waste disposal unit

Name: Unknown

Risk type: Injuries

Category: Electrical appliances and equipment

Brand: Franke

Type / number of model: PM3

Risk level: Serious risk

The casing could break.

Casing fragments could be ejected at high speed and may hit the user.

The product does not comply with the requirements of the Low Voltage Directive.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Waste disposal unit for domestic use.

Batch number / Barcode: 134.0255.233

Country of origin: China

Alert submitted by: Italy



Alert number: A12/0316/18

Product: Branch saw

Name: MAG-PRO Garden

Risk type: Cuts, Injuries

Category: Hand tools

Brand: MAG-PRO

Type / number of model: 2682

Risk level: Serious risk

As there is no locking mechanism to keep it in place, the blade can detach from the handle uring use and fall on the user.

As a consequence, the user can suffer cuts and/or injuries.

Measures ordered by public authorities (to: Manufacturer): Recall of the product from end users

Description: The product is sold in individual packages with the name "Oksasaha Teleskoopivarrella"

Batch number / Barcode: 6430033336519

Country of origin: China

Alert submitted by: Finland



Alert number: A12/0307/18

Product: Kick scooter

Name: City custom scooter

Risk type: Injuries

Category: Hobby/sports equipment

Brand: Sportline

Type / number of model: Item: 20223; No. 7020

Risk level: Serious risk

The folding structure of the steering column is not sufficiently resistant to load and can break.

A user riding the scooter might lose balance and fall, leading to injuries.

The product does not comply with the relevant European standard EN 14619.

Measures ordered by public authorities (to: Importer): Recall of the product from end users, Withdrawal of the product from the market

Description: Orange and black coloured foldable metal scooter with adjustable steering column. Load capacity: 100 kg. Packaging: cardboard box

Batch number / Barcode: 8711866202232

Country of origin: Unknown

Alert submitted by: Hungary



Alert number: A12/0308/18

Product: Kick scooter

Name: 125 mm scooter

Risk type: Injuries

Category: Hobby/sports equipment

Brand: Cygnus

Type / number of model: S-125

Risk level: Serious risk

The steering column is not sufficiently resistant to load and can break.

A user riding the scooter might lose balance and fall, leading to injuries.

The product does not comply with the relevant European standard EN 14619.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market

Description: Red and black foldable metal scooter with adjustable steering column. Load capacity: 100 kg. Packaging: cardboard box

Batch number / Barcode: 7640168470630

Country of origin: China

Alert submitted by: Hungary

Products were found and measures were taken also in: Croatia



Alert number: A12/0317/18

Product: Skateboard

Name: Unknown

Risk type: Injuries

Category: Hobby/sports equipment

Brand: Unknown

Type / number of model: KDS-3108AB

Risk level: Serious risk

The axle and the aluminium suspension of the product are not properly resistant to impact.

In case of shock, the axle may bend and the aluminium suspension break, which can lead to an accident.

The product does not comply with the relevant European standard EN 13613.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market

Description: Black, four-wheeled, smooth-surfaced skateboard. The product has black plastic wheels. Load capacity: 20- 50 kilograms

Batch number / Barcode: 5998273717334

Country of origin: China

Alert submitted by: Hungary



Alert number: A12/0333/18

Product: Lift

Name: Unknown

Risk type: Injuries

Category: Lifts

Brand: ThyssenKrupp

Type / number of model: Unknown

Risk level: Serious risk

The upper part of the side rail of the car sling may crack.

The side rail could rupture causing the car to fall.

The product does not comply with the requirements of the Lifts Directive.

Measures taken by economic operators: Corrective action (By: Manufacturer)

Description: Lift

Batch number / Barcode: Production 1999 - 2017 using the TCS25 car sling

Country of origin: Germany

Alert submitted by: Germany

Products were found and measures were taken also in: Denmark, Hungary



Alert number: A12/0319/18

Product: Floodlight

Name: Projecteur Halogène

Risk type: Electric shock

Category: Lighting equipment

Brand: CEBA

Type / number of model: PH400

Risk level: Serious risk

The resistance to humidity is inadequate.

Water may penetrate inside the product leading to a risk of electric shock for the user.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

Measures taken by economic operators: Making the marketing of the product subject to prior conditions (By: Importer)

Description: Halogen floodlight, 400 W , intended to be water resistant.

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: France



Alert number: A12/0335/18

Product: LED tube

Name: T5 LED TUBE 9W

Risk type: Electric shock

Category: Lighting equipment

Brand: LuXray

Type / number of model: HS-T5-600

Risk level: Serious risk

The live end of the tube is accessible.

The user could touch the live parts and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standards EN 60320 and EN 60598.

Measures ordered by public authorities (to: Distributor): Recall of the product from end users, Withdrawal of the product from the market

Description: LED tube. Tubes can connect in series. Packaging: cardboard box.

Batch number / Barcode: Unknown

Country of origin: Unknown

Alert submitted by: Hungary



Alert number: A12/0323/18

Product: Circular saw

Name: Circular Saw

Risk type: Electric shock

Category: Machinery

Brand: RTRMAX

Type / number of model: RTH 182

Risk level: Serious risk

The mechanical strength of the enclosure is inadequate.

The enclosure can break leaving live parts accessible.

The product does not comply with the requirements of the Machinery Directive and relevant European standard EN 60745.

Measures ordered by public authorities (to: Importer): Ban on the marketing of the product and any accompanying measures

Description: Circular saw, packaged in a cardboard box.

Batch number / Barcode: 8694461347570

Country of origin: China

Alert submitted by: Bulgaria



Alert number: A12/0299/18

Product: Passenger car

Name: Karoq

Risk type: Injuries

Category: Motor vehicles

Brand: Skoda

Type / number of model: Type-approval numbers: e8*2007/46*0272; Types: NU

Risk level: Serious risk

In the event of the curtain airbag being deployed, parts of the covering of the A-pillar could break off.

These parts could injure the people in the vehicle.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Passenger car

Batch number / Barcode: Vehicles produced between 10 October 2017 and 19 November 2017 are affected.

Country of origin: Czech Republic

Alert submitted by: Germany

Products were found and measures were taken also in: Bulgaria, Croatia, Estonia, Finland, Greece, Slovakia, Slovenia, Sweden, The Netherlands

Alert number: A12/0300/18

Product: Passenger car

Name: Alhambra

Risk type: Injuries

Category: Motor vehicles

Brand: SEAT

Type / number of model: 7N*

Risk level: Serious risk

The passenger airbag module may have been produced with an inadequate welded connection between the detonator and generator.

In the event of an accident, the airbag may not deploy correctly, reducing the protection of the passenger.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Passenger car

Batch number / Barcode: Model year 2017, produced between 13.9.2016 and 2.11.2016.

Country of origin: Spain

Alert submitted by: Spain

Products were found and measures were taken also in: Germany, Slovakia, Slovenia, Sweden, The Netherlands

Alert number: A12/0301/18**Product:** Passenger car**Name:** Leon**Risk type:** Injuries**Category:** Motor vehicles**Brand:** SEAT**Type / number of model:** 5F**Risk level:** Serious risk

In the event of deployment of the passenger airbag, the casing of the gas generator could be damaged.

Metal parts may become detached from the casing and cause injury to the occupants of the vehicle.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Passenger car**Batch number / Barcode:** Model year 2015, produced between 19.9.2014 and 6.10.2014.**Country of origin:** Spain**Alert submitted by:** Spain**Products were found and measures were taken also in:** Germany, Sweden, The Netherlands**Alert number:** A12/0302/18**Product:** Motorcycle**Name:** Roadmaster**Risk type:** Injuries**Category:** Motor vehicles**Brand:** Indian Motorcycles**Type / number of model:** Unknown**Risk level:** Serious risk

Water may enter a rear light wiring harness and cause corrosion.

Corroded wires may cause erratic operation of the rear and brake lights, leading to an accident.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Motorcycle**Batch number / Barcode:** Motorcycles built between 06/06/2014 and 27/07/2017.**Country of origin:** United States**Alert submitted by:** United Kingdom**Products were found and measures were taken also in:** Greece, Sweden, The Netherlands**Alert number:** A12/0303/18**Product:** Passenger car**Name:** A3**Risk type:** Fire**Category:** Motor vehicles**Brand:** Audi**Type / number of model:** Type approval number: e1 * 2001/116 * 0217 * ; Type: 8P**Risk level:** Serious risk

The starter motor may overheat.

This could lead to a fire breaking out in the vehicle.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Passenger car**Batch number / Barcode:** The vehicles affected were produced between March 2011 and August 2011.**Country of origin:** Germany**Alert submitted by:** Germany**Products were found and measures were taken also in:** Bulgaria, Croatia, Denmark, Estonia, Finland, Greece, Romania, Slovakia, Slovenia, Sweden, The Netherlands**Alert number:** A12/0305/18**Product:** Passenger car**Name:** RC F**Risk type:** Fire**Category:** Motor vehicles**Brand:** Lexus**Type / number of model:** USC10; EC-type approval number: e11*2007/46*1532.**Risk level:** Serious risk

The pulsation damper in one of the high pressure fuel pumps could be defective, leading to vibration which could cause the pump cover to develop a fatigue crack.

The crack could expand and fuel may leak, which could lead to a vehicle fire.

Measures taken by economic operators: Recall of the product from end users (By: Importer)

Description: Passenger car**Batch number / Barcode:** Production period: 6/6/2014 - 4/12/2017**Country of origin:** Japan**Alert submitted by:** Portugal**Products were found and measures were taken also in:** Bulgaria, Hungary, Poland, Sweden, The Netherlands

Alert number: A12/0306/18
Product: Passenger car
Name: Range Rover, Discovery
Risk type: Fire
Category: Motor vehicles
Brand: Land Rover
Type / number of model: Range Rover, Range Rover Sport, Range Rover Evoque, Range Rover Velar, Discovery Sport, All-New Discovery.
Risk level: Serious risk
The brazing of the fuel rail end caps may not properly seal the fuel rail ends.
Over time, this can lead to a liquid fuel leak into the engine bay.
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Description: Passenger car
Batch number / Barcode: Vehicles built between 05/05/2016 and 31/01/2018.
Country of origin: United Kingdom
Alert submitted by: United Kingdom
Products were found and measures were taken also in: Finland, Greece, Malta, Poland, Sweden, The Netherlands

Alert number: A12/0309/18
Product: Motorcycle
Name: GL1800A Goldwing
Risk type: Injuries
Category: Motor vehicles
Brand: Honda
Type / number of model: Type:SC68, EU Type Approval numbers: e4*92/61*0107*06, e3*2002/24*2803*00-04
Risk level: Serious risk
The ammonium nitrate propellant used in the air bag inflator may degrade over time due to heat cycles and exposure to moisture.
In the event of the airbag being deployed, the excessive internal pressure may cause the inflator body to rupture and metal fragments may pass through the cushion material causing injury to the rider.
Measures taken by economic operators: Recall of the product from end users (By: Distributor)
Description: Motorcycle
Batch number / Barcode: The recall affects model year 2010 – 2016 vehicles, produced from 23/09/2008 to 22/10/2015.
Country of origin: Japan
Alert submitted by: Greece
Products were found and measures were taken also in: Croatia, Estonia, Finland, Poland, Portugal, Slovakia, Slovenia, Sweden, The Netherlands

Alert number: A12/0310/18
Product: Passenger car
Name: Various models
Risk type: Fire
Category: Motor vehicles
Brand: Jaguar
Type / number of model: XE, XF, E-PACE, F-PACE, F-TYPE
Risk level: Serious risk
The brazing of the fuel rail end caps may not properly seal the fuel rail ends.
Over time, this can lead to a liquid fuel leak into the engine bay.
Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Description: Passenger car
Batch number / Barcode: Vehicles built between 01/09/2016 and 17/08/2017 with 2.0L petrol engine.
Country of origin: United Kingdom
Alert submitted by: United Kingdom
Products were found and measures were taken also in: Bulgaria, Finland, Greece, Poland, Sweden, The Netherlands

Alert number: A12/0314/18

Product: Motorcycle

Name: Various models

Risk type: Injuries

Category: Motor vehicles

Brand: Triumph

Type / number of model: Classic Range, Thruxton, Thruxton R, Thruxton 1200 (Dual Seat), Thruxton 1200R (Dual Seat)

Risk level: Serious risk

The engine management software may not always maintain a stable engine idle when the throttle is opened and closed very quickly, with the clutch disengaged.

This could lead to the engine stalling without warning, which could cause an accident.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Motorcycle

Batch number / Barcode: Motorcycles built between 12/11/2015 and 22/12/2017.

Country of origin: United Kingdom

Alert submitted by: United Kingdom

Products were found and measures were taken also in: Croatia, Estonia, Germany, Greece, Malta, Poland, Slovenia, Sweden, The Netherlands

Alert number: A12/0326/18

Product: Van

Name: T6

Risk type: Injuries

Category: Motor vehicles

Brand: VW

Type / number of model: EC type-approval number: e1*2007/46*0130, e1*2001/116*0289, e1*2001/116*0220; Type: 7JO, 7HMA, 7HC

Risk level: Serious risk

The front passenger airbag may have been folded incorrectly when it was manufactured.

A small front-seat passenger may be insufficiently protected in the event of an accident where the airbag is deployed.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Van

Batch number / Barcode: Vehicles produced between 9 November 2017 and 8 December 2017 are affected.

Country of origin: Germany

Alert submitted by: Germany

Products were found and measures were taken also in: Bulgaria, Denmark, Estonia, Ireland, Poland, Slovakia, Slovenia, Sweden, The Netherlands

Alert number: A12/0332/18

Product: Passenger car

Name: Various models

Risk type: Burns

Category: Motor vehicles

Brand: VW

Type / number of model: Golf, Golf Cabrio, Passat, Polo, Sharan, Golf Plus, Scirocco, Passat CC, Eos, Touran, Golf Variant, Jetta, Beetle, Beetle Cabrio, Tiguan

Risk level: Serious risk

A spring in the starter motor's magnetic switch was incorrectly installed.

The starter motor may overheat, which could lead to a fire breaking out in the vehicle.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Passenger car

Batch number / Barcode: The vehicles concerned were manufactured between March and July 2011

Country of origin: Germany

Alert submitted by: Germany

Products were found and measures were taken also in: Bulgaria, Croatia, Denmark, Estonia, Finland, Greece, Iceland, Ireland, Poland, Slovakia, Slovenia, Sweden, The Netherlands

Alert number: A12/0292/18

Product: Safety shoes

Name: Unknown

Risk type: Injuries

Category: Protective equipment

Brand: Zante

Type / number of model: Siena

Risk level: Serious risk

The safety shoes are not sufficiently resistant to impact.

This could result in an injury to the user's feet in case of a shock.

The product does not comply with the requirements of the Personal Protective Equipment Directive and the relevant European standard EN ISO 20345.

Measures ordered by public authorities (to: Importer): Import rejected at border

Description: Safety shoes

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0295/18

Product: Safety shoes

Name: Unknown

Risk type: Injuries

Category: Protective equipment

Brand: SUBWAY by JHAYBER

Type / number of model: Model: 85021 'Indiana Camel'

Risk level: Serious risk

The safety shoes are not sufficiently resistant to impact.

This could result in an injury to the user's feet in case of a shock.

The product does not comply with the requirements of the Personal Protective Equipment Directive and the relevant European standard EN ISO 20345.

Measures ordered by public authorities (to: Importer): Import rejected at border

Description: Safety footwear in cardboard packaging

Batch number / Barcode: 8432891626973

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0287/18

Product: Fancy-dress make-up set

Name: Maquillage

Risk type: Chemical

Category: Toys

Brand: Festifolie

Type / number of model: ITEM n. 39038

Risk level: Serious risk

The make-up contains nickel (measured value up to 12 mg/kg).

Nickel is a strong sensitizer and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin.

The product does not comply with the requirements of the Toy Safety Directive.

Measures ordered by public authorities (to: Importer): Ban on the marketing of the product and any accompanying measures

Description: Fancy-dress/Carnival make-up set.

Batch number / Barcode: 3 120370 390383; Batch K0474

Country of origin: China

Alert submitted by: Italy

Products were found and measures were taken also in: France



Alert number: A12/0288/18

Product: Inflatable toy

Name: Rock-n-Roll

Risk type: Environment

Category: Toys

Brand: Unknown

Type / number of model: Item No.: AP0220 (from invoice), Store's code: 315623

Risk level: Serious risk

The transparent plastic valve contains short-chain chlorinated paraffins (SCCPs) (measured value up 0.62% per weight).

SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bioaccumulate in wildlife and humans, posing a risk to human health and the environment.

The product does not comply with the Regulation on persistent organic pollutants (POP Regulation).

Measures ordered by public authorities (to: Importer): Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market

Description: Inflatable guitar made of PVC in green and black. Aprox. height: 90 cm. Sold without packaging.

Batch number / Barcode: Unknown

Country of origin: China

Alert submitted by: Greece



Alert number: A12/0293/18

Product: Toy gun

Name: Eva Pop Gun

Risk type: Choking

Category: Toys

Brand: Super Juguete

Type / number of model: Ref. 999503

Risk level: Serious risk

The suction cups can easily detach from the projectiles.

If a child puts the projectile in the mouth, the suction cup may detach and obstruct the airways.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Measures ordered by public authorities (to: Importer): Import rejected at border

Description: Suction-cup gun supplied in a cardboard box

Batch number / Barcode: 8435265703526

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0294/18

Product: Toy cooking set

Name: Kitchen Tableware

Risk type: Choking

Category: Toys

Brand: Marco's Toys

Type / number of model: Ref 1664

Risk level: Serious risk

The cooker control button easily becomes detached, generating a small part.
A small child may put this small part in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Measures ordered by public authorities (to: Importer): Import rejected at border

Description: Toy cooking set with various utensils; supplied in a cardboard and blister packaging

Batch number / Barcode: 8435399016646

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0296/18

Product: Toy guitar

Name: Guitar Music

Risk type: Choking

Category: Toys

Brand: NAFENG

Type / number of model: Ref 03-6620

Risk level: Serious risk

The toy breaks easily, generating small parts.
A small child may put a small part in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard, EN 71-1.

Measures ordered by public authorities (to: Importer): Import rejected at border

Description: Guitar with lights and sound effects supplied in a cardboard box

Batch number / Barcode: 8349000366207

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0313/18

Product: Keychain

Name: Five nights at Freddy's

Risk type: Chemical

Category: Toys

Brand: Funko

Type / number of model: 102231

Risk level: Serious risk

The amount of nickel released by the metallic part of the key ring is too high (measured value: 6.15 µg/cm²/week).

Nickel is a strong sensitizer and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin.

The product does not comply with the REACH Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Distributor)

Description: Keychain with a yellow bird. The bird wears a bib with the text LET'S EAT.

Batch number / Barcode: 849803088415

Country of origin: China

Alert submitted by: Sweden

Products were found and measures were taken also in: Slovakia



Alert number: A12/0315/18

Product: Toy plastic purse set

Name: Unknown

Risk type: Chemical

Category: Toys

Brand: Fashion Girl

Type / number of model: Unknown

Risk level: Serious risk

The red plastic material of the straps and flat strings of the bags contains diisononylphthalate (DINP) (measured value: 20 % by weight).

The product does not comply with the REACH Regulation.

Measures ordered by public authorities (to: Importer): Import rejected at border

Description: Set of two small pink plastic purses with pictures of girls on blue/blue-yellow background. Smaller bag has a keyring on it. Packed in a transparent blister and pink cardboard packaging.

Batch number / Barcode: 6412165066243

Country of origin: China

Alert submitted by: Finland



Alert number: A12/0320/18

Product: Plastic doll

Name: Belinda Mermaid

Risk type: Chemical

Category: Toys

Brand: Jiali Toys, Superjuguetes

Type / number of model: Ref: 55199

Risk level: Serious risk

The plastic material of the doll contains di-(2-ethylhexyl) phthalate (DEHP) (measured value: more than 20% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Measures ordered by public authorities (to: Importer): Import rejected at border

Description: Plastic mermaid doll sold in a cardboard box with window.

Batch number / Barcode: 845285714478

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0322/18

Product: Toy block set

Name: DARADISE BLOCKS

Risk type: Choking

Category: Toys

Brand: TOINSA

Type / number of model: Product ref. 03-0014

Risk level: Serious risk

Small parts can easily be detached from the plastic figures (the head).

A small child may put this small part in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.

Measures ordered by public authorities (to: Importer): Import rejected at border

Description: Plastic toy block set, including small figures, supplied in a plastic bag.

Batch number / Barcode: 8349000300140

Country of origin: China

Alert submitted by: Spain



Alert number: A12/0334/18

Product: Plastic swing

Name: Papi

Risk type: Injuries

Category: Toys

Brand: Metalcar

Type / number of model: 1054

Risk level: Serious risk

The knots of the rope can come loose and the rope may detach from the seat.

A child could consequently fall from the swing.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-8.

Measures ordered by public authorities (to: Distributor): Withdrawal of the product from the market

Description: Green, plastic swing for small children. The swing rope is knotted under the seat and the swing is equipped with a horn.

Batch number / Barcode: 5997421710548

Country of origin: Hungary

Alert submitted by: Hungary



Alert number: A12/0336/18

Product: Activity balls

Name: Activiteitenballen

Risk type: Choking

Category: Toys

Brand: Playing Kids

Type / number of model: Itemnr 25749ASW1

Risk level: Serious risk

The balls are not closed properly and could open, resulting in release of small parts.

A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.

Measures taken by economic operators: Recall of the product from end users (By: Distributor)

Description: Box with several transparent plastic balls with shapes and figures in different colours inside, making rattling noises. For the development of motor skills of babies.

Batch number / Barcode: 1.) 4894532160617; batchcode 06/16 , 2.) 4894532440276; 07/2017

Country of origin: China

Alert submitted by: The Netherlands

Products were found and measures were taken also in: France



Alert number: A12/0337/18

Product: Toy gun set

Name: Super soft bullet gun

Risk type: Chemical

Category: Toys

Brand: P.H. KRIS - TAEM

Type / number of model: 00-73101

Risk level: Serious risk

The suction cups contain di-(2-ethylhexyl) phthalate (DEHP) (measured value: 4 % by weight), dibutyl phthalate (DBP) (measured value: 2.1% by weight) and diisobutyl phthalate (DIBP) (12.1 % by weight).

These phthalates may harm the health of children causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Importer)

Description: Set of plastic toy gun and three projectiles. Plastic suction cups are attached to the projectiles. Packed in a blister with cardboard back.

Batch number / Barcode: 5906160173101

Country of origin: China

Alert submitted by: Poland



Alert number: A12/0338/18

Product: Plastic doll

Name: Beauty in marine trip

Risk type: Chemical

Category: Toys

Brand: Unknown

Type / number of model: 02012G

Risk level: Serious risk

The doll's head contains di-(2-ethylhexyl) phthalate (DEHP) (measured value: 27.2 % by weight).

This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Importer)

Description: Plastic mermaid doll with plastic accessories. Packed in a blister with cardboard back.

Batch number / Barcode: 7460801009245

Country of origin: China

Alert submitted by: Poland



Alert number: A11/0020/18

Product: Circular saw

Name: Circular Saw

Risk type: Cuts

Category: Machinery

Brand: BORT

Type / number of model: BHK-160U; art. 93727215

Risk level: Other risk level

The upper guard of the saw does not fully cover the blade-cutting zone.

Hair or clothing of the user might get caught in the saw.

The product does not comply with the requirements of the Machinery Directive and relevant European standard EN 60745.

Measures taken by economic operators: Withdrawal of the product from the market (By: Importer)

Description: Electrical circular saw, 1250 W, packed in cardboard box.

Batch number / Barcode: UMG1500500074/08/2015

Country of origin: China

Alert submitted by: Latvia



