



European Commission ([http://ec.europa.eu/index\\_en.htm](http://ec.europa.eu/index_en.htm)) Consumers ([http://ec.europa.eu/consumers/index\\_en.htm](http://ec.europa.eu/consumers/index_en.htm))

Consumers safety ([http://ec.europa.eu/consumers/consumers\\_safety/index\\_en.htm](http://ec.europa.eu/consumers/consumers_safety/index_en.htm))

Safety products ([http://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/index\\_en.htm](http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/index_en.htm))

🏠 [Rapid Alert System home \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/repository/content/pages/rapex/index\\_en.htm\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

☰ [Back to report listings \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.listNotifications&year=2018\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2018)

🔍 [Search alerts \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=main.search\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search)

👍 [Safe Products Online \(https://ec.europa.eu/consumers/consumers\\_safety/safety\\_products/rapex/alerts/?event=SafeProductsOnline\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline)

## The Rapid Alert System for Non-Food Products (RAPEX)

### *RAPEX - Weekly overview report of notifications*

week 19 - 2018

**Alert number:** A12/0667/18

**Product:** Children's booster seat

**Name:** 3 Stage Booster Seat

**Risk type:** Injuries, Suffocation

**Category:** Childcare articles and children's equipment

**Brand:** Venture

**Type / number of model:** Mini Booster Seat

**Risk level:** Serious risk

The booster seat has an inadequate locking mechanism, restraining and chair attachment system. A child may fall off the seat and suffer injuries. Moreover, the plastic packaging of the product is too large and too thin without being perforated: If a child plays with the packaging, the plastic can cover the mouth and nose, causing the child to suffocate.

The product does not comply with the relevant European standard EN 16120.

**Measures taken by economic operators:** Warning consumers of the risks (By: Importer)

**Description:** Booster seat for children between 6 and 36 months (maximum weight of 15kg), designed to be fitted to a chair. Packaged in a cardboard box.

**Batch number / Barcode:** 50700461909323

**Country of origin:** China

**Alert submitted by:** United Kingdom



**Alert number:** A12/0671/18

**Product:** Children's cot

**Name:** Adrian

**Risk type:** Entrapment

**Category:** Childcare articles and children's equipment

**Brand:** Comptine

**Type / number of model:** code : 88570

**Risk level:** Serious risk

The upper and lower limbs of a small child may become trapped in the gaps between the cot's bars.

The product does not comply with the requirements of the relevant European Standard EN 716.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Children's wooden cot

**Batch number / Barcode:** lot 10813117 / EAN 3254568848827

**Country of origin:** Poland

**Alert submitted by:** France



**Alert number:** A12/0660/18

**Product:** Hand cream

**Name:** Крем-бальзам "Целитель"

**Risk type:** Chemical

**Category:** Cosmetics

**Brand:** Aromat

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains a mixture of methylchloroisothiazolinone and methylisothiazolinone (MCI/MI).

Dermal contact with products containing MCI/MI can provoke allergic contact dermatitis, especially to sensitised persons.

In addition, the product contains isobutylparaben.

The product does not comply with the Cosmetic Products Regulation.

**Measures ordered by public authorities (to: Importer):** Ban on the marketing of the product and any accompanying measures

**Description:** Hand cream supplied in a tube made of white and green coloured plastic with a green screw cap (70 g), supplied in a white cardboard packaging.

**Batch number / Barcode:** Batch No. 19 02 2017, barcode 4820147051712

**Country of origin:** Ukraine

**Alert submitted by:** Lithuania



**Alert number:** A12/0662/18

**Product:** Hair styling product

**Name:** FINISH shaping pomade

**Risk type:** Chemical

**Category:** Cosmetics

**Brand:** Unknown

**Type / number of model:** Unknown

**Risk level:** Serious risk

The product contains a mixture of the preservatives Methylchloroisothiazolinone and Methylisothiazolinone (MCI/MI).

Dermal contact with MCI and MI containing products can provoke allergic contact dermatitis to sensitised persons.

The product does not comply with the Cosmetic Products Regulation

**Measures ordered by public authorities (to: Distributor):** Ban on the marketing of the product and any accompanying measures

**Description:** Hair styling product supplied in a bright grey plastic container with screw cap.

**Batch number / Barcode:** 0551AN, barcode 8032825191702

**Country of origin:** Italy

**Alert submitted by:** Lithuania



**Alert number:** A12/0642/18

**Product:** Electric heater

**Name:** Electric Oil Filled Radiator

**Risk type:** Burns

**Category:** Electrical appliances and equipment

**Brand:** SENCOR

**Type / number of model:** SOH 3009BE

**Risk level:** Serious risk

The radiator may become pressurised during use.

This could lead to hot oil leaking.

The product does not comply with the requirements of the Low Voltage Directive.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)

**Company recall page:**

<http://www.sencor.cz/dobrovolne-stazeni> (<http://www.sencor.cz/dobrovolne-stazeni>)

**Description:** Electric oil-filled radiator

**Batch number / Barcode:** Lot 2016300912

**Country of origin:** China

**Alert submitted by:** Czech Republic



**Alert number:** A12/0651/18

**Product:** Charger

**Name:** Unknown

**Risk type:** Electric shock

**Category:** Electrical appliances and equipment

**Brand:** Flextronics (COUNTERFEIT)

**Type / number of model:** A1444 (COUNTERFEIT)

**Risk level:** Serious risk

The electrical insulation is inadequate.

The user could receive an electric shock from accessible parts.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60950.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Small white charger

**Batch number / Barcode:** Unknown

**The product is counterfeit**

**Country of origin:** Unknown

**Alert submitted by:** Denmark



**Alert number:** A12/0654/18

**Product:** Hairdryer

**Name:** PROFESSIONAL HAIR DRYER

**Risk type:** Burns, Electric shock, Fire

**Category:** Electrical appliances and equipment

**Brand:** PROGA.MA

**Type / number of model:** Model: GM-1802; No: 16772

**Risk level:** Serious risk

The hair dryer does not have a thermal cut-out device. The plastic material of the casing is combustible.

The hair dryer can overheat and catch fire. Melted plastic can cause burns and leave live parts accessible.

The product does not comply with the Low Voltage Directive and the relevant European standard EN 60335.

**Measures ordered by public authorities (to: Importer):** Recall of the product from end users, Withdrawal of the product from the market

**Description:** Electric hairdryer with folding handle, packed in a cardboard box.

**Batch number / Barcode:** 6 957952 218028

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/0655/18

**Product:** Hairdryer

**Name:** Super hair dryer

**Risk type:** Burns, Electric shock, Fire

**Category:** Electrical appliances and equipment

**Brand:** NOVA

**Type / number of model:** N-674; No: 16771 / 1200109

**Risk level:** Serious risk

The hairdryer does not have a thermal cut-out device. The plastic material of the casing is combustible. The mains cable is not properly anchored.

The hair dryer can overheat and catch fire. Melted plastic can cause burns and leave live parts accessible. The mains cable could detach leaving the live conductors accessible.

The product does not comply with the Low Voltage Directive and the relevant European standard EN 60335.

**Measures ordered by public authorities (to: Importer):** Recall of the product from end users, Withdrawal of the product from the market

**Description:** Electric hairdryer packed in a cardboard box.

**Batch number / Barcode:** 6 925979 750029

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/0636/18

**Product:** Caster board

**Name:** Unknown

**Risk type:** Injuries

**Category:** Hobby/sports equipment

**Brand:** Maxima

**Type / number of model:** Article No.200143, Batch No. L0217

**Risk level:** Serious risk

The outer line of the board is not sufficiently rounded.

As a consequence there are sharp edges which can lead to injury.

The product does not comply with the relevant European Standard EN 13613.

**Measures ordered by public authorities (to: Importer):** Ban on the marketing of the product and any accompanying measures

**Description:** Skateboard (caster board), divided into two platforms, interconnected with torsion suspension, with 2 silicone wheels.

**Batch number / Barcode:** 3 800784 201436

**Country of origin:** China

**Alert submitted by:** Bulgaria



**Alert number:** A12/0637/18

**Product:** Lighting chain

**Name:** LED ROPE LIGHT 10M

**Risk type:** Electric shock

**Category:** Lighting chains

**Brand:** Unknown

**Type / number of model:** WT-LED-G- 10 24

**Risk level:** Serious risk

Water can enter the flashing unit.

The user could receive an electric shock from accessible parts.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

**Measures ordered by public authorities (to: Retailer):** Recall of the product from end users

**Description:** 10-metre LED lighting chain intended for outdoor use.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0659/18

**Product:** Lighting chain

**Name:** 100 LED LIGHT

**Risk type:** Electric shock, Fire

**Category:** Lighting chains

**Brand:** Unknown

**Type / number of model:** XM-LED1-100C

**Risk level:** Serious risk

The cable is not properly anchored. The accessible wires have only basic insulation. The cable is too thin. The product is not protected against moisture.

The basic insulated cable could detach or damage leaving the live conductors accessible. Water penetration may cause an electric shock. The cable could overheat leading to a fire.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

**Measures ordered by public authorities (to: Distributor):** Recall of the product from end users, Withdrawal of the product from the market

**Description:** Lighting chain with 100 purple LED lamps intended for outdoor use. Packaging: cardboard box.

**Batch number / Barcode:** 9 796104 579016

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/0661/18

**Product:** Lighting chain

**Name:** BUON NATALE 100L LED

**Risk type:** Electric shock, Fire

**Category:** Lighting chains

**Brand:** Unknown

**Type / number of model:** 17292 / 501272

**Risk level:** Serious risk

The cable is not properly anchored. The accessible wires have only basic insulation. The cable is too thin.

The basic insulated cable could detach or damage leaving the live conductors accessible. The cable could overheat leading to a fire.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

**Measures ordered by public authorities (to: Distributor):** Recall of the product from end users, Withdrawal of the product from the market

**Description:** Lighting chain with 96 LED lamps (12 blue, 20 green, 32 yellow, 32 red). Packaging: cardboard box.

**Batch number / Barcode:** 8 010805 012728

**Country of origin:** China

**Alert submitted by:** Hungary



**Alert number:** A12/0670/18

**Product:** Lighting chain

**Name:** GUIRLANDE LUMINEUSE

**Risk type:** Electric shock

**Category:** Lighting chains

**Brand:** Lights

**Type / number of model:** GS-50

**Risk level:** Serious risk

The cable is not properly anchored.

The cable could detach leaving live parts accessible.

The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.

**Measures taken by economic operators:** Recall of the product from end users (By: Importer)

**Description:** Lighting chain with multicoloured bulbs. Sold in a clear round plastic box.

**Batch number / Barcode:** 3660092574864

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0635/18

**Product:** Gantry Crane

**Name:** Gantry Crane

**Risk type:** Injuries

**Category:** Machinery

**Brand:** Pellegrini

**Type / number of model:** GCM 10/20

**Risk level:** Serious risk

The gantry crane braking system can fail during strong wind.

This can lead to an uncontrolled movement of the cranes, causing them to derail, collapse and cause damage.

The product does not comply with the Machinery Directive.

**Measures ordered by public authorities:** Other

**Description:** Gantry crane

**Batch number / Barcode:** Serial no. 9053, 9054. Manufactured: 2012

**Country of origin:** Italy

**Alert submitted by:** Poland



**Alert number:** A12/0633/18  
**Product:** All-terrain vehicle  
**Name:** ACE  
**Risk type:** Environment, Fire  
**Category:** Motor vehicles  
**Brand:** Polaris  
**Type / number of model:** ACE 500, ACE 570, ACE 900  
**Risk level:** Serious risk  
 Fuel may leak from the fuel pump flange assembly.  
 This could cause environmental damage and/or create a fire hazard.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** All-terrain vehicles  
**Batch number / Barcode:** Vehicles built between 11/08/2016 and 28/02/2018.  
**Country of origin:** United States  
**Alert submitted by:** United Kingdom

**Alert number:** A12/0634/18  
**Product:** Bus  
**Name:** Integro, Intouro, Setra, Turismo, Travego  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** EvoBus  
**Type / number of model:** Type-approval numbers: e1\*2007/46\*0024, \*0023, \*0132, \*0022, \*0025, \*0012, \*0014, \*0018, \*0021, \*0019 Types: 632 01, 632 03, 632 07, 632 04, 632 02, 633 01, 633 04, 633 05, 633 02, 633 03 3  
**Risk level:** Serious risk  
 The upper door bearing could break.  
 This could lead to the door falling off while the vehicle is moving.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Bus  
**Batch number / Barcode:** Vehicles produced between March 2015 and October 2017 are affected.  
**Country of origin:** Germany  
**Alert submitted by:** Germany

**Alert number:** A12/0646/18  
**Product:** Passenger car  
**Name:** 3008  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Peugeot  
**Type / number of model:** e2\*2007/46\*0534\*01, e2\*2007/46\*0534\*02, e2\*2007/46\*0534\*03, e2\*2007/46\*0534\*04, e2\*2007/46\*0534\*05  
**Risk level:** Serious risk  
 The bolts attaching the tow bar may not be correctly tightened.  
 Parts of the tow bar could detach and fall on the road.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car  
**Batch number / Barcode:** Vehicles manufactured between 15/06/2017 and 15/01/2018  
**Country of origin:** France  
**Alert submitted by:** France  
**Products were found and measures were taken also in:** The Netherlands

**Alert number:** A12/0648/18  
**Product:** Motorcycle  
**Name:** 111ci  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Indian Motorcycles  
**Type / number of model:** Unknown  
**Risk level:** Serious risk  
 The right hand switch control cube could be faulty.  
 This could cause the motorcycle to power-up or start unintentionally, placing the rider at a risk of injury.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Motorcycle  
**Batch number / Barcode:** Specific motorcycles built between 20/04/2017 and 17/11/2017.  
**Country of origin:** United States  
**Alert submitted by:** United Kingdom

**Alert number:** A12/0650/18  
**Product:** Passenger car  
**Name:** Q2, A3, A4, A5  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Audi  
**Type / number of model:** Type-approval numbers: e1\*2007/46\*1552\*, e1\*2007/46\*0607\*, e1\*2001/116\*0430\*, e1\*2001/116\*0217\*; types: GA, 8V, B8, 8P  
**Risk level:** Serious risk  
The adhesive attaching the windscreen is not sufficiently secure.  
In the event of an accident, the protective effect of the passenger airbag could be compromised.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car  
**Batch number / Barcode:** The vehicles affected were produced on 29.8.2017.  
**Country of origin:** Germany  
**Alert submitted by:** Germany  
**Products were found and measures were taken also in:** The Netherlands

**Alert number:** A12/0652/18  
**Product:** Passenger car  
**Name:** SLS AMG  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Mercedes-Benz  
**Type / number of model:** Type-approval numbers: e1\*2007/46\*0233\*09-11 Typ: 197  
**Risk level:** Serious risk  
The control device for seat occupant detection may not work correctly.  
In the event of an accident where the airbags are deployed, this could lead to deployment of the passenger airbag in the presence of a child seat, or non-deployment of the passenger airbag in the presence of a person.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car  
**Batch number / Barcode:** The vehicles affected were produced between 10 October 2016 and 14 March 2017.  
**Country of origin:** Germany  
**Alert submitted by:** Germany

**Alert number:** A12/0653/18  
**Product:** Passenger car  
**Name:** Rio  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** KIA  
**Type / number of model:** Type-approval number: e11\*2007/46\*3777\*00  
**Risk level:** Serious risk  
The cable length of the rear door lock assemblies may be incorrect.  
Although appearing to engage, the child lock may not engage.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car  
**Batch number / Barcode:** Manufactured from 0.04.2017 to 05.06.2017.  
**Country of origin:** Republic of Korea  
**Alert submitted by:** Poland  
**Products were found and measures were taken also in:** Ireland, The Netherlands

**Alert number:** A12/0656/18  
**Product:** Passenger car  
**Name:** X3  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** BMW  
**Type / number of model:** G3X, type approval number: e1\*2007/46\*1797  
**Risk level:** Serious risk  
In case of deployment of the driver airbag module, the gas generator could burst.  
If the gas generator bursts, metal fragments could pass through the airbag cushion material.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car  
**Batch number / Barcode:** Vehicles manufactured between 8 December 2017 and 17 March 2018 are affected.  
**Country of origin:** Germany  
**Alert submitted by:** Germany  
**Products were found and measures were taken also in:** Ireland, The Netherlands

**Alert number:** A12/0657/18  
**Product:** All-terrain vehicle  
**Name:** Phoenix 200  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Polaris  
**Type / number of model:** Unknown  
**Risk level:** Serious risk  
 The throttle lever stop may not operate properly due to damage during shipping.  
 Inability to control the vehicle as expected could cause the rider to crash or fall off.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** All-terrain vehicle  
**Batch number / Barcode:** Vehicles built between 19/07/2013 and 26/01/2017.  
**Country of origin:** United States  
**Alert submitted by:** United Kingdom  
**Products were found and measures were taken also in:** Ireland

**Alert number:** A12/0668/18  
**Product:** Light truck  
**Name:** XZU710, XZU720, XZU730  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Hino  
**Type / number of model:** Unknown  
**Risk level:** Serious risk  
 The front passenger airbag inflator may be susceptible to moisture intrusion over time.  
 This could lead to the inflator rupturing in the event that the airbag is deployed. The ruptured parts could be propelled into the vehicle cabin causing injuries to the occupants.  
**Measures taken by economic operators:** Recall of the product from end users (By: Importer)  
**Description:** Light truck  
**Batch number / Barcode:** Unknown  
**Country of origin:** Japan  
**Alert submitted by:** Malta

**Alert number:** A12/0669/18  
**Product:** Heavy goods vehicles  
**Name:** P-, G-, R-, T-series and L-,P-,G-,R-,S-series  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Scania  
**Type / number of model:** Various models  
**Risk level:** Serious risk  
 There is insufficient protection from dirt and spray water by the dust covers mounted in the factory.  
 This could cause damage to the CNG (Compressed Natural Gas) tanks and lead to accidents.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Heavy goods vehicles  
**Batch number / Barcode:** The vehicles in question were manufactured between 2010 and 2017.  
**Country of origin:** Sweden  
**Alert submitted by:** Germany

**Alert number:** A12/0672/18  
**Product:** Passenger car  
**Name:** 488 GTB, 488 Spider  
**Risk type:** Injuries  
**Category:** Motor vehicles  
**Brand:** Ferrari  
**Type / number of model:** Type-approval number: e3\*2007/46\*0040\*12-14; type: F142  
**Risk level:** Serious risk  
 Because of a software defect, critical brake disk wear is not indicated by a warning light or warning message.  
 This could lead to damage to the brake disk and increased risk of an accident.  
**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)  
**Description:** Passenger car  
**Batch number / Barcode:** The vehicles affected were produced between January 2015 and November 2015.  
**Country of origin:** Italy  
**Alert submitted by:** Germany  
**Products were found and measures were taken also in:** The Netherlands



**Alert number:** A12/0673/18**Product:** Passenger car**Name:** Tribeca**Risk type:** Injuries**Category:** Motor vehicles**Brand:** Subaru**Type / number of model:** Type-approval number: e13\*2001/116\*0190\*00-05; type:WX**Risk level:** Serious risk

There is a defect in the gas generator of the passenger airbag.

In case of deployment of the airbag, uncontrolled inflation could occur, releasing metal fragments which could cause injury to the occupants.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)**Description:** Passenger car**Batch number / Barcode:** The vehicles concerned were manufactured between 2006 and 2014.**Country of origin:** Japan**Alert submitted by:** Germany**Products were found and measures were taken also in:** The Netherlands**Alert number:** A12/0676/18**Product:** Motorcycle**Name:** Leoncino 500 and TRK 502**Risk type:** Injuries**Category:** Motor vehicles**Brand:** BENELLI**Type / number of model:** EC type approval numbers: e13\*168/2013\*00200\*01 (Leoncino 500) and e13\*168/2013\*00123\*01 (TRK 502)**Risk level:** Serious risk

The front brake pump may be defective.

Under particular conditions, the defect could lead to an increased stopping distance.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)**Description:** Motorcycle**Batch number / Barcode:** The recall affects model year 2017 motorcycles**Country of origin:** China**Alert submitted by:** Greece**Alert number:** A12/0679/18**Product:** Pick-up truck**Name:** Ranger**Risk type:** Injuries**Category:** Motor vehicles**Brand:** Ford**Type / number of model:** Type Approval Number: E11\*2007/46\*0154\*12**Risk level:** Serious risk

The vehicles may have been fitted with a defective airbag initiator.

This may prevent the side airbag deploying in the event of an accident.

**Measures taken by economic operators:** Recall of the product from end users (By: Manufacturer)**Description:** Pick-up truck**Batch number / Barcode:** Vehicles built between 07/10/2016 and 17/11/2016 are affected.**Country of origin:** South Africa**Alert submitted by:** United Kingdom**Alert number:** A12/0649/18**Product:** Protective eyewear**Name:** Lunettes incolores [colourless eyewear]**Risk type:** Injuries**Category:** Protective equipment**Brand:** Delta tactics**Type / number of model:** AC12504**Risk level:** Serious risk

The frame is not resistant enough and can break under impact.

As a result, the user could get injured.

The product does not comply with the requirements of the Personal Protective Equipment Directive.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)**Description:** Protective eyewear intended, in particular, for use during airsoft games**Batch number / Barcode:** Unknown**Country of origin:** Spain**Alert submitted by:** France

**Alert number:** A12/0666/18

**Product:** Climbing rope

**Name:** Sport Rope

**Risk type:** Injuries

**Category:** Protective equipment

**Brand:** Unknown

**Type / number of model:** Reference: 03F-5113

**Risk level:** Serious risk

The rope is insufficiently resistant to dynamic loads.

The rope could break during use causing the climber to fall to the ground.

The product does not comply with the Personal Protective Equipment Directive and the relevant European standard EN 892.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Climbing rope in various colours

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0658/18

**Product:** Firework

**Name:** DUMBUM

**Risk type:** Damage to hearing

**Category:** Pyrotechnic articles

**Brand:** Klasek

**Type / number of model:** P6B

**Risk level:** Serious risk

The sound pressure level is too high. This can cause damage to hearing.

The product does not comply with the requirements of the Pyrotechnics Directive and the relevant European standard EN 15947.

**Measures ordered by public authorities (to: Manufacturer):** Withdrawal of the product from the market

**Description:** Flash bangers packed in boxes of 5 units. The packaging bears the inscription "DUMBUM Petarda Simply the best..."

**Batch number / Barcode:** Year of manufacture 2016, Batch number: 1/16, Bar Code: 8595182430742

**Country of origin:** China

**Alert submitted by:** Czech Republic



**Alert number:** A12/0645/18

**Product:** Wooden pencil set

**Name:** Boîtes de crayons bois

**Risk type:** Chemical

**Category:** Stationery

**Brand:** Editions Valoire-Estel

**Type / number of model:** 1731

**Risk level:** Serious risk

The black pencil contains lead (measured value: 83 mg/kg).

A child can put the pencil in its mouth and be exposed to lead.

Exposure to lead is harmful for human health and can cause developmental neurotoxicity.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Wooden case with a ruler on the sliding top, containing 6 coloured pencils (red, orange, blue, black, green and yellow).

**Batch number / Barcode:** EAN: 3 557020 173100

**Country of origin:** Spain

**Alert submitted by:** France



**Alert number:** A12/0638/18

**Product:** Soft toy

**Name:** Unknown

**Risk type:** Chemical, Choking

**Category:** Toys

**Brand:** Protec inermidia rios

**Type / number of model:** Unknown

**Risk level:** Serious risk

The suction cup detaches from the toy and a small child could put it in the mouth and choke. The plastic of the suction cup of the toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 28.3% by weight).

This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation, with the requirement of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures taken by economic operators:** Recall of the product from end users (By: Retailer)

**Description:** Green soft toy representing a giraffe, with a suction cup attached by a string.

**Batch number / Barcode:** 6975428189603

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0639/18

**Product:** Soft toy

**Name:** Unknown

**Risk type:** Chemical, Choking

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** JTCE3800

**Risk level:** Serious risk

The suction cup detaches from the toy and a small child could put it in the mouth and choke. The plastic of the suction cup of the toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 20% by weight).

This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation, with the requirement of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures taken by economic operators:** Recall of the product from end users (By: Distributor)

**Description:** Soft toy in the shape of an owl with a suction cup attached.

**Batch number / Barcode:** 3760233238003

**Country of origin:** Hong Kong

**Alert submitted by:** France



**Alert number:** A12/0640/18

**Product:** Beach toy set

**Name:** Toys

**Risk type:** Choking

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** Unknown

**Risk level:** Serious risk

The pink castle mould can break easily generating small parts.

A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures taken by economic operators:** Recall of the product from end users (By: Retailer)

**Description:** Plastic coloured beach toys, packed in a plastic net with a label.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0641/18

**Product:** Toy helicopter

**Name:** Cartoon Helicopter

**Risk type:** Choking

**Category:** Toys

**Brand:** XING HONG TOY

**Type / number of model:** HG-582

**Risk level:** Serious risk

Small parts can easily detach from the toy (the plastic wheel and the plastic base).

Small children may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the European Standard EN 71-1.

**Measures taken by economic operators:** Recall of the product from end users (By: Retailer)

**Description:** Toy plastic helicopter with music and lights.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** France



**Alert number:** A12/0643/18

**Product:** Puzzle clock

**Name:** MY FUNNY CLOCK

**Risk type:** Choking

**Category:** Toys

**Brand:** ABC SCHOOL

**Type / number of model:** Ref. 00277

**Risk level:** Serious risk

The clock's hands come off easily and are small parts.

A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.

**Measures ordered by public authorities (to: Importer):** Import rejected at border

**Description:** Puzzle clock with slot-in, geometric shapes, packaged in a blister pack.

**Batch number / Barcode:** 1432296002779

**Country of origin:** China

**Alert submitted by:** Spain



**Alert number:** A12/0644/18

**Product:** Plastic doll

**Name:** Lovely Doll Series

**Risk type:** Choking

**Category:** Toys

**Brand:** YALE TOYS

**Type / number of model:** Reference 17823 - 7008S

**Risk level:** Serious risk

The doll's arms come off and are small parts.

A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures ordered by public authorities (to: Importer):** Import rejected at border

**Description:** Plastic doll with a bib around the neck, packaged in a cardboard box.

**Batch number / Barcode:** 8436019617823

**Country of origin:** China

**Alert submitted by:** Spain



**Alert number:** A12/0647/18

**Product:** Toy cars

**Name:** POWER Racing car

**Risk type:** Choking

**Category:** Toys

**Brand:** EUROJUGUETES

**Type / number of model:** Ref. 50782

**Risk level:** Serious risk

The aeriels and sirens of the cars detach, generating small parts.

A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.

**Measures ordered by public authorities (to: Importer):** Import rejected at border

**Description:** Plastic toy car set: ambulance, police car and fire engine in a blister packaging.

**Batch number / Barcode:** 8430373016933

**Country of origin:** China

**Alert submitted by:** Spain



**Alert number:** A12/0663/18

**Product:** Expandable toys

**Name:** Growing toys

**Risk type:** Choking, Injuries

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** Unknown

**Risk level:** Serious risk

The dinosaurs and the balls are small parts.

Small children may put them in the mouth and choke.

Moreover, the dinosaurs and the balls expand 600% in size when in contact with water. If the child puts them in the mouth or swallows them, the contact with saliva or stomach liquids will cause these pieces to expand, which can result in occlusion of the respiratory track or intestinal blockage.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.

**Measures ordered by public authorities (to: Importer):** Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market

**Description:** An expandable (600%) toy dinosaur and small, colourful balls packed in a transparent bag. Sold in a plastic and cardboard packaging containing 20 units.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Greece



**Alert number:** A12/0664/18

**Product:** Kitchen play set

**Name:** Cutlery Play Set

**Risk type:** Choking

**Category:** Toys

**Brand:** D663

**Type / number of model:** Code 51005, ref. PAK 2872

**Risk level:** Serious risk

The control switches on the toy cooker detach, generating small parts.

A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.

**Measures ordered by public authorities (to: Importer):** Import rejected at border

**Description:** Toy kitchen set with various utensils in a cardboard-blister packaging.

**Batch number / Barcode:** 8422259510055

**Country of origin:** China

**Alert submitted by:** Spain

**Products were found and measures were taken also in:** The Netherlands



**Alert number:** A12/0665/18

**Product:** Toy kitchen set

**Name:** La hora del té

**Risk type:** Suffocation

**Category:** Toys

**Brand:** Toy Planet

**Type / number of model:** Ref TPKEE021665

**Risk level:** Serious risk

The sugar bowl has a hemispheric shape.

It could cover the nose and mouth of small children, leading to suffocation.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

**Measures ordered by public authorities (to: Importer):** Import rejected at border

**Description:** Toy tea set with various utensils, packed in a cardboard box with window.

**Batch number / Barcode:** 4892668216659

**Country of origin:** China

**Alert submitted by:** Spain



**Alert number:** A12/0674/18

**Product:** Plastic doll

**Name:** Girl

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** SNF930153

**Risk level:** Serious risk

The plastic material of the doll's head contains 2-ethylhexyl phthalate (DEHP) (measured value: 15,8 % by weight).

This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Importer)

**Description:** Plastic doll. Packaged in cardboard box with plastic window

**Batch number / Barcode:** EAN: 6991209301538

**Country of origin:** China

**Alert submitted by:** Poland



**Alert number:** A12/0675/18

**Product:** Plastic toys

**Name:** Zabawka

**Risk type:** Chemical

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** PTE094972

**Risk level:** Serious risk

The plastic material of the toy contains 2-ethylhexyl phthalate (DEHP) (measured value: 22,8 %).

This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Importer)

**Description:** Set of two plastic ponies and a toy plastic baby bottle. Packaged in plastic bag with cardboard label.

**Batch number / Barcode:** EAN: 6991200949722

**Country of origin:** China

**Alert submitted by:** Poland



**Alert number:** A12/0677/18**Product:** Mermaid doll**Name:** TOYS TOYS**Risk type:** Chemical**Category:** Toys**Brand:** Unknown**Type / number of model:** Unknown**Risk level:** Serious risk

The plastic material of the doll contains di-(2-ethylhexyl) phthalate (DEHP) (measured value: up to 29.5% by weight).

This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

**Measures ordered by public authorities (to: Distributor):** Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market

**Description:** Plastic mermaid doll with pink/brown long hair, blue bra and blue tail, packed in transparent plastic bag.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Greece

**Alert number:** A12/0678/18**Product:** Toy slime**Name:** Unknown**Risk type:** Chemical**Category:** Toys**Brand:** BARREL-O-SLIME**Type / number of model:** MT1978**Risk level:** Serious risk

The product contains boron (measured value: 3871 mg/kg).

Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.

**Measures ordered by public authorities (to: Distributor):** Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market

**Description:** Black toy slime, packed in black plastic barrel (height: 4.5 cm, diameter: 4 cm), wrapped with transparent plastic film. Sold in a promotion box (30 pieces).

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Greece

**Alert number:** A12/0680/18**Product:** Push-along toy**Name:** Zabawka**Risk type:** Chemical, Choking**Category:** Toys**Brand:** Unknown**Type / number of model:** NGHF087402**Risk level:** Serious risk

The battery compartment can easily be opened without use of any tools and the button cell batteries inside are easily accessible. Moreover, small parts may easily detach from the toy.

A small child may put one of these small parts in the mouth and choke on it. If a button battery is swallowed, this can cause damage to the gastrointestinal tract.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.

**Measures taken by economic operators:** Withdrawal of the product from the market (By: Importer)

**Description:** Plastic push-along toy, powered with button cell batteries. Packaged in plastic bag.

**Batch number / Barcode:** EAN: 5902388099193

**Country of origin:** China

**Alert submitted by:** Poland



**Alert number:** A12/0681/18  
**Product:** Liquid for soap bubbles  
**Name:** BUBBLE  
**Risk type:** Chemical  
**Category:** Toys  
**Brand:** Cartoon funny toys  
**Type / number of model:** Unknown  
**Risk level:** Serious risk

The product does not bear the required pictograms, warnings and instructions for use in Greek.  
As a consequence, parents are not aware of the risks and might leave the child unattended with the product. The child may swallow the soap solution, causing vomiting, diarrhea or other gastrointestinal disorder.

The product does not comply with the requirements of the Toy Safety Directive.

**Measures ordered by public authorities (to: Distributor):** Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market

**Description:** Refill liquid for soap bubble toys in a yellow bottle with multicolored label and white lid.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Greece



**Alert number:** A12/0682/18

**Product:** Plastic doll

**Name:** LAL

**Risk type:** Chemical

**Category:** Toys

**Brand:** Xu Shun Wan Ju, YONG

**Type / number of model:** NO: 881

**Risk level:** Serious risk

The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 31.7 % by weight).  
This phthalate may harm the health of children, causing possible damage to the reproductive system.

The product does not comply with the REACH Regulation.

**Measures ordered by public authorities (to: Retailer):** Withdrawal of the product from the market

**Description:** Plastic doll about 33 cm tall with red shoes and long hair.

**Batch number / Barcode:** Unknown

**Country of origin:** China

**Alert submitted by:** Czech Republic



**Alert number:** A11/0033/18

**Product:** Water gun

**Name:** Water gun

**Risk type:** Injuries

**Category:** Toys

**Brand:** Unknown

**Type / number of model:** No. 508 (on the product); ITEM NO. OWGDH0266 (on the packaging)

**Risk level:** Other risk level

The design of the trigger on the water gun is not appropriate.

The fingers of the children may become trapped between the moving and the fixed parts of the trigger and get injured.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard En 71-1.

**Measures ordered by public authorities (to: Distributor):** Withdrawal of the product from the market

**Description:** Plastic water gun with 700 ml water tank, sold without packaging.

**Batch number / Barcode:** 3245676282665, Batch NO.: 122016

**Country of origin:** China

**Alert submitted by:** Hungary

